

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 28 Jun 2019

Preliminary Advice

Vehicle No	: SJY9035R	Accident Date	: 24/06/2019
Make	: NISSAN SYLPHY	Policy No.	: DMPCSN3025571900
Assignment Date	: 26/06/2019	Excess	: S\$3,500.00
Date of Inspection	: 27/06/2019	Est. Duration of Repair	: -
Inspection At	: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, n/s body and parts claimed are consistent to the accident.
The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	TOTAL LOSS
Lump Sum Repair :S\$		

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 19,000.00
COE / PARF Rebate	:S\$ 14,410.00
Salvage Value	:S\$
Margin for Repair	:S\$ 4,590.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :