

LCRF PTE LTD
 CARROS CENTER
 60 JALAN LAM HUAT #04-01 S(737869)
 Main +65 62524991

Axa Insurance

8 Shenton Way, #24-01 AXA Tower,
 Singapore 068811
 Tel:

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : SLL9232H
 CHASSIS NO : NHP1707067354
 MAKE / MODEL : TOYOTA SIENTA HYBRID
 DATE OF ACCIDENT : 17 JUN 2019
 YOUR INSURED VEHICLE NUMBER : GBC2498C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

	<u>PARTS DISCRPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER / RR	1PC	\$450.00	\$450.00
2	FRONT BUMPER SIDE RETAINER / RR	1PC	\$120.00	\$120.00
3	FRONT BUMPER FOG LAMP GARNISH / CVT	1PC	\$144.00	\$144.00
4	FRONT BUMPER SIDE BRACKET / MIS	1PC	\$75.00	\$75.00
5	HEADLAMP RH / RR	1PC	\$990.00	\$990.00
6	HEADLAMP PANEL RH / X R	1PC	\$175.00	\$175.00
7	FRONT FENDER RH / RR	1PC	\$540.00	\$540.00
8	FRONT FENDER EMBLEM / RR	1PC	\$45.00	\$45.00
9	FRONT FENDER INNER SHIELD / CR4	1PC	\$225.00	\$225.00
10	BONNET X R	1PC	\$570.00	\$570.00
11	BONNET HINGE X	1PC	\$96.00	\$96.00

LIST TOTAL S\$:	\$3,430.00
25.00% DISCOUNT S\$:	\$857.50
	\$2,572.50

SPECIAL NETT

1	FRONT BUMPER CLIP	<i>1pc</i>	1 SET	\$35.00	<i>30 ✓</i>
2	FRONT FENDER INNER SHIELD CLIP	<i>1pc</i>	1 SET	\$35.00	<i>20 ✓</i>

Special Nett Total S\$: \$70.00

LABOUR CHARGES

1	TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE STRAIGHTEN.FRONT FENDER ,FRONT HEADLAMP PANEL,BONNET			\$1,200.00	<i>550</i>
2	TO PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)FRONT FENDER,FRONT BUMPER,HEADLAMP PANEL			\$1,200.00	<i>600</i>
3	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO			\$120.00	<i>70</i>
4	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS.			\$100.00	<i>20 / 30</i>
5	TO CONDUCT ALL WHEEL ALIGNMENT CHECK			\$120.00	<i>30 / 60</i>

LABOUR TOTAL S\$:	<u> </u> \$2,740.00
TOTAL S\$:	\$5,382.50
7% GST	\$376.78
GRAND TOTAL S\$:	<u> </u> \$5,759.28

Steve (LKK)
8322 8813
Stevechan@1kkautb.com

with Mr/ndc 26/6/19, 2.00 pm
5 # days
48 P/P
Ry # spy
Beh

Prepared By :-
 Henry Ng
 Motor Claims
 TEL: 62524991
 EMAIL: henry@lioncityrentals.com.sg