

05/2010

INS. CASE OWNER:

CC4/FWD1901

1328

Ueb3/9

LKK:
IDAC:

Surveyor:

mmfws

DOI:

ASSIGNMENT
20/6/19

Date / Time:

20/6/19

Registered in Merimot:

20/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

FBK 71412

Claim No.:

120190005831

Name of Insured:

TIMOFOR RANDBAL PATENEK

Policy No.:

PNMLW17-00001981-01

Insured Tel No.:

HP:

Make / Model:

Banyu

Excess Sec II :SS

D.O.A.:

6/6/19

Place of Accident:

ITE TMS TPE

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(VA- YES / NO)

Of GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SME 29632



INSRS:
WSP:
Tel:
Liability:
RMKS:

Lee Brothers



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting hr (1st):	
	Non-Reporting hr (2nd):	
	Non-Reporting hr (Final):	
	Notification hr (if non-pickup):	
	Call OI:	
	After call hr to OI:	
	Documentation Check List:	Handler Typist
	Notification hr (if non-pickup)	<input checked="" type="checkbox"/>
	After call hr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: MAVON
 Repair Cost: SS 1000.00 (3 days) Reduction: SS 519.65 to 62 Email Call

FINAL SETTLEMENT Date/Time: Confirm with: Adeline Email Call
 Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 21 If NO or B 25, Ass. Lia:
 Repair Cost: SS 2033.00 or REPAIR ENDED TP.

Loss of Rental (LOR): SS 400.00 (4 days) x 100.00
 Loss of Use (LOU): SS (5 x days)
 Loss of Income (LOI): SS (5 x days)
 LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search: SS 36.45
 Medical: SS
 Disbursement: SS (e.g. Tow/ Independent)
 Legal Cost: SS

Total: SS 2469.45 Global Sum SS: -
 1) Claim status: Normal/Reject/Private Settle
 2) Report Format: TP
 3) Survey fee: \$500

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS 2469.45 Name 1: Lee Brothers Automotive Pte Ltd

Payee 2: (Strike if N.A.) SS Name 2:
 Payee 3: (Strike if N.A.) SS Name 3:

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883
 Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.
FWD SINGAPORE PTE LTD
 6 TEMASEK BOULEVARD
 #18-01 SUNTEC TOWER FOUR
 SINGAPORE 038986
FBK7141Z

Not Allowed
with
1/5 \$1900
3 days
wh/wh/wh
28/6/19

ESTIMATE
 DATE : 25.06.2019
 VEHICLE NO : SME2563Z
 HYUNDAI
 MAKE/MODEL : ELANTRA
 ACC DATE : 06.06.2019

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS

LIST PRICE			
1	1 REAR BOOT	1,782.4	1,782.40 x
2	1 REAR BOOT RUBBER	115.8	115.80 x
3	1 REAR BOOT LOCK	135.8	135.80 x
4	1 REAR BOOT EMBLEM LOGO	28.0	28.00 x
5	1 REAR BOOT EMBLEM ELANTRA	48.8	48.80 x
6	1 REAR BOOT EMBLEM S	38.8	38.80 x
7	1 REAR BUMPER	556.8	556.80
8	1 REAR BUMPER REFLECTOR LH	68.8	68.80
9	1 REAR BUMPER REINFORCEMENT	328.0	328.00
10	1 REAR BUMPER UNDER COVER LH	94.3	94.30 x
11	2 REAR BUMPER SIDE RETAINER RH/LH	44.8	89.60 x
			<u>3,287.10</u>
		LESS 20%	657.42
			<u>2,629.68</u>

SPECIAL NETT ITEMS			
1	1 FRONT BUMPER LOWER SPOILER	680.0	680.00 ✓
2	1 (SET) FRONT BUMPER CLIPS	45.0	45.00
3	1 (SET) FRONT BUMPER REVERSE SENSOR	280.0	280.00 x
			<u>1,005.00</u>

LABOUR CHARGES :			
1	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS		500.00 300
2	TO SPRAY PAINTING ON ACCIDENT PORTION		700.00 500
3	TO CHECK WIRING		20.00 2
4	TO REMOVE, REFIX INNER TRIM		80.00 60
5	TO REMOVE, REPLACE REVERSE SENSOR		80.00 50
6	TO TUFF KOTE		40.00 x
			<u>1,420.00</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 5,054.68

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883
 Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.
FWD SINGAPORE PTE LTD
 6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER FOUR
 SINGAPORE 038986
FBK7141Z

*NOT Afford
 rlr
 1/5 3 day
 wh/br/fflr
 26/6/19*

ESTIMATE
 DATE : 25.06.2019
 VEHICLE NO : SME2563Z
 HYUNDAI
 MAKE/MODEL : ELANTRA
 ACC DATE : 06.06.2019

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
LIST PRICE			
1	1 REAR BOOT	1,782.40	1,782.40
2	1 REAR BOOT RUBBER	115.80	115.80
3	1 REAR BOOT LOCK	135.80	135.80
4	1 REAR BOOT EMBLEM LOGO	28.00	28.00
5	1 REAR BOOT EMBLEM ELANTRA	48.80	48.80
6	1 REAR BOOT EMBLEM S	38.80	38.80
7	1 REAR BUMPER	556.80	556.80
8	1 REAR BUMPER REFLECTOR LH	68.80	68.80
9	1 REAR BUMPER REINFORCEMENT	328.00	328.00
10	1 REAR BUMPER UNDER COVER LH	94.30	94.30
11	2 REAR BUMPER SIDE RETAINER RH/LH	44.80	89.60
			3,287.10
LESS 20%			657.42
			2,629.68
SPECIAL NETT ITEMS			
1	1 FRONT BUMPER LOWER SPOILER	680.00	680.00
2	1 (SET) FRONT BUMPER CLIPS	45.00	45.00
3	1 (SET) FRONT BUMPER REVERSE SENSOR	280.00	280.00
			1,005.00
LABOUR CHARGES :			
1	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS		500.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION		700.00
3	TO CHECK WIRING		20.00
4	TO REMOVE, REFIX INNER TRIM		80.00
5	TO REMOVE, REPLACE REVERSE SENSOR		80.00
6	TO TUFF KOTE		40.00
			1,420.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 5,054.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1200G
Vehicle Details	
Vehicle No.:	SME2563Z
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	G4FGJU270970
Chassis No.:	KMHD841CMJU760479
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,572.00
Original Registration Date:	25 Sep 2018
First Registration Date:	25 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$12,572.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Sep 2028
PARF Rebate Amount:	\$9,429.00
Intended COE Rebate Details	
COE Expiry Date:	24 Sep 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,000.00
COE Rebate Amount:	\$25,890.00
Total Rebate Amount:	\$35,319.00

The information contained herein is correct as at 26 Jun 2019

OK

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Wednesday, 26 June 2019 11:45 AM
To: admin-d@lkkauto.com; admin-a@lkkauto.com
Cc: motorclaims.sg@fwd.com; josey.loh@fwd.com
Subject: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs Our Ref: 1201900015891

Dear Sir/Madam,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Venessa Chan - SGUser
Sent: Wednesday, 26 June 2019 11:43 AM
To: Jason
Cc: Josey Loh Kah Wai - SGUser; Motor Claims SG - SG Common
Subject: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs Our Ref: 1201900015891

Hi Adeline,

Thank you for your selection of LKK Auto Consultants Pte Ltd.
We will proceed to assign survey.

Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims

P: Adeline

T: 12.04 p.m

v. ln


E: ✓

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Jason [<mailto:karen@leebrothers.com.sg>]

Sent: Wednesday, 26 June 2019 10:46 AM

To: Venessa Chan - SGUser

Subject: RE: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs Our Ref: 1201900015891

Dear Venessa,

Kindly arrange for 1. LKK Auto Consultants Pte Ltd

Thanks & Best Regards

Adeline Seng

Lee Brothers Automotive Pte Ltd

1 Kaki Bukit Ave 6

#02-47 Autobay

Singapore 417883

Tel: 6509 5521

Fax: 6509 5523

From: venessa.chan@fwd.com [<mailto:venessa.chan@fwd.com>]

Sent: Wednesday, 26 June, 2019 8:47 AM

To: karen@leebrothers.com.sg

Cc: motorclaims.sg@fwd.com; josey.loh@fwd.com

Subject: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs Our Ref: 1201900015891

WITHOUT PREJUDICE

Dear Adeline,

We refer to your email dated on 25.06.2019 of the PRI Notice of your client's vehicle SME2563Z.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT Appraisal Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.


*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Jason [<mailto:karen@leebrothers.com.sg>]
Sent: Tuesday, 25 June 2019 5:18 PM
To: Motor Claims SG - SG Common
Subject: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs

Dear Sir / Ma'am,

Kindly arrange PRI for our vehicle SME2563Z.

Do provide us with the surveyor list.

Thanks & Best Regards

Adeline Seng
Lee Brothers Automotive Pte Ltd
1 Kaki Bukit Ave 6
#02-47 Autobay
Singapore 417883
Tel: 6509 5521
Fax: 6509 5523

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 3 July 2019 3:22 PM
To: karen@leebrothers.com.sg
Subject: RE: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs Our Ref: 1201900015891

WITHOUT PREJUDICE
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Venessa Chan - SGUser
Sent: Wednesday, 26 June 2019 11:43 AM
To: Jason
Cc: Josey Loh Kah Wai - SGUser; Motor Claims SG - SG Common
Subject: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs Our Ref: 1201900015891

Hi Adeline,

Thank you for your selection of LKK Auto Consultants Pte Ltd.
We will proceed to assign survey.

Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E venessa.chan@fwd.com

W www.fwd.com.sg



From: Jason [<mailto:karen@leebrothers.com.sg>]

Sent: Wednesday, 26 June 2019 10:46 AM

To: Venessa Chan - SGUser

Subject: RE: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs Our Ref: 1201900015891

Dear Venessa,

Kindly arrange for 1. LKK Auto Consultants Pte Ltd

Thanks & Best Regards

Adeline Seng
Lee Brothers Automotive Pte Ltd
1 Kaki Bukit Ave 6
#02-47 Autobay
Singapore 417883
Tel: 6509 5521
Fax: 6509 5523

From: venessa.chan@fwd.com [<mailto:venessa.chan@fwd.com>]

Sent: Wednesday, 26 June, 2019 8:47 AM

To: karen@leebrothers.com.sg

Cc: motorclaims.sg@fwd.com; josey.loh@fwd.com

Subject: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs Our Ref: 1201900015891

WITHOUT PREJUDICE

Dear Adeline,

We refer to your email dated on 25.06.2019 of the PRI Notice of your client's vehicle SME2563Z.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT Appraisal Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.


*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Jason [<mailto:karen@leebrothers.com.sg>]
Sent: Tuesday, 25 June 2019 5:18 PM
To: Motor Claims SG - SG Common
Subject: Accident involving SME2563Z and FBK7141Z along CTE towards TPE on 06.06.2019 at 1510hrs

Dear Sir / Ma'am,

Kindly arrange PRI for our vehicle SME2563Z.

Do provide us with the surveyor list.

Thanks & Best Regards

Adeline Seng
Lee Brothers Automotive Pte Ltd
1 Kaki Bukit Ave 6
#02-47 Autobay
Singapore 417883
Tel: 6509 5521
Fax: 6509 5523

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Print Received Message

This mail is associated with :

***SME2563Z (1201900015891)
[FBK7141Z]**

TP

SEE CHOR TAT BENJAMIN

Jun 6 2019 12:00AM

[Tailford Randall Patrick]

LEE BROTHERS AUTOMOTIVE PTE. LTD.

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 25/09/2019 19:16 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2469.45) - SME2563Z - Claim Handler: Josey Loh

Approved:2469.45.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2019 Edit Reg		26 Jun 2019 00:00 Edit Adj Rpt	S\$1,900.00 Edit Estimates	S\$1,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Tailford Randall Patrick, ID: S9014969E								
Main Claimant:	SEE CHOR TAT BENJAMIN, ID: S8511200G								
Vehicle Reg. No.:	SME2563Z	Date of Loss:	06/06/2019 00:00 - :59 [8 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900015891	Policy/Cover Note No.:	PNMC2017-00001781-01 (Third Party Only) Coverage: 22/12/2018 - 21/12/2019						
Vehicle Reg. No. (Insured):	FBK7141Z	Policy No. (Claimant):	P2198866						
Repairer:	LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ) 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 65095521								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 05/07/2019]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
• FWD_SG (25/09/2019): Alert - Adj Mandate Approved (S\$2469.45) - SME2563Z - Claim Handler: Josey Loh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME2563Z (1201900015891)
 [FBK7141Z]
 TP
 SEE CHOR TAT BENJAMIN
 Jun 6 2019 12:00AM
 [Tailford Randall Patrick]
 LEE BROTHERS AUTOMOTIVE PTE. LTD.

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print			
1	(Draft)	Third Party Express Settlement - Payment Breakdown						Edit			
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print			
1	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
2	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
3	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
4	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
5	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
6	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
7	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
8	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
9	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
10	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
11	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
12	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
13	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
14	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
15	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
16	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
17	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
18	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
19	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
20	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
21	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
22	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
23	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
24	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
25	10/09/19 12:40	General View						Load JPG	<input checked="" type="checkbox"/>		
26	10/09/19 12:40	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>		
27	10/09/19 12:40	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>		
28	10/09/19 12:40	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>		
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print			
1	26/06/19 16:25	EMAIL FROM FWD DD 26062019						Load PDF			
2	26/06/19 16:25	FWD EMAIL TO INSURED DD 26062019						Load PDF			
3	27/06/19 18:02	TP ESTIMATE- MARKED						Load PDF			
4	27/06/19 18:02	TP GIA REPORT						Load PDF			
5	04/09/19 14:01	WORKSHOP INVOICE						Load PDF			
6	04/09/19 14:01	RENTAL RECEIPT						Load PDF			
7	04/09/19 14:01	LTA SEARCH						Load PDF			
8	04/09/19 14:01	GIA SEARCH						Load PDF			
9	04/09/19 14:01	LOD						Load PDF			
10	25/11/19 09:42	AUTHORISATION TO ACT FORM						Load PDF			
11	25/11/19 09:42	Release Voucher						Load PDF			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
No.	Finalized On	FWD Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	27/06/19 10:49	FBK7141Z E-FILE REPORT.	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="text-align: right;"> ^ v </div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	FBK7141Z (Insd veh)	Model:	HYUNDAI ELANTRA 1.6 (A)
	SME2563Z (TP veh)		
Date of Accident:	06/06/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	5,408.51
Final Repair Cost	:	\$	2,033.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	400.00 4 days
LTA / GIA Search Fee	:	\$	36.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	2,469.45
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	LEE BROTHERS AUTOMOTIVE PTE. LTD.	:	\$ 2,469.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

25 Nov
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19011328/UGB3Q2
Date: 25/11/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNMC2017-00001781-01
Claimant SME2563Z **Insured Vehicle No :** FBK7141Z
Vehicle No : SME2563Z
 Date of Loss: 06/06/2019 Nature of Claim: TP Claim No: 1201900015891

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME2563Z**
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGJU270970
 Reg. Date: 25/09/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU760479
 Colour: Red Odometer: 6550 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Nexen 7 mm Rear Left Side: Nexen 7 mm
 Front Right Side: Nexen 7 mm Rear Right Side: Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,634.68	1,487.88	2,146.80	59.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	930.00	490.00	34.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,054.68	2,417.88	2,636.80	52.17
Approved Total (Overridden) (S\$)		1,900.00		
(S\$)	5,054.68	1,900.00	3,154.68	62.41
+ GST 7.00/7.00% (S\$)	353.83	133.00	220.83	62.41
Nett Amount (S\$)	5,408.51	2,033.00	3,375.51	62.41
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		2,469.45		

INSPECTION

Date of Assignment: 26/06/2019
 Date Inspected: 26/06/2019 Inspected At: LEE BROTHERS AUTOMOTIVE PTE. LTD. (HQ)
 1 Kaki Bukit Ave 6, #02-47 Autobay @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Sep 2019)
Parts: 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SME2563Z)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT (DENTED)	Not Consistent With The Impact	1,782.40 FL	*- FL
2	1		*REAR BOOT RUBBER	Not Necessary	115.80 FL	*- FL
3	1		*REAR BOOT LOCK	Not Necessary	135.80 FL	*- FL
4	1		*REAR BOOT EMBLEM LOGO	Not Necessary	28.00 FL	*- FL
5	1		*REAR BOOT EMBLEM ELANTRA	Not Necessary	48.80 FL	*- FL
6	1		*REAR BOOT EMBLEM S	Not Necessary	38.80 FL	*- FL
7	1		*REAR BUMPER	Distorted	556.80 FL	*556.80 FL
8	1		*REAR BUMPER REFLECTOR LH	Scratched	68.80 FL	*68.80 FL
9	1		*REAR BUMPER REINFORCEMENT	Dented	328.00 FL	*328.00 FL
10	1		*REAR BUMPER UNDER COVER LH	Not Necessary	94.30 FL	*- FL
11	2		*REAR BUMPER SIDE RETAINER RH/LH	Not Necessary	89.60 FL	*- FL
12	1		*FROTN BUMPER LOWER SPOILER	Cut	680.00 FS	*680.00 FS
13	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
14	1		*SET FRONT BUMPER REVERSE SENSOR	Not Necessary	280.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (S\$)	4,292.10	1,678.60
- List Item Discount on L Items 20.00/20.00% (S\$)	657.42	190.72
Total Parts (S\$)	3,634.68	1,487.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS	New	500.00	300.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	New	700.00	500.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE,REFIX INNER TRIM	New	80.00	60.00
5	TO REMOVE,REPLACE REVERSE SENSOR	New	80.00	50.00
6	TO TUFF KOTE	New	40.00	0.00
Gross Labour Cost (S\$)			1,420.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >