

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER FOUR

SINGAPORE 038986

FBK7141Z

*NOT Allowed
r/b
1/3 3 days
why, what, when
26/6/19*

ESTIMATE

DATE : 25.06.2019

VEHICLE NO : SME2563Z

HYUNDAI

MAKE/MODEL : ELANTRA

ACC DATE : 06.06.2019

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>LIST PRICE</u>			
1	1 REAR BOOT	1,782.40	1,782.40
2	1 REAR BOOT RUBBER	115.80	115.80
3	1 REAR BOOT LOCK	135.80	135.80
4	1 REAR BOOT EMBLEM LOGO	28.00	28.00
5	1 REAR BOOT EMBLEM ELANTRA	48.80	48.80
6	1 REAR BOOT EMBLEM S	38.80	38.80
7	1 REAR BUMPER	556.80	556.80
8	1 REAR BUMPER REFLECTOR LH	68.80	68.80
9	1 REAR BUMPER REINFORCEMENT	328.00	328.00
10	1 REAR BUMPER UNDER COVER LH	94.30	94.30
11	2 REAR BUMPER SIDE RETAINER RH/LH	44.80	89.60
			3,287.10
LESS 20%			657.42
			2,629.68

<u>SPECIAL NETT ITEMS</u>			
1	1 FRONT BUMPER LOWER SPOILER	680.00	680.00
2	1 (SET) FRONT BUMPER CLIPS	45.00	45.00
3	1 (SET) FRONT BUMPER REVERSE SENSOR	280.00	280.00
			1,005.00

<u>LABOUR CHARGES :</u>			
1	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS	500.00	300
2	TO SPRAY PAINTING ON ACCIDENT PORTION	700.00	500
3	TO CHECK WIRING	20.00	2
4	TO REMOVE, REFIX INNER TRIM	80.00	60
5	TO REMOVE, REPLACE REVERSE SENSOR	80.00	50
6	TO TUFF KOTE	40.00	X
		1,420.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 5,054.68