

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : NIZAH BINTI OSMAN

Accident Date : 19.03.2019

Vehicle No : FU 7121 G

Vehicle Model : HONDA CB400

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Top cowling	\$ 102 220.00
1	Front fender	\$ 320 196.00
1	Headlamp	\$ 102 380.00
1	Headlamp bracket	\$ 102 65.00
1	Headlamp rear bracket	\$ 321 85.00
2	Fork inner tubes	\$ 321 620.00
2	Fork outer tubes	\$ 321 640.00
1	Fork under bracket 288	\$ 321 335.00
2	Front brake discs	\$ 321 910.00
1	Front rim shaft	\$ 321 68.00
1	Front sport rim	\$ 321 850.00
1	Meter	\$ 102 880.00
1	Handle-bar	\$ 321 145.00
1	Handle-grip (1 set)	\$ 102 90.00
2	Side mirrors	\$ 320 190.00
1	Clutch lever	\$ 102 58.00 X
1	Brake lever	\$ 302 65.00
2	Front signals	\$ 320 170.00
1	Fuel tank	\$ 102 950.00 X
1	Front footrest-R/H	\$ 102 75.00
1	Front footrest bracket	\$ 321 245.00
1	Brake pedal	\$ 102 98.00 X
1	Rear footrest-R/H	\$ 102 70.00
1	Exhaust pipe	\$ 102 865.00
1	Exhaust pipe protector	\$ 302 55.00
1	Rear signal-R/H	\$ 102 85.00
1	Rear tailboard	\$ 102 335.00 X
1	Rear fender	\$ 102 95.00
1	Rear taillamp	\$ 102 280.00
1	Horn	\$ 102 80.00
		\$ 9,200.00
	Less 10%	\$ 920.00
		\$ 8,280.00

not Adm
LH
2/5 # 6000/
5 day
To high H. At long
26/6/19

c/f: \$ 8,280.00

Special Nett Items

1	Number plate (1 set)	\$	SM	28.00	10
2	Fork oils	\$	SM	30.00	—
2	Fork oil seals	\$	SM	56.00	—
1	Steering cone (1 set)	\$	SM	80.00	—
1	Steering pamper	\$	SM	480.00	X
1	E.R.P IU	\$	11	175.00	X
1	Front tyre	\$	SM	300.00	X
1	Crash bar (1 set)	\$	SM	300.00	—
		\$		1,449.00	

<u>S/No.</u>	<u>Labour</u>
1	To provide towing service.
2	To provide labour.
3	To repair body frame.
4	To check wiring and reset headlamp focusing

\$		50.00	35
\$		480.00	300
\$	11	350.00	X
\$	11	80.00	X
\$		960.00	

Grand Total \$ **10,689.00**


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7745.
8245