

Estimate

25/06/2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
AXA TOWER #27-01
SINGAPORE 068811

Attention :- **XA009**

Page # :- 1
 Veh # :- SLX7723H
 Veh Model :- B.M.W. 320I AT 2.0L ABS D/AIRB
 Estimate# :- CK419340
 Claim # :-
 ACC. Date :- 24/06/19
 Terms :- C.O.D Days
 Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel : **(65) 6476 3333**
 Fax : (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

Tel : **(65) 6272 3892**
 Fax : (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	RH FRONT FENDER <i>bt ✓</i>	1 PC	989.00	989.00
2.	RH SIDE ROCKER GARNISH <i>x</i>	1 PC	635.00	635.00
3.	RH SIDE ROCKER GARNISH BRACKET <i>x</i>	1 PC	40.00	40.00
4.	RH FRONT FENDER SIGNAL LAMP <i>x</i>	1 PC	80.00	80.00
5.	FRONT FENDER INNER SHIELD CLIPS <i>de ✓</i>	10 PCS	5.00	50.00
LIST TOTAL S\$				1,794.00
5% DISCOUNT S\$				-89.70
				1,704.30
LABOUR :				
TO STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS				200 300.00
TO APPLY RUST PROOF ON AFFECTED AREAS				30.00
TO SPRAY PAINT ON REPLACED, REPAIRED AREAS				200 450.00
LABOUR TOTAL S\$				780.00

inconsistent
Rasul
Hp 9000068
2 days
4/5
26/06/19 @ 1530
Resin after repair

E. & O.E

NON-TAX AMOUNT S
 AMOUNT S\$ 2,484.30
 GST @ 7 % 173.90
 AMOUNT DUE S\$ 2,658.20

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: