

**REPAIR ESTIMATE**

VEHICLE NO : SHA 18815

DATE : 26.06.2019

MAKE :

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER X			\$ 1,126.60
REAR TRUNK LID LOCK X			\$ 457.90
REAR TRUNK LID GLASS (BLACK COLOR) X			\$ 1,569.70
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE -			\$ 889.70
REAR TRUNK LID LOGO(PRIUS) -			\$ 52.90
REAR TRUNK LID LOGO(HYBRID) X			\$ 52.90
REAR TRUNK LID LOGO(TOYOTA STAR) -			\$ 47.00
REAR BUMPER -			\$ 458.60
REAR BUMPER RE-INFORCEMENT -			\$ 318.80
REAR BUMPER SIDE RETAINER ?			\$ 112.70
REAR BUMPER UNDER SIDE CENTRE COVER -			\$ 552.60
REAR BUMPER TOWING COVER -			\$ 82.70
REAR BUMPER CLIPS -			\$ 22.00
TAIL LAMP ASSY (UPPER) (LH/RH) LH- RH X		\$ 557.90	\$ 1,115.80
TAIL LAMP ASSY (LOWER) (LH/RH) LH- RH X		\$ 548.40	\$ 1,096.80
<b>SUB TOTAL</b>			<b>\$ 7,956.70</b>
<b>LESS 20% <del>25%</del></b>			<b>\$ 1,591.34</b>
<b>DISCOUNTED TOTAL</b>			<b>\$ 6,365.36</b>
REAR BUMPER REVERSE SENSOR -			\$ 135.70
REAR BUMPER RUBBER MAT -			\$ 50.00
			<b>\$ 185.70</b>
			<b>NETT NETT</b>
<b>LABOUR CHARGE</b>			
Panel Beating			\$ 300
Spray Painting Charge	3 PIP		\$ 400.00
Wiring Charge	PIP		\$ 600.00
Tuff Kote			\$ 50.00
Remove/Refix Reverse Sensor	Before Paint p/h		\$ 50.00
			\$ 80.00
<b>TOTAL LABOUR</b>			<b>\$ 1,180.00</b>
<b>ESTIMATE TOTAL</b>			<b>\$ 7,731.06</b>

LKK Auto Consultants  
 the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: [Signature]  
 Date: 26/6/19

Ka hui 10/11/19  
 26/6/19  
 3 PIP  
 PIP  
 Before Paint p/h

NETT NETT

400  
 20  
 X  
 30

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.