

INSURANCE

INS. CASE OWNER:

CC 4/EGI1901

1426, T. 06/2/19

LKK:

IDAC:

Surveyor:

TAM/1/19

DOI:

ASSIGNMENT

1/2/19

Date / Time:

26/6/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBF 5122T

Claim No.:

Name of Insured:

TMK SERVICES PTE LTD

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

21/6/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO; TP GIA REPORT: YES / NO

Insured Liability:

Final? Yes / No

SGT 6839U

INSRS:
WSP:
Tel:
Liability:
RMKS:Hin
lungINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
SGT 6839U - X	GBF 5122T - X	
LIABILITY UNCLEAR: REQUEST FOR EVIDENCE.		
	Non-Reporting hr (1st):	
	Non-Reporting hr (2nd):	
	Non-Reporting hr (Final):	
	Notification hr (if non-pickup):	
	Call OE:	21/09/19
	After call hr to OE:	
	Documentation Check List: Handler Typist	
	Notification hr (if non-pickup)	
	After call hr to OE:	
	Authorisation To Act:	
	Release Voucher: (NO NEED)	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost: 1/3 SS 2,100	(4 days) Reduction:	65 %
Confirm by: MTM	Email: ☒	Call: ☐
FINAL SETTLEMENT	Date/Time: 14.12.19	Confirm with: AMM
Final Liability: 100 % 50	(Agreed / Assessed) BOLA S/N No.:	30
Repair Cost: 0/11 + 2,299.40	SS 1,173.50	BOTH PARTY TURNING
Loss of Rental (LOR): -	SS -	(days)
Loss of Use (LOU): +300.40	SS 250.40	(5 100 x 5 days)
Loss of Income (LOI): -	SS -	(5 x days)
LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ (Tick only one)		
GIA/LTA Search: +2.40	SS 2.40	
Medical: -	SS -	
Disbursement: -	SS -	(e.g. Tow/Independent)
Legal Cost: -	SS -	
Total: +2,799.00	SS 1,373.50	Global Sum SS: 1,400.40
FINAL PAYMENT	Date/Time: 04.12.19	Confirm with: AMM
Payee 1:	SS 1,400.00	Name 1: Hin Lung Workshop
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

ISSUED BY

Tanpin

EGT

ASSIGNMENT

From:

Date:

1.7.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SGT 68394

at Workshop no:

Hin lung wleap

of

Blk 1008 Bkt merah lane 3 # 0120

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

2pm

(Policy Condition)

01/07/99 2pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS ^{mp}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGT 68394

VI Regn:

2016 Dec

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Teana

CC 1997

Colour:

Bronze

A/C:

Insured / Std / NI / NA

Sp Reading

36 503

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/Nr:

MNT B3AL332000 5998

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

4 ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D.O.A:

D.O.I

01/07/19

Survey held at

Hin Lung Bm

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4: 2.100 (REQ: 4.665.70 69%)

Date/Time, File Pass to:

☐

: Preli. Report

if

☐

: Final Report

Date/Time, File Return to:

3:

Add Fee:

☐

: Site Insp: (\$

☐

: Interview: (\$

☐

: Tech. Insp: (\$

☐

: Wheel end: (\$

Report Format:

Long Short/MS/CS

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

5 + 10 = 15

Phone

Other

Total

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0650/06/19
M/s : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD, #04-01
SUNTEC TOWER FIVE
SINGAPORE 038985

Page: 1
Date: 26/06/2019

Attn :

Dear Sir/Madam,

ACCIDENT REPAIR ON : SGT6839U - TEANA-2.0 (A) 0
INSURED : CHEN YAW TIONG
DATE OF ACCIDENT : 21/06/2019
YOUR INSURED VEH NO: GBF5122T

Tan Kah 97495249
WP
17/17E 2pm
Resurvey after repair
4-5 days
3400/hinlung.com

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
REPLACEMENT OF PARTS				
	*NETT PRICE			
1	REAR RH DOOR	1 @ 1,098.00	1,098.00	Ry
2	REAR RH DOOR WEATHERSTRIP	1 @ 151.40	151.40	x m
3	REAR RH DOOR STICKERS	3 @ 33.10	99.30	x m
4	REAR RH FENDER	1 @ 1,288.20	1,288.20	Rx
5	REAR RH FENDER SPLASH SHIELD	1 @ 186.40	186.40	x m
6	SPLASH SHIELD RIVETS	6 @ 4.40	26.40	x m
SUB-TOTAL			2,849.70	
	*SPECIAL NETT			
7	REAR RH SPORT RIM	1 @ 1,366.00	1,366.00	cul ✓
8	REAR RH TYRE	1 @ 350.00	350.00	x m

LABOUR CHARGES

1	REPLACE NEW PARTS, REMOVE/REFIT ALL	400.00	✓
1	ATTACHMENT PARTS TO FACILITATE REPAIR		
1			
2	DISMANTLE AND TRANSFER DOOR FITTINGS	400.00	x m
2	AND MECHANISM TO NEW DOOR/FACILITATE		
2	REPAIR.		
2			
3	CHECK WIRING AND PROPER FUNCTIONING	80.00	30
3			
4	SPRAY PAINT ON THE EFFECTED AREAS	1,200.00	800
4	WITH 2K PAINT.		
4			
5	CHECK AND RE-ADJUST 4 WHEEL ALIGNMENT	120.00	80

Nett Total Before GST

Yours faithfully,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

6,765.70
2676
4/5/2100, 4 days



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVENUE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EGH19011426/T1eb3

Date: 02/07/2019

The Motor Claims Department
M/s ERGO INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SGT6839U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.07.2019 at the premises of M/s Hin Lung Workshop and have the following to report:-

Workshop Estimate Amount	: S\$	6,765.70
Revised Estimate Amount	: S\$	1,366.00
"Check" Items Amount	: S\$	1,310.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
O/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4-5 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0650/06/19
M/s : ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD, #04-01
SUNTEC TOWER FIVE
SINGAPORE 038985
Attn :

Page: 1
Date: 26/06/2019

Tan Kah 97495749
WP

17/190 2pm

Lampson
Resurvey after repair
4-5 days

save the auto.com

Dear Sir/Madam,

ACCIDENT REPAIR ON : SGT6839U - TEANA-2.0 (A) 0
INSURED : CHEN YAW TIONG
DATE OF ACCIDENT : 21/06/2019
YOUR INSURED VEH NO: GBF5122T

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
REPLACEMENT OF PARTS				
*NETT PRICE				
1	REAR RH DOOR	1 @	1,098.00	1,098.00 <i>Ry</i>
2	REAR RH DOOR WEATHERSTRIP	1 @	151.40	151.40 x
3	REAR RH DOOR STICKERS	3 @	33.10	99.30 x
4	REAR RH FENDER	1 @	1,288.20	1,288.20 <i>Ry</i>
5	REAR RH FENDER SPLASH SHIELD	1 @	186.40	186.40 x
6	SPLASH SHIELD RIVETS	6 @	4.40	26.40 x
SUB-TOTAL				2,849.70
*SPECIAL NETT				
7	REAR RH SPORT RIM	1 @	1,366.00	1,366.00 <i>cut</i> ✓
8	REAR RH TYRE	1 @	350.00	350.00 x

LABOUR CHARGES

1	REPLACE NEW PARTS, REMOVE/REFIT ALL	400.00	✓
1	ATTACHMENT PARTS TO FACILITATE REPAIR		
1			
2	DISMANTLE AND TRANSFER DOOR FITTINGS	400.00	x
2	AND MECHANISM TO NEW DOOR/FACILITATE		
2	REPAIR.		
2			
3	CHECK WIRING AND PROPER FUNCTIONING	80.00	30
3			
4	SPRAY PAINT ON THE EFFECTED AREAS	1,200.00	8000
4	WITH 2K PAINT.		
4			
5	CHECK AND RE-ADJUST 4 WHEEL ALIGNMENT	120.00	80

Nett Total Before GST

6,765.70

Yours faithfully,

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 7679B

Vehicle Details

Vehicle No.: SGT6839U
Vehicle to be Exported: Yes
Intended Deregistration Date: 21 Jun 2019
Vehicle Make: NISSAN
Vehicle Model: TEANA 2.0 XL CVT
Primary Colour: Brown
Manufacturing Year: 2016
Engine No.: MR20043072R
Chassis No.: MNTBBAL33Z0005998
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$24,563.00
Original Registration Date: 29 Dec 2016
First Registration Date: 29 Dec 2016
Transfer Count: 0
Actual ARF Paid: \$26,389.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 28 Dec 2026
PARF Rebate Amount: \$19,791.00

Intended COE Rebate Details

COE Expiry Date: 28 Dec 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,206.00
COE Rebate Amount: \$42,260.00
Total Rebate Amount: \$62,051.00

The information contained herein is correct as at 21 Jun 2019

OK

• Nivitha (LKK Auto)

From: Jeannie Cheng <jeannie.cheng@ergo.com.sg>
Sent: Wednesday, 26 June 2019 4:54 PM
To: admin-d@lkkauto.com
Cc: sur@lkkauto.com; Survey Report (ERGO Insurance Pte. Ltd.)
Subject: FW: PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019| ERGO REF: CDMCG19001175/PX/jc
Attachments: SAS2622185.pdf; ESTIMATE.JPG; GBF5122T OI.PDF

9.44am @ 27/6/19
person @ Anna
while VNI

Hi LKK,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and try to finalize with the repairer on the repairs.

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

NOTE: Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard #04-01 Suntec Tower Five
Singapore 038986
DID : +65 6825 9199 x 194
jeannie.cheng@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Jeannie Cheng
Sent: Wednesday, June 26, 2019 4:52 PM
To: 'hlungws'
Cc: Survey Report (ERGO Insurance Pte. Ltd.)
Subject: RE: PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019| ERGO REF: CDMCG19001175/PX/jc

WITHOUT PREJUDICE

Dear Anna,

We will assign the selected surveyor accordingly.

Thank you.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038965
CFO +65 6379 9199 x 194
jeannie.cheng@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: hlungws [<mailto:hlungws@singnet.com.sg>]
Sent: Wednesday, June 26, 2019 3:34 PM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Cc: Jeannie Cheng; Survey Report (ERGO Insurance Pte. Ltd.)
Subject: RE: PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019| ERGO REF: CDMCG19001175/PX/jc

Dear Jeannie,

We selecting LKK Auto Consultants Pte Ltd to survey the car.

Thanks & Regards,
Anna
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: ERGO Insurance Pte. Ltd. (Claims Department) [<mailto:claims@ergo.com.sg>]
Sent: Wednesday, 26 June 2019 3:07 PM
To: hlungws <hlungws@singnet.com.sg>

Cc: Jeannie Cheng <jeannie.cheng@ergo.com.sg>; Survey Report (ERGO Insurance Pte. Ltd.)
<Survey_Report@ergo.com.sg>
Subject: RE: PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019 | ERGO REF: CDMCG19001175/PX/jc

WITHOUT PREJUDICE

Dear Anna,

We acknowledged receipt of your email for the PRS request as below.

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below.

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd

Kindly let us have your reply on the selection of the surveyor.

We can't confirm liability as both parties gave conflicting versions.

Thank you.

Warmest Regards,
Jeannie Cheng
ERGO Insurance Pte. Ltd

5 Temasek Boulevard #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9199 x 154
jeannie.cheng@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not receive, reproduce, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening this attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: hlungws [mailto:hlungws@singnet.com.sg]
Sent: Wednesday, June 26, 2019 2:21 PM
To: ERGO Insurance Pte. Ltd. (Claims Department)
Subject: Re : SGT6839U / GBF5122T , DOA 21/06/2019 , TP Survey & Liability

Dear Sirs,

We refer to the above subject and we are the authorized representative for Owner of motor vehicle no. SGT6839U to resolve the above matter.

The attach documents are for your reference.

For your information, the **vehicle is not in workshop** and we need to arrange with the owner.

Kindly let us hear from you and we wish to know on the **liability**.

Thanks & Regards,

Anna

Hin Lung Workshop

Tel: 6858 3000 Fax: 6476 0075

Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

Asher Sng (LKKAUTO)

From: workshop <workshop@hinlung.com.sg>
Sent: Wednesday, 4 December 2019 9:06 AM
To: Asher Sng (LKKAUTO)
Subject: Re : PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019| ERGO REF: CDMCG19001175/PX/jc - TP Survey & Liability

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Asher,

We accept the settlement at Global Sum of S\$1,400 (all-in).

Thanks & Regards,
Anna
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Thursday, 21 November 2019 6:09 PM
To: Hin Lung Workshop <workshop@hinlung.com.sg>
Subject: RE: PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019| ERGO REF: CDMCG19001175/PX/jc - TP Survey & Liability

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

On a without prejudice, for a quick and amicable settlement, we propose the settlement at Global Sum S\$1,400.00 (all-in).

Please kindly let us have your acceptance.

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Hin Lung Workshop <workshop@hinlung.com.sg>
Sent: Friday, 15 November 2019 11:30 AM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Subject: RE: PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019 | ERGO REF: CDMCG19001175/PX/jc - TP Survey & Liability

Hi Asher,

As spoken, we enclosed one LOD as arranged.

Please advise us on the Settlement with Global Sum so that I can inform my insured how much he has to pay for the repairs.

Thanks & Regards,
Anna
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: Hin Lung Workshop [<mailto:workshop@hinlung.com.sg>]
Sent: Thursday, 14 November 2019 5:24 PM
To: 'Asher Sng (LKKAUTO)' <AsherSng@lkkauto.com>
Cc: 'Taufikh (LKKAUTO)' <Taufikh@lkkauto.com>
Subject: Re : PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019 | ERGO REF: CDMCG19001175/PX/jc - TP Survey & Liability

Hi Asher,

As spoken, we enclosed one Tax Invoice as arranged.

Please advise us on the Settlement with Global Sum so that I can inform my insured how much he has to pay for the repairs.

Thanks & Regards,
Anna
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: hlungws [<mailto:hlungws@singnet.com.sg>]
Sent: Tuesday, 22 October 2019 3:31 PM

To: 'Taufikh (LKKAUTO)' <Taufikh@lkkauto.com>
Cc: 'Asher Sng (LKKAUTO)' <AsherSng@lkkauto.com>
Subject: Re : PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019 | ERGO REF: CDMCG19001175/PX/jc - TP Survey & Liability
Importance: High

Hi Taufikh,

As spoken, please let us know how much is the Lump Sum Repairs as we need to inform insured as it is a 50%/50% case.

Thanks & Regards,
Anna
Hin Lung Workshop
Tel: 6858 3000 Fax: 6476 0075
Address: Blk 1008 Bukit Merah Lane 3 #01-20 Singapore 159722

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Friday, 27 September 2019 10:37 AM
To: hlungws <hlungws@singnet.com.sg>
Subject: RE: PRS IRO SGT6839U | OI : GBF5122T | DOA: 21/06/2019 | ERGO REF: CDMCG19001175/PX/jc - TP Survey & Liability

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/Madam,

We refer to the above matter.

We are of the opinion that this is a case of conflicting versions. There is no conclusive evidence to substantiate either's parties version.

Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation and not jeopardizing our insured claim against the liable party, we are prepared to offer 50% to your client's claim.

Meanwhile, kindly forward to us with any evidence (if any) to support your claim

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,
Asher Sng | Case Handler
LKK Auto Consultants Pte Ltd
phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 31 July 2019 12:33 PM



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s ERGO INSURANCE PTE LTD

Date: 19/12/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBF 5122T (Insd Veh)	Your Ref. No. : CDMCG19001175/PX/jc
	SGT 6839U (TP Veh)	Our Ref. No. : CC4/EGI19011426/T1eb3q2
Date of Accident	21/6/2019	

Liability	50%	
Final Repair Cost	: \$ 1,123.50	
Loss of Use	: \$ 250.00	5 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	1,375.50	
Final Settlement Sum	: \$ 1,400.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	HIN LUNG WORKSHOP	: \$ 1,400.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CC4/EGI19011426/T1eb3q2

5 TEMASEK BOULEVARD
#04-05 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 19-12-2019



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 5122T	Veh. Inspected	SGT 6839U
Policy No.	DMCG18005125	Coverage (\$)	0.00
Claim No.	CDMCG19001175/PX/jc	Excess (\$)	0.00
Assign From	JEANNIE	Assign Date	26/06/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN TEANA	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MNTBBAL33Z0005998	Colour	BRONZE
Odometer	36503	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/06/2019	Inspection Date	01/07/2019
Survey held at	HIN LUNG WORKSHOP BLK 1008 BUKIT MERAH LANE 3 #01-20 SINGAPORE 159722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 6839U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR RH DOOR	TO REPAIR SEE LABOUR	1,098.00	-
1	REAR RH DOOR WEATHERSTRIP	NOT NECESSARY	151.40	-
3	REAR RH DOOR STICKERS @\$33.10	NOT NECESSARY	99.30	-
1	REAR RH FENDER	TO REPAIR SEE LABOUR	1,288.20	-
1	REAR RH FENDER SPLASH SHIELD	NOT NECESSARY	186.40	-
6	SPLASH SHIELD RIVETS @\$4.40 (CONSISTENT)	NOT NECESSARY	26.40	-
			2,849.70	-
<u>SPECIAL NETT ITEMS</u>				
1	REAR RH SPORT RIM (SN)	CUT	1,366.00	1,366.00
1	REAR RH TYRE (SN)	NOT NECESSARY	350.00	-
			1,716.00	1,366.00
<u>LABOUR</u>				
	REPLACE NEW PARTS ,REMOVE/REFIT ALL ATTACHMENT PARTS TO FACILITATE REPAIR .INCLUSIVE OF THE REPAIR OF REAR RH DOOR AND REAR RH FENDER .		400.00	400.00
	DISMANTLE AND TRANFER DOOR FITTINGS AND MECHANISM TO NEW DOOR /FACILITATE REPAIR.	NOT NECESSARY	400.00	-
	CHECK WIRING AND PROPER FUNCTIONING.		80.00	30.00
	SPRAY PAINT ON THE AFFECTED AREAS WITH 2K PAINT.		1,200.00	800.00
	CHECK AND RE-ADJUST 4 WHEEL ALIGNMENT.		120.00	80.00
			2,200.00	1,310.00
GRAND TOTAL			6,765.70	2,676.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CC4/EGI19011426/T1eb3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.