

KAY MOTOR
BLOCK 9 SIN MING INDUSTRIAL ESTATE
#01-46
SINGAPORE 575644
Tel: 6458 2283 Fax: 6459 8863
Email:kayautosg@yahoo.com

Merdeka Construction Co Pte Ltd

3 July 2019

ESTIMATE TO REPAIR NISSAN CABSTAR – GW 7786R

1pc	o/s front door
1pc	o/s front door view mirror
1pc	o/s front step board
1pc	o/s front corner panel
1pc	o/s front side lamp
1pc	front bumper

less 30%

Lettering

To remove & refit o/s door glass & mechanism
To putty & spray painting
To repair & panelbeat o/s door pillar,
dismantle & fit the above parts.

*Not Withair
1/1/2019 B?
Purway Abu Pany
4 days*

<i>Pr</i>	\$ 1882.79	✓
<i>SL</i>	149.00	X
<i>nd lwr</i>	256.35	✓
<i>B₁</i>	486.00	✓
<i>B₂</i>	214.80	✓
<i>nd lwr</i>	903.10	✓

3892.04

1167.61

2724.43

nc 50.00 sn *20sn*

50.00 ✓

550.00 *4500*

580.00 *4500*

Total: \$ 3954.43

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: