

Kp

KAY MOTOR
BLOCK 9 SIN MING INDUSTRIAL ESTATE
#01-46
SINGAPORE 575644
Tel: 6458 2283 Fax: 6459 8863
Email: kayautosg@yahoo.com

Merdeka Construction Co Pte Ltd

3 July 2019

ESTIMATE TO REPAIR NISSAN CABSTAR - GW 7786R

1pc	o/s front door	1696.20
1pc	o/s front door view mirror	
1pc	o/s front step board	
1pc	o/s front corner panel	428.90
1pc	o/s front side lamp	
1pc	front bumper	675.50

less 30% 10}

Lettering

To remove & refit o/s door glass & mechanism
To putty & spray painting
To repair & panelbeat o/s door pillar,
dismantle & fit the above parts.

Not Notarized
L12m 83100h
Purvey Atu Pany
4day

As	\$ 1882.79	✓
SL	149.00	X
nd lwr	256.35	✓
Bj	486.00	✓
BN	214.80	✓
nd lwr	903.10	✓

3892.04

~~1167.61~~

2724.43

nc 50.00 sn 20sn

50.00

550.00

580.00

Total: \$ 3954.43

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: