

ASS. REC. BY:

REF: CS/SM019011462/Utd302

Special Instruction:

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Hwang Shiang yi of SMODate/Time: 28.6.19 9.14 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJT 3487K

Insured:

SGB 9622 Cat Workshop m/s Fastech Auto

Tel:

67465405of 1 Kaki Bukit Ave 6 #01-46Policy No: D19MTPV01000209

Claim No:

CMTD1903079

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 28.6.19 0.47 a.m

Person Contacted:

NancyVehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---|
| | <u>SGB 9622 C : NA / MSG 17008205 / h4 D.O.A : 25/04/2017</u> |
| | <u>SJT 3487K : CS3 / INC12004936 / TIF D.O.A : 03/03/2012</u> |
| | <u>11715:19pm- pending estimate send via merimen</u> |

08/11/13) wef

ASS. REC. BY: Marcus

REF:

5m /

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SY734876

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1/10/2019

Vehicle: IN / OUT

Date:

Person Contacted:

body 2400

Date / Time

Action / Instruction

have car 3mks plus.
27A 1876 net 4124

3/7/19 1/5 & 4000 conf. with Mr. Uled: 2376.92: 8590)

RECEIVED 08 JUL 2019

Date/Time, File Pass to?

1) 8/7 Typast

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

_____ \$ + RS, _____ \$

) Photos

) Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I: (\$ 4000)

| |
|-----|
| 450 |
| 11 |
| |
| |
| 461 |

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
| Main | 27 Jun 2019 | | 28 Jun 2019 09:14 Assign | | | | New Assignment Cancel Case |

| Main | Reference | Claim Details | Documents | Show All | | | | | |
|---|-----------|--|------------------------|------------------------------------|---------|-------------|--------------|------------|-------|
| CLAIM SUBFOLDER DETAILS [Created by insurer] | | | | | | | | | |
| Insured: | | EDDY LIM SZE NGUAN, ID: S1699579G | | | | | | | |
| Main Claimant: | | KHUSAINI BIN KAYAT, ID: S7031795H | | | | | | | |
| Vehicle Reg. No.: | | SJT3487K | Date of Loss: | 26/06/2019 17:00 - :59 | | | | | |
| Claim Type: | | TP / CMTD1903079 | Policy/Cover Note No.: | D19MTPV01000209 (Comprehensive) | | | | | |
| Vehicle Reg. No. (Insured): | | SGB9622C | Policy No. (Claimant): | | | | | | |
| | | Excess: | | | | | | | |
| Repairer: | | Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405 | | | | | | | |
| Handling Insurer: | | Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205] | | | | | | | |
| Adjuster: | | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/07/2019] | | | | | | | |
| Adj Asg. Remarks: | | WS: NANCY 6746 5405 | | | | | | | |
| ASSOCIATED MAIL RECEIVED View All Compose Case Mail | | | | | | | | | |
| There are no mail for this case. | | | | | | | | | |
| ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete | | | | | | | | | |
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results. | | | | | | | | | |

View Sent Message

This mail is associated with :

***SJT3487K (CMTD1903079)**
[SGB9622C]

TP
KHUSAINI BIN KAYAT
Jun 26 2019 5:00PM
[EDDY LIM SZE NGUAN]
Fastech Auto Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 01/07/2019 15:19 PM.
To SHANGYI.HWANG@SOMPO.COM.SG
Subject SJT3487K (CMTD1903079) [SGB9622C]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJT 3487K on 27/6/2019
We are pending estimate from repairer.

Regards,
Denise
LKK AUTO

DOCUMENTS SUMMARY

There are no documents.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

Enjoy life while saving money.

SUBSCRIBE TO LIFE

avante

Price Range

Depreciation

2009

Vehicle Type



Home » Used Cars » 1 & Ones Motoring Pte Ltd » Hyundai Avante 1.6A

Hyundai Avante 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

| | | | |
|-----------------|------------------------------|-----------------|---------------------------------------|
| Price | \$8,800 | | |
| Depreciation | N.A. | Reg Date | 11-Aug-2009 (1mth 14days COE left) |
| Mileage | 113,700 km (11.5k /yr) | Manufactured ? | 2009 |
| Road Tax | \$738 /yr | Transmission | Auto |
| Dereg Value | \$5,773 as of today (change) | OMV ? | \$11,216 |
| COE | \$13,658 | ARF ? | \$11,216 |
| Engine Cap | 1,591 cc | Power | 89.7 kW (120 bhp) |
| Curb Weight | 1,264 kg | No. of Owners ? | 2 |
| Type of Vehicle | Mid-Sized Sedan | | |

Features

Responsive And Fuel Efficient 1.6L 4-Cylinders In-Line 16 Valves DOHC CVT Engine, 4 Speed Auto Transmission. ABS/SRS Airbags, Climate Air Con Control View specs of the Hyundai Avante (2007-2011)

Accessories

Multi-Function Steering Control, Double Din 7" DVD Player, Reverse Sensors, Sport Rims, Leather Seats, Fog Lamp, Auto Retractable Folding Mirror.

Description

Ideal For Short Term Drive Or Extend COE Later. Also Selling \$24.8K For Brand New 5 Years COE. Agent Unit. Fully Serviced / Well Maintained. Original Stock Condition, Low Mileage Done, Guaranteed Accident Free, No Repair Needed. Can Trade In, Bank / In House Loan Available. Don't Miss. View To Believe. Please Call For Viewing Now

Category

PART 1 car

Status

Av:



Location Map

Shortlist

Com

Report Error

M

Seller Information

| | |
|-------------------|-------|
| Company | 1 & 1 |
| | » dea |
| | » 28 |
| Address | 5 Ka |
| | Seac |
| Location | Euno |
| Contact Person(s) | Fran |

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



This mid-year, get more reward:
you go with HSBC Credit Cards



avante

Price Range

Depreciation

2009

Vehicle Type

Home » Used Cars » SG Motor Link Pte Ltd » Hyundai Avante 1.6A S

Hyundai Avante 1.6A S

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$11,800

Depreciation N.A.

Reg Date 20-Oct-2009
(3mths 22days COE left)

Mileage 88,000 km (9.1k /yr)

Manufactured 2009

Road Tax \$738 /yr

Transmission Auto

Dereg Value \$5,770 as of today (change)

OMV \$11,539

COE N.A.

ARF \$11,539

Engine Cap 1,591 cc

Power 89.7 kW (120 bhp)

Curb Weight 1,264 kg

No. of Owners 1

Type of Vehicle Mid-Sized Sedan

Features

View specs of the Hyundai Avante (2007-2011)

Accessories

New Tyre.

Description

1 Owner, Low Mileage, Very Good Condition, Vehicle As Per Picture Is Original Condition, Renew 5 Years COE Sell \$ 26800. Owner Use It To Fetch Kid To School. Come View To Believe It.

Category

PARF Car, Premium Ad Car, Low Mileage Car

Sta



Price Chart



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1795H

Vehicle Details

Vehicle No.: SJT3487K
Vehicle to be Exported: No
Intended Deregistration Date: 27 Jun 2019
Vehicle Make: HYUNDAI
Vehicle Model: AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour: Black
Manufacturing Year: 2009
Engine No.: G4FC9U746459
Chassis No.: KMH DU41BMAU893188
Maximum Power Output: 89.7 kW (120 bhp)
Open Market Value: \$11,605.00
Original Registration Date: 02 Oct 2009
First Registration Date: 02 Oct 2009
Transfer Count: 3
Actual ARF Paid: \$10,940.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 01 Oct 2019
PARF Rebate Amount: \$5,470.00

Intended COE Rebate Details

COE Expiry Date: 01 Oct 2019
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$8,231.00
COE Rebate Amount: \$406.00
Total Rebate Amount: \$5,876.00

The information contained herein is correct as at 27 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|------------------------------------|
| Date Of Report | 27/06/2019 12:17 |
| Date Of Accident | 26/06/2019 17:00 |
| Exact Location Of Accident | BLK 105A JALAN BUKIT MERAH CARPARK |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJT3487K |
| Insured/Policyholder | |
| Name Of Registered Owner | KHUSAINI BIN KAYAT |
| NRIC No | S7031795H |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-91712838 |
| Alternative Phone No | OFFICE-91712838 |

Vehicle Particulars

| | |
|--|--------------------------------|
| Manufacturer | HYUNDAI |
| Model | AVANTE 1.6 AT ABS D/AB 2WD 4DR |
| Exact Purpose for which vehicle was being used at time of accident | |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--|
| Name of Insurance Company | NTUC INCOME INSURANCE CO-OPERATIVE LTD |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | 5106630134 CLASSIC |
| Cover Note Number | |

Driver

| | |
|----------------------|------------------------|
| Name of Driver | KHUSAINI BIN KAYAT |
| NRIC No | S7031795H |
| Date Of Birth | 01/10/1970 |
| Occupation | INDOOR |
| Date Of Driving Pass | 02/07/2001 |
| Driving Experience | 17 YEARS AND 11 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-91712838 |
| Fax Number | |
| Contact Number | OFFICE-91712838 |
| Email Address | NOEMAIL |

| | |
|---|------------------------------------|
| Address | BLK 106 #09-1870 JALAN BUKIT MERAH |
| Postcode | 160106 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|---|
| Type Of Accident | HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 3 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 0 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

| | |
|---|------------|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Remarks/ Reasons: | WITH OWNER |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|---------------------|
| Vehicle Registration Number | SGB9622C |
| Vehicle Make/Model/Colour | NISSAN SUNNY 1.6EXA |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

DETAILS OF OTHER VEHICLE PROPERTY 2

| | |
|-------------------------------------|--------------------|
| Vehicle Registration Number | SLC5023T |
| Vehicle Make/Model/Colour | HONDA VEZEL 1.5X A |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 21 JUN 2019

IDAC KAKI BUKIT (VAL)
 23 Kaki Bukit Ave 4
 Singapore 415933
 Tel: 67416697 Fax: 67492775
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



A - SJ.T 3487 K
B - SG.B 9622 C
C - SL.E 5023 T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time. I parked my car at BIK 105A Jalan Bukit Merah Carpark. I was informed by police officer that my car was hit by vehicle B when I came to the scene. there was another vehicle C also involved in an accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature

Date & Time:


Driver's Signature
(If driver is not the policyholder)

Date & Time: 27 JUN 2019

IDAC KAKI BU. I* (VNC)

23 Kaki Bukit Road 4

Singapore 415135

Tel: 67416600 Fax: 67416605

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Not Acknowledged
d/s # 40001
7 Aug.

SJT 3487K

| QTY | PARTICULAR | AMOUNT S\$ |
|------|---|------------------|
| 1PCS | BOOTLID | 11 \$907.60 X |
| 1PCS | BOOTLID REAR LOGO | 11 \$25.80 X |
| 1PCS | BOOTLID 'AVANTE' EMBLEM | 11 \$30.80 X |
| 1PCS | BOOTLID 'S' EMBLEM | 11 \$28.20 X |
| 1PCS | BOOTLID INNER LOCK | 11 \$183.60 X |
| 1PCS | BOOTLID WEATHERSTRIPS | 11 \$165.30 X |
| 2PCS | BOOTLID HINGES @ \$110.10 | 11 \$220.20 X |
| 2PCS | BOOTLID REFLECTORS @ \$189.60 | 11 \$379.20 X |
| 1PCS | BOOTLID INNER TRIM | 11 \$185.30 X |
| 1SET | BOOTLID INNER TRIM CLIPS | 11 \$50.00 X |
| 1PCS | REAR BUMPER | R 1 \$486.90 X |
| 1PCS | REAR BUMPER REINFORCEMENT | 11 \$354.00 X |
| 2PCS | REAR BUMPER REINFORCEMENT STAYS @ \$135 | 11 \$270.00 X |
| 5PCS | REAR BUMPER REINFORCEMENT BRACKETS @ \$21 | 11 \$105.00 X |
| 2PCS | REAR BUMPER SIDE RETAINERS @ \$45.50 | 11 \$91.00 X |
| 1SET | REAR BUMPER CLIPS | 11 \$50.00 ✓ |
| 1PCS | REAR BUMPER SPONGE | 11 \$145.30 X |
| 2PCS | TAILLAMPS @ \$266.50 | 11 \$533.00 X |
| 2PCS | TAILLAMPS HOUSING PANEL @ \$185.10 | 11 \$370.20 X |
| 1PCS | REAR END PANEL | 11 \$637.90 X |
| 1PCS | REAR END PANEL TOP GARNISH | 11 \$188.60 X |
| 1PCS | REAR FLOOR PANEL | 11 \$928.10 X |
| 1PCS | REAR FLOOR PANEL TOP BOARD | 11 \$280.60 X |
| 1PCS | REAR EXHAUST | 11 \$693.80 X |
| 2PCS | REAR EXHAUST MOUNTINGS @ \$45.00 | 11 \$90.00 X |
| 1PCS | BONNET | 311 \$1,102.00 ✓ |
| 1PCS | BONNET LOCK | 311 \$83.60 ✓ |
| 2PCS | BONNET HINGES @ \$89.50 | 511 \$179.00 X |
| 1PCS | BONNET INNER RUBBER | 111 \$42.00 ✓ |
| 1PCS | BONNET INSULATOR | 111 \$266.30 X |
| 1SET | BONNET INSULATOR CLIPS | 111 \$50.00 X |
| 2PCS | HEADLAMPS @ \$581.60 | one \$1,163.20 ✓ |
| 1PCS | FRONT GRILLE 325.00 | one \$385.00 ✓ |
| 1PCS | FRONT GRILLE LOGO | 111 \$22.80 ✓ |
| 1PCS | FRONT BUMPER | 111 \$480.60 ✓ |
| 2PCS | FRONT BUMPER BRACKETS @ \$45.00 | 111 \$90.22 ✓ |
| 1PCS | FRONT BUMPER SPONGE | 111 \$145.80 ✓ |
| 1PCS | FRONT BUMPER LOWER GRILLE 86.50 | 111 \$105.20 ✓ |

202

11516-12

| | | | | |
|------|--|---------|-------------|-----|
| 1PCS | FRONT BUMPER REINFORCEMENT | D/S | \$431.50 | ✓ |
| 2PCS | FRONT BUMPER SIDE RETAINERS @\$36.50 | set | \$73.00 | ✓ |
| 2PCS | FRONT FENDERS @\$405.30 | M/S set | \$810.60 | 1PC |
| 2PCS | FRONT FENDER 'VVT' EMBLEM @\$42.00 | set | \$84.00 | ✓ |
| 1PCS | FRONT SUPPORT PANEL | set/cu | \$958.00 | ✓ |
| 1PCS | HORN UNIT | 11 | \$90.00 | X |
| 2PCS | FRONT SUPPORT PANEL SIDE COVERS @\$45.50 | 11 | \$91.00 | ✓ |
| 1PCS | AIRCON CONDENSER | D/S | \$950.00 | ✓ |
| 1PCS | AIRCON SUCTION HOSE | 11 | \$295.00 | X |
| 1PCS | AIRCON DISCHARGE HOSE | 11 | \$305.00 | X |
| 1PCS | RADIATOR | dis/tw | \$885.00 | ✓ |
| 1PCS | RADIATOR FAN ASSY | cu/5m | \$685.00 | ✓ |
| 1PCS | FRONT PANEL INNER SHIELD O/S | 11 | \$162.50 | X |
| 1SET | FRONTPANEL INNER SHIELD CLIPS O/S | 11 | \$50.00 | X |
| 2PCS | FRONT FOG LAMPS @\$310.20 | 2070 | \$620.40 | X |
| 1PCS | AIR DUCT | 11 | \$115.30 | X |
| | | | \$18,149.20 | |

| | | | |
|--------|-----------------------------|-----|------------|
| S.NETT | | | |
| 1SET | REAR BUMPER REVERSE SENSOR | 11 | \$280.00 X |
| 1PCS | REAR BUMPER LOWER SKIRTING | 11 | \$850.00 X |
| 1PCS | REAR END PANEL SEALANT | 11 | \$50.00 X |
| 1PCS | REAR FLOOR PANEL INSULATOR | 11 | \$200.00 X |
| 1PCS | FRONT LICENSE PLATE | 320 | \$50.00 40 |
| 1BOL | RADIATOR COOLANT | 11 | \$50.00 30 |
| 1PCS | FRONT BUMPER LOWER SKIRTING | 11 | \$980.00 X |
| 1SET | FRONT HEADLAMP GARNISH | 11 | \$120.00 X |
| 1PCS | BATTERY | 11 | \$300.00 X |

| | | | |
|--|--------|------------|------|
| TO CHECK WIRING | refix | \$80.00 | 30 |
| TO DISMANTLE & REPLACING REVERSE SENSOR | sensor | \$80.00 | 50 |
| TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY | | \$150.00 | 80 |
| TO DISMANTLE & REFIX REAR EXHAUST | 11 | \$100.00 | X |
| TO DISMANTLE & REFIX PETROL TANK | 11 | \$100.00 | X |
| TO DISMANTLE & REPLACING BOOTLID MECHANISM | 11 | \$100.00 | X |
| TO REFILL AIRCON GAS | | \$150.00 | 100 |
| TO MOUNT VEHICLE ON CAR O-LINER | 11 | \$380.00 | X |
| LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS | | \$2,800.00 | 1000 |
| TO PUTTY & SPRAY PAINTING | | \$2,800.00 | 1400 |

\$27,769.20

27742.42

- the Repairer of the following
- To resurvey before/after survey painting
 - To display damaged part(s) do
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19011462/UTD3N2

Date: 09/07/2019

REFERENCE

| | | | |
|-----------------------|-------------------------------------|----------------------|-----------------|
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. | Policy No: | D19MTPV01000209 |
| Claimant Vehicle No : | SJT3487K | Insured Vehicle No : | SGB9622C |
| Date of Loss: | 26/06/2019 | Nature of Claim: | TP |
| | | Claim No: | CMTD1903079 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|--------------------|
| Reg No: | SJT3487K | Engine No: | G4FC9U746459 |
| Make & Model: | HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A) | Chassis No: | KMH DU41BMAU893188 |
| Reg. Date: | 02/10/2009 (Man. Year: 2009) | Odometer: | 155756 km |
| Colour: | Black | | |
| Engine Capacity: | 1591 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 195/60R15 | Rear Tyre Size: | 195/60R15 |
| Front Left Side: | BF-Goodrich 6 mm | Rear Left Side: | BF-Goodrich 6 mm |
| Front Right Side: | BF-Goodrich 6 mm | Rear Right Side: | BF-Goodrich 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|------------------|--------------|
| Parts | 21,002.42 | 6,593.62 | 14,408.80 | 68.61 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 6,740.00 | 2,660.00 | 4,080.00 | 60.53 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 27,742.42 | 9,253.62 | 18,488.80 | 66.64 |
| Approved Total (Overridden) (S\$) | | 4,000.00 | | |
| (S\$) | 27,742.42 | 4,000.00 | 23,742.42 | 85.58 |
| + GST 7.00/7.00% (S\$) | 1,941.97 | 280.00 | 1,661.97 | 85.58 |
| Nett Amount (S\$) | 29,684.39 | 4,280.00 | 25,404.39 | 85.58 |

INSPECTION

| | | |
|---------------------|--------------------------|--|
| Date of Assignment: | 28/06/2019 | |
| Date Inspected: | 27/06/2019 Inspected At: | Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883 |

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|----------------------|--|---|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 08 Jul 2019) |
| Parts: | 143 | HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SJT3487K) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|-------------------------------------|---------------------|------------|--------------|
| 1 | 1 | *BOOTLID | Not Necessary | 907.60 F | *- FL |
| 2 | 1 | *BOOTLID REAR LOGO | Not Necessary | 25.80 F | *- FL |
| 3 | 1 | *BOOTLID AVANTE EMBLEM | Not Necessary | 30.80 F | *- FL |
| 4 | 1 | *BOOTLID S EMBLEM | Not Necessary | 28.20 F | *- FL |
| 5 | 1 | *BOOTLID INNER LOCK | Not Necessary | 183.60 F | *- FL |
| 6 | 1 | *BOOTLID WEATHERSTRIPS | Not Necessary | 165.30 F | *- FL |
| 7 | 2 | *BOOTLID HINGES | Not Necessary | 220.20 F | *- FL |
| 8 | 2 | *BOOTLID REFLECTORS | Not Necessary | 379.20 F | *- FL |
| 9 | 1 | *BOOTLID INNER TRIM | Not Necessary | 185.30 F | *- FL |
| 10 | 1 | *SET BOOTLID INNER TRIM CLIPS | Not Necessary | 50.00 F | *- FL |
| 11 | 1 | *REAR BUMPER | Repair | 486.90 F | *- FL |
| 12 | 1 | *REAR BUMPER REINFORCEMENT | Not Necessary | 354.00 F | *- FL |
| 13 | 2 | *REAR BUMPER REINFORCEMENT STAYS | Not Necessary | 270.00 F | *- FL |
| 14 | 5 | *REAR BUMPER REINFORCEMENT BRACKETS | Not Necessary | 105.00 F | *- FL |
| 15 | 2 | *REAR BUMPER SIDE RETAINERS | Not Necessary | 91.00 F | *- FL |
| 16 | 1 | *SET REAR BUMPER CLIPS | Necessary | 50.00 F | *50.00 FL |
| 17 | 1 | *REAR BUMPER SPONGE | Not Necessary | 145.30 F | *- FL |
| 18 | 2 | *TAILLAMPS | Not Necessary | 533.00 F | *- FL |
| 19 | 2 | *TAILLAMPS HOUSING PANEL | Not Necessary | 370.20 F | *- FL |
| 20 | 1 | *REAR END PANEL | Not Necessary | 637.90 F | *- FL |
| 21 | 1 | *REAR END PANEL TOP GARNISH | Not Necessary | 188.60 F | *- FL |
| 22 | 1 | *REAR FLOOR PANEL | Not Necessary | 928.10 F | *- FL |
| 23 | 1 | *REAR FLOOR PANEL TOP BOARD | Not Necessary | 280.60 F | *- FL |
| 24 | 1 | *REAR EXHAUST | Not Necessary | 693.80 F | *- FL |
| 25 | 2 | *REAR EXHAUST MOUNTINGS | Not Necessary | 90.00 F | *- FL |
| 26 | 1 | *BONNET | Buckled | 1,102.00 F | *1,102.00 FL |
| 27 | 1 | *BONNET LOCK | Bent | 83.60 F | *83.60 FL |
| 28 | 2 | *BONNET HINGES | Serviceable | 179.00 F | *- FL |
| 29 | 1 | *BONNET INNER RUBBER | Necessary | 42.00 F | *42.00 FL |
| 30 | 1 | *BONNET INSULATOR | Not Necessary | 266.30 F | *- FL |
| 31 | 1 | *SET BONNET INSULATOR CLIPS | Not Necessary | 50.00 F | *- FL |
| 32 | 2 | *HEADLAMPS | Cracked | 1,163.20 F | *1,163.20 FL |
| 33 | 1 | *FRONT GRILLE | Cracked | 385.00 F | *325.00 FL |
| 34 | 1 | *FRONT GRILLE LOGO | Necessary | 22.80 F | *22.80 FL |
| 35 | 1 | *FRONT BUMPER | Distorted | 480.60 F | *480.60 FL |
| 36 | 2 | *FRONT BUMPER BRACKETS | Bent | 90.22 F | *90.22 FL |
| 37 | 1 | *FRONT BUMPER SPONGE | Torn | 145.80 F | *145.80 FL |
| 38 | 1 | *FRONT BUMPER LOWER GRILLE | Twisted | 105.20 F | *86.50 FL |
| 39 | 1 | *FRONT BUMPER REINFORCEMENT | Distorted | 431.50 F | *431.50 FL |
| 40 | 2 | *FRONT BUMPER SIDE RETAINERS | Bent | 73.00 F | *73.00 FL |
| 41 | 1 | *FRONT FENDERS | N/s Bent/O/s Repair | 810.60 F | *405.30 FL |
| 42 | 2 | *FRONT FENDER VVTI EMBLEM | Necessary | 84.00 F | *84.00 FL |
| 43 | 1 | *FRONT SUPPORT PANEL | Bent/Cracked | 958.00 F | *958.00 FL |
| 44 | 1 | *HORN UNIT | Not Necessary | 90.00 F | *- FL |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|---|-------------------|------------|------------|
| 45 | 2 | *FRONT SUPPORT PANEL SIDE COVERS | Torn | 91.00 F | *91.00 FL |
| 46 | 1 | *AIRCON CONDENSER | Distorted | 950.00 F | *950.00 FL |
| 47 | 1 | *AIRCON SUCTION HOSE | Not Necessary | 295.00 F | *- FL |
| 48 | 1 | *AIRCON DISCHARGE HOSE | Not Necessary | 305.00 F | *- FL |
| 49 | 1 | *RADIATOR | Distorted/Twisted | 885.00 F | *885.00 FL |
| 50 | 1 | *RADIATOR FAN ASSY | Cracked/Jammed | 685.00 F | *685.00 FL |
| 51 | 1 | *FRONT PANEL INNER SHIELD O/S | Not Necessary | 162.50 F | *- FL |
| 52 | 1 | *SET FRONT PANEL INNER SHIELD CLIPS O/S | Not Necessary | 50.00 F | *- FL |
| 53 | 2 | *FRONT FOG LAMPS | Not fitted | 620.40 F | *- FL |
| 54 | 1 | *AIR DUCT | Not Necessary | 115.30 F | *- FL |
| 55 | 1 | *SET REAR BUMPER REVERSE SENSOR | Not Necessary | 280.00 FS | *- FS |
| 56 | 1 | *REAR BUMPER LOWER SKIRTING | Not Necessary | 850.00 FS | *- FS |
| 57 | 1 | *REAR END PANEL SEALANT | Not Necessary | 50.00 FS | *- FS |
| 58 | 1 | *REAR FLOOR PANEL INSULATOR | Not Necessary | 200.00 FS | *- FS |
| 59 | 1 | *FRONT LICENSE PLATE | Broken | 50.00 FS | *40.00 FS |
| 60 | 1 | *BOL RADIATOR COOLANT | Necessary | 50.00 FS | *30.00 FS |
| 61 | 1 | *FRONT BUMPER LOWER SKIRTING | Not Necessary | 980.00 FS | *- FS |
| 62 | 1 | *SET FRONT HEADLAMP GARNISH | Not Necessary | 120.00 FS | *- FS |
| 63 | 1 | *BATTERY | Not Necessary | 300.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (\$\$) | 21,002.42 | 8,224.52 |
| - List Item Discount on L Items 0.00/20.00% (\$\$) | 0.00 | 1,630.90 |
| Total Parts (\$\$) | 21,002.42 | 6,593.62 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO CHECK WIRING | New | 80.00 | 30.00 |
| 2 | TO DISMANTLE & REFIX REVERSE SENSOR | New | 80.00 | 50.00 |
| 3 | TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY | New | 150.00 | 80.00 |
| 4 | TO DISMANTLE & REFIX REAR EXHAUST | New | 100.00 | 0.00 |
| 5 | TO DISMANTLE & REFIX PETROL TANK | New | 100.00 | 0.00 |
| 6 | TO DISMANTLE & REPLACING BOOTLID MECHANISM | New | 100.00 | 0.00 |
| 7 | TO REFILL AIRCON GAS | New | 150.00 | 100.00 |
| 8 | TO MOUNT VEHICLE ON CAR O-LINER | New | 380.00 | 0.00 |
| 9 | LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS | New | 2,800.00 | 1,000.00 |
| 10 | TO PUTTY & SPRAY PAINTING | New | 2,800.00 | 1,400.00 |
| Gross Labour Cost (\$\$) | | | 6,740.00 | 2,660.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >