

INSURANCE

INS. CASE OWNER:

Lynting

CC 4, ASM 1480, R14039

LOK:

IDAC:

Surveyor:

Resu

DOI:

ASSIGNMENT

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$5

Is driver the owner?

GBE 59422

LYGB PAINTS AND HARDWARE CO

HP:

D.O.A:

(YES / NO) Nature of Accident :

Claim No.:

Policy No.:

Make / Model :

Place of Accident :

SMOISTK/INW4

PM9201

TOYOTA

ALONG QUEAM RD

If NO. Driver Name / Age : SAMMIR WAMPONG THU

Driver Tel No.:

(V/L: YES / NO)

Of GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

% Final ? Yes / No

GBE 59422

URGENT



INSRS:
WSP:
Tel:
Liability:
RMKS:

Kah motor



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

GBE 59422 - 1 GBE 59422 - 1

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup):

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

UTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

3/7/19

Called OI to inform TP claim (Sent via email)

Email liability clear

TP V. Video, Old envelope with 1/1/19

18/10/19

DS found sent

2/10/19

File -> Shupei to close.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessment)

BOLA S/N No.:

If No or B 28, Ass. Lia:

Repair Cost

\$5 1766.66

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5 180.00

(

days)

Loss of Income (LOI):

\$5

(

days)

LOR only

LOU only

LOR + LOU

LOR + LO

(Tick only one)

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost:

\$5

Total:

\$5 1916.66

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 1916.66

Name 1:

Kah Motor Co. sdn Bhd.

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

URGENT

3/3/20

Ref

REF: ASM (AXA)

W

9/39F

ASSIGNMENT

From:

Date: 16.7.2019

Veh No:

SKZ 3545H

Yr Regn: 2016 / Jan

Estimated Cost:

Type: ☒ M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 3545H

Make: Honda JAZZ 1.3A

CC: 1318

at Workshop n/s: Kah motor

Colour: Black

A/C: Insured / Std / NI / NA

of 255 Alexandra

Sp. Reading: 066234

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No: JHMHK 38506 X 220094

Claims No:

Gen. Cont: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: 82896295 (Son Hai)

Modi: Nil / ☒ R / STD A/Rim or

Tyre Size

F:

175/65R15

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS: ☒ DUB / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

55K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

3.

days

Res: Yes or No

Lump Sum:

%

3 V.A. Yes or No

CA / REV / REP. / 24 HRS

100%

Vehicle: IN / OUT

Date:

Person Contacted:

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

27/06/19

D.O.A:

15/07/19

Survey held at

KAH MOTOR

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

N/S Fnt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PIP \$ 1651.09 (Ked \$ 8529.71 / 80%)

Date/Time, File Pass to?

☐

: Preli Report

11

☐

: Final Report

Date/Time, File Return to?

21

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) 3 - R.S. 50

) Photos:

) Others:

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6541 3836

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No: M200050223
Company Ref. No: 580FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19002836	Page	1
	8 SHENTON WAY	Date	: 27 Jun 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: NG SIN HAI		
Registration No	: SKZ3545H	Engine No	: L13B11010122		
Chassis No	: JHMGK3850GX220094	Date Time	: 27 Jun 2019 7:51:47 PM		
Model	: JAZZ 1.3LXR CVT 16YM	Surveyor Name	:		
Owner's Name	: CHUA KIEN SOON	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (JNO.)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING (LIN) X	1	45.00		45.00	3.15	48.15
33150-T5A-JB1	HEADLIGHT ASSY. L ?	1	479.70	25	359.77	25.18	384.95
60100-T5A-000ZZ	HOOD COMP X	1	537.50	25	403.12	28.22	431.34
71105-T5A-000	COVERFR GRILLE X	1	12.00	25	9.00	0.63	9.63
71120-TAR-003	GRILLE ASSYFR X	1	258.10	25	193.57	13.55	207.12
91505-TM8-003	CLIP BUMPER m	4	2.30	25	6.90	0.48	7.38
04711-T5A-000ZZ	FACE FR BUMPER 2mm	1	504.60	25	378.45	26.49	404.94
71102-T5A-000	LOWER GRILLEFR BUMPER ?	1	28.30	25	21.22	1.49	22.71
71103-T5A-000	GARNISH FR BUMPER ?	1	11.30	25	8.47	0.59	9.06
71104-T5A-000ZF	COVERFR TOWING X	1	14.50	25	10.87	0.76	11.63
71108-T5A-000	GARNISH L FR BUMPER X	1	11.30	25	8.47	0.59	9.06
71110-T5A-000	SPOILERFR BUMPER LIP X	1	58.00	25	43.50	3.05	46.55
71130-T5A-000ZZ	BEAM COMPFR BUMPER X	1	223.80	25	167.85	11.75	179.60
71140-T5A-000	BRACKETR HEADLIGHT X	1	24.10	25	18.07	1.26	19.33
71145-T5A-000	BASEFR LICENCE PLATE X	1	52.00	25	39.00	2.73	41.73
71190-T5A-000	BRACKETL HEADLIGHT X	1	21.90	25	16.42	1.15	17.57
71193-T5A-000	SPACERR FR BUMPER 1.7	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL FR BUMPER 2.0	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP BUMPER m	17	2.30	25	29.32	2.05	31.37

Printed on 27/6/2019 7:59:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual items.

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SKZ3545H

Chassis No : JHMGK3850GX220094

Model : JAZZ 1.3LXR CVT 16YM

Owner's Name : CHUA KIEN SOON

Ins Policy No. :

Date of Accident : 27/6/2019

Document No. : SQT19002836

Date : 27 Jun 2019

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : L13B11010122

Date | Time : 27 Jun 2019 7:51:47 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
60261-T5R-A00ZZ	PANELL FR.FENDER X	1	398.60	25	298.95	20.93	319.88
74100-T5A-000	FENDER ASSYR.FR INNER X	1	73.30	25	54.97	3.85	58.82
90682-SEA-003	CLIP ABUMPER X	6	2.60	25	11.70	0.82	12.52
91501-TR0-003	CLIP INNER FENDER X	22	2.80	25	46.20	3.23	49.43
60400-T5B-310ZZ	BULKHEAD COMPFR X	1	381.70	25	286.27	20.04	306.31
80100-T5B-003	CONDENSER ASSY X	1	704.40	25	528.30	36.98	565.28
19010-SR1-901	RADIATOR COMP X	1	1211.20	25	908.40	63.59	971.99
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 X	6	23.20	25	104.40	7.31	111.71
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J X	1	836.00	25	627.00	43.89	670.89
Sum Item					4640.79	324.86	4,965.65
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS	1	380.00	X 30	380.00	26.60	406.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS	1	330.00	X 30	330.00	23.10	353.10
BKBH01M	CUT OFF & RENEW BULKHEAD, STRAIGHTEN	1	2500.00	X 560	2500.00	175.00	2675.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	1	2000.00	X 450	2000.00	140.00	2140.00
BKBU01R	REMOVE AND RENEW LHF RIM	1	50.00	X 10	50.00	3.50	53.50
Sum Labor					5540.00	387.80	5,927.80

Survey By

Date & Time

Excess

Status

Signature

RASUL - Hp 90010068

15/6/19 @ 1435

3 days

Rasy 54 paint

Total Amount 10,180.79 712.66 10,893.45

Total (Inclusive of GST) — 10,893.45

Printed on 27/6/2019 7:59:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

(GST Amount is calculated from individual items)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

L&S Auto Consultants hereby notify the Repairer of the following:

- To require satisfactory spray painting
- To repair damaged parts during recovery
- Parts prices are subject to change
- Third party survey is on a "without prejudice" basis
- No illegal modifications are allowed
- Supplementary item(s) may be required and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19002836	Page	1
	8 SHENTON WAY	Date	: 27. Jun 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: NG SIN HAI		
Registration No	: SKZ3545H	Engine No	: L13B11010122		
Chassis No	: JHMGK3850GX220094	Date Time	: 27. Jun 2019 7:51:47 PM		
Model	: JAZZ 1.3LXR CVT 16YM	Surveyor Name	:		
Owner's Name	: CHUA KIEN SOON	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/6/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X	1	45.00		45.00	3.15	48.15
33150-T5A-J81	HEADLIGHT ASSY.L ?	1	479.70	25	359.77	25.18	384.95
60100-T5A-000ZZ	HOOD COMP X	1	537.50	25	403.12	28.22	431.34
71105-T5A-000	COVERFR.GRILLE X	1	12.00	25	9.00	0.63	9.63
71120-TAR-003	GRILLE ASSYFR X	1	258.10	25	193.57	13.55	207.12
91505-TM8-003	CLIP,BUMPER m	4	2.30	25	6.90	0.48	7.38
04711-T5A-000ZZ	FACE.FR.BUMPER 2m / ?	1	504.60	25	378.45	26.49	404.94
71102-T5A-000	LOWER GRILLEFR.BUMPER ?	1	28.30	25	21.22	1.49	22.71
71103-T5A-000	GARNISHR.FR.BUMPER ?	1	11.30	25	8.47	0.59	9.06
71104-T5A-000ZF	COVERFR.TOWING X	1	14.50	25	10.87	0.76	11.63
71108-T5A-000	GARNISHL.FR.BUMPER X	1	11.30	25	8.47	0.59	9.06
71110-T5A-000	SPOILERFR.BUMPER LIP X	1	58.00	25	43.50	3.05	46.55
71130-T5A-000ZZ	BEAM COMPFR.BUMPER	1	223.80	25	167.85	11.75	179.60
71140-T5A-000	BRACKETR.HEADLIGHT X	1	24.10	25	18.07	1.26	19.33
71145-T5A-000	BASEFR.LICENCE PLATE X	1	52.00	25	39.00	2.73	41.73
71190-T5A-000	BRACKETL.HEADLIGHT X ?	1	21.90	25	16.42	1.15	17.57
71193-T5A-000	SPACERR.FR.BUMPER 1 ?	1	10.40	25	7.80	0.55	8.35
71198-T5A-000	SPACERL.FR.BUMPER m	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER m	17	2.30	25	29.32	2.05	31.37

Printed on 27/6/2019 7:59:30 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SKZ3545H

Chassis No : JHMGK3850GX220094

Model : JAZZ 1.3LXR CVT 16YM

Owner's Name : CHUA KIEN SOON

Ins Policy No. :

Date of Accident : 27/6/2019

Document No. : SQT19002836 Page 2

Date : 27. Jun 2019

Customer No. : WZA006

Svc Advisor : NG SIN HAI

Engine No : L13B11010122

Date | Time : 27. Jun 2019 7:51:47 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
60261-T5R-A00ZZ	PANELL.FR.FENDER X	1	398.60	25	298.95	20.93	319.88
74100-T5A-000	FENDER ASSY.FR INNER X	1	73.30	25	54.97	3.85	58.82
90682-SEA-003	CLIP ABUMPER X	6	2.60	25	11.70	0.82	12.52
91501-TR0-003	CLIP INNER FENDER X	22	2.80	25	46.20	3.23	49.43
60400-T5B-310ZZ	BULKHEAD COMPFR X	1	381.70	25	286.27	20.04	306.31
80100-T5B-003	CONDENSER ASSY X	1	704.40	25	528.30	36.98	565.28
19010-5R1-901	RADIATOR COMP X	1	1211.20	25	908.40	63.59	971.99
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2 X	6	23.20	25	104.40	7.31	111.71
42700-T5A-N91	DISKALUMINIUM WHEEL 16X6J X	1	836.00	25	627.00	43.89	670.89
Sum Item					4640.79	324.86	4,965.65
BOSUN	SUNDRIES	1	100.00 30		100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00		180.00	12.60	192.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	380.00 X		380.00	26.60	406.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	330.00 X		330.00	23.10	353.10
BKBH01M	CUT OFF & RENEW BULKHEAD. STRAIGHTEN	1	2500.00 560		2500.00	175.00	2675.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2000.00 450		2000.00	140.00	2140.00
BKBU01R	REMOVE AND RENEW LHF RIM	1	50.00 X		50.00	3.50	53.50
Sum Labor					5540.00	387.80	5,927.80

Survey By

Date & Time

Excess

Status

Signature

Total Amount 10,180.79 712.66 10,893.45

Total (Inclusive of GST) 10,893.45

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to change
- Third party survey is on a "without prejudice" basis
- No illegal modifications at all
- Supplementary repair work after survey is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 27/6/2019 7:59:30 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd., it will be refunded.

Handwritten notes:

RASUL - Hp 90010068

15/6/19 @ 1435

3 days

Resy 54 paint

**HONDA****SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE PTE
 Chassis No: JHMGK3850GX220094
 License No: SKZ3545H
 Mileage: 56665
 Engine No: L13B11010122

Document No: SVO19045286
 Printed By: SHNG
 Order Date: 15. July 2019
 Order Time: 2:52:01 PM
 Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:)							
	OWNER:CHUA KIEN SOON							
	OWNER INSURER:TOKIO							
	ACC DATE:26/07/2019							
	SURVEYED BY:RASUL							
	DATE:15/07/2019							
	REF NO:							
	TP INSURER:AXA							
	TP VEH:GBE5942Z							
91505-TM8-003	CLIP,BUMPER	4	2.30 ✓	25	6.90	0.48	7.38	
04711-T5A-000ZZ	FACE.FR.BUMPER	1	504.60 ✓	25	378.45	26.49	404.94	
71190-T5A-000	BRACKETL.HEADLIGHT	1	21.90 ✓	25	16.42	1.15	17.57	
91505-TM8-003	CLIP,BUMPER	17	2.30 ✓	25	29.32	2.05	31.37	
	SUM PARTS:				431.09	30.17	461.26	
BOSUN	0701	1	30.00 ✓		30.00	2.10	32.10	
	SUNDRIES							
BML01I	0701	1	180.00 ✓		180.00	12.60	192.60	
	INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)							
BKBH01M	1729	1	560.00 ✓		560.00	39.20	599.20	
	CUT OFF & RENEW BULKHEAD. STRAIGHTEN ALIGN CHASSIS & RENEW DAMAGE PARTS,							
BP06R	1718	1	450.00 ✓		450.00	31.50	481.50	
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)							
	SUM LABOUR:				1,220.00	85.40	1,305.40	
	TOTAL SGD				1,651.09	115.57	1,766.66	
	Total Payable (SGD)						1,766.66	

GST Amount is calculated from individual line(s)

◀ Service Request Details

Claim

S9M01S5K

Reference

None ✎

Loss Date

June 27, 2019

Report Date

Jun 28, 2019 8:52:00 AM

Request Date

June 28, 2019

Due Date

July 5, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P. Sin Hai

T. 9.15am

R: Out

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKZ3545H

(YH000001)

HONDA

Service Address

...

Primary Contact/Insured

CHYE SENG PAINTS AND HARDWARE CO
BLK 452 ANG MO KIO AVENUE 10, #01-1767, 560452, Singapore
64548424
MELVINKHOOSK@GMAIL.COM

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: Ng Sin Hai <shng@kahmotor.onmicrosoft.com>
Sent: Thursday, 27 June, 2019 7:49 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: RE: 3rd party direct settlement SKZ3545H/ & your insured GBE5942Z/DOA:27/06/2019/Est \$
Attachments: MRM42424942.PDF
Categories: Shailendra

Dear Motor Claims,

Please refer to the attached pdf, we are assisting our insured vehicle SKZ3545H to file a 3rd party claim against your insured vehicle GBE5942Z and to request for direct settlement.

Please assist and expedite to check the claim liability soonest.

Thank you and have a nice day,☺

Warmest Regards,

Ng Sin Hai
Kah Motor Co. Sdn. Bhd
(A member of Oriental Holdings Berhad)
Body Repair & Paint Centre
255 Alexandra Road
Singapore 159937
DID: 6471 5419
HP: 9072 1769
E-mail: shng@honda.com.sg



Visit our
Facebook page

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Hsiao Tong (LKKAUTO)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Monday, 14 October 2019 2:40 PM
To: amind@lkk.com.sg; Hsiao Tong (LKKAUTO)
Cc: Jerome Tan; Winson Chow
Subject: FW: SKZ3545H- TP CLAIM AGAINST GBE5942Z DOA: 27.05.2019
Attachments: 4635_001.pdf

Your Ref: GBE5942Z

Our Ref: SKZ3545H

M/s: AXA Insurance Singapore Pte Ltd

C/o: LKK Auto Consultants Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Case Handler

Dear All,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

Will appreciate your response after receiving this email.

Best Regards

Desmond Toh

Contact No. 65145848

Kah Motor Co Sdn Bhd

Website : www.honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this

communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Hsiao Tong (LKKAUTO)

From: Chye Seng <cs@chyesengpaints.com>
Sent: Thursday, 4 July 2019 2:58 PM
To: Jimmy Chen (LKK Auto)
Subject: Re: OUR REF : CC4/ASM19011480/wb3 - ACCIDENT INVOLVING GBE5942Z AND SKZ3545H AT TRAFFIC LIGHT JUNCTION ALONG QUTRAM RD
Attachments: minndrivinglicense.pdf; employmentauthorisation.pdf; PHOTO-2019-07-04-14-52-44 2.jpg; PHOTO-2019-07-04-14-52-48.jpg; PHOTO-2019-07-04-14-52-47.jpg

Hi Jimmy,

Thank you for your email.

I have attached the documents as requested. Please let me know if there's anything else you need.

Thank you.

On Wed, Jul 3, 2019 at 5:19 PM Jimmy Chen (LKK Auto) <jimmychen@lkkauto.com> wrote:

Dear Sir/Mdm,

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third-party claim(s) from **Kah Motor Co. Sdn. Bhd** acting on behalf of the owner of **SKZ3545H** against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected because of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third-party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this email. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to jimmychen@lkkauto.com within 7 days from the date of this email **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)

- Driver's driving license or foreign driving license (if any) – Please provide us with a soft copy of **SAI MINN MINN PHAY THU** driver license, you may send it to us by replying to this email.
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization – Please assist to provide us with a copy of the letter of authorization which shows that the driver **SAI MINN MINN PHAY THU** was authorized to drive your vehicle during the time of the accident, you may send the soft copy to us by replying to this email.
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This email should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorized driver may have committed.

In the event of receiving and handling of any third-party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2928 or jimmychen@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Best Regards,

Jimmy Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jimmychen@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

With Regards

Chye Seng Paints & Hardware Co



<TP - Mandate IA> - S9M01S5K [ACCIDENT INVOLVING GBE 5942Z(OI) & SKZ 3545H(TP) ON 27/06/2019]

Type

🔔 Question

Message

Liability: 100%. Insured driver had encroached into third party's lane while turning and collided with third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$1,916.67(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 17-Oct-19

Reply



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/10/2019

Survey Details:

Date of loss	27-Jun-19
Date of appointment	28-Jun-19
Date of survey	15-Jul-19
Location of survey	KAH MOTOR CO SDN BERHAD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SKZ 3545H
Make and Model	HONDA JAZZ 1.3 CVT ABS D/AIRBAG
Date of registration	20/1/2016
Excess	
Market Value	\$55,000
Part Rebate	\$42,447
Nett Loss	\$12,553

Repair details:

Initial Estimate	\$ 10,180.79
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 431.09
Check items (estimate)	NIL
Labour	\$ 1,220.00
Total	\$ 1,651.09
Lump Sum(if applicable)	\$ -
Number of days for repair	3



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OID encroached into third party lane while turning right.

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$	1,766.67
Loss of use	\$	150.00 (3days x \$50.00)
Loss of rental		NIL no. of days
Loss of income		NIL no. of days
LTA search fees		NIL
Others		NIL
Proposed Total	\$	1,916.67

Hsiao Tong (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Thursday, 17 October 2019 8:59 AM
To: Hsiao Tong (LKKAUTO)
Subject: RE: New message for service request 124204, vehicle number SKZ3545H

<input type="checkbox"/> RECD TP ESTIMATE_F FROM RASUL**PASS TO VIVIAN	STU	22/7/2019 2:02:52 PM
<input type="checkbox"/> Case Tranfer To Hsiao Tong***File Pass To Hsiao Tong	STU	15/10/2019 8:41:42 AM
<input type="checkbox"/> Message AXA: Liability: 100%. Insured driver had encroached into third party's lane while turning and collided with third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$1,916.67(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 17-Oct-19	CHT	17/10/2019 7:48:20 AM
<input type="checkbox"/> 10/17/19 8:54 AM LOH Cynthia----- APPROVE	LSP	17/10/2019 8:46:37 AM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Thursday, 17 October 2019 8:56 AM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 124204, vehicle number SKZ3545H

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: cynthia.loh@axa.com.sg <cynthia.loh@axa.com.sg>
Sent: Thursday, 17 October, 2019 8:55 AM
To: admin-d@lkkauto.com
Subject: New message for service request 124204, vehicle number SKZ3545H

AXA Insurance has sent you a message for claim number S9M0155K.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Friday, 18 October 2019 9:26 AM
To: Desmond Toh
Cc: Jerome Tan; Winson Chow; Admin A
Subject: RE: SKZ3545H- TP CLAIM AGAINST GBE5942Z DOA: 27.05.2019 //LKK REF: CC4/ASM19011480/R1pb3
Attachments: EXPRESS SETTLEMENT FORM_SKZ3545H.pdf

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement at \$1,916.66(all-in).

Please duly sign the document enclosed and return to us (LKK) for our necessary action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Monday, 14 October 2019 2:40 PM
To: amind@lkk.com.sg; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Jerome Tan <jerometan@honda.com.sg>; Winson Chow <winsonchow@honda.com.sg>
Subject: FW: SKZ3545H- TP CLAIM AGAINST GBE5942Z DOA: 27.05.2019

Your Ref: GBE5942Z

Our Ref: SKZ3545H

M/s: AXA Insurance Singapore Pte Ltd
C/o: LKK Auto Consultants Pte Ltd
8 Shenton Way

#27-01 AXA Tower
Singapore 068811

Attn: Case Handler

Dear All,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

Will appreciate your response after receiving this email.

Best Regards
Desmond Toh
Contact No. 65145848
Kah Motor Co Sdn Bhd
Website : www.honda.com.sg



BLUE SKIES FOR
OUR CHILDREN



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
Body Repair & Paint Centre
6A Mandal Estate
Singapore 728903
Tel : +65 6841 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd
c/o LKK Auto Consultants Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attn: Motor Claims Department

Date : 2/10/2019

Your ref : GBE5942Z

Dear Sir / Madam,

Our ref : SKZ3545H

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SKZ3545H & GBE5942Z ON 27/06/2019

We refer to the item(s) marked ☒ below:

- ☒ We refer to your email dated 10/07/2019.
- ☐ We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- ☒ Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to **desmondtoh@honda.com.sg**.
- ☐ We return your discharge voucher duly completed.
- ☐ Kindly expedite settlement of the following :-
- | | |
|-----------------------|---|
| Repair Cost | S\$1,766.66 payable to Kah Motor Co. Sdn. Bhd. |
| GIA search fees | |
| LTA search fees | |
| Loss of rental | |
| | [] |
| Loss of use | S\$50.00 x 3 days : S\$150.00 payable to CHUA KIEN SOON. |
| | [] |
| Loss of rental on PRI | |
| | [] |
| Loss of use on PRI | |
| | [] |

☐ Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.

☒ Enclosures

☐ Repair/Excess Bill
☐ Rental Invoice
☐ Others: _____

☒ Letter of Authority
☐ GIA Search

☐ LTA Search

Thank you,

Yours faithfully,


Ng Sin Hai

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer Code : CU0129734

Payment Term : 30 Days

Service Tax InvoiceGST Reg No. M200050223
Company Ref. No. S80FC1380G

Invoice No. : SINV-BM19001696
Invoice Date : 28/09/19
Order No. : SVO19045286
Reference :
Job Card No. : 10815
Date/Time Received : 27/06/19 / 7:51:47 PM
Licence No. : SKZ3545H
Model : JAZZ 1.3LXR CVT 16YM
Car Chassis No. : JHMGK3850GX220094
Car Engine No. : L13B11010122
Mileage : 56665
Service Advisor : NG SIN HAI 1596
Served By : SHNG
Page : 1

						7% GST Amount Incd		
No.	Description	Qty.	UoM	U. Price	Disc %	Amount	Amount	GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:CHUA KIEN SOON OWNER INSURER:TOKIO ACC DATE:27/06/2019 SURVEYED BY:RASUL DATE:15/07/2019 REF NO: TP INSURER:AXA TP VEH:GBE5942Z							
BOSUN	0701 SUNDRIES	1	Hours	30.00		30.00	2.10	32.10
BMLD1I	0701 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	Hours	180.00		180.00	12.60	192.60
BKBH01M	1729 CUT OFF & RENEW BULKHEAD. STRAIGHTEN	1	Hours	560.00		560.00	39.20	599.20
BP06R	1718 ALIGN CHASSIS & RENEW DAMAGE PARTS. SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	Hours	450.00		450.00	31.50	481.50
91505-TM8-003	CLIP,BUMPER	4	Each	2.30	25	6.90	0.48	7.38
04711-T5A-000ZZ	FACE,FR.BUMPER	1	Each	504.60	25	378.45	26.49	404.94
71190-T5A-000	BRACKETL.HEADLIGHT	1	Each	21.90	25	16.42	1.15	17.57
91505-TM8-003	CLIP,BUMPER	17	Each	2.30	25	29.32	2.05	31.37
Sum Labor						1,220.00	85.40	1,305.40
Sum Item						431.09	30.17	461.26
Total SGD						1,651.09	115.57	1,766.66
Total Payable (SGD)								1,766.66

Printed by SHNG on: 28 Sep 2019 at 2:29:16 PM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.
Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).Payment due upon Payment Terms as stated above. Please make payment strictly in accordance with payment terms.
Interest will be charged at 2% per month on overdue amounts.Please give us your
feedback by scanning
the QR Code using
mobile device.

Hsiao Tong (LKKAUTO)

From: Jimmy Chen (LKK Auto)
Sent: Wednesday, 3 July 2019 5:19 PM
To: CS@CHYESENGPAINTS.COM
Cc: Vic (LKKAUTO)
Subject: OUR REF : CC4/ASM19011480/wb3 - ACCIDENT INVOLVING GBE5942Z AND SKZ3545H AT TRAFFIC LIGHT JUNCTION ALONG QUTRAM RD
Attachments: LETTER OF EMPLOYMENT AND AUTHORIZATION TEMPLATE.pdf

Dear Sir/Mdm,

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a third-party claim(s) from **Kah Motor Co. Sdn. Bhd** acting on behalf of the owner of **SKZ3545H** against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected because of the claim against your policy.

As Insurers, they shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third-party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this email. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to jimmychen@lkkauto.com within 7 days from the date of this email **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any) – Please provide us with a soft copy of **SAI MINN MINN PHAY THU** driver license, you may send it to us by replying to this email.
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Copy of the letter of authorization – Please assist to provide us with a copy of the letter of authorization which shows that the driver **SAI MINN MINN PHAY THU** was authorized to drive your vehicle during the time of the accident, you may send the soft copy to us by replying to this email.
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA Customer Care Centre.

This email should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorized driver may have committed.

In the event of receiving and handling of any third-party injury claim(s), we shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2928 or jimmychen@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Best Regards,

Jimmy Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2928 | email: jimmychen@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OWNER'S VEHICLE NO.) SKZ 3545H &
(THIRD PARTY'S VEHICLE NO.) G8E5942Z ON 27/6/19
ALONG Chin Swee Road

I hereby authorize Kah Motor Co. Sdn Bhd (Kah Motor) and its agents or any person authorized by Kah Motor to do all or any of the following:

- To submit, resolve and make any claim(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher/indemnity forms and all necessary documents in connection with and arising out of the above claim.
- Any payment should be made in favour of my name / Kah Motor Co. Sdn. Bhd.



Owner Signature
(Co stamp & authorized signature if is Co registered vehicle)

Name : Chua Kien Soon

NRIC No : S1479139F

Vehicle No : SKZ 3545H

Date : 18/7/19



WITHOUT PREJUDICE to:

Any Personal Injury Claims

AXA THIRD PARTY DIRECT SETTLEMENT

Vehide No:	GBE 5942Z (Insd veh)	Model: Honda Jazz (1318cc)
	SKZ 3545H (TP veh)	
Date of Accident/ Time:	27/06/2019	

Repair Estimate	: \$	10,893.45	
Final Repair Cost (w/GST)	: \$	1,766.66	
Loss of Use	: \$	150.00	3 days at \$ 50.00 per day
Rental (if any)	: \$	-	days at \$ per day
LTA / GIA Search Fee	: \$	-	
Others:	: \$	-	
	: \$		
Final Settlement Sum	: \$	1,916.66	

Payee Name : KAH MOTOR CO SDN BERHAD

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: <u>15</u>
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident

KAH MOTOR CO. SDN. BHD.
BODY REPAIR & PAINT CENTRE
8 MANDAI ESTATE
SINGAPORE 729805
TEL: 6514 5266 FAX: 6365 1949

Signature of workshop representative / Workshop stamp
Name of Representative: Desmond Toh
Date: 18/10/2019

Signature of Witness / Workshop stamp (if applicable)
Name of Witness: Jerome Tan
Date: 18/10/2019

Signature of AXA's surveyor/representative
Name of AXA's surveyor /Representative:
Date:



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19011480/R1pb3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: CYNTHIA LOH

Date : 25-10-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 5942Z	Veh. Inspected	SKZ 3545H
Policy No.	P2029201	Coverage (\$)	0.00
Claim No.	S9M01S5K	Excess (\$)	0.00
Assign From		Assign Date	28/06/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ 1.3 A	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHMGK3850GX220094	Colour	BLACK
Odometer	66234	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	DUNLOP	6 mm
L/H Front Tyre	175/65 R15	DUNLOP	6 mm
R/H Rear Tyre	175/65 R15	DUNLOP	6 mm
L/H Rear Tyre	175/65 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/06/2019	Inspection Date	15/07/2019
Survey held at	255 ALEXANDRA RD		
Repairer	KAH MOTOR.CO.SDN.BHD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3545H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	NUMBER PLATE WITH CASING (SN) (CONSISTENT)	NOT NECESSARY	45.00	-
1	HEADLIGHT ASSY ,L (SN) (CONSISTENT)	NOT NECESSARY	359.77	-
1	HOOD COMP (SN) (CONSISTENT)	NOT NECESSARY	403.12	-
1	COVERFR.GRILLE (SN) (CONSISTENT)	NOT NECESSARY	9.00	-
1	GRILLE ASSYFR (SN) (CONSISTENT)	NOT NECESSARY	193.57	-
4	CLIP,BUMPER (SN) (CONSISTENT)	NECESSARY	6.90	6.90
1	FACE ,FR BUMPER (SN) (CONSISTENT)	TORN	378.45	378.45
1	LOWER GRILLEFR BUMPER (SN) (CONSISTENT)	NOT NECESSARY	21.22	-
1	GARNISHR.FR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	8.47	-
1	COVERFR.TOWING (SN) (CONSISTENT)	NOT NECESSARY	10.87	-
1	GARNISHL.FR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	8.47	-
1	SPOILERFR.BUMPER LIP (SN) (CONSISTENT)	NOT NECESSARY	43.50	-
1	BEAM COMPFR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	167.85	-
1	BRACKETR.HEADLIGHT (SN) (CONSISTENT)	NOT NECESSARY	18.07	-
1	BASEFR LICENCE PLATE (SN) (CONSISTENT)	NOT NECESSARY	39.00	-
1	BRACKETL.HEADLIGHT (SN) (CONSISTENT)	CRACKED	16.42	16.42
1	SPACERR.FR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	7.80	-
1	SPACERL.FR.BUMPER (SN) (CONSISTENT)	NOT NECESSARY	7.80	-
17	CLIP.BUMPER (SN) (CONSISTENT)	NECESSARY	29.32	29.32
1	PANELL.FR.FENDER (SN) (CONSISTENT)	NOT NECESSARY	298.95	-
1	FENDER ASSYR.FR INNER (SN) (CONSISTENT)	NOT NECESSARY	54.97	-
6	CLIP ABUMPER (SN) (CONSISTENT)	NOT NECESSARY	11.70	-
22	CLIP,INNER FENDER (SN) (CONSISTENT)	NOT NECESSARY	46.20	-
1	BULKHEAD COMPFR (SN) (CONSISTENT)	NOT NECESSARY	286.27	-
1	CONDENSER ASSY (SN) (CONSISTENT)	NOT NECESSARY	528.30	-
1	RADIATOR COMP (SN) (CONSISTENT)	NOT NECESSARY	908.40	-
6	COOLANT ANTI-FREEZE TYRE 2 (SN) (CONSISTENT)	NOT NECESSARY	104.40	-
1	DISKALUMINIUM WHEEL 16X6J (SN) (CONSISTENT)	NOT NECESSARY	627.00	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	100.00	30.00
			4,740.79	461.09

Report Ref No. CC4/ASM19011480/R1pb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	INSPECT FR LIGHTING MECHANISMS & FOCUS .		180.00	180.00
	REMOVE & REINSTALL A/C CONDENSER WITH FITTINGS.	NOT NECESSARY	380.00	-
	REMOVE & INSTALL RADIATOR WITH FITTINGS.	NOT NECESSARY	330.00	-
	CUT OFF & RENEW BULKHEAD .STRAIGHTEN .		2,500.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,000.00	450.00
	REMOVE AND RENEW LHF RIM.	NOT NECESSARY	50.00	-
			5,440.00	1,190.00
	GRAND TOTAL		10,180.79	1,651.09
RECOMMENDED COST OF REPAIRS				1,651.09

Report Ref No. CC4/ASM19011480/R1pb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

S9M0135K

Reference

CC4/ASH19011480/R1ub3d2

Loss Date

27 June 2019

Report Date

28 Jun 2019 8:52:00 AM

Request Date

28 June 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SICZ3543H

Make

TPVD

Model

HONDA

Service Address

...

Primary Contact/Insured

CHYE SENG PAINTS AND HARDWARE CO

BLK 452 ANG MO KIO AVENUE 10, #01-1767, 560452, Singapore

64548424

MELVINKHOSK@GMAIL.COM

Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Actions

Next Step

Wait for: Approve Invoice

Add Payment

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement	Reports & Statement		Merimen	

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
LKKInvoice1 (6).pdf	Invoice	Surveyor / Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
LKKinspection (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2019
LKK Resurvey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
TP ESTIMATE_MARKED(FINAL).pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
LKK Survey Photos.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
PARF_COE_Illustrate_Engany.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
TP-MANDATE IA d6 171019.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	17 October 2019
TP-IA 3545.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	16 July 2019
PHOTOS FROM OI GBE 5942Z.docx	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	4 July 2019
LOA.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	4 July 2019

Claim Portal

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 CHD DL.pdf	Letters and Correspondence	Policy Holders / Insured	LJK AUTO CONSULTANTS PTE LTD (TP)	4 July 2019
 5K2 3545H_00001.jpg	Evidence	Video	LJK AUTO CONSULTANTS PTE LTD (TP)	3 July 2019
 P2029201_CL_00004_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	KUMAR Shalindra	28 June 2019
 P2029201_EN_00004_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	KUMAR Shalindra	28 June 2019
 PRI FROM WORKSHOP WITH TP CIA. 5K23545H.mpeg	Letters and Correspondence	Workshop	KUMAR Shalindra	28 June 2019