LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

LKK Auto Consultants Pte Ltd From:

> 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Ruth Chua Gek Tiang 03 Jul 2019 Attn: Date:

Preliminary Advice

Vehicle No : FBN5048H Accident Date : 13/06/2019

Policy No. : D18MTMC01006709 Make : YAMAHA XABRE

Assignment Date : 28/06/2019 **Excess** : S\$600.00

Date of Inspection :3/7/2019 Est. Duration of Repair :3

:BIKE PRODUCTION PTE LTD Inspection At

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,620.90
Revised Amount	:S\$	2,929.00
Check Items (Estimated)	:S\$	630.00
Total	:S\$	3,559.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

9,000.00 Pre-Accident Value :S\$ COE / PARF Rebate :S\$ 3,670.00

Salvage Value :S\$

Margin for Repair :S\$ 5,330.00

Remarks

(X	.)	have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :