

ASS. REC. BY:

REF: CS/ASM/19011917/ d302

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Kitty Tio of ASM. Date/Time: 20/6/2019

Estimated Cost: Bill to:

 OD /  TP /  WS /  TP RES /  OD RES /  EVA /  INV /  MV /  CS

To Inspect Vehicle No: SMC 4338 E Insured:

at Workshop m/s SONE Tel: 67476106

of 1 Kaki Bukit Ave 6 #02-15

Policy No: Claim No: S9M0L57Q

Sum Insured: Excess: Nil

Make of Veh: D.O.A. 27/6/2019

(Client's Record)

 CA /  REV /  REP. /  REV 24 HRS

H.O.D. Endorsement:

Date/Time: 20/6 Person Contacted: Vehicle:  IN /  OUT

Date/Time Action/Instruction (✓) Estimate

SMC 4338 E - NA / AIG 19011915 / NA D.O.A. 27/6/2019

14/19 Send preli revised via SMART claim

3/7/19 @ 1:30pm Informed Yng Supplementary approved

15/7/19 Final fig \$ 649.23 Confirmed by email (Ref 1045.88, 149)

ACM

ASSIGNMENT

From: \_\_\_\_\_ Date: 28/6

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMC 4338E

at Workshop no: SME

of: 1 Kaki Bukit Ave 6 #02-15

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: NIL

(Client's Record)

Make of Veh: \_\_\_\_\_

Veh No: SMC 4338E Yr Regn: 2018 June

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Toyota Uios C.C: 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp Reading: 16062 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR2B23F3X01134157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 195/50R16

R: 195/50R16

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA if consistent / REV / REP. / 24 HRS

Vehicle: IN / OUT

Front Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A: 27/6/19 D.O.I: 28/06/19

Survey held at: SME

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>OO AXA</u>
	<u>MV: 75K</u>
	<u>PV: 41.8K</u>
	<u>Nett: 33.21c</u>

RECEIVED 16 JUL 2019

*[Signature]*  
15/7/2019

Date/Time, File Path to:  : Prel. Report

: Final Report

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:	<u>200</u>
Transportation:	
S + PC:	
Trip:	
Other:	
TOTAL	<u>200</u>

Date/Time, File Path to: 15/7 - typst

Report Format: SMART claim

Emp/Sup/TE: 6492-23

Add Fee:  Site Insp (\$)  Interview (\$)  Tech. Insp (\$)  Material (\$)

⏪ **Re:SMC 4338E-SUPPLEMENTARY**

Type

🔔 Question

Message

Hi Veron, Please proceed with supplementary.

Reply

## New Message

Type \*

Message

Subject \*

SMC 4338E-SUPPLEMENTARY

Message \*

Dear Kitty,  
We have received supplementary from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident and is economical to repair. Best Regards Veron Chen

Cancel

Send



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408053 TEL : (065) 6286396 FAX : (065) 6286438

### Immediate Advice

To : AXA Insurance Pte Ltd

Date: 3/7/2019

#### Survey details

Date of loss	27/6/2019
Date of appointment	28/6/2019
Date of survey	28/6/2019
Location of survey	SME MOTOR PTE LTD

#### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SMC 4338E
Make and Model	TOYOTA VIOS
Date of registration	29/6/2018
Excess	NIL
Market Value	\$75,000.00
Part Rebate	\$45,569.00
Nett Loss	\$29,431.00

#### Repair details

Initial Estimate	\$7,538.11 (INCL. SUPPLEMENTARY \$176)
------------------	--

#### Proposed/Revised repair cost:

Revised Estimate Amount	\$4,720.80
*Check items (Estimated)	\$1,545.50
Labour	\$1,167.31
Total Repair (Estimated)	\$7,433.61 (INCL.SUPPLEMENTARY \$176)
Lump Sum (Estimated)	

Number of days of repair	8 days (est)
--------------------------	--------------

#### Remarks:

The vehicle sustained damages at the front portion  
  
Damages Consistent  
Repair Cost Economical

## New Message

Type \*

Message

Subject \*

IA SUBMITTED FOR SMC 4338E

Message \*

Dear Kitty,  
Please be informed that IA submitted. We have Authorize repair. Thanks Veron Chen

Cancel

Send



Auto  
Consultants  
Pte Ltd

81 UBI AVE 1, #01-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408683 TEL : (065) 62263561 FAX : (065) 62264312

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 1/7/2019

### Survey details

Date of loss	27/6/2019
Date of appointment	28/6/2019
Date of survey	28/6/2019
Location of survey	SME MOTOR PTE LTD

### Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SMC 4338E
Make and Model	TOYOTA VIOS
Date of registration	29/6/2018
Excess	NIL
Market Value	\$75,000.00
Part Rebate	\$45,569.00
Nett Loss	\$29,431.00

### Repair details

Initial Estimate	\$7,362.11
------------------	------------

### Proposed/Revised repair cost:

Revised Estimate Amount	\$4,544.80
"Check items (Estimated)	\$1,545.50
Labour	\$1,167.31
Total Repair (Estimated)	\$7,257.61
Lump Sum (Estimated)	

Number of days of repair	8 days (est)
--------------------------	--------------

### Remarks:

The vehicle sustained damages at the front portion

Damages Consistent  
Repair Cost Economical

We have authorize repair

## ◀ Service Request Details

Claim

S9M01S7Q

Reference

None 

Loss Date

June 27, 2019

Report Date

Jun 28, 2019 2:13:00 PM

Request Date

June 28, 2019

Due Date

July 5, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

### Actions

---

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

---

Incident Vehicle Registration #

SMC4338E

Model  
VIOS 1.5

### Service Address

---

1 Kaki Bukit Ave 6 #02-15, . . , 417883

### Primary Contact/Insured

---

TAN TAT CHUAN  
BLK 235 YSIHUN STREET 21, #10-452, 760235, Singapore  
92765392

### Claim Handler

---

TEO Kitty  
6568804602  
kitty.teo@axa.com.sg

Additional Instructions  
W/S - SME X/S - NIL

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6682I
Vehicle Details	
Vehicle No.:	SMC4338E
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G (AUTO)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	2NR5239907
Chassis No.:	MR2B23F3X01134197
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$15,201.00
Original Registration Date:	29 Jun 2018
First Registration Date:	29 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$15,201.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2028
PARF Rebate Amount:	\$11,400.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,700.00
COE Rebate Amount:	\$34,169.00
<b>Total Rebate Amount:</b>	<b>\$45,569.00</b>

The information contained herein is correct as at 01 Jul 2019

OK

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6682I
Vehicle Details	
Vehicle No.:	SMC4338E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	01 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G (AUTO)
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	2NR5239907
Chassis No.:	MR2B23F3X01134197
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$15,201.00
Original Registration Date:	29 Jun 2018
First Registration Date:	29 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$15,201.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2028
PARF Rebate Amount:	\$11,400.00
Intended COE Details	
COE Expiry Date:	28 Jun 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,700.00
COE Rebate Amount:	\$30,400.00
<b>Total Rebate Amount:</b>	<b>\$41,800.00</b>

The information contained herein is correct as at 01 Jul 2019

OK

It's that simple. Open an eSaver account today.

[Apply now](#)

Interest 1.5% to 2.5% with automatic payment by direct debit. Payable by 31.12.18. 18.25 C.C.B.C.

**FOR SALE BY OWNER**

Post an Advertisement  
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

**Almost 2012 BMW 528i Luxury, 118000km, New Road Tax**

Nicely Done Up With 20" Breyton, M-Sport Bodykit, No Repair Needed!

[Auto Zone Singapore](#) | [StarAd](#)

**Lake View Credit Pte Ltd** VIEW OUR LIST

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category Save Search Print Sort by Date Posted | 20 results/page

5 vehicles | **Search**  [Advanced Search](#) [Search](#) [View All](#)

Search Selection	Vios	Any	Any	2018	Any	Any	Any	Available
------------------	------	-----	-----	------	-----	-----	-----	-----------



**Toyota Vios 1.5A G** | **\$73,800** | **\$7,560 /yr** | **20-Mar-2018** | **1,496 cc** | **5,168 km** | **Sedan** | **Available**

5 Years Warranty! Like New! Only 5K Km, Free Road Tax Till 19 Sep, Lowest Depreciation In The Market! High Spec G Model! Low Interest 2.28%, In House Loan Available, Upgraded Transferable Infinity War...

Posted: 27-Jun-2018 | Tags: 2018 Toyota Vios, 2018 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota



**Toyota Vios 1.5A E** | **\$76,888** | **\$7,960 /yr** | **18-Apr-2018** | **1,496 cc** | **15,350 km** | **Sedan** | **Available**

1 Private Owner, Car AS Good As New, 100% In House Loan Approval, First Owner Lost Is YOUR Gain, Well Known For Its Reliability And Low Fuel Consumption, Hurry And Do Call Us Today Should You Need Mor...

Posted: 29-Jun-2018 | Tags: 2018 Toyota Vios, 2018 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota



**Toyota Vios 1.5A E** | **\$75,800** | **\$7,660 /yr** | **29-Jun-2018** | **1,496 cc** | **8,600 km** | **Sedan** | **Available**

Well Known For Its Reliability And Low Fuel Consumption, App Now To Arrange A Viewing!

**Borneo Motors (S)**

Posted: 17-Jun-2018 | Tags: 2018 Toyota Vios, 2018 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota



**Toyota Vios 1.5A G** | **\$79,800** | **\$7,900 /yr** | **17-Aug-2018** | **1,496 cc** | **17,800 km** | **Sedan** | **Available**

Don't Miss It! Low Mileage As Good As New. In Original Condition, Well Kept By Owner And Serviced By Agent. Warranty Still Available. Low Mileage Done. High Loan And Trade In Welcome. Viewing By Appt...

**Tay Motor & Credit Pte Ltd**

Posted: 29-Jun-2018 | Tags: 2018 Toyota Vios, 2018 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota

[Car Buying](#) | 
 [Car Selling](#) | 
 [Car Ownership](#) | 
 [Car Aftermarket](#) | 
 [On The Move](#) | 
 [Lifestyle](#)

**2233E Bidded Carplates For Sale!**



**Toyota Vios 1.5A E** | **\$73,988** | **\$7,060 /yr** | **28-Dec-2018** | **1,496 cc** | **13,000 km** | **Sedan** | **Available**

Almost Brand New Car, First Owner's Lost Is Your Gain, Well Known For Its Reliability And Low Fuel Consumption, Hurry And Do Call Us Today Should You Need More Details.Flexible Loan Packages Available...

Posted: 10-Jun-2018 | Tags: 2018 Toyota Vios, 2018 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Vios, Vios, Used Toyota

Save this search criteria, to get email alerts whenever a match is found. [Save Search](#)

For old advertisements, view [Expired ads](#) 20 results/page

[Compare](#)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/06/2019 17:53
Date Of Accident	27/06/2019 11:30
Exact Location Of Accident	AIRPORT RD (SLIP RD TO EUNOS LINK)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC4338E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN TAT CHUAN
NRIC No	S1266682I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92765392
Alternative Phone No	OFFICE-92765392

### Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2145069
Cover Note Number	

### Driver

Name of Driver	TAN TAT CHUAN
NRIC No	S1266682I
Date Of Birth	06/09/1957
Occupation	INDOOR
Date Of Driving Pass	11/03/1985
Driving Experience	34 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92765392
Fax Number	
Contact Number	OFFICE-92765392
EMail Address	NOEMAIL

Address	BLK 235 YISHUN ST 21 #10-452
Postcode	2776
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

VEHICLE B STOP. I COULDN'T STOP IN TIME AND HIT ONTO VEHICLE B REAR RIGHT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH1020U
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**IMPORTANT NOTICE**

1. Please state correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

552301115M



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

VEHICLE B STOP I COULDN'T STOP IN TIME (A10)  
 HIT ONTO VEHICLE B REAR RIGHT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature  
 Date & Time

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time

Reporting Centre Personnel's Signature  
 Name  
 NRIC/ID No.

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 28/06/2019 10:17 AM

**Full Report**  
 Registration: SMC4338E  
 Printed: 28/06/2019 10:17 AM

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Gary Seah	Currency:	SGD
Claim Reference:		Date of Incident:	27/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer: TOYOTA  
 Model: VIOS  
 Sub Model: G  
 Model Sheet Number: 70 AY 53  
 Registration: SMC4338E  
 VIN number:  
 Odometer:

**Model Specs**

AIR CONDITIONING	1.5 LTR 79 KW	EQUIPMENT RR	PREPARE OFF VEHICLE
SPECIAL EDITION	CLEAR COAT HARD	TWO COAT PEARL/MICA	

**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B100	R + R LEFT FRONT WING		5.0	22.50
B100	R + R RIGHT FRONT WING		5.0	22.50
B110)	RENEW LEFT FRONT WING		1.0	4.50
	INCLUDES: TRANSFER ATTACHED PARTS			
B030	RENEW RADIATOR GRILLE		2.0	9.00
B010)	R + R FRONT BUMPER		4.0	18.00
B020)	RENEW FRONT BUMPER (REMOVED)		7.0	31.50
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT			
B010)	R + R FRONT BUMPER REINFORCEMENT		2.0	9.00
B040)	R + R LEFT HEADLAMP		1.0	4.50
B040)	R + R RIGHT HEADLAMP		1.0	4.50
B040)	ADJUST HEADLAMPS		2.0	9.00
B060	R + R BONNET		2.0	9.00
B070)	RENEW BONNET		2.0	9.00
	INCLUDES: R + R OR RENEW ATTACHED PARTS			

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 28/06/2019 10:17 AM

Full Report  
 Registration: SMC4338E  
 Printed: 28/06/2019 10:17 AM

Code	Description	WU	Price SGD
B080	R + R BONNET HINGE/S	1.0	4.50
B060	R + R BONNET INSULATION	1.0	4.50
B140	R + R FRONT PANEL CPL	13.0	58.50
B085	R + R COWL PANEL TRIM INCLUDES: WIPER ARMS REMOVE AND REFIT	2.0	9.00
G010	WINDSCREEN R + R (COWL GRILLE REMOVED) INCLUDES: VA-PILLAR TRIMS, REAR VIEW MIRROR AND ALL REQUIRED ATTACHED PARTS R + R.	31.0	139.50
B085)	RENEW FRONT SCREEN FRAME TRIM	1.0	4.50
160401)	RENEW FAN SHROUD (FAN REMOVED)	2.0	9.00
M010)	RENEW CONDENSER (REMOVED)	1.0	4.50
M010	R + R RADIATOR/CONDENSER	4.0	18.00
M020)	RENEW RADIATOR (RADIATOR REMOVED)	3.0	13.50
1117	L/F WHEELHOUSE CPL REPAIR	20.0*	90.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		11.30	113.0
<b>Total of Labour</b>			508.50

**Paint**

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
Paint Work SYSTEM AZT Time Basis 10WU/h			
	BONNET NEW PART PAINTING	12.0	
	L/F WING NEW PART PAINTING	10.0	
	FRONT PANEL CPL SURFACE PAINT	6.0	
	FRONT BUMPER NEW PART PAINT K1R	13.0	
	FRT BUMPER REINF SURFACE PAINT	6.0	
	R/F WING SURFACE PAINT	5.0	
	L/F WHEELHOUSE CPL SURFACE PAINT	5.0	
	LEFT FRONT DOOR SURFACE PAINT	8.0	
	LEFT A-PILLAR SURFACE PAINT	4.0	

**Paint Material Per Part**

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	28.90
0741	L/F WING NEW PART PAINTING	19.09

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 28/06/2019 10:17 AM

Full Report  
 Registration: SMC4338E  
 Printed: 28/06/2019 10:17 AM

**Paint Material Per Part**

Code	Description	Price SGD
1009	FRONT PANEL CPL SURFACE PAINT	12.45
0281	FRONT BUMPER NEW PART PAINT K1R	62.98
0340	FRT BUMPER REINF SURFACE PAINT	10.46
0742	R/F WING SURFACE PAINT	9.21
1117	L/F WHEELHOUSE CPL SURFACE PAINT	9.71
1481	LEFT FRONT DOOR SURFACE PAINT	20.92
2237	LEFT A-PILLAR SURFACE PAINT	1.99

**Labour Cost - Paint**

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		69.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>99.0</b>	<b>445.50</b>

**Material Cost - Paint**

	Price SGD
New Part Painting	47.99
New Part Painting - Plastic K1R	62.98
Surface-/Blend Paint	64.74
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>213.31</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0253	FRONT BUMPER GRILLE	53112 YP030	De Led	>10	✓ 145.00
0255	L/F BUMPER COVER	52128 YP050	cut		✓ 85.00
0281	FRONT BUMPER	52119 YP902	Disturbed		✓ 240.00
0317	L/F BUMPER BRACKET	52536 0D270	3/4"		✓ 55.00
0318	R/F BUMPER BRACKET	52535 0D270	3/4"		✓ 55.00
0351	CLIP FASTENING	52161 16010	near		✓ 20.00
0410	GRILLE	53111 YP050	cut		✓ 60.00
0417	GRILLE MOULDING	53122 YP902	cut		✓ 95.00
0420	CLIP FASTENING	52161 16010	near	20	✓ 8.00
0471	BONNET	53301 0D330	Disturbed		✓ 330.00
0475	L/F HINGE	53420 0D400	3 Bert		✓ 35.00
0476	R/F HINGE	53410 0D400	3 Bert		✓ 35.00

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 28/06/2019 10:17 AM

Full Report  
 Registration: SMC4338E  
 Printed: 28/06/2019 10:17 AM

Code	Description	Part Number	Supplier	Price SGD
0493	BONNET LOCK	53510 0D361	? NH	? 60.00
0561	LEFT HEADLAMP ASSY	81150 YP010	smashed	✓ 365.00
0562	RIGHT HEADLAMP ASSY	81110 YP010	? NH	? 365.00
0741	L/F WING	53802 0D240	Dented	✓ 295.00
0841	L/F WHEELHOUSE COVER	53876 YP010	Paint Not new	+ 95.00
0843	L/FASTENING CLIP	47749 50090	New	— 20.00
1009	FRONT PANEL CPL	53210 0D926	Broken	✓ 300.00
1019	L/UPP RADIATOR BRKT	53214 0D210	Dented	✓ 40.00
1191	L/F AIR DUCT	53286 YP010	Dented	— 50.00
1393	COWL	55708 0D430	Cracked 280	✓ 260.00
1401	WINDSCREEN	56101 0D740	Cracked 1430	✓ 420.00
1411	WINDSCREEN BOND KIT	PZ49I 00C1131	Paint Nec	+ 0.00
1419	FRT SCREEN SEAL KIT	56117 50130		+ 0.00
4465	CONDENSER	88460 0D290	Dented	— 380.00
7761	RADIATOR CPL	16400 0Y191	? Dented	? 450.00
7767	RADIATOR SHROUD	16711 0Y160	? NH	? 125.00
7790	FAN MOTOR	16363 0Y040	? NH	? 220.00
7793	COOLING FAN	16361 0M110	? NH	? 120.00
1000	L/GRILLE CHROME	L/GRILLE CHROME	Cracked	— 60.00
1001	L/DAYLIGHT	L/DAYLIGHT	Cracked	✓ 220.00
1002	AIR CLEANER BOX	AIR CLEANER BOX	Cracked	✓ 360.00
1003	AIR DUCT	AIR DUCT	? NH	? 65.00
1004	L/WIPPER CORNER	GARNISH	Dented	✓ 35.00
f: OEM Parts	<b>Savings</b>			<b>0.00</b>
n: Non-OEM Parts	<b>Subtotal</b>			<b>5,468.00</b>
u: Used parts	<b>Addition(+10.00%)</b>			<b>546.80</b>
	<b>Total</b>			<b>6,014.80</b>

**Extras**

Code	Description	Price SGD
1005	NUMBER PLATE Bent	✓ 35.00*
1006	RADIATOR COOLANT nec	✓ 20.00*
1007	AIRCON COOLANT ne	✓ 50.00*
1008	FRT WINDSCREEN GUM ne	✓ 60.00*
1009	ERP BRACKET nec	✓ 15.00*
	<b>Total Extras</b>	<b>180.00</b>

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 28/06/2019 10:17 AM

Full Report  
 Registration: SMC4338E  
 Printed: 28/06/2019 10:17 AM

**Final Calculation**

	SGD	SGD
<b>Parts</b>	5,468.00	
Addition(+10.00%)	546.80	
<b>Total Parts</b>		<b>6,014.80</b>
<b>Labour Time Base 10 WU/h</b>		
Total 113.0 WU X 45.00 SGD/h	508.50	477
<b>Total of Labour</b>		<b>508.50</b>
<b>Total Of Extras</b>		<b>180.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 99.0 WU X 45.00 SGD/h	445.50	463.50
Material Cost	213.31	218.23
<b>Total Paint Including Material</b>		<b>658.81</b>
<b>Repair Cost Excludes GST</b>		<b>7,362.11</b>
GST (+7.0%)		515.35
<b>Repair Cost Included GST</b>		<b>7,877.46</b>

**Comments**

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

*Adrian Ling*  
*7/7 28/06/19.*  
*08 Days*  
*Authorised Repairs. 1655 51*  
*Excess: NIL*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 28/06/2019 10:17 AM

Full Report  
 Registration: SMC4338E  
 Printed: 28/06/2019 10:17 AM

Code	Description	Part Number	Supplier	Price SGD
0493	BONNET LOCK	53510 0D361	Neu	60.00
0561	LEFT HEADLAMP ASSY	81150 YP010	smashed	365.00
0562	RIGHT HEADLAMP ASSY	81110 YP010	Neu	365.00
0741	L/F WING	53802 0D240	Displed	295.00
0841	L/F WHEELHOUSE COVER	53876 YP010	Neu	95.00
0843	L/FASTENING CLIP	47749 50090	Neu	20.00
1009	FRONT PANEL CPL	53210 0D926	Painted	300.00
1019	L/UPP RADIATOR BRKT	53214 0D210	Displed	40.00
1191	L/F AIR DUCT	53286 YP010	Displed	50.00
1393	COWL	55708 0D430	Emulid	260.00
1401	WINDSCREEN	56101 0D740	Crackd	420.00
1411	WINDSCREEN BOND KIT	PZ49I 00C1131	Just Neu	0.00
1419	FRT SCREEN SEAL KIT	56117 50130		0.00
4465	CONDENSER	88460 0D290	Deated	380.00
7761	RADIATOR CPL	16400 0Y191	Deated	450.00
7767	RADIATOR SHROUD	16711 0Y160	Neu	125.00
7790	FAN MOTOR	16363 0Y040	Neu	220.00
7793	COOLING FAN	16361 0M110	Neu	120.00
1000	L/GRILLE CHROME	L/GRILLE CHROME	Crackd	60.00
1001	L/DAYLIGHT	L/DAYLIGHT	Crackd	220.00
1002	AIR CLEANER BOX	AIR CLEANER BOX	Crackd	360.00
1003	AIR DUCT	AIR DUCT	Neu	65.00
1004	L/WIPPER CORNER	GARNISH	Depled	35.00
Savings				0.00
Subtotal				5,468.00
Addition(+10.00%)				546.80
<b>Total</b>				<b>6,014.80</b>

f: OEM Parts  
 n: Non-OEM Parts  
 u: Used parts

**Extras**

Code	Description	Price SGD
1005	NUMBER PLATE Bent	35.00*
1006	RADIATOR COOLANT Neu	20.00*
1007	AIRCON COOLANT re	50.00*
1008	FRT WINDSCREEN GUM Neu	60.00*
1009	ERP BRACKET Neu	15.00*
<b>Total Extras</b>		<b>180.00</b>

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 28/06/2019 10:17 AM

Full Report  
 Registration: SMC4338E  
 Printed: 28/06/2019 10:17 AM

**Final Calculation**

	SGD	SGD
<b>Parts</b>		
Addition(+10.00%)	5,468.00	
<b>Total Parts</b>	546.80	<b>6,014.80</b>
<b>Labour Time Base 10 WU/h</b>		
Total 113.0 WU X 45.00 SGD/h	508.50	
<b>Total of Labour</b>		<b>508.50</b>
<b>Total Of Extras</b>		<b>180.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 99.0 WU X 45.00 SGD/h	445.50	
Material Cost	213.31	
<b>Total Paint Including Material</b>		<b>658.81</b>
<b>Repair Cost Excludes GST</b>		<b>7,362.11</b>
GST (+7.0%)		515.35
<b>Repair Cost Included GST</b>		<b>7,877.46</b>

**Comments**

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS

Support top switch \$110 Deduct ✓  
 horn \$50 Deduct ✓

S.S.  
 02/07/19.

Adrian Lim  
 P/P 28/06/19.

08 Days

Authorised Repairs.

Excess: NIL

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 11/07/2019 4:19 PM

**Full Report**  
**Registration: SMC4338E**  
**Printed: 11/07/2019 4:19 PM**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Gary Seah	Currency:	SGD
Claim Reference:		Date of Incident:	27/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

**Vehicle**

Manufacturer:	TOYOTA
Model:	VIOS
Sub Model:	G
Model Sheet Number:	70 AY 53
Registration:	SMC4338E
VIN number:	
Odometer:	

**Model Specs**

AIR CONDITIONING	1.5 LTR 79 KW	EQUIPMENT RR	PREPARE OFF VEHICLE
SPECIAL EDITION	CLEAR COAT HARD	TWO COAT PEARL/MICA	

**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B100	R + R LEFT FRONT WING		5.0	22.50
B100	R + R RIGHT FRONT WING		5.0	22.50
B110)	RENEW LEFT FRONT WING		1.0	4.50
	INCLUDES: TRANSFER ATTACHED PARTS			
B030	RENEW RADIATOR GRILLE		2.0	9.00
B010)	R + R FRONT BUMPER		4.0	18.00
B020)	RENEW FRONT BUMPER (REMOVED)		7.0	31.50
	INCLUDES: REQUIRED ATTACHED PARTS			
	REMOVE AND REFIT			
B010)	R + R FRONT BUMPER REINFORCEMENT		2.0	9.00
B040)	R + R LEFT HEADLAMP		1.0	4.50
B040)	R + R RIGHT HEADLAMP		1.0	4.50
B040)	ADJUST HEADLAMPS		2.0	9.00
B060	R + R BONNET		2.0	9.00
B070)	RENEW BONNET		2.0	9.00
	INCLUDES: R + R OR RENEW ATTACHED PARTS			

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 11/07/2019 4:19 PM

Full Report  
 Registration: SMC4338E  
 Printed: 11/07/2019 4:19 PM

Code	Description	WU	Price SGD
B080	R + R BONNET HINGE/S	1.0	4.50
B060	R + R BONNET INSULATION	1.0	4.50
B140	R + R FRONT PANEL CPL	13.0	58.50
B085	R + R COWL PANEL TRIM INCLUDES: WIPER ARMS REMOVE AND REFIT	2.0	9.00
G010	WINDSCREEN R + R (COWL GRILLE REMOVED) INCLUDES: VA-PILLAR TRIMS, REAR VIEW MIRROR AND ALL REQUIRED ATTACHED PARTS R + R.	31.0	139.50
B085)	RENEW FRONT SCREEN FRAME TRIM	1.0	4.50
M010)	RENEW CONDENSER (REMOVED)	1.0	4.50
M010	R + R RADIATOR/CONDENSER	4.0	18.00
M020)	RENEW RADIATOR (RADIATOR REMOVED)	3.0	13.50
1117	L/F WHEELHOUSE CPL REPAIR	20.0*	90.00
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		11.10	111.0
<b>Total of Labour</b>			499.50

**Paint**

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
Paint Work <b>SYSTEM AZT</b> Time Basis 10WU/h			
	BONNET NEW PART PAINTING	12.0	
	L/F WING NEW PART PAINTING	10.0	
	FRONT PANEL CPL SURFACE PAINT	6.0	
	FRONT BUMPER NEW PART PAINT K1R	13.0	
	GRILLE NEW PART PAINT K1R	4.0	
	FRT BUMPER REINF SURFACE PAINT	6.0	
	R/F WING SURFACE PAINT	5.0	
	L/F WHEELHOUSE CPL SURFACE PAINT	5.0	
	LEFT FRONT DOOR SURFACE PAINT	8.0	
	LEFT A-PILLAR SURFACE PAINT	4.0	

**Paint Material Per Part**

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	28.90
0741	L/F WING NEW PART PAINTING	19.09

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 11/07/2019 4:19 PM

Full Report  
 Registration: SMC4338E  
 Printed: 11/07/2019 4:19 PM

**Paint Material Per Part**

Code	Description	Price SGD
1009	FRONT PANEL CPL SURFACE PAINT	12.45
0281	FRONT BUMPER NEW PART PAINT K1R	62.98
0410	GRILLE NEW PART PAINT K1R	4.92
0340	FRT BUMPER REINF SURFACE PAINT	10.46
0742	R/F WING SURFACE PAINT	9.21
1117	L/F WHEELHOUSE CPL SURFACE PAINT	9.71
1481	LEFT FRONT DOOR SURFACE PAINT	20.92
2237	LEFT A-PILLAR SURFACE PAINT	1.99

**Labour Cost - Paint**

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		73.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>103.0</b>	<b>463.50</b>

**Material Cost - Paint**

	Price SGD
New Part Painting	47.99
New Part Painting - Plastic K1R	67.90
Surface-/Blend Paint	64.74
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>218.23</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0253	FRONT BUMPER GRILLE	53112 YP030			210.00
0255	L/F BUMPER COVER	52128 YP050			85.00
0281	FRONT BUMPER	52119 YP902			240.00
0317	L/F BUMPER BRACKET	52536 OD270			55.00
0318	R/F BUMPER BRACKET	52535 OD270			55.00
0334	RADIATOR BRACKET	53141 OD190			110.00
0351	CLIP FASTENING	52161 16010			20.00
0410	GRILLE	53111 YP050			60.00
0417	GRILLE MOULDING	53122 YP902			95.00
0420	CLIP FASTENING	52161 16010			20.00
0471	BONNET	53301 OD330			330.00

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 11/07/2019 4:19 PM

Full Report  
 Registration: SMC4338E  
 Printed: 11/07/2019 4:19 PM

Code	Description	Part Number	Supplier	Price SGD
0475	L/F HINGE	53420 0D400		35.00
0476	R/F HINGE	53410 0D400		35.00
0561	LEFT HEADLAMP ASSY	81150 YP010		365.00
0741	L/F WING	53802 0D240		295.00
0843	L/FASTENING CLIP	47749 50090		20.00
1009	FRONT PANEL CPL	53210 0D926		300.00
1019	L/UPP RADIATOR BRKT	53214 0D210		40.00
1191	L/F AIR DUCT	53286 YP010		50.00
1393	COWL	55708 0D430		280.00
1401	WINDSCREEN	56101 0D740		430.00
1411	WINDSCREEN BOND KIT	PZ49I 00C1131		0.00
1419	FRT SCREEN SEAL KIT	56117 50130		0.00
4465	CONDENSER	88460 0D290		380.00
7761	RADIATOR CPL	16400 0Y191		450.00
9646	HORN	86520 0D160		50.00
1000	L/GRILLE CHROME	L/GRILLE CHROME		60.00
1001	L/DAYLIGHT	L/DAYLIGHT		220.00
1002	AIR CLEANER BOX	AIR CLEANER BOX		360.00
1004	L/WIPPER CORNER	GARNISH		35.00
				0.00
				4,685.00
				468.50
				5,153.50

f: OEM Parts  
 n: Non-OEM Parts  
 u: Used parts

**Savings**  
**Subtotal**  
**Addition(+10.00%)**  
**Total**

**Extras**

Code	Description	Price SGD
1005	NUMBER PLATE	35.00*
1006	RADIATOR COOLANT	20.00*
1007	AIRCON COOLANT	50.00*
1008	FRT WINDSCREEN GUM	60.00*
1009	ERP BRACKET	15.00*
	<b>Total Extras</b>	<b>180.00</b>

**SME Motor Pte Ltd**  
**1 Kaki Bukit Ave 6, BLK D,**  
**#02-15**  
**417883**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 11/07/2019 4:19 PM

**Full Report**  
**Registration: SMC4338E**  
**Printed: 11/07/2019 4:19 PM**

**Final Calculation**

	SGD	SGD
<b>Parts</b>	4,685.00	
Addition(+10.00%)	468.50	
<b>Total Parts</b>		<b>5,153.50</b>
<b>Labour Time Base 10 WU/h</b>		
Total 111.0 WU X 45.00 SGD/h	499.50	
<b>Total of Labour</b>		<b>499.50</b>
<b>Total Of Extras</b>		<b>180.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 103.0 WU X 45.00 SGD/h	463.50	
Material Cost	218.23	
<b>Total Paint Including Material</b>		<b>681.73</b>
<b>Repair Cost Excludes GST</b>		<b>6,514.73</b>
GST (+7.0%)		456.03
<b>Repair Cost Included GST</b>		<b>6,970.76</b>

**Comments**

\* - USER SUPPLIED DATA  
 NN - NO MANUFACTURERS CODE EXISTS  
 ) - WU PARTIAL INCL IN OTHER POSITIONS

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Finalized

Claim Reference:  
Assessment number: 19/AXA/OD-327(06)  
Version: 1810  
Date calculated: 12/07/2019 4:21 PM

**Full Report**  
**Registration: SMC4338E**  
**Printed: 12/07/2019 4:22 PM**

---

**Summary Information**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	27/06/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

---

**Vehicle Details**

<b>Vehicle</b>			
Manufacturer:	TOYOTA		
Model:	VIOS		
Sub Model:	G		
Model Sheet Number:	70 AY 53		
Registration:	SMC4338E		
VIN number:			
Odometer:			
<b>Model Specs</b>			
AIR CONDITIONING	1.5 LTR 79 KW	EQUIPMENT RR	PREPARE OFF VEHICLE
SPECIAL EDITION	CLEAR COAT HARD	TWO COAT PEARL/MICA	

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 12/07/2019 4:21 PM

Full Report  
 Registration: SMC4338E  
 Printed: 12/07/2019 4:22 PM


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
 Date of Inspection:

**Damage Areas**

All   
 Underbody



**Labour**

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
B100	R + R LEFT FRONT WING		5.0	22.50
B100	R + R RIGHT FRONT WING		5.0	22.50
B110)	RENEW LEFT FRONT WING INCLUDES: TRANSFER ATTACHED PARTS		1.0	4.50
B030	RENEW RADIATOR GRILLE		2.0	9.00
B010)	R + R FRONT BUMPER		4.0	18.00
B020)	RENEW FRONT BUMPER (REMOVED) INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		7.0	31.50
B010)	R + R FRONT BUMPER REINFORCEMENT		2.0	9.00
B040)	R + R LEFT HEADLAMP		1.0	4.50
B040)	R + R RIGHT HEADLAMP		1.0	4.50
B040)	ADJUST HEADLAMPS		2.0	9.00
B060	R + R BONNET		2.0	9.00
B070)	RENEW BONNET INCLUDES: R + R OR RENEW ATTACHED PARTS		2.0	9.00

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 12/07/2019 4:21 PM

**Full Report**  
 Registration: SMC4338E  
 Printed: 12/07/2019 4:22 PM

Code	Description	WU	Price SGD
B080	R + R BONNET HINGE/S	1.0	4.50
B060	R + R BONNET INSULATION	1.0	4.50
B140	R + R FRONT PANEL CPL	13.0	58.50
B085	R + R COWL PANEL TRIM INCLUDES: WIPER ARMS REMOVE AND REFIT	2.0	9.00
G010	WINDSCREEN R + R (COWL GRILLE REMOVED) INCLUDES: VA-PILLAR TRIMS, REAR VIEW MIRROR AND ALL REQUIRED ATTACHED PARTS R + R.	31.0	139.50
B085)	RENEW FRONT SCREEN FRAME TRIM	1.0	4.50
M010)	RENEW CONDENSER (REMOVED)	1.0	4.50
M010	R + R RADIATOR/CONDENSER	4.0	18.00
M020)	RENEW RADIATOR (RADIATOR REMOVED)	3.0	13.50
1117	L/F WHEELHOUSE CPL REPAIR	15.0*	67.50
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		10.60	106.0
<b>Total of Labour</b>			477.00

**Paint**

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
Paint Work		SYSTEM AZT	
		Time Basis 10WU/h	
	BONNET NEW PART PAINTING	12.0	
	L/F WING NEW PART PAINTING	10.0	
	FRONT PANEL CPL SURFACE PAINT	6.0	
	FRONT BUMPER NEW PART PAINT K1R	13.0	
	GRILLE NEW PART PAINT K1R	4.0	
	FRT BUMPER REINF SURFACE PAINT	6.0	
	R/F WING SURFACE PAINT	5.0	
	L/F WHEELHOUSE CPL SURFACE PAINT	5.0	
	LEFT FRONT DOOR SURFACE PAINT	8.0	
	LEFT A-PILLAR SURFACE PAINT	4.0	

**Paint Material Per Part**

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	28.90
0741	L/F WING NEW PART PAINTING	19.09

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 12/07/2019 4:21 PM

**Full Report**  
 Registration: SMC4338E  
 Printed: 12/07/2019 4:22 PM

**Paint Material Per Part**

Code	Description	Price SGD
1009	FRONT PANEL CPL SURFACE PAINT	12.45
0281	FRONT BUMPER NEW PART PAINT K1R	62.98
0410	GRILLE NEW PART PAINT K1R	4.92
0340	FRT BUMPER REINF SURFACE PAINT	10.46
0742	R/F WING SURFACE PAINT	9.21
1117	L/F WHEELHOUSE CPL SURFACE PAINT	9.71
1481	LEFT FRONT DOOR SURFACE PAINT	20.92
2237	LEFT A-PILLAR SURFACE PAINT	1.99

**Labour Cost - Paint**

	Hrs	WU	Price SGD
Factor	45.00 SGD/h		
Time Paint		73.0	
Preparation Main Work Metal	2.50	25.0	112.50
Preparation Comp. Work Plastic	0.50	5.0	22.50
<b>Total</b>	<b>10 WU/h</b>	<b>103.0</b>	<b>463.50</b>

**Material Cost - Paint**

	Price SGD
New Part Painting	47.99
New Part Painting - Plastic K1R	67.90
Surface-/Blend Paint	64.74
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
<b>Total</b>	<b>218.23</b>

**Spare Parts**

Code	Description	Part Number	Supplier	prices as at 2015-06-01/01	Price SGD
0253	FRONT BUMPER GRILLE	53112 YP030			210.00
0255	L/F BUMPER COVER	52128 YP050			85.00
0281	FRONT BUMPER	52119 YP902			240.00
0317	L/F BUMPER BRACKET	52536 0D270			55.00
0318	R/F BUMPER BRACKET	52535 0D270			55.00
0334	RADIATOR BRACKET	53141 0D190			110.00
0351	CLIP FASTENING	52161 16010			20.00
0410	GRILLE	53111 YP050			60.00
0417	GRILLE MOULDING	53122 YP902			95.00
0420	CLIP FASTENING	52161 16010			20.00
0471	BONNET	53301 0D330			330.00

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 12/07/2019 4:21 PM

Full Report  
 Registration: SMC4338E  
 Printed: 12/07/2019 4:22 PM

Code	Description	Part Number	Supplier	Price SGD
0475	L/F HINGE	53420 0D400		35.00
0476	R/F HINGE	53410 0D400		35.00
0561	LEFT HEADLAMP ASSY	81150 YP010		365.00
0741	L/F WING	53802 0D240		295.00
0843	L/FASTENING CLIP	47749 50090		20.00
1009	FRONT PANEL CPL	53210 0D926		300.00
1019	L/UPP RADIATOR BRKT	53214 0D210		40.00
1191	L/F AIR DUCT	53286 YP010		50.00
1393	COWL	55708 0D430		280.00
1401	WINDSCREEN	56101 0D740		430.00
1411	WINDSCREEN BOND KIT	PZ49I 00C1131		0.00
1419	FRT SCREEN SEAL KIT	56117 50130		0.00
4465	CONDENSER	88460 0D290		380.00
7761	RADIATOR CPL	16400 0Y191		450.00
9646	HORN	86520 0D160		50.00
1000	L/GRILLE CHROME	L/GRILLE CHROME		60.00
1001	L/DAYLIGHT	L/DAYLIGHT		220.00
1002	AIR CLEANER BOX	AIR CLEANER BOX		360.00
1004	L/WIPPER CORNER	GARNISH		35.00
				0.00
				4,685.00
				468.50
				5,153.50

f: OEM Parts  
 n: Non-OEM Parts  
 u: Used parts

**Savings**  
**Subtotal**  
**Addition(+10.00%)**  
**Total**

0.00  
 4,685.00  
 468.50  
 5,153.50

**Extras**

Code	Description	Price SGD
1005	NUMBER PLATE	35.00*
1006	RADIATOR COOLANT	20.00*
1007	AIRCON COOLANT	50.00*
1008	FRT WINDSCREEN GUM	60.00*
1009	ERP BRACKET	15.00*
	<b>Total Extras</b>	<b>180.00</b>

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park,**  
**51 Ubi Avenue 1**  
**408933**

Claim Reference:  
 Assessment number: 19/AXA/OD-327(06)  
 Version: 1810  
 Date calculated: 12/07/2019 4:21 PM

**Full Report**  
**Registration: SMC4338E**  
**Printed: 12/07/2019 4:22 PM**

**Final Calculation**

	SGD	SGD
<b>Parts</b>	4,685.00	
Addition(+10.00%)	468.50	
<b>Total Parts</b>		<b>5,153.50</b>
<b>Labour Time Base 10 WU/h</b>		
Total 106.0 WU X 45.00 SGD/h	477.00	
<b>Total of Labour</b>		<b>477.00</b>
<b>Total Of Extras</b>		<b>180.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 103.0 WU X 45.00 SGD/h	463.50	
Material Cost	218.23	
<b>Total Paint Including Material</b>		<b>681.73</b>
<b>Repair Cost Excludes GST</b>		<b>6,492.23</b>
GST (+7.0%)		<b>454.46</b>
<b>Repair Cost Included GST</b>		<b>6,946.69</b>

**Comments**

- \* - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
- ) - WU PARTIAL INCL IN OTHER POSITIONS



# Top Line Auto Parts Pte Ltd

(GST. REG. NO: 201821729K)

222 Tagore Lane, TG Building #03-07, Singapore 787603

Tel: +65 6253 5595 | Fax: +65 6665 0307

www.toplineautoparts.sg | info@toplineautopart.sg

## TAX INVOICE

M/S : SME MOTOR PTE LTD

1 KAKI BUKIT AVE 6  
BLK D #02-15/16/17/18 AUTOBAY @ KAKI BUKIT  
SINGAPORE 417883

NO: INV1901237  
PAGE: 1  
DATE: 28/06/2019  
A/C CODE: SMP0001

Part No	Description	Location	Qty	Unit Price	Amount	
				SIN	SIN	
<b>Our D/O No: DO1900001</b>						
1	56101-0D411	GLASS WINDSHIELD	D5-7	1	430.00	430.00
2	53301-0D280	HOOD SUB ASSY	A6	1	330.00	330.00 ✓
3	53410-0D400	HINGE ASSY HOOD RH	B8-1	1	35.00	35.00 ✓
4	53420-0D400	HINGE ASSY HOOD LH	B8-1	1	35.00	35.00 ✓
5	53111-0D912	GRILLE RADIATOR OUTSIDE	B1-3	1	95.00	95.00 ✓
6	53124-0D040	MOULDING RADIATOR GRILLE UPPER LH	B2-5	1	60.00	60.00
7	52119-0U932	COVER FRONT BUMPER	TOP OFC-2	1	240.00	240.00 ✓
8	53112-0D650	GRILLE RADIATOR LOWER NO.1	TOP E-9	1	210.00	210.00 ✓
9	81440-0D060	LAMP ASSY DAYTIME RUNNING LH	B8	1	220.00	220.00
10	81170-0DF50	UNIT ASSY HEADLAMP LH	TGN	1	365.00	365.00 ✓
11	52128-0D430	COVER FRONT BUMPER HOLE LH	B1-4	1	85.00	85.00 ✓
12	53210-0D920	SUPPORT ASSY RADIATOR	B13	1	300.00	300.00 ✓
13	53214-0D160	SUPPORT RADIATOR UPPER LH	A2-2	1	40.00	40.00 ✓
14	88460-0D290	CONDENSER ASSY COOLER	TOP A-6	1	380.00	380.00
15	53286-0D370	SEAL RADIATOR SIDE AIR NO.2	B1-1	1	50.00	50.00 ✓
16	17700-0Y190	AIR CLEANER	TGN	1	360.00	360.00
17	53802-0D100	FENDER SUB ASSY FRONT LH	A9	1	295.00	295.00 ✓
18	55708-0D272	WIPER GARNISH	TGN	1	280.00	280.00 ✓
19	53867-0D220	SEAL FRONT FENDER TO COWL SIDE LH	B1-3	1	35.00	35.00
20	53114-0D020	GRILLE RADIATOR INNER	TOP A-4	1	60.00	60.00 ✓



# Top Line Auto Parts Pte Ltd

(GST REG. NO: 201821729K)

222 Tagore Lane, TG Building #03-07, Singapore 787603

Tel: +65 6253 5595 | Fax: +65 6665 0307

www.toplineautoparts.sg | info@toplineautopart.sg

M/S: SME MOTOR PTE LTD

## TAX INVOICE

NO: INV1901237  
PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount
21	86520-0D160	HORN		SIN	SIN
22	52535-0D230	RETAINER FRONT BUMPER SIDE RH	1	50.00	50.00
23	52536-0D230	RETAINER FRONT BUMPER SIDE LH	1	55.00	55.00 ✓
24	52161-16010	PIECE FRONT BUMPER	1	55.00	55.00 ✓
25	52161-0K040	PIECE FRONT GRILLE	10	2.00	20.00
26	16400-0Y191	RADIATOR ASSY	10	2.00	20.00 ✓
27	90467-07217	CLIP (FRONT FENDER SHIELD)	1	450.00	450.00
28	53141-0D071	COVER RADIATOR	10	2.00	20.00 ✓
			1	110.00	110.00 ✓
TOTAL QUANTITY:			55	TOTAL	SIN 4,685.00
				ADD GST @ 7%	327.95
				GRAND TOTAL	<b>SIN 5,012.95</b>

SINGAPORE DOLLAR FIVE THOUSAND TWELVE AND CENTS NINETY FIVE ONLY  
DELIVERY TO 02-18

Print / ELTON : 02/07/2019 2:31:54  
SALESMAN: ELTON  
For TOP LINE AUTO PARTS PTE. LTD.

Interest Rate 3% per month will be imposed on overdue account(s).  
GOODS SOLD ARE NOT RETURNABLE

AUTHORISED SIGNATURE

E. & O. E.

GOODS RECEIVED BY

**Veron Chen (LKKAuto)**

---

**From:** ying@smemotor.com.sg  
**Sent:** Monday, 15 July 2019 4:05 PM  
**To:** Veron Chen (LKKAuto); SUR  
**Subject:** Re: SMC4338E PENDING FOR FINALISE

hi Veron,

Amount confirmed.

thanks  
ying

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, July 12, 2019 4:58 PM  
**To:** ying@smemotor.com.sg ; SUR  
**Subject:** RE: SMC4338E PENDING FOR FINALISE

Dear Ying,

Our finalize amount \$6492.23 @ 8 working days.

Please check and confirm

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ying@smemotor.com.sg <ying@smemotor.com.sg>  
**Sent:** Thursday, 11 July 2019 4:29 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** SMC4338E PENDING FOR FINALISE

Hi Veron,

Please check and confirm.

thanks & regards  
YING

**From:** ptr2@smemotor.com.sg  
**Sent:** Thursday, July 11, 2019 3:24 PM  
**To:** ying  
**Subject:** Attached Image