

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

30-10-19

Date Of Accident : 27-06-2019

OUR REF : SJV 8054H/T/19

JOYRIDE CAR RENTAL PTE LTD

1 Kaki Bukit Ave 6

#02-34 (BLK D)

Singapore 417883

Lkk - Adrian

Date In/out: 27/06/19 to 02/07/19

TPAIG

Veron

ESTIMATE BILL ON VEH. NO. : SJV 8054H

MODEL : TOYOTA ALTIS

CHASSIS NO. : MR053ZEE106167777

LIST ITEM

Rear Bumper Fascia	Deformed		✓	372.85
Rear Bumper Side Retainer - LH & RH	Nec	2pcs @ 132.25	124	264.50
Rear Bumper Side Attachment - LH & RH	NH Nec	2pcs @ 141.40	X	282.80
Rear Bumper Reflector - LH & RH	NH nec	2pcs @ 181.90	X	363.80
Rear Bumper Clips	Nec	10pcs @ 12.90	30	129.00
Rear Bumper Sponge	Cracked		✓	182.60
Rear Bumper Beam	NH nec		X	372.25
Rear Bumper Stay - LH & RH	LH Dented	2pcs @ 141.40	8560	282.80
Boot Lid	Repis		X	781.75
Boot Lid Weather Stripe	} NH Nec		X	182.25
Boot Lid Rubber Stopper			X	43.10
Boot Lid Emblum "1.6"	} Nec		✓	41.90
Boot Lid Emblum "Corolla"			✓	41.35
Boot Lid Emblum "Altis"			✓	43.10
Boor Lid Badge			✓	41.10
Rear End Panel	Dented		✓	781.10
Rear End Panel Top Trim	Deformed		✓	289.90

Rear End Panel Top Trim Clips *N/A*

4pcs @ 12.90

20 51.60

205350

15440.12

Less Discount 25%:

4,547.75

1,136.94

3,410.81

SPECIAL NETT ITEMS

Reverse Sensor with Control Unit

Donnyed

200

200

380.00

LABOUR CHARGE

To Check Wiring System.

30

50.00

To Tuff Coat Affected Areas.

60

180.00

To Remove & Refix Interior Upholstery.

80

120.00

To Remove & Refix Reverse Sensor.

1630

60

120.00

To Remove & Refix Boot Lid Mechanism.

X

180.00

To Respray Affected Areas.

800

1,000.00

To Renew Damages Parts, Straighten & Repair & Aligned All Parts.

600

900.00

6,340.81

GST 7% :

443.86

TOTAL AMOUNT :

6,784.67

total 3370.12

L/S : 27K.

06 Days.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

27K