

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51760
Date Estimated : 01/07/2019
Prepared By : Chua Kee Sin

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -
Performance Premium Selection Ltd
280 Kampong Arang Road
East Coast Centre
Singapore 438180

- ACCOUNT - 66
~~MSIG Insurance (S) Pte Ltd~~ AIG
~~4 Shenton Way~~
~~#21-01 SGX Centre 2~~
~~Singapore 068807~~

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9145U	ED05858	29/04/2019	216i GT	0

DESCRIPTIONVALUE

Replace right rear side fender rear boot lid, rear bumper and
remove attachment etc include knock on accident dent 9

5100 7,650.00

Spray painting right side rear fender, rear bumper, rear boot
lid, floor pan and tail pan

3195 4,082.00

To replace rear windscreen glass.

487 574.00

To conduct water leak tests.

63 75.00

To supply and install rear windscreen solar film.

451 531.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To supply and install rear right window glass
solar film.

361 425.00

To carry out body cavity preservation.
(For cut panel).

451 531.00

To carry out body cavity preservation.
(2 panel).

200 236.00

To check steering geometry and conduct wheel alignment in
accordance with BMW specifications. (1x)

451 531.00

Sundries.

/ 150.00

Total Labour 1: 15,056.00

DESCRIPTIONQTYPRICVALUE

PLASTIC NUT FOR COARSE THREADED PIN

6

0.80

all 4.80

BOOTLID

1

1,204.35

b6 1,204.35

REAR RH SIDE PANEL - photo

1

1,466.65

b6 1,466.65

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 51760	Page No. : 2 of 6
Date Estimated	: 01/07/2019	
Prepared By	: Chua Kee Sin	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9145U	ED05858	29/04/2019	216i GT	0

DESCRIPTION	QTY	PRIC	VALUE
Positionieru	1	5.65	? 5.65
REINFORCEMENT PLATE UNIVERSAL	1	52.20	? 52.20
Reinforcemen	1	52.40	? 52.40
Reinforcemen	1	52.40	? 52.40
Reinforcemen	1	52.40	? 52.40
T WELD BOLT L=5.4MM	10	0.85	? 8.50
RR BUMPER RH SIDE GUIDE	1	61.50	de 61.50
REAR BUMPER CARRIER	1	458.10	? 458.10
SUPPORT	1	45.30	? 45.30
LEFT PROTECT	1	11.20	x 11.20
RIGHT PROTEC	1	11.20	? 11.20
REAR BUMPER TOWING FLAP EYE PRIMED	1	42.85	de 42.85
REAR BUMPER TRIM STRIP (BLACK)	1	70.75	aut 70.75
REAR BUMPER PANEL PRIMED (LINES PDC	1	1,029.50	de 1,029.50
SET MOUNTS PDC SENSOR REAR	1	60.35	ne 60.35
LETTERING 216 I	1	64.10	ne 64.10
GROMMET	2	0.75	ne 1.50
PLAQUE 74MM	1	71.25	ne 71.25
PLASTIC NUT	4	0.85	ne 3.40
BUMP STOP	10	3.50	ne 35.00
REAR WINDOW	1	654.35	? 654.35
HOOK AND LOOP FASTENER	4	2.85	? 11.40
REAR RH SIDE WINDOW FIXED (ALU HOCH	1	277.00	? 277.00
RR RH WHEEL HOUSING COVER	1	135.05	? 135.05
BOOTLID SEALING	1	143.00	ne 143.00
REAR RH REFLECTOR	1	37.90	Cur 37.90
Rear light ing	1	270.50	? 270.50
REAR RH LIGHT IN TRUNK LID	1	255.65	? 255.65
RH GUTTER STRIP	1	51.95	? 51.95
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	ne 20.20
ULTRASONIC SENSOR GLACIERSILBER(WA8	4	368.80	? 1,475.20
CAVITY PROTECTION WAX REMOVER 500ML	1	18.45	he 18.45
BLIND RIVET AVIBVLB	8	0.55	ne 4.40
SCREW (SF PLUS M5X15)	3	0.55	ne 1.65
(DG/SL) BODY ADHESIVE K5B (195ML)	1	326.80	ne 326.80
(DG) BODYWORK ADHESIVE K5A (50ML)	1	112.70	ne 112.70
(DG) CLEANER R1 (100ML)	1	26.15	ne 26.15
(DG) CLEANER R1 (100ML)	1	26.15	ne 26.15
(DG) CLEANER R1 (100ML)	1	26.15	ne 26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	ne 263.10
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	1	131.55	ne 131.55
PUNCH RIVET N4	36	0.55	ne 19.80
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	ne 27.85
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	ne 27.85
Total Parts :			9,210.15

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 51760**
Date Estimated : **01/07/2019**
Prepared By : **Chua Kee Sin**

Page No. : **3 of 6**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMK9145U	ED05858	29/04/2019	216i GT	0

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 618792 Claim No. _____

Date & Time 6/8/19 Excess S\$ _____

Surveyor's Name Tan Kah Sign [Signature]

Surveyor's Tel 9749574 Authorised Yes / No

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail Tan Kah

No. of Working Days Recommend 8-10 days

Labour 1	:	15,056.00
Parts	:	9,210.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,698.63
Grand Total	:	25,964.78

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****