

VIC

BMW Dealer

### Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

28 JUN 2019

### E S T I M A T E

Estimate No. : b1 51732	Page No. : 1 of 5
Date Estimated : 28/06/2019	
Prepared By : Joseph Yaguel	

- ESTIMATE REPAIR FOR - Choo Way Jiang 70 Shrewsbury Road  Singapore 307836	- ACCOUNT - 40000 AIG Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0

DESCRIPTION	VALUE
Replacing front bumper panel and attachments	<del>850</del> 1,700.00
Spray front bumper	<del>934</del> 1,038.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	<del>150</del> 177.00
To supply front emboss number plate.	<del>51</del> 83.00
Sundries	<del>80</del> ? 150.00
<b>Total Labour 1:</b>	<b>3,148.00</b>

  

DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER TOP CARRIER <i>7 x sue</i>	1	415.50	415.50
FRT SHOCK ABSORBER <i>7 x sue</i>	1	45.00	45.00
INSERT AIR INLET MIDDLE <i>7 x sue</i>	1	114.85	114.85
LICENCE PLATE BASE ECE <i>7 x sue</i>	1	69.25	69.25
Closed grid, left <i>7 x sue</i>	1	74.85	74.85
COVER LOWER PART CENTRE <i>7 x sue</i>	1	42.75	42.75
FRT BUMPER PANEL PRIMED (SRA) <i>da</i>	1	1,078.65	1,078.65
FRT LH GRILLE (LUXURY) <i>sch</i>	1	128.00	128.00
FRT RH GRILLE (LUXURY) <i>sch</i>	1	128.00	128.00
FRT BUMPER LOWER MOUNT <i>7 x sue</i>	1	133.80	133.80
DECOUPLING RING PDC TORQUE CONVERTE <i>7 x sue</i>	4	5.05	20.20
<b>Total Parts :</b>			<b>2,250.85</b>

BMW Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrads)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No.	: b1 51732	Page No. :	2 of 5
Date Estimated	: 28/06/2019		
Prepared By	: Joseph Yaguel		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date & Time 08/07/19 @ 16:20 Excess S\$ \_\_\_\_\_

Surveyor's Name Rahul Sign \_\_\_\_\_

Surveyor's Tel 90000628 Authorised Yes / No \_\_\_\_\_

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No \_\_\_\_\_ PML Yes / No \_\_\_\_\_

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 3 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

	Labour 1	:	3,148.00
	Parts	:	2,250.85
	Labour 2	:	0.00
	Excess	:	0.00
	Total GST @ 7%	:	377.92
	Grand Total	:	<u>5,776.77</u>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sirme Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 51732  
Date Estimated : 28/06/2019  
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -  
Choo Way Jiang  
70 Shrewsbury Road

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 307836

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# SET MOUNTING PDC/PMA SENSOR FRT * <i>new</i>	75.30	1.00		75.30
# PLAQUE 82MM * <i>new</i>	71.25	1.00		71.25
# (DG/SL) ADHESIVE SET K6 * <i>new</i>	53.05	1.00		53.05

Total Labour : 0.00  
Total Parts : 199.60  
Total Labour & Parts : 199.60

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-00200B1-X



## FINAL REPORT

Estimate No. : b1 51732  
Date Estimated : 28/06/2019  
Prepared By : Joseph Yaguel

Page No. :

REPAIR FOR -  
Choo Way Jiang  
70 Shrewsbury Road

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 307836

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments include knocking out dents caused by the accident	850.00		850.00 ✓
To spray paint front bumper	934.00		934.00 ✓
To check electrical wiring systems at the front section for proper function	150.00		150.00 ✓
To supply front emboss number plate	83.00		83.00 ✓
Sundries	80.00		80.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
INSERT AIR INLET MIDDLE	114.85	1.00		114.85
LICENCE PLATE BASE ECE	69.25	1.00		69.25
FRT BUMPER PANEL PRIMED (SRA)	1,078.65	1.00		1,078.65
# SET MOUNTING PDC/PMA SENSOR FRT *	75.30	1.00		75.30
FRT LH GRILLE (LUXURY)	128.60	1.00		128.60
FRT RH GRILLE (LUXURY)	128.60	1.00		128.60
# PLAQUE 82MM *	71.25	1.00		71.25
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

# SUPPLEMENTARY ITEMS

Total Labour :	2,097.00
Total Parts :	1,719.55
Total Labour & Parts :	3,816.55
Deduction for Excess :	0.00
Total Repair Costs less Excess:	<b>3,816.55</b>
GST @7%:	267.16
Grand Total :	4,083.71