

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

28 JUN 2019

ESTIMATE

Estimate No. : b1 51732	Page No. : 1 of 5
Date Estimated : 28/06/2019	
Prepared By : Joseph Yaguel	

<p>- ESTIMATE REPAIR FOR - Choo Way Jiang 70 Shrewsbury Road Singapore 307836</p>	<p>- ACCOUNT - 40000 <i>AIG</i> Cash Sales - Service Singapore</p>
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0

DESCRIPTION	VALUE
Replacing front bumper panel and attachments	850 1,700.00
Spray front bumper	934 1,038.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To supply front emboss number plate.	81 83.00
Sundries	? 150.00
Total Labour 1:	3,148.00

DESCRIPTION	QTY	PRIC	VALUE
FRT BUMPER TOP CARRIER ?	1	415.50	415.50
FRT SHOCK ABSORBER ?	1	45.00	45.00
INSERT AIR INLET MIDDLE ?	1	114.85	114.85
LICENCE PLATE BASE ECE <i>sc</i>	1	69.25	69.25
Closed grid, left ?	1	74.85	74.85
COVER LOWER PART CENTRE ?	1	42.75	42.75
FRT BUMPER PANEL PRIMED (SRA) <i>da</i>	1	1,078.65	1,078.65
FRT LH GRILLE (LUXURY) <i>sc</i>	1	128.00	128.00
FRT RH GRILLE (LUXURY) <i>sc</i>	1	128.00	128.00
FRT BUMPER LOWER MOUNT ?	1	133.80	133.80
DECOUPLING RING PDC TORQUE CONVERTE ?	4	5.05	20.20
Total Parts :			2,250.85

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 51732	Page No. : 2 of 5
Date Estimated : 28/06/2019	
Prepared By : Joseph Yaguel	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGA2662M	D967694	22/05/2015	420IA GC	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date & Time 02/07/19 @ 1620	Excess S\$ _____
Surveyor's Name RPM	Sign _____
Surveyor's Tel 900 0062	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail _____	
No. of Working Days Recommend 3 days	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

	Labour 1	:	3,148.00
	Parts	:	2,250.85
	Labour 2	:	0.00
	Excess	:	0.00
	Total GST @ 7%	:	377.92
	Grand Total	:	5,776.77

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **