

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 27/06/19

Address : SIEW KONG GLASS MAKERS PTE LTD
3 TUAS LINK

SINGAPORE 638523

Reference : TP 1207/06/19

Vehicle No : GBD7327S

Make/Model : TOYOTA DYNA 150 MANUAL

Insurance Co. : CHINA TAIPING

CHASSIS

CC

STEAT35Y70K204219

2,982

RE : QUOTATION TO GBD 7327S FOR THIRD PARTY CLAIMS.

REG DATE: 31 MAR 2015

PARTS REQUIRED

QTY

AMT \$

1)	FRONT BUMPER	1	\$	478.54	DEF
2)	FRONT BUMPER ENFORCEMENT	1	\$	165.32	BT
3)	FRONT GRILLE	1	\$	420.16	DEF
4)	TOYOTA "LOGO"	1	\$	69.20	MIS
5)	"DYNA" EMBLEM	1	\$	65.53	NEC
6)	HEADLAMPS	2	\$	1,187.56	CRK
7)	FRONT CROSS MEMBER	1	\$	680.00	?
8)	FRONT PANEL	1	\$	910.79	DEF
9)	FRONT MOULDING CENTRE	1	\$	285.15	DEF LH X SW, RH X MI
10)	FRONT SIDE LH / RH BLACK	2	\$	189.76	DEF
11)	WIPER PANEL	1	\$	261.84	DEF
12)	WIPER MOTOR	1	\$	768.03	X SW
13)	WIPER LINKAGE	1	\$	332.39	?
14)	WIPER WATER NOZZLE	2	\$	93.94	LH SCR, RH MIS
15)	WIPER BLADE	2	\$	189.06	WIP
16)	WIPER ARM	2	\$	229.96	SCR
17)	FRONT WINDSCREEN	1	\$	1,065.74	CRK
18)	FRONT WINDSCREEN RUBBER	1	\$	233.60	DEF
19)	DASHBOARD ASSY	1	\$	827.01	?
20)	FRONT TORSION BAR COMPLETE SET	1	\$	1,574.94	?
21)	ASSORTED CLIPS	10	\$	50.00	?
22)	FRONT PANEL PROTECTION BAR	1	\$	366.52	?

LIST PRICE TOTAL

\$ 10,445.04

LESS DISCOUNT 25%

\$ 2,611.26

LIST PRICE TOTAL AFTER LESS

\$ 7,833.78

NETT PRICE TOTAL

\$0.00

TOTAL PARTS COST

\$7,833.78