



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref : S9M01SCJ

Date: 29<sup>th</sup> Nov 2021

Our Ref : CC4/ASM19011733/Upa3q2

**M/s AXA Insurance Pte Ltd**

8 Shenton Way #24-01

AXA Tower

Singapore 068811

(The Motor Claims Department)

Attn: Vale Oh

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJT 5984D  
INSURED VEHICLE SLZ 9593S ACCIDENT ON 28/06/2019**

Instruction was received to inspect the vehicle Reg. No. SJT 5984D. The inspection was conducted on 03/07/2019 at the premises of M/s Yew Tee Automobile Tech PL, Blk 6 Woodlands Road 399F Yew Tee Ind.Estate, Singapore 678006.

The following vehicle information was recorded:

Registration Number	: SJT 5984D
Make/Model	: NISSAN LATIO CVT 1.5 ABS D/AIRBAG 2WD 4DR
Year of Registration	: 2009
Body Colour	: WHITE
Chassis Number	: JN1BAAC11Z0021073
Engine Capacity	: 1498 cc
Speedometer Reading	: 145220 KM

The vehicle sustained damages at the rear & front portion. (Details see photographs enclosed)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as “**uneconomical Total Loss**”.

Market Value S\$ 13,000.00 (est)

Less: LTA Reimbursement Value (RV) (S\$ 10,506.00)

Nett Liability S\$ 2,494.00  
=====

Vehicle Inspected By:

CHUA KANG SENG  
Licensed Appraiser

K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.