

ASS. REC. BY:

REF

A19 (C3/A19 19011751 / Aq d302

ASSIGNMENT

From:
Estimated Cost:

Date: 27 10 19

Veh No: SKS 5332D Yr Regn: 2015, April

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SKS 5332D

at Workshop n/s: Premium Automobile

of 55 ubi road 1

Insured:

Policy No.

Claims No: 8388 77221456

Sum Insured:

Excess:


800 05/3/19

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: TSK

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 11/8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / ☐ REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Truck / Trailer or

Make: Audi A4 cc 1798

Colour: Black A/C: Insured / Std / NI / NA

Sp Reading: 122923 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAU22SK2FA094809.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inoper / Jammed / Leaked / Burnt or

Brake: ☒ Inoper / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD / STD A/Rim or

Tyre Size: F: 245/40R18.

R: 245/40R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bol. 06 mm

R/Bol. 06 mm

L/Bol. 06 mm

L/Bol. 06 mm

D.O.A. D.O.I. 02/07/19

Survey held at

Premium.

Des. of Damages: ☒ Fr / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis/frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 A19.

SKS 5332D - 2

04/31/19 @ 7.11pm relet to Victor via premium. (repairs willing to undertake cost US \$1400)

mv: 78

PV: 638K.

Nett. 14.2K

RECEIVED 10 OCT 2019

04/21/19 @ 5.04pm Victor informed ☒ at 8.14K via premium.

05/31/19 @ 9.58am informed Troy via not more than 13.84K & Ex: 8800 by email.

23/10/19 @ 10.27am confirmed with Mr Gus from A19 \$14000, 7 days. (Rad 517913, 56%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

200

Transportation:

Photos

Others

TOTAL

11

211

Report Format:

MER-OP

Lump Sum / I.B.I. (\$

14000

Add Fee:

☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 23 October 2019 10:27 AM
To: Boo seng yak; SUR; Carrine Leong; Chang Chee Sing;
jiajee.yap@premiumauto.com.sg
Subject: RE: FINAL CLOSURE - SKS5332D - OD AIG - SURVEYED 2 JUL 19

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$14,000.00 before excess \$800.00 & GST and 7 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Friday, 11 October 2019 3:37 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg
Subject: FINAL CLOSURE - SKS5332D - OD AIG - SURVEYED 2 JUL 19

Hi Adrian and all,

We have repaired this vehicle at a proposed Lump Sum \$14,000.00 @10 days exclude 2 Sundays. Photographs is also attached.

Please confirm by return to conform acceptance that we may close file early.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Friday, 11 October 2019 3:37 PM
To: Adrian Ling (LKKAUTO); SUR; Shiau Chan (LKKAUTO); Carrine Leong; Chang Chee Sing; jiajee.yap@premiumauto.com.sg
Subject: FINAL CLOSURE - SKS5332D - OD AIG - SURVEYED 2 JUL 19
Attachments: WhatsApp Image 2019-07-06 at 10.56.30 AM (resize).jpeg; WhatsApp Image 2019-07-06 at 10.56.37 AM (1) (resize).jpeg; WhatsApp Image 2019-07-06 at 10.56.33 AM (resize).jpeg; WhatsApp Image 2019-07-06 at 10.56.34 AM (resize).jpeg; WhatsApp Image 2019-07-06 at 10.56.36 AM (resize).jpeg; WhatsApp Image 2019-07-06 at 10.56.39 AM (resize).jpeg; WhatsApp Image 2019-07-06 at 10.56.28 AM (resize).jpeg; WhatsApp Image 2019-07-08 at 10.02.26 AM (resize).jpeg; WhatsApp Image 2019-07-08 at 10.02.26 AM (1) (resize).jpeg; WhatsApp Image 2019-07-13 at 10.24.22 AM (resize).jpeg; WhatsApp Image 2019-07-13 at 10.24.25 AM (resize).jpeg; WhatsApp Image 2019-07-13 at 10.24.23 AM (resize).jpeg; WhatsApp Image 2019-07-06 at 10.56.37 AM (resize).jpeg; WhatsApp Image 2019-07-06 at 10.56.38 AM (resize).jpeg

Hi Adrian and all,

We have repaired this vehicle at a proposed Lump Sump \$14,000.00 @10 days exclude 2 Sundays. Photographs is also attached.

Please confirm by return to conform acceptance that we may close file early.

Best regards - jb

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 5 July 2019 9:58 AM
To: Claims
Cc: SUR
Subject: RE: OD CLAIMS FOR SKS 5332 D- DOA : 28/06/2019 VEH IN

Dear TRoy,

As instructed by our client, please proceed to repair the insured vehicle **SKS 5332D** at repair cost not more than **\$14,000.00 on Lump Sum basis (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 4 July 2019 2:57 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIMS FOR SKS 5332 D- DOA : 28/06/2019 VEH IN

Dear Shiau Chan,

Sorry for the late reply, we propose lump sum repair of \$14,000 before GST.
Kindly give us an update.

Thanks

Best Regards,

TRoy Goh

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 198902272W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	01 Jul 2019 15:09	Cim Veh Model Changed		[] Merimen Administrator
2	01 Jul 2019 15:09	Cim Created	Reg No: SKS5332D, Policy No: 2100409448-04, Acct Date: 2019/06/28. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA119085321	[I] Merimen Administrator
3	03 Jul 2019 11:17	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
4	03 Jul 2019 11:17	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
5	03 Jul 2019 11:17	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
6	03 Jul 2019 11:17	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/12	[A] LEE SU THING
7	03 Jul 2019 11:17	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] LEE SU THING
8	03 Jul 2019 11:17	Cim Registration Modified	Rep:1137->200611.	[A] LEE SU THING
9	03 Jul 2019 11:17	Cim Veh Model Changed	(201404) AUDI A4 1.8 TFSI MU Attraction (A).	[A] LEE SU THING
10	03 Jul 2019 11:17	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
11	03 Jul 2019 11:59	Adj Rpt Initiated		[A] SHIAU CHAN
12	03 Jul 2019 11:59	Insured Phone No Updated	[None] -> [+6596311525]	[A] SHIAU CHAN
13	03 Jul 2019 11:59	Cim Dtl Modified	JPJ Reg. Date: -> 2015/04/22.	[A] SHIAU CHAN
14	03 Jul 2019 11:59	Cim Details Notified		[A] SHIAU CHAN
15	03 Jul 2019 17:17	Cim Registration Modified	Init.Est.1->6,000 - 7,000, Excess: -> 800.00, 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Gan, Hunchung
16	03 Jul 2019 17:17	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
17	04 Jul 2019 14:13	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/07/12	[A] SHIAU CHAN
18	04 Jul 2019 14:13	Adj Mandate Request	Cur.Reg:0.00:DAMAGES CONSISTENT, PENDING REPAIR COST FROM REPAIRER.	[A] SHIAU CHAN
19	04 Jul 2019 15:06	Adj Mandate Request Cancelled		[A] SHIAU CHAN
20	04 Jul 2019 15:10	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/07/12	[A] SHIAU CHAN
21	04 Jul 2019 15:11	Adj Mandate Request	Cur.Reg:19920.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$14,000.00 ON LUMP SUM BASIS, WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
22	04 Jul 2019 16:36	Cim Registration Modified	Acct Time:09:25:00->09:00:00.	[I] AIG OneClaim Integration User
23	04 Jul 2019 17:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/07/12. Mandate Remarks: Repair limit at \$14,000.00, Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
24	04 Jul 2019 17:04	Adj Mandate Set	Approved:14000.00:Repair limit at \$14,000.00. Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2199026	03/07/2019 11:59	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKS5332D		11.77

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gan, Hunchung

Date: 04 Jul 2019

Preliminary Advice

Vehicle No	: SKS5332D	Accident Date	: 28/06/2019
Make	: AUDI A4	Policy No.	: 2100409448-04
Assignment Date	: 03/07/2019	Excess	: S\$800.00
Date of Inspection	: 02/07/2019	Est. Duration of Repair	: 9.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,813.00
Revised Amount	:S\$	16,124.00
Check Items (Estimated)	:S\$	3,796.00
Total	:S\$	19,920.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	63,814.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,816.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired; you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER WILLING TO UNDERTAKE THE REPAIR COST NOT MORE THAN \$14,000.00 ON LUMP SUM BASIS.

Shiau Chan (LKKAuto)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 4 July 2019 2:57 PM
To: Shiau Chan (LKKAuto)
Cc: 'Claims'
Subject: RE: OD CLAIMS FOR SKS 5332 D- DOA : 28/06/2019 VEH IN

Dear Shiau Chan,

Sorry for the late reply, we propose lump sum repair of \$14,000 before GST.
Kindly give us an update.

Thanks

Best Regards,
T Roy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 4 July 2019 9:01 AM
To: Claims
Subject: RE: OD CLAIMS FOR SKS 5332 D- DOA : 28/06/2019 VEH IN

Dear Troy,

Any updates? As we need seek mandate approval from insurance.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 03 Jul 2019

Preliminary Advice

Vehicle No	: SKS5332D	Accident Date	: 28/06/2019
Make	: AUDI A4	Policy No.	: 2100409448-04
Assignment Date	: 03/07/2019	Excess	: S\$0.00
Date of Inspection	: 02/07/2019	Est. Duration of Repair	: 9.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,813.00
Revised Amount	:S\$	16,124.00
Check Items (Estimated)	:S\$	3,796.00
Total	:S\$	19,920.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	78,000.00
COE / PARF Rebate	:S\$	63,814.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,816.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details

Owner ID Type:	Singapore NRIC
Owner ID:	2519D

Vehicle Details

Vehicle No.:	SK55332D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jul 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.8 TFSI MU ATTRACTION
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	CJE097129
Chassis No.:	WAUZZZBK2FA094809
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$31,315.00
Original Registration Date:	22 Apr 2015
First Registration Date:	22 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$25,841.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Apr 2025
PARF Rebate Amount:	\$19,380.00

Intended COE Rebate Details

COE Expiry Date:	21 Apr 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$76,612.00
COE Rebate Amount:	\$44,434.00
Total Rebate Amount:	\$63,814.00

The information contained herein is correct as at 03 Jul 2019

OK



☐ Audi A4 1.8A TFSI MU \$85,000 \$11,580 /yr 25-Sep-2015 1,798 cc 35,000 km Luxury Available

Consignment Code: A033. Consignment Unit. Flexible Loan Packages Available To Choose From. No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us. Viewing By Appointment.

Consignment

Posted: 25-Apr-2019 Tags: 2015 Audi A4, 2015 audi a4, Audi A4, audi a4, Audi A4, a4, Used Audi



☐ Audi A4 1.8A TFSI MU Attraction \$89,800 \$11,970 /yr 28-Oct-2015 1,798 cc 25,000 km Luxury Available

Sale Due To Overseas Relocation, Price Negotiable Only In This Week, Very Careful Owner, Very Low Mileage (25,000km). Full Audi Service Record At Premium Automobile, 100% Accident Free, Min T Condition, Well Maintained Interior And Exterior, Please Whatsapp...

Direct Owner

Posted: 23-Jun-2019 Tags: 2015 Audi A4, 2015 audi a4, Audi A4, audi a4, Audi A4, a4, Used Audi



☐ Audi A4 1.8A TFSI MU Attraction \$83,500 \$10,960 /yr 30-Oct-2015 1,798 cc 64,000 km Luxury Available

Black On Black Interior, Serviced/ Maintained By Agent, Flexible Loan Package Tailor To Suits You, Very Well Maintained, Improved Model Which Is More Reliable, Low Depreciation Luxury Sedan, View And Judge The Condition For Yourself.

Posted: 25-Jun-2019 Tags: 2015 Audi A4, 2015 audi a4, Audi A4, audi a4, Audi A4, a4, Used Audi



BlackVue DR750S Car Camera

Equipped with Sony Starvis CMOS Sensor, this blackvue full HD cloud camera gives you best image quality under any light condition. Find the list of the best cameras available, each with product information and user reviews.

Find out more!



☐ Audi A4 1.8A TFSI MU Attraction Plus \$85,000 \$11,060 /yr 27-Nov-2015 1,798 cc 70,000 km Luxury Available

This Car Drives Smooth, Quiet And Has Maintenance Done Punctually, No Kids Ever Sat On This Car, This Lightly Driven Car Is Still Showroom Condition. No Problems, Quiet Car No Dealers/Consignment Agent Please! Car Comes With Reverse Cam And High End Garml...

Direct Owner

Posted: 18-Jun-2019 Tags: 2015 Audi A4, 2015 audi a4, Audi A4, audi a4, Audi A4, a4, Used Audi



☐ Audi A4 1.8A TFSI MU Attraction \$88,800 \$11,640 /yr 30-Nov-2015 1,798 cc 42,000 km Luxury Available

Special Offer 1.98% Interest Rate, 1 Owner With Low Mileage, New Road Tax Till 29 Nov 2019, Fully Maintained By Audi! Car In Zero Modification, Very Well Kept Interior/Exterior, Still In Near New Car Condition, View And Test Drive To Believe!

Premium Car

Auto Zoom Enterprise Pte Ltd

Posted: 28-Jun-2019 Tags: 2015 Audi A4, 2015 audi a4, Audi A4, audi a4, Audi A4, a4, Used Audi



☐ Audi A4 1.8A TFSI MU Attraction \$87,888 \$11,360 /yr 28-Dec-2015 1,798 cc 80,000 km Luxury Available

Hassle-free Loan Available! High Trade In Available. Beautiful Scuba Blue Paintwork W One Careful Owner, Always Shelter Parked, Most Wear N Tear Replaced. Most Popular German Sedan Around! Luxurious Plush Leather Coupled With Its Engaging Drive, Make This A Uni...

Premium Car

Cars 88 Pte Ltd

Posted: 13-Jun-2019 Tags: 2015 Audi A4, 2015 audi a4, Audi A4, audi a4, Audi A4, a4, Used Audi



☐ Audi A4 1.8A TFSI MU Attraction \$89,800 \$11,650 /yr 30-Dec-2015 1,798 cc 57,000 km Luxury Available

Latest Arrival, Immaculate Condition, Premium Automobile Agent Unit, Interior Smell Like New Car, Trade In And Loan Available, Special Interest Rate Offer 1.98%, Hurry Make An Appointment To View This Unit Now.

Premium Car

Lay Auto Pte Ltd

Posted: 28-Jun-2019 Tags: 2015 Audi A4, 2015 audi a4, Audi A4, audi a4, Audi A4, a4, Used Audi

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page


Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or mini-vans, SUV, MPV, hatchback, to COE cars & CPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, current rates & car insurance. Find buy used Audi A4, Audi A4 Singapore, used Audi A4 Singapore, used Audi A4, used vehicles Singapore or even buy used Audi A4 Singapore. We have new car dealers companies, parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner site for job openings for Singapore jobs. Real estate properties for sale, house, car performance parts, car decoration, foreign destination, commercial vehicle leasing & COE results.

All prices and sales information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or timely. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

WHILE LISTED HERE

Follow sgCarMart.com



Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	01/07/2019 14:53
Date Of Accident	28/06/2019 09:25
Exact Location Of Accident	ALONG CLEMENTI ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKS5332D
Insured/Policyholder	
Name Of Registered Owner	JOSEPHINE LEE LYE CHENG
NRIC No	S1602519D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96311525
Alternative Phone No	OTHERS-96311525
Vehicle Particulars	
Manufacturer	AUDI
Model	A4 1.8 TFSI MU ATTRACTION
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100409448-04
Cover Note Number	
Driver	
Name of Driver	TAN CHUAN HAO JEREMY
NRIC No	S9220803F
Date Of Birth	15/06/1992
Occupation	INDOOR
Date Of Driving Pass	05/12/2012
Driving Experience	6 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91177254
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 63 TAMPINES AVENUE 1
#12-04
Postcode 529777
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured CHILDREN
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

ACCIDENTALLY HIT THE LORRY BACK, ALONG CLEMENTI ROAD ON 28/06/2019 AT 9.25AM.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP833H
Vehicle Make/Model/Colour LORRY
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver NG TIN HWA
NRIC/Passport Number S1787201Z
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: GUEI SHI HAO, TAY J
NRIC/ID No: G5527126

A → yprash
B → sks s330D

The diagram shows a vertical stack of two rectangular boxes. The top box is labeled 'A' and the bottom box is labeled 'B'. A vertical line is drawn to the right of the stack. An arrow points upwards from the bottom of the stack towards the box labeled 'B'.

ACCIDENTALLY HIT THE LARY ~~WATER~~ BACK BLEND
ELEMENT RD #2 28/06/19 AT 9.25 AM

(We declare the foregoing particulars are true in every respect.)

Reporting Conf: 2004 10/10/04 10/10/04
Name: Col. Shi HAO, Tex
NRIC/ITA No: 1001001001

Accident Photo



Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : JOSEPHINE LEE LYE CHENG
Period of Insurance : 22 Apr 2019 To 21 Apr 2020
Engine No. : CJE097129
Chassis No. : WAUZZZ8K2FA094809

Vehicle No. : SKS5332D
Policy No. : 2100409448-04
Endorsement No. :
Issued Date : 08 Mar 2019

ABOUT THE COVER

Make/Model : AUDI A4 1.8 TFSI MU ATTRACTION (WBW)
Engine Capacity/Tonnage : 1,798.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive*

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2015
Insuring with COE/PAFF : Yes

* At The Policyholder's
to Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$2,000 as "Young and/or Inexperienced Driver Excess" ("YIDRE") if You are or Your Authorised Driver (named or unnamed) is under the age of 22 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for local, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 183) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

JOSEPHINE LEE LYE CHENG - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center, Add: 55 Ubi Road 1, Singapore 408699 63462323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 183), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third-Party Risks) Rules, 1955 (Malaysia).

0504125245

PREMIUM LEASING - GN

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. N. K.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit VMA(Summons)/Correspondence from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0803/2019/TG
Date	:	1-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms. Josephine Lee Lye Cheng
Address	:	Blk 63 Tampines Avenue 1 #12-04 Singapore 529777
Telephone	:	(HP) +65 96311525 (HP) +65 96617828 (Mr. Steve)
Type of Claim	:	Own Damage Claim
Policy No.	:	2100409448-04
Vehicle No	:	SKS 5332 D
Model Code	:	Audi A4 1.8 TFSI MU (A)
Model / Year	:	Apr-15
Engine No	:	CJE 097129
	:	WAUZZZ8K2FA094809
Mileage	:	122923 KM
Date In	:	1-Jul-19
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Jun-19
Place of Accident	:	Along Clementi Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKS 5332 D

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To remove and reinstall aircon condenser, charged air cooler and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ✱
3	To dismantle and renew front bumper, both fenders, bonnet and both headlights. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	\$ 6,300.00 <i>1500 (without Lock carrier) 3000 (with Lock carrier)</i>
4	To respray front bumper, both front fenders and bonnet. ✓	\$ 3,800.00 2200
5	To carry out diagnostic check	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 11,852.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 5332 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
1	FRONT BUMPER <i>Delud</i>	\$	2,100.00 ✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	234.00 +
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	207.00 +
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	\$	123.00 +
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>new</i>	\$	177.00 ✓
6	FRONT BUMPER SUPPORT ELEMENT - UPPER <i>new</i>	\$	54.00 +
7	RADIATOR GRILLE <i>new</i>	\$	1,005.00 ✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$	123.00 +
9	FRONT BUMPER VENT GRILLE - RH <i>new</i>	\$	123.00 +
10	FRONT WHEEL SPOILER - LH / RH	2 \$	90.00 +
11	FOAM FILLER PIECE <i>new</i>	\$	113.00 +
12	FRONT BUMPER SIDE REINFORCEMENT <i>new</i>	\$	802.00 +
13	RADIATOR TOP COVER <i>Delud</i>	\$	116.00 ✓
14	FRONT BUMPER GRILLE SUPPORT - LH / RH <i>new</i>	2 \$	23.00 ✓
15	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	66.00 +
16	CAUTION STICKER <i>new</i>	\$	13.00 ✓
17	AC STICKER <i>new</i>	\$	22.00 ✓
18	FRONT FENDER - LH / RH <i>Regis</i>	2 \$	1,807.00 +
19	FRONT FENDER ATTACHMENT PARTS <i>new</i>	2 \$	103.00 +
20	FRONT FENDER BRACKET - LH / RH <i>new</i>	2 \$	95.00 +
SUB - TOTAL SPARE PARTS CHARGES		\$	7,396.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Net.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 5332 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
21	REAR FENDER BRACKET - LH / RH <i>new</i>	2 \$	89.00 +
22	POP RIVET <i>new</i>	8 \$	24.00 +
23	FRONT SUPPORT FENDER BRACKET - LH / RH <i>new</i>	2 \$	214.00 +
24	STONE CHIP GUARD <i>new</i>	2 \$	133.00 ✓
25	ADHESIVE TAPE <i>new</i>	2 \$	100.00 +
26	BONNET <i>Dented</i>	\$	2,549.00 ✓
27	BOLT SOCKET <i>new</i>	3 \$	7.00 +
28	FRONT BONNET PROTECTIVE FILM <i>new</i>	\$	42.00 ✓
29	FRONT BONNET ATTACHMENT PARTS <i>new</i>	\$	152.00 +
30	FRONT BONNET EDGE PROTECTION <i>new</i>	\$	25.00 ✓
31	CATCH HOOK <i>Bent</i>	\$	127.00 2 ✓
32	LID LOCK <i>new</i>	\$	196.00 +
33	GAS FILLED STRUT <i>new</i>	\$	109.00 +
34	BONNET LOCK COVER <i>new</i>	\$	21.00 +
35	MICRO SWITCH <i>new</i>	\$	67.00 +
36	HEADLIGHT MOUNTING - LH / RH <i>new</i>	\$	214.00 ✓
37	HEADLIGHT BRACKET - LH / RH <i>new</i>	\$	192.00 ✓
38	HEADLIGHT - LH / RH <i>new</i>	2 \$	4,304.00 ✓
39	POWER MODULE FOR DAYLIGHT <i>new</i>	\$	520.00 +
40	HEADLIGHT CONTROL UNIT <i>new</i>	\$	1,051.00 +
SUB - TOTAL SPARE PARTS CHARGES		\$	10,136.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 5332 D

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
41	GAS DISCHARGE LAMP <i>Not in</i>	\$	398.00 +
42	LIFT CYLINDER - LH / RH <i>Not in</i>	2 \$	383.00 +
43	HEADLIGHT HOSE <i>Not in</i>	\$	170.00 ✓
44	LOCK CARRIER MOUNTING FOR RADIATOR <i>Not in</i>	\$	928.00 X
45	HEXAGON SOCKET BOLT <i>Not in</i>	2 \$	5.00 +
46	SPEED NUT <i>Not in</i>	2 \$	5.00 +
47	COOLANT <i>Not in</i>	4 \$	84.00 +
48	RADIATOR SUPPORT MOUNTING - LH / RH <i>Not in</i>	2 \$	69.00 X
49	RADIATOR AIR GUIDE - LH / RH <i>Not in</i>	2 \$	47.00 ✓
50	FRONT NO. PLATE <i>Dented</i>	\$	40.00 ✓
51	SUNDRIES <i>Not in</i>	\$	300.00 X
TOTAL SPARE PARTS CHARGES		\$	19,961.00
TOTAL LABOUR CHARGES		\$	11,852.00
GRAND TOTAL		\$	31,813.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name

: Adrian Lim

Surveyed Date

: 02/07/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: xHe Authorized, 06 Days (Without Load Carrier)
09 Days (With Load Carrier)

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 5332 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
1	FRONT BUMPER <i>Del'd</i>	\$	2,100.00 ✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	234.00 +
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	207.00 +
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	\$	123.00 +
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>new</i>	\$	177.00 +
6	FRONT BUMPER SUPPORT ELEMENT - UPPER	\$	54.00 ✓
7	RADIATOR GRILLE <i>new</i>	\$	1,005.00 ✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$	123.00 +
9	FRONT BUMPER VENT GRILLE - RH	\$	123.00 +
10	FRONT WHEEL SPOILER - LH / RH	2 \$	90.00 ✓
11	FOAM FILLER PIECE	\$	113.00 ?
12	FRONT BUMPER SIDE REINFORCEMENT	\$	802.00 ?
13	RADIATOR TOP COVER <i>Del'd</i>	\$	116.00 ✓
14	FRONT BUMPER GRILLE SUPPORT - LH / RH <i>new</i>	2 \$	23.00 ✓
15	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	68.00 ✓
16	CAUTION STICKER	\$	13.00 ✓
17	AC STICKER	\$	22.00 ✓
18	FRONT FENDER - LH / RH <i>Regis</i>	2 \$	1,807.00 +
19	FRONT FENDER ATTACHMENT PARTS <i>new</i>	2 \$	103.00 ✓
20	FRONT FENDER BRACKET - LH / RH	2 \$	95.00 ✓
SUB - TOTAL SPARE PARTS CHARGES		\$	7,396.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Matt.

Paul
10/07/19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 5332 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
21	REAR FENDER BRACKET - LH / RH <i>new</i>	2 \$	89.00 +
22	POP RIVET <i>new</i>	8 \$	24.00 +
23	FRONT SUPPORT FENDER BRACKET - LH / RH <i>new</i>	2 \$	214.00 +
24	STONE CHIP GUARD <i>new</i>	2 \$	133.00 ✓
25	ADHESIVE TAPE <i>new</i>	2 \$	100.00 +
26	BONNET <i>Dented</i>	\$	2,549.00 ✓
27	BOLT SOCKET <i>new</i>	3 \$	7.00 +
28	FRONT BONNET PROTECTIVE FILM <i>new</i>	\$	42.00 ✓
29	FRONT BONNET ATTACHMENT PARTS ?	\$	152.00 ?
30	FRONT BONNET EDGE PROTECTION <i>new</i>	\$	25.00 ✓
31	CATCH HOOK ? <i>new</i>	\$	127.00 ?
32	LID LOCK <i>new</i>	\$	196.00 +
33	GAS FILLED STRUT <i>new</i>	\$	109.00 +
34	BONNET LOCK COVER ?	\$	21.00 ?
35	MICRO SWITCH <i>new</i>	\$	67.00 +
36	HEADLIGHT MOUNTING (LH) (RH) <i>new</i> <i>OK</i>	\$	214.00 +
37	HEADLIGHT BRACKET (LH) (RH) <i>new</i> <i>OK</i>	\$	192.00 +
38	HEADLIGHT - LH / RH <i>Combined</i>	2 \$	4,304.00 ✓
39	POWER MODULE FOR DAYLIGHT <i>new</i>	\$	520.00 +
40	HEADLIGHT CONTROL UNIT <i>new</i>	\$	1,051.00 +
SUB - TOTAL SPARE PARTS CHARGES		\$	10,136.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKS 5332 D

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	
41	GAS DISCHARGE LAMP <i>new</i>	\$	398.00 <i>x</i>
42	LIFT CYLINDER - LH / RH <i>new</i>	2 \$	383.00 <i>x</i>
43	HEADLIGHT HOSE <i>new cut</i>	\$	170.00 <i>x</i>
44	LOCK CARRIER MOUNTING FOR RADIATOR <i>new ?</i>	\$	928.00 <i>?</i>
45	HEXAGON SOCKET BOLT <i>new</i>	2 \$	5.00 <i>x</i>
46	SPEED NUT <i>new</i>	2 \$	5.00 <i>x</i>
47	COOLANT <i>?</i>	4 \$	84.00 <i>?</i>
48	RADIATOR SUPPORT MOUNTING - LH / RH <i>R</i>	2 \$	69.00 <i>?</i>
49	RADIATOR AIR GUIDE - LH / RH <i>new (R)</i>	2 \$	47.00 <i>x</i>
50	FRONT NO. PLATE <i>Dented</i>	\$	40.00 <i>✓</i>
51	SUNDRIES <i>?</i>	\$	300.00 <i>?</i>
TOTAL SPARE PARTS CHARGES		\$	19,961.00
TOTAL LABOUR CHARGES		\$	11,852.00
GRAND TOTAL		\$	31,813.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Net.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SKS 5332 D

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0803/2019/KK

29 October 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SKS 5332 D, Audi A4 1.8T FSI MU.

With reference to the above-mentioned vehicle, no. **SKS 5332 D**, claimant, **Ms, Josephine Lee Lye Cheng**, please find the related document per attached.

1. A copy of the Original invoice no. 85014403 – S\$ 14,124.00.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SKS 5332 D


from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore

281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre

281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6475 1023

Ubi Service Centre

55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service

Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 09:58

Company Reg.No.199902271W

GST Reg.No.199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85014403 Date : 25/10/2019 Order : SK55332D Term : 30	Account: A0006 (T O) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SK55332D (V 25911)

Regn Date: 22/04/2015

Mileage: 127768

WIP No : 58896

Model : A4 1.8T FSI MU 8K203H

Chassis: WAUZZZ8K2FA094809

Engine: CIE 097129

Dept : U

You have been assisted by:- UB-Nora (11)

		Details	Qty	Unit Price	Amount
S	SUBLET	To carry out contractual LUMP SUM repair basis as agreed	14,000.00	1.00	14,000.00
Q	EXC	Insurance Excess/Liability	-800.00	1.00	-800.00

Parts 0.00
Labour 0.00
Sublet 14,000.00
Menus 0.00
Lubricant 0.00

Sub- Total 13,200.00

7% GST 924.00

Grand Total 14,124.00



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKS 5332 D

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0803/2019/TG
16 July 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 1.8 TFSI MU (A)
Vehicle Chassis No. : WAUZZZ8K2FA094809
Vehicle Regn No. : **SKS 5332 D**
Vehicle Mileage : 122923 KM
Vehicle Owner : Ms. Josephine Lee Lye Cheng
Certificate No : 2100409448-04
Own Damage Excess : \$856.00 (Incl. 7% GST)
Accident Date : 28 June 2019
Place : Along Clementi Road
Repair Cost : \$ 14,124.00
WIP No. : 58896
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


08 30 am
17/7/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jul 2019 11:59		03 Jul 2019 11:17 Edit Adj Rpt	S\$14,000.00 Edit Estimates	S\$14,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: JOSEPHINE LEE LYE CHENG , ID: S16025190, Tel: +6596311525									
Vehicle Reg. No.: SKS5332D		Date of Loss: 28/06/2019 09:00 - :59 [50 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 8388772214SG		Policy/Cover Note No.: (Comprehensive) Excess: S\$800.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 12/07/2019]									
Driver/Custodian: TAN CHUAN HAO JEREMY (27 / Male), NRIC: S9220803F, Tel: +6591177254 Email: NOEMAIL									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (04/07/2019): Alert - Adj Mandate Approved (S\$14000.00) - SKS5332D - Claim Handler: Gan, Hunch... - AIG_SG (03/07/2019): SKS5332D / OD / 28/06/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKS5332D (8388772214SG)

OD

Jun 28 2019 9:00AM

[JOSEPHINE LEE LYE CHENG]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Assessment Reports												1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	04/07/19 14:13	Adjuster Immediate Advice											Load HTM				
2	04/07/19 15:10	Adjuster Immediate Advice											Load HTM				
Photos/Images												3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	04/07/19 14:14	General View											Load JPG	☒			
2	04/07/19 14:14	Chassis Number											Load JPG	☒			
3	04/07/19 14:14	General View											Load JPG	☒			
4	04/07/19 14:14	General View											Load JPG	☒			
5	04/07/19 14:14	General View											Load JPG	☒			
6	04/07/19 14:14	General View											Load JPG	☒			
7	04/07/19 14:14	General View											Load JPG	☒			
8	04/07/19 14:14	General View											Load JPG	☒			
9	04/07/19 14:14	General View											Load JPG	☒			
10	04/07/19 14:14	General View											Load JPG	☒			
11	04/07/19 14:14	General View											Load JPG	☒			
12	04/07/19 14:14	General View											Load JPG	☒			
13	04/07/19 14:14	General View											Load JPG	☒			
14	04/07/19 14:14	General View											Load JPG	☒			
15	04/07/19 14:14	General View											Load JPG	☒			
16	04/07/19 14:14	General View											Load JPG	☒			
17	04/07/19 14:14	General View											Load JPG	☒			
18	04/07/19 14:14	General View											Load JPG	☒			
19	04/07/19 14:14	General View											Load JPG	☒			
20	04/07/19 14:14	General View											Load JPG	☒			
21	04/07/19 14:14	General View											Load JPG	☒			
22	04/07/19 14:14	General View											Load JPG	☒			
23	04/07/19 14:14	General View											Load JPG	☒			
24	04/07/19 14:14	General View											Load JPG	☒			
25	04/07/19 14:14	General View											Load JPG	☒			
26	04/07/19 14:14	General View											Load JPG	☒			
27	04/07/19 14:14	General View											Load JPG	☒			
28	04/07/19 14:14	General View											Load JPG	☒			
29	04/07/19 14:14	General View											Load JPG	☒			
30	04/07/19 14:14	General View											Load JPG	☒			
31	04/07/19 14:14	General View											Load JPG	☒			
32	04/07/19 14:14	General View											Load JPG	☒			
33	04/07/19 14:14	General View											Load JPG	☒			
34	04/07/19 14:14	General View											Load JPG	☒			
35	04/07/19 14:14	General View											Load JPG	☒			
36	04/07/19 14:14	General View											Load JPG	☒			
37	22/10/19 17:55	Reinspection Photo											Load JPG	☒			
38	22/10/19 17:55	Reinspection Photo											Load JPG	☒			
39	22/10/19 17:55	Reinspection Photo											Load JPG	☒			
40	22/10/19 17:55	Reinspection Photo											Load JPG	☒			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
42	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
43	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
44	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
45	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
46	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
47	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
48	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
49	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
50	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
51	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
52	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
53	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
54	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
55	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
56	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
57	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
58	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
59	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
60	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
61	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
62	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
63	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
64	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
65	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
66	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
67	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
68	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
69	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
70	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
71	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
72	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
73	22/10/19 17:55	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/07/19 11:46	Singapore Accident Statement	 Load PDF	
2	03/07/19 11:46	Certificate of Insurance	 Load PDF	
3	03/07/19 11:46	Insured Person's NRIC	 Load PDF	
4	03/07/19 11:46	Driver's Driving License	 Load PDF	
5	03/07/19 11:46	ESTIMATE	 Load PDF	
6	04/07/19 14:11	Log card (if available)	 Load PDF	
7	04/07/19 14:11	SGCARMART	 Load PDF	
8	06/11/19 15:49	Workshop Invoice	 Load PDF	
9	06/11/19 16:14	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	01/07/19 15:09	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	01/07/19 15:05	Accident Photo	 Load JPG	☒
2	01/07/19 15:05	Accident Photo	 Load JPG	☒
3	01/07/19 15:05	Accident Photo	 Load JPG	☒
4	01/07/19 15:05	Accident Photo	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				☒
5	01/07/19 15:05	Accident Photo	Load JPG	☒
6	01/07/19 15:05	Accident Photo	Load JPG	☒
7	01/07/19 15:05	Accident Photo	Load JPG	☒
8	01/07/19 15:05	Accident Photo	Load JPG	☒
9	01/07/19 15:05	Accident Photo	Load JPG	☒
10	01/07/19 15:05	Accident Photo	Load JPG	☒
11	01/07/19 15:05	Accident Photo	Load JPG	☒
12	01/07/19 15:05	Accident Photo	Load JPG	☒
13	01/07/19 15:05	Accident Photo	Load JPG	☒
14	01/07/19 15:05	Accident Photo	Load JPG	☒
15	01/07/19 15:05	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	01/07/19 15:00	Sketch Plan	Load JPG	☒
2	01/07/19 15:00	Sketch Plan #2	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19011751/AQD3E2

Date: 06/11/2019

REFERENCE

Insured/Claimant: JOSEPHINE LEE LYE CHENG
Date of Loss: 28/06/2019Policy No:
Nature of Claim: OD Claim No: 8388772214SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS5332D	Engine No:	CJE097129
Make & Model:	AUDI A4, 1.8 TFSI MU Attraction (A)	Chassis No:	WAUZZZ8K2FA094809
Reg. Date:	22/04/2015 (Man. Year: 2015)	Odometer:	122923 km
Colour:	Black		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,961.00	11,299.00	8,662.00	43.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,852.00	4,252.00	7,600.00	64.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,813.00	15,551.00	16,262.00	51.12
Approved Total (Overridden) (S\$)		14,000.00		
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	31,013.00	13,200.00	17,813.00	57.44
+ GST 7.00/7.00% (S\$)	2,170.91	924.00	1,246.91	57.44
Nett Amount (S\$)	33,183.91	14,124.00	19,059.91	57.44

INSPECTION

Date of Assignment: 03/07/2019

Date Inspected: 02/07/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	1,005.00 FS	*1,005.00 FS
2	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	123.00 FS	*- FS
3	1		*FRONT BUMPER VENT GRILLE - RH	Not Necessary	123.00 FS	*- FS
4	2		*FRONT WHEEL SPOILER - LH/RH	Not Necessary	90.00 FS	*- FS
5	1		*FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
6	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	802.00 FS	*- FS
7	1		*RADIATOR TOP COVER	Deformed	116.00 FS	*116.00 FS
8	2		*FRONT BUMPER GRILLE SUPPORT - LH/RH	Cracked	23.00 FS	*23.00 FS
9	2		*FRONT BUMPER GUIDE SECTION - LH/RH	Not Necessary	66.00 FS	*- FS
10	1		*CAUTION STICKER	Necessary	13.00 FS	*13.00 FS
11	1		*AC STICKER	Necessary	22.00 FS	*22.00 FS
12	2		*FRONT FENDER - LH/RH	Repair	1,807.00 FS	*- FS
13	2		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	103.00 FS	*- FS
14	2		*FRONT FENDER BRACKET - LH/RH	Not Necessary	95.00 FS	*- FS
15	2		*REAR FENDER BRACKET - LH/RH	Not Necessary	89.00 FS	*- FS
16	8		*POP RIVET	Not Necessary	24.00 FS	*- FS
17	2		*FRONT SUPPORT FENDER BRACKET - LH/RH	Not Necessary	214.00 FS	*- FS
18	2		*STONE CHIP GUARD	Necessary	133.00 FS	*133.00 FS
19	2		*ADHESIVE TAPE	Not Necessary	100.00 FS	*- FS
20	1		*BONNET	Dented	2,549.00 FS	*2,549.00 FS
21	3		*BOLT SOCKET	Not Necessary	7.00 FS	*- FS
22	1		*FRONT BONNET PROTECTIVE FILM	Necessary	42.00 FS	*42.00 FS
23	1		*FRONT BONNET ATTACHMENT PARTS	Not Necessary	152.00 FS	*- FS
24	1		*FRONT BONNET EDGE PROTECTION	Necessary	25.00 FS	*25.00 FS
25	1		*CATCH HOOK	Bent	127.00 FS	*127.00 FS
26	1		*LID LOCK	Not Necessary	196.00 FS	*- FS
27	1		*GAS FILLED STRUT	Not Necessary	109.00 FS	*- FS
28	1		*BONNET LOCK COVER	Not Necessary	21.00 FS	*- FS
29	1		*MICRO SWITCH	Not Necessary	67.00 FS	*- FS
30	1		*HEADLIGHT MOUNTING - LH/RH	Cracked	214.00 FS	*214.00 FS
31	1		*HEADLIGHT BRACKET - LH/RH	Cracked	192.00 FS	*192.00 FS
32	2		*HEADLIGHT - LH/RH	Cracked	4,304.00 FS	*4,304.00 FS
33	1		*POWER MODULE FOR DAYLIGHT	Not Necessary	520.00 FS	*- FS
34	1		*HEADLIGHT CONTROL UNIT	Not Necessary	1,051.00 FS	*- FS
35	1		*GAS DISCHARGE LAMP		398.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*LIFT CYLINDER - LH/RH	Not Necessary	383.00 FS	*- FS
37	1		*HEADLIGHT HOSE	Cut	170.00 FS	*170.00 FS
38	1		*LOCK CARRIER MOUNTING FOR RADIATOR	Not Necessary	928.00 FS	*- FS
39	2		*HEXAGON SOCKET BOLT	Not Necessary	5.00 FS	*- FS
40	2		*SPEED NUT	Not Necessary	5.00 FS	*- FS
41	4		*COOLANT	Not Necessary	84.00 FS	*- FS
42	2		*RADIATOR SUPPORT MOUNTING - LH/RH	Not Necessary	69.00 FS	*- FS
43	2		*RADIATOR AIR GUIDE - LH/RH	Cracked	47.00 FS	*47.00 FS
44	1		*FRONT NO. PLATE	Dented	40.00 FS	*40.00 FS
45	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
46	1		*FRONT BUMPER	Deformed	2,100.00 FS	*2,100.00 FS
47	1		*FRONT BUMPER FIXING PARTS	Not Necessary	234.00 FS	*- FS
48	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	207.00 FS	*- FS
49	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	123.00 FS	*- FS
50	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Cracked	177.00 FS	*177.00 FS
51	1		*FRONT BUMPER SUPPORT ELEMENT - UPPER	Not Necessary	54.00 FS	*- FS
F=Franchise part. S=SpcNett.					Total Parts (\$\$)	19,961.00 11,299.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	New	1,200.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FENDERS, BONNET AND BOTH HEADLIGHTS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	6,300.00	1,500.00
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS AND BONNET.	New	3,800.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			11,852.00	4,252.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >