



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Ref: CC4/ASM19011778/Bpa3q2 Date: 17/09/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 2451D	Veh. Inspected	SLM 6088Y	
Policy No.	P2219056	Coverage (\$)	0.00	
Claim No.	S9M01SPI	Excess (\$)	0.00	
Assign From		Assign Date	03/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMHU366180	Colour	SILVER	
Odometer	58913 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	PIRELLI	7 mm	
L/H Front Tyre	225/45 R17	PIRELLI	7 mm	
R/H Rear Tyre	225/45 R17	PIRELLI	7 mm	
L/H Rear Tyre	225/45 R17	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/07/2019	Inspection Date	05/07/2019	
Survey held at	160 SIN MING DRIVE #01-14			
Repairer	TEAM AUTOPRO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	