

Our Ref: GBE7663R190620

Date: 23/07/2019

Your Ref:

e

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
AIG Building
Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

TRAFFIC ACCIDENT ALONG . BKE
INVOLVING . GBE7663R AND . GBH6891P ON . 20/06/2019

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**), the registered owners of m/vehicle - GBE7663R at all material times of the above accident. Our/my vehicle was surveyed by "AIG Asia" authorized appraiser and we/I based our/my claims on his recommendation for **S\$ 10,800-00** being the repair for 09 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle . GBH6891P when the same was involved in the aforesaid accident with our/my m/vehicle - GBE7663R.

We/I whereby you are the insurers of m/vehicle GBH6891P and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle - GBE7663R has suffered loss and damage as follows:

(a) Cost of repairs	S\$	<u>10,800-00</u>
(b) LOU for pre-repair notice <u>02</u> days @ S\$ <u>80-00</u> [2953 cc]		<u>160-00</u>
(c) LOU Fee for <u>09</u> days @ S\$ <u>80-00</u> [2953 cc]		<u>720-00</u>
(d) GIA / LTA search fee		<u>2-00</u>
(e)		
Total Amount	S\$	<u>11,682-00</u>

We/I enclose herewith copies of the supporting documents for vehicle no. GBE7663R as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices and documents;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle GBE7663R
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBE7663R190620

Final Bill

Customer	Page 01 - 03
Name: AIG Asia Pacific Insurance Pte Ltd	Date: 23-07-19
Address: Motor Claims Department	Vehicle No: GBE7663R
78 Shenton Way #07-16	Model/Make: Toyota Hiace
AIG Building Singapore 079120	3.0 DX Diesel Turbo MT 2WD

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 1,950.90	\$ -
2	Tailgate Inner Lock	\$ 359.00	\$ -
3	Tailgate Outer Handle	\$ 137.60	\$ -
4	Tailgate Rubber	\$ 426.70	\$ -
5	Tailgate Inner Trim Board	\$ 165.30	\$ -
6	Tailgate Inner Trim Board Clips 1 set	\$ 50.00	SN \$ -
7	Tailgate "Corporate" Advertisement & Artwork	\$ 180.00	SN \$ -
8	Tailgate Windscreen Glass Moulding	\$ 219.00	\$ -
9	Tailgate Windscreen Glass Sealant	\$ 50.00	SN \$ -
10	Tailgate "70 KM/H" Sticker	\$ 15.00	SN \$ -
11	Tailgate "8 PAX" Sticker	\$ 15.00	SN \$ -
12	Tailgate "Toyota" Motif	\$ 68.10	\$ -
13	Tail Lamp 02 pcs (@ S\$365.10)	\$ 730.20	\$ -
14	Tail Lamp Lower Garnish	\$ 435.20	\$ -
15	Bumper	\$ 465.00	\$ -
16	Bumper Clips 1 set	\$ 48.00	SN \$ -
17	Bumper Reverse Sensor	\$ 220.00	SN \$ -
18	Bumper Inner Bracket 02 pcs (@ S\$380.40)	\$ 760.80	\$ -
19	Bumper Side Holder 02 pcs (@ S\$139.00)	\$ 278.00	\$ -
20	Exhaust Silencer	\$ 917.60	\$ -
21	Number Plate Outer Garnish	\$ 397.00	\$ -
22	Number Plate and Base	\$ 48.00	SN \$ -
23	End Panel Inner	\$ 936.20	\$ -
24	End Panel Outer	\$ 566.10	\$ -
25	End Panel Top Plate	\$ 299.50	\$ -
26	End Panel Sealant	\$ 50.00	SN \$ -
27	Fender (Body Panel)	\$ 1,308.10	\$ -
28	Fender Inner Panel	\$ 1,069.10	\$ -
29	Fender "Corporate" Advertisement & Artwork	\$ 180.00	SN \$ -
	Floor Panel Top Wooden Board	\$ 650.00	SN \$ -
	C/F Balance ---->	\$ 12,995.40	\$ -



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE7663R190620

Final Bill

Customer	Page 02 - 03
Name: AIG Asia Pacific Insurance Pte Ltd	Date: 23-07-19
Address: Motor Claims Department	Vehicle No: GBE7663R
78 Shenton Way #07-16	Model/Make: Toyota Hiace
AIG Building Singapore 079120	3.0 DX Diesel Turbo MT 2WD

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 12,995.40	\$ -
31	Front Bumper	\$ 796.80	\$ -
32	Bumper Beam Center	\$ 217.50	\$ -
33	Bumper Clips 1 set	\$ 50.00	SN \$ -
34	Bumper Bracket	\$ 178.00	\$ -
35	Bumper Side Holders (@ S\$137.20)	\$ 274.40	\$ -
36	Bumper Centre Grille	\$ 155.80	\$ -
37	Bumper Top Beam	\$ 189.60	\$ -
38	Bumper Carbon "Sticker" Lower	\$ 180.00	SN \$ -
39	Grille	\$ 487.70	\$ -
40	Grille Clip 1 set	\$ 35.00	SN \$ -
41	Grille Chrome	\$ 287.50	\$ -
42	Grille Inner	\$ 675.10	\$ -
43	Head Lamp 02 pcs (@ S\$930.70)	\$ 1,861.40	\$ -
44	Head Lamp clips 1 set	\$ 65.00	\$ -
45	Head Lamp Bracket 02 pcs (@ S\$19.70)	\$ 39.40	SN \$ -
46	Radiator	\$ 2,372.30	\$ -
47	Radiator Fan Motor	\$ 624.30	\$ -
48	Radiator Fan Blade	\$ 290.20	\$ -
49	Radiator Fan Cowling	\$ 587.30	\$ -
50	Radiator Coolant 1 bottles	\$ 50.00	SN \$ -
51	Aircon Condenser	\$ 1,448.00	\$ -
52	Number Plate and Base	\$ 48.00	SN \$ -
53	Support Panel	\$ 766.30	\$ -
54	Brace Panel	\$ 434.80	\$ -
55	Aircon Condenser	\$ 1,448.00	\$ -
56	Windscreen Glass Moulding	\$ 303.60	\$ -
57	Windscreen Glass Sealant	\$ 50.00	SN \$ -
	C/F Balance --->	\$ 26,911.40	\$ -



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBE7663R190620

Final Bill

Customer	Page 03 - 03
Name: AIG Asia Pacific Insurance Pte Ltd	Date: 23-07-19
Address: Motor Claims Department	Vehicle No: GBE7663R
78 Shenton Way #07-16	Model/Make: Toyota Hiace
AIG Building Singapore 079120	3.0 DX Diesel Turbo MT 2WD

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 26,911.40	\$ -
31	Front Bumper	\$ 796.80	\$ -
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	\$ -
	To check all wiring & electrical component for proper function	\$ 80.00	\$ -
	Remove and refix rear bumper reverse sensor	\$ 100.00	\$ -
	Remove & reinstall Rear Windscreen Glass to facilitate repairs	\$ 120.00	\$ -
	Remove & reinstall Front Windscreen Glass to facilitate repairs	\$ 120.00	\$ -
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 180.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,500.00	\$ -
	To putty & spray painting & including touch up paint on accident affected	\$ 1,800.00	\$ -
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	\$ -

Total Parts & Labour of estimate for damaged vehicle	\$ 31,768.20
--	--------------

Total amount in Lump Sum Basis for repaired vehicle	\$ 10,800.00
---	--------------

SDLS: Ten Thousand Eight Hundred Only



M/s Liu's Brother Auto Engrg Wks



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**
6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-105650
Date of Request: 02/07/2019

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 02/07/2019
Enquiry By: Susan Low Siew Yian
TP Vehicle No: GBH6891P
Accident Date: 20/06/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBH6891P	AIG Asia Pacific Insurance Pte. Ltd.	23/08/2018-22/08/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-105650
 Date of Request: 02/07/2019

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
 1 Kaki Bukit Ave 6 #01-01
 Auto Bay@Kaki Bukit
 Singapore 417883

Dear Sir/Madam,

Enquiry Date: 02/07/2019
 Enquiry By: Susan Low Siew Yan
 TP Vehicle No.: GBH6891P
 Accident Date: 20/06/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:
 Date:
 GIRO Cash Cheque