

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road I #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : TAN CHEE KEONG (CHEN ZHIQIANG)
 BLK 473D UPPER SERANGOON CRESCENT #15-
 SINGAPORE 538473

Estimate No: EST1504990
 Date: 13 Jul 2019
 Policy No: P10077042R00
 Veh Reg No: SLF349X
 Make/Model: HONDA VEZEL 1.5Z
 HYBRID CVT ABS
 D/AIRBAG 2WD

ATTN: FIRST CAPITAL

Your Ref No: TP 0719-5581
 Claim Type: Third Party
 Accident Date: 28/06/2019
 TP Veh Reg No: SHC 7779 E

Chassis No: RU31208154
 Engine No: LEB5908163
 Reg. Date: 11/08/2016

Estimate Repair Cost to Vehicle No :SLF349X

Description	U/Price	Quantity	Price S\$	Amount S\$
Supplementary Parts to Repair				
List Price				
1 RHR FENDER INNER TRIM	320.8000	1 PCS	320.80	
2 GRILLE TOP BRACKET	45.8000	1 PCS	45.80	
3 BONNET	892.3000	1 PCS	892.30	
4 rear bumperbar	85.40		1,258.90	1,007.12
		Less 20%	251.78	
Special Net				
5 REAR BOOT INNER SOUND ROOF INSULATOR & LABOUR CHARGE	500.0000	1 SER	500.00	500.00
			500.00	500.00
		Total		S\$ 1,507.12
		GST Amount		S\$ 105.50
		Total Amount Payable		S\$ 1,612.62

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

SUPP 1575.44

PARTS 7803.04

SN 380.00

LAD. 4150.00

13908.48