

Kd

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No EST0022632
Banukumar Ramya

Page 1 of 3
Your ref TP-GBC 1296S EQ
Job No 70654
Our ref 19 07 03
Payment
Date 31/12/2019

Attn:

Vehicle No SLX 2851D
Vehicle Model Honda Vezel
Accident on 2/7/2019

Not Authorised
Running B4 per
6 days

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts					
✓ 1.00	Pc	Rear tailgate	550.00		550.00 ✓
✓ 1.00	Pc	Rear tailgate garnish	130.00		130.00 ✓
✓ 1.00	Pc	Rear tailgate lamp LH	140.00		140.00 ✓
✓ 1.00	Pc	Rear tail lamp LH	205.00		205.00 ✓
✓ 1.00	Pc	Rear bumper	180.00		180.00 ✓
✓ 1.00	Pc	Rear bumper garnish LH	65.00		65.00 ✓
✓ 1.00	Pc	Rear end panel	300.00		300.00 ✓
✓ 1.00	Pc	Rear end panel top cover	35.00		35.00 ✓
✓ 1.00	Pc	Rear Vezel emblem	28.00		28.00 ✓
✓ 1.00	Pc	Rear logo emblem	15.00		15.00 ✓
✓ 2.00	Pcs	Rear windscreen mouldings	15.00		30.00 ✓
✓ 1.00	Pc	Rear bumper retainer LH	10.00		10.00 ✓
✓ 4.00	Pcs	Rear bumper lower clips	1.50		6.00 ✓
Total amount of parts supplied - S\$1694.00					
1.00		10% of parts supplied	169.40		169.40

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST No EST0022632
Banukumar Ramya

Page 2 of 3
Your ref TP-GBC 1296S EQ
Job No 70654
Our ref 19.07.03
Payment
Date 3/7/2019

Attn:

Vehicle No SLX 2851D
Vehicle Model Honda Vezel
Accident on 2/7/2019

Quantity	Unit	Description	Unit price	Disc pct	Amount
		Special nett item			
1.00	Pc	Rear number plate	35.00		35.00 ✓
		Labour & Misc			120/-
1.00		To remove & refix rear windscreen	140.00		140.00
1.00		To supply sealant	45.00		45.00 ✓
1.00		To transfer rear parking sensor	40.00		40.00 ✓
1.00		To transfer rear tailgate spoiler	40.00		40.00 ✓
1.00		To transfer rear reversing camera	30.00		30.00 ✓
1.00		To dismantle & refix rear fender side trim, etc	60.00		60.00 ✓
1.00		To straighten rear body including cutting and welding to knock dents on rear floor	800.00		800.00 700/-

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022632
Banukumar Ramya

Page 3 of 3
Your ref TP-GBC 1296S EQ
Job No 70654
Our ref 19.07.03
Payment
Date 3/7/2019

Attn

Vehicle No SLX 2851D
Vehicle Model Honda Vezel
Accident on 2/7/2019

Quantity	Unit	Description	Unit price	Disc pct	Amount
		panel, rear tail lamp panel LH and renew of parts			
1.00		To spray paint (Pearl white)	1,000.00		1,000.00

9000

12

✓
✓
✓
✓
✓
7000

Sub Total 4,053.40
GST 7.00% 283.74
Total SS 4,337.14

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

SUPPLEMENTARY ESTIMATE

EST No EST0022632
Banukumar Raniya

Page 1 of 1
Your ref TP-GBC 1296S EQ
Job No 70654
Our ref 19 07 03
Payment
Date 9/7/2019

Attn

Vehicle No SLX 2851D
Vehicle Model Honda Vezel
Accident on 2/7/2019

Quantity	Unit	Description	Unit price	Disc pct	Amount
SUPPLEMENTARY ITEM					
1.00	Pc	Rear buzzer smart	50.00		50.00
1.00		10% of part supplied	5.00		5.00

Sub-Total 55.00
GST 7.00% 3.85
Total 58.85

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."