

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022632
Banukumar Ramya

Page 1 of 3
Your ref. TP-GBC 1296S EQ
Job No. 70654
Our ref. 19.07.03
Payment
Date 3/7/2019

Attn

Vehicle No SLX 2851D
Vehicle Model : Honda Vezel
Accident on ... 2/7/2019

Not Authorise
Recovery B4 pain
6 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear tailgate	550.00		550.00
1.00	Pc	Rear tailgate garnish	130.00		130.00
1.00	Pc	Rear tailgate lamp LH	140.00		140.00
1.00	Pc	Rear tail lamp LH	205.00		205.00
1.00	Pc	Rear bumper	180.00		180.00
1.00	Pc	Rear bumper garnish LH	65.00		65.00
1.00	Pc	Rear end panel	300.00		300.00
1.00	Pc	Rear end panel top cover	35.00		35.00
1.00	Pc	Rear Vezel emblem	28.00		28.00
1.00	Pc	Rear logo emblem	15.00		15.00
2.00	Pcs	Rear windscreen mouldings	15.00		30.00
1.00	Pc	Rear bumper retainer LH	10.00		10.00
4.00	Pcs	Rear bumper lower clips	1.50		6.00
Total amount of parts supplied - S\$1694.00					
1.00		10% of parts supplied:	169.40		169.40

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022632
Banukumar Ramya

Page 2 of 3
Your ref. TP-GBC 1296S EQ
Job No. 70654
Our ref. 19.07.03
Payment
Date 3/7/2019

Attn

Vehicle No SLX 2851D
Vehicle Model : Honda Vezel
Accident on ... 2/7/2019

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Special nett item:					
1.00	Pc	Rear number plate	35.00	<i>Net/hrs</i>	35.00 <i>&</i>
Labour & Misc:					
1.00		To remove + refix rear windscreen	140.00		140.00 <i>120/</i>
1.00		To supply sealant	45.00		45.00 <i>L</i>
1.00		To transfer rear parking sensor	40.00		40.00 <i>L</i>
1.00		To transfer rear tailgate spoiler	40.00		40.00 <i>L</i>
1.00		To transfer rear reversing camera	30.00		30.00 <i>L</i>
1.00		To dismantle + refix rear fender side trim, etc	60.00		60.00 <i>L</i>
1.00		To straighten rear body including cutting and welding, to knock dents on rear floor	800.00		800.00 <i>For</i>

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 記) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0022632
Banukumar Ramya

Page 3 of 3
Your ref. TP-GBC 1296S EQ
Job No. 70654
Our ref. 19.07.03
Payment
Date 3/7/2019

Attn

Vehicle No SLX 2851D
Vehicle Model : Honda Vezel
Accident on ... 2/7/2019

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		panel, rear tail lamp panel LH and renew of parts			
1.00		To spray paint (Pearl white)	1,000.00		1,000.00

9000

10/1/19 =

Sub-Total 4,053.40
GST 7.00% 283.74
Total S\$ 4,337.14

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support jolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."