

ASS. REC. BY:

REF: CSK1119011828/ Evt3n2

Special Instruction:

Surveyor: STAVE

ASSIGNMENT (Office)

From (Person): Ong Chin Kiat

of CT1

Date/Time: 3.7.19 15.48 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SW 2194X

Insured:

SJC 2113

at Workshop m/s

My Car Con SULTAN

Tel:

98686000 / 88668832

of 5346 Ave 1 #01-33

Policy No:

DMPCN30257519000

Claim No:

SNM19D20302502

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

4.7.19 9.59 AM

Person Contacted:

Kai King

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SW 2194X - MAI INC 190114681 24 ROK - 28/06/2019
	SJC 2113 - X

Steve

CTI

ASSIGNMENT

11/03/10

From: Date: 4-7-2019

Estimated Cost

OD (IP) WS / TP RES / OD RES / EVA / HV / MV

To inspect Vehicle No: SJW 2194X

at Workshop ref: My Car Consultant

at 53 ubi Ave 1 #01-33

Insured:

Policy No:

Claim No:

Car Insured:

Excess:

(Client's Name)

Model of Vch:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Est. or Market Value:

ADAC Accident Report

Consistent? Yes or No

ADA / PTC Query

Consistent? Yes or No

Est. Reporting

days

Res

Yes or No

Est. Claim

%

Vol

Yes or No

CA / REV / REP / 24 HRS

my

Vehicle: IN / OUT

Date:

Person Contacted

Date / Time

Action / Instruction

MV- 20,950

PV- 13,195

NV- 6895

Finalize 7K, 14 days

(Real 24,494.73, 78%)

RECEIVED 23 JUL 2019

Client Email, File Photo etc

☐

Prof. Report

0

☐

Final Report

Client Email, File Photo etc

23h -typist

Report Format:

merimen

Lump Sum / L.B.L (\$

7000f

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

Vehicle

SJW 2194X

Vt Regn:

Type: ☒ Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

Colour:

Black

Chassis No:

158966

Engine:

CAT:

JH1M6E 88599523496

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ border / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ border / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / ☒ STD / ☐ STD AIR / ☐ or

Type Size:

F:

295/502R16

R:

k

BS ☒ DUN / ☐ EXHNOVA / ☐ GY / ☐ TS / ☐ LIZA / ☐ MIC / ☐ OHISU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/dal

6

mm

R/dal

6

mm

L/dal

6

mm

L/dal

6

mm

D.O.A

28/6/19

D.O.A

4/7/19

Survey held at

My Car Consultant

Dist. of Damages: ☒ Front / ☒ Rear / ☐ Q/S / ☐ N/S / ☐ D/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

22/7/19

5/7

Client Email, File Photo etc

☐

Prof. Report

0

☐

Final Report

Client Email, File Photo etc

23h -typist

Report Format:

merimen

Lump Sum / L.B.L (\$

7000f

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

Survey Fee:

Transportation

23h -typist

Others

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jul 2019		03 Jul 2019 15:48 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TOH WILSON, ID: S82002168								
Main Claimant:	LIM JIA HUI BARRY, ID: S9112105J								
Vehicle Reg. No.:	SJW2194X	Date of Loss:	28/06/2019 07:00 - :59 [111 Months and 17 Days From LTA Reg Date (Mon Yr)]						
Claim Type:	TP / SNM19D203025C02	Policy/Cover Note No.:	DMPCSN30257519000						
Vehicle Reg. No. (Insured):	SJX221J	Policy No. (Claimant):	S097552929-01						
		Excess:	S\$0.00						
Repairer:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/07/2019]								
Driver/Custodian (Insured):	TOH WILSON (37 / Male) , NRIC: S82002168 Email:								
Adj Asg. Remarks:	please contact Kai Ling at 9868 6000 to arrange for survey. thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Steve Chen (LKK Auto)

From: Steve Chen (LKK Auto)
Sent: Monday, July 22, 2019 6:27 PM
To: admin@mycar.sg
Subject: SJW2194Y Repair Limit

Dear HuiQin,

We confirm the finalize 7k (L/S, before GST). 14 days.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor
LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: My Car Consultant [<mailto:admin@mycar.sg>]
Sent: Monday, July 22, 2019 12:55 PM
To: Steve Chen (LKK Auto)
Subject: re: SJW2194Y Repair Limit

WITHOUT PREJUDICE

Dear Steve,

I'd like to close this case base on your suggested quantum at:

\$7,000.00 (Repair limit) & 14 repair days

Best Regards,

Huiqin

Direct line: 88668832 | Fax: 69255219

My Car Consultant Pte Ltd
53 Ubi Avenue 1
Paya Ubi Industrial Park #01-33
Singapore 408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

From: "Steve Chen (LKK Auto)" <SteveChen@lkkauto.com>
Sent: Tuesday, July 16, 2019 7:46 PM
To: "My Car Consultant" <admin@mycar.sg>
Subject: SJW2194Y Repair Limit

Dear HuiQin,

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2105J

Vehicle Details

Vehicle No.:	SJW2194X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Jul 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5L AT ABS D/AB HID 2WD 5DR
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	L15A71004316
Chassis No.:	JHMG88509S203496
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$23,615.00
Original Registration Date:	11 Mar 2010
First Registration Date:	11 Mar 2010
Transfer Count:	2
Actual ARF Paid:	\$23,615.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Mar 2020
PARF Rebate Amount:	\$11,807.00

Intended COE Rebate Details

COE Expiry Date:	10 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$17,274.00
COE Rebate Amount:	\$1,388.00
Total Rebate Amount:	\$13,195.00

The information contained herein is correct as at 04 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/06/2019 14:53
Date Of Accident	28/06/2019 07:10
Exact Location Of Accident	ALONG BKE TOWARDS KJE AFTER MANDAI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJW2194X
Insured/Policyholder	
Name Of Registered Owner	LIM JIA HUI BARRY
NRIC No	S9112105J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98217662
Alternative Phone No	OTHERS-98217662

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ 1.5L AT ABS D/AB HID 2WD 5DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097552929-01
Cover Note Number	

Driver

Name of Driver	LIM JIA HUI BARRY
NRIC No	S9112105J
Date Of Birth	06/04/1991
Occupation	INDOOR
Date Of Driving Pass	28/01/2015
Driving Experience	4 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98217662
Fax Number	
Contact Number	OTHERS-98217662
EMail Address	NOEMAIL

Address	BLK 351D CANBERRA ROAD #14-279
Postcode	754351
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8529999 - FAX NO: 68522299
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT : T/20190628/2060

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJX221J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TOH WILSON
NRIC/Passport Number	S8200216B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJQ2323Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AMIN BIN HARON
NRIC/Passport Number	S1628302I
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 280619 0920H

Driver's Signature

(if driver is not the policyholder)


Date & Time: 280619 0920H

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

PS PER POLICE REPORT.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: 28/06/19 09:20H

Driver's Signature: JA
(If driver is not the policyholder)
Date & Time: 10/6/9 09:04

Reporting Centre Personnel's Signature
Name: _____
NRIC/PIN No.: _____



**SINGAPORE
POLICE FORCE**



T/20190628/2060

1 of 4

Report No. T/20190628/2060

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 758827
Tel No: 1800-8529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/06/2019 12:03		Vide Report No.:		Station Diary No.: 93	
Informant's Particulars					
Name of Informant: LIM JIA HUI, BARRY			Address: APT BLK 351D CANBERRA ROAD #14-279 SINGAPORE 754351		
ID Type / ID No.: NRIC NO / S9112105J			Contact No.: Home/Office: Mobile: 98217662		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 28	Date of Birth: 06/04/1991	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: REGULAR SAF			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 28/06/2019 07:10	Type of Location: Straight Road
Location: Along Road 1 BUKIT TIMAH EXPRESSWAY KRANJI EXPRESSWAY BKE TOWARDS KJE AFTER MANDAI EXIT				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Colour	Condition	No. of Pass. Inher.
SJQ2323Y	Car					0
SJW2194X	Car	HONDA	JAZZ 1.5L AT ABS D/AB HD 2WD 5DR	Black	Seriously Damaged	0
SUX221J	Car					0



**SINGAPORE
POLICE FORCE**



T/20190628/2050

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

2 of 4

Report No: T/20190628/2050

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SJW2194X	NTUC Income Insurance Co-Operative Limited	5097552929-01	11/03/2019	10/03/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Driver				
Name	AMIN BIN HARON		ID No.	S16283021
Related Vehicle	SJQ2323Y (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	LIM JIA HUI, BARRY		ID No.	S9112105J
Related Vehicle	SJW2194X (Car)		Contact No.	98217662
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	TOH WILSON		ID No.	S8200216B
Related Vehicle	SJX221J (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999



T/20190626/2669

1 of 4

Report No: T/20190626/2669

CONTINUATION OF REPORT

Brief Details.

On 28/06/2019 at about 0710hrs, I was driving my vehicle along BKE towards KJE and that time the traffic volume was heavy. There was a vehicle (SJQ2323Y) in front me suddenly jam brake. I applied brake as well and out of sudden I felt impact from behind, my vehicle moved forward and collided into the said vehicle in front of me. The vehicle that collided onto rear side of my vehicle is SJX221J. That time no one injure and we exchanged particulars.

I wish to state that my vehicle doesn't have any in-car camera.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999



TQ201905280060

Report No: TQ201905280060

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report
L/
Sgt 3 FOO CHEA YEE

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
20/06/2019 12:03

Officer In Charge Of Case:
TP / GIA /
(Staff Sgt WONG SIEU LUI)
Contact No. - 65476151

Classification Of Case:

Authentication Stamp
NP108





MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:
Vehicle:
Make / Model:
Chassis:

4 Jul 19
SJW2194Y
HONDA / FIT

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	FRONT BUMPER / OR	1		\$ 730.40
2	FRONT BUMPER SIDE RETAINER / OR	2	1 pc - 20	\$ 150.50
3	FRONT BUMPER REINFORCEMENT / OR	1		\$ 415.40
4	FRONT BUMPER CENTR GRILLE / OR	1		\$ 316.70
5	FRONT BUMPER TOW COVER / MIS	1		\$ 87.10
6	FRONT BUMPER SIDE GRILLE / CRU	1		\$ 107.40
7	FRONT GRILLE / OR	1		\$ 315.20
8	FRONT GRILLE EMBLEM / APC	1		\$ 56.20
9	FRONT SUPPORT PANEL / OR	1		\$ 763.90
10	FRONT HEADLAMP / OR	2		\$ 1,537.40
11	FRONT FENDER LH-R RH - OR	2		\$ 1,390.30
12	FRONT FENDER INNER SHIELD X NAI	2		\$ 314.80
13	BONNET / OR	1		\$ 864.20
14	BONNET LOCK / OR	1		\$ 161.50
15	BONNET HINGE / OR	2		\$ 70.00
16	AIR CONDENSER / OR	1		\$ 837.50
17	AIRCON MOTOR ? X NAI	1		\$ 483.80
18	AIRCON FAN COWLING ? / OR	1		\$ 187.40
19	RADIATOR ASSY / OR	1		\$ 1,615.29
20	RADIATOR FAN MOTOR ? X NAI	1		\$ 631.30
21	RADIATOR FAN COWLING ? / OR	1		\$ 213.49
22	REAR NUMBER PLATE LAMP ? X NAI	2		\$ 155.90
23	REAR BUMPER / OR	1		\$ 890.80
24	REAR BUMPER RETAINER / OR	2	1 pc - 30	\$ 160.00
25	REAR END PANEL / OR	1		\$ 796.60
26	END PANEL TOP GARNISH ? / CRU	1		\$ 260.80
27	REAR TAILLAMP / OR	2		\$ 810.40
28	TAILGATE / OR	1		\$ 1,662.70
29	TAILGATE ABSORBER X NAI	2		\$ 321.00
30	TAILGATE EMBLEM ? X NAI	1		\$ 70.00
31	TAILGATE EMBLEM - (Jazz) / APC	1		\$ 54.00
32	TAILGATE OUTER GARNISH ? X NAI	2		\$ 325.20
33	TAILGATE INNER HANDLE ? X NAI	1		\$ 139.00
34	TAILGATEWIPER MOTOR X NAI	1		\$ 440.70
35	REAR TAILGATE GLASS X NAI	1		\$ 1,309.10
36	REAR TAILGATE GLASS MOULDING / APC	1		\$ 135.00
37	TAILGATE LOCK / OR	1		\$ 290.10
38	TAILGATE LOCK STRIKER X NAI	1		\$ 155.00
39	TAILGATE HINGE X NAI	2		\$ 179.00
40	TAILGATE WEATHERSTRIP / CRU	1		\$ 193.50
41	TAILGATE INNER BOARD / CRU	1		\$ 774.00
42	SPARE TYRE TOP BOARD ? X NAI	1		\$ 292.50
43	FLOOR COMPARTMENT ? X R	1		\$ 1,237.73
44	REAR FENDER INNER TRIM ? X RPT Rd	2		\$ 2,422.00
45	REAR FENDER INNER PANEL ? X NAI	2		\$ 1,218.00
46	REAR TAILLAMP PANEL ? X NAI	2		\$ 689.20
47	REAR FENDER INNER TRIM ? / CRU	2	1 pc - 266	\$ 810.30
48	REAR TAILGATE UPPER SIDE GARNISH ? X NAI	2		\$ 390.10
49	REAR FENDER AIR VENT ? X NAI	2		\$ 190.30
50	REAR EXHAUST ASSY ? X NAI	1		\$ 862.90
51	REAR EXHAUST MOUNTING ? X NAI	2		\$ 120.30

11,473.69
- 20%
9178.95

S/NETT ITEMS

52
53
54
55
56
57
58
59
60
61
62

FRONT NUMBER PLATE / BR
FRONT BUMPER CLIP / APC
COOLANT / APC
REAR NUMBER PLATE / RWT
REAR REVERSE CAMERA x NN
REAR REVERSE SENSOR / BR
REAR BUMPER CLIP / APC
REAR FENDER INNER TRIM CLIP / APC
FLOOR INSULATOR / APC
JOINT SEALANT / APC
WINDSCREEN SEALANT / APC (Rear)

1 SET
1 SET
1
1
1
1 SET
1 SET
1 SET
1
1
1

\$ 28,605.91
\$ 5,721.18
\$ 22,884.73
\$ 60.00
\$ 50.00
\$ 60.00
\$ 60.00
\$ 500.00
\$ 300.00
\$ 60.00
\$ 50.00
\$ 150.00
\$ 150.00
\$ 150.00
\$ 1,590.00

75
70
20
35
800
200
70
20
50
60
40

Parts Total:

\$ 24,474.73

Labour to:

63
64
65
66
67
68
69
70
71
72
73
74
75

CHECK FRONT, REAR WIRING AND LIGHTNING SYSTEM
REMOVE, RENEW CONDENSER AND TOP UP GAS
REMOVE, RENEW RADIATOR AND TOP UP COOLANT
REMOVE, REFIT REAR LINING, TRIM AND GARNISH
REMOVE AND RENEW REAR REVERSE SENSOR
REMOVE AND RENEW REAR EXHAUST ASSY
REMOVE AND REFIT FUEL TANK
REMOVE AND RENEW FLOOR INSULATOR
REMOVE AND REFIT REAR WINDSCREEN
TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW
PANEL BEATING ON AFFECTED AREAS
SPRAY PAINTING ON AFFECTED AREAS
APPLY ANTI RUST ON AFFECTED AREAS

\$ 70.00
\$ 150.00
\$ 150.00
\$ 200.00
\$ 150.00
\$ 150.00
\$ 150.00
\$ 150.00
\$ 150.00
\$ 200.00
\$ 1,500.00
\$ 1,400.00
\$ 200.00
\$ 4,620.00

30
100
50
50
20
50
x
20
100
50
1400
30
3310

29094.73

Grand total:

\$ 31,494.73

Store (LKK) will provide 4/7/19
14 days

L/S
Rng AF Spg

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 9178.95
N- 520
L- 3310
13,008.95
L/S- 10,497.16
= 10400

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119011828/EVD3N2

Date: 26/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30257519000	
Claimant Vehicle No :	SJW2194X	Insured Vehicle No :	SJX221J	
Date of Loss:	28/06/2019	Nature of Claim:	TP	Claim No: SNM19D203025C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW2194X		
Make & Model:	HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)	Engine No:	L15A71004316
Reg. Date:	11/03/2010 (Man. Year: 2008)	Chassis No:	JHMGE88509S203496
Colour:	Black	Odometer:	158966 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50ZR16	Rear Tyre Size:	205/50ZR16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	24,474.73	9,698.95	14,775.78	60.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,620.00	3,310.00	1,310.00	28.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,094.73	13,008.95	16,085.78	55.29
Approved Total (Overridden) (S\$)		7,000.00		
Nett Amount (S\$)	29,094.73	7,000.00	22,094.73	75.94

INSPECTION

Date of Assignment:	03/07/2019	
Date Inspected:	04/07/2019 Inspected At:	My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park Singapore 408934

Estimated Period of Repair: 14.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2019)
Parts:	144	HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW2194X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Broken	730.40 FL	*523.00 FL
2	2	*FRONT BUMPER SIDE RETAINER	Broken	150.50 FL	*40.00 FL
3	1	*FRONT BUMPER REINFORCEMENT	Dented	415.40 FL	*245.00 FL
4	1	*FRONT BUMPER CENTR GRILLE	Broken	316.70 FL	*189.00 FL
5	1	*FRONT BUMPER TOW COVER	Missing	87.10 FL	*58.00 FL
6	1	*FRONT BUMPER SIDE GRILLE	Crushed	107.40 FL	*68.00 FL
7	1	*FRONT GRILLE	Broken	315.20 FL	*315.20 FL
8	1	*FRONT GRILLE EMBLEM	Necessary	56.20 FL	*56.20 FL
9	1	*FRONT SUPPORT PANEL	Dented	763.90 FL	*637.00 FL
10	2	*FRONT HEADLAMP	Broken	1,537.40 FL	*1,537.40 FL
11	1	*FRONT FENDER	O/s Dented/N/s Repair	1,390.30 FL	*398.00 FL
12	2	*FRONT FENDER INNER SHIELD	Not Necessary	314.80 FL	*- FL
13	1	*BONNET	Dented	864.20 FL	*548.00 FL
14	1	*BONNET LOCK	Bent	161.50 FL	*161.50 FL
15	2	*BONNET HINGE	Bent	70.00 FL	*70.00 FL
16	1	*AIR CONDENSER	Dented	837.50 FL	*762.00 FL
17	1	*AIRCON MOTOR	Not Necessary	483.80 FL	*- FL
18	1	*AIRCON FAN COWLING	Broken	187.40 FL	*187.40 FL
19	1	*RADIATOR ASSY	Broken	1,615.29 FL	*1,137.00 FL
20	1	*RADIATOR FAN MOTOR	Not Necessary	631.30 FL	*- FL
21	1	*RADIATOR FAN COWLING	Broken	213.49 FL	*213.49 FL
22	2	*REAR NUMBER PLATE LAMP	Not Necessary	155.90 FL	*- FL
23	1	*REAR BUMPER	Broken	890.80 FL	*890.80 FL
24	2	*REAR BUMPER RETAINER	Broken	160.00 FL	*60.00 FL
25	1	*REAR END PANEL	Dented	796.60 FL	*276.00 FL
26	1	*END PANEL TOP GARNISH	Crushed	260.80 FL	*260.80 FL
27	2	*REAR TAILLAMP	Broken	810.40 FL	*810.40 FL
28	1	*TAILGATE	Dented	1,662.70 FL	*771.00 FL
29	2	*TAILGATE ABSORBER	Not Necessary	321.00 FL	*- FL
30	1	*TAILGATE EMBLEM	Not Necessary	70.00 FL	*- FL
31	1	*TAILGATE EMBLEM (JAZZ)	Necessary	54.00 FL	*54.00 FL
32	2	*TAILGATE OUTER GARNISH	Not Necessary	325.20 FL	*- FL
33	1	*TAILGATE INNER HANDLE	Not Necessary	139.00 FL	*- FL
34	1	*TAILGATE WIPER MOTOR	Not Necessary	440.70 FL	*- FL
35	1	*REAR TAILGATE GLASS	Not Necessary	1,309.10 FL	*- FL
36	1	*REAR TAILGATE GLASS MOULDING	Necessary	135.00 FL	*135.00 FL
37	1	*TAILGATE LOCK	Bent	290.10 FL	*189.00 FL
38	1	*TAILGATE LOCK STRIKER	Not Necessary	155.00 FL	*- FL
39	2	*TAILGATE HINGE	Not Necessary	179.00 FL	*- FL
40	1	*TAILGATE WEATHERSTRIP	Crushed	193.50 FL	*193.50 FL
41	1	*TAILGATE INNER BOARD	Crushed	774.00 FL	*155.00 FL
42	1	*SPARE TYRE TOP BOARD	Not Necessary	292.50 FL	*- FL
43	1	*FLOOR COMPARTMENT	Repair	1,237.73 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	2		*REAR FENDER INNER TRIM	Repeated	2,422.00 FL	*- FL
45	2		*REAR FENDER INNER PANEL	Not Necessary	1,218.00 FL	*- FL
46	2		*REAR TAILLAMP PANEL	Not Necessary	689.20 FL	*- FL
47	2		*REAR FENDER INNER TRIM	Crushed	810.30 FL	*532.00 FL
48	2		*REAR TAILGATE UPPER SIDE GARNISH	Not Necessary	390.10 FL	*- FL
49	2		*REAR FENDER AIR VENT	Not Necessary	190.30 FL	*- FL
50	1		*REAR EXHAUST ASSY	Not Necessary	862.90 FL	*- FL
51	2		*REAR EXHAUST MOUNTING	Not Necessary	120.30 FL	*- FL
52	1		*SET FRONT NUMBER PLATE	Broken	60.00 FS	*35.00 FS
53	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
54	1		*COOLANT	Necessary	60.00 FS	*20.00 FS
55	1		*REAR NUMBER PLATE	Cut	60.00 FS	*35.00 FS
56	1		*REAR REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
57	1		*SET REAR REVERSE SENSOR	Broken	300.00 FS	*200.00 FS
58	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
59	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*20.00 FS
60	1		*FLOOR INSULATOR	Necessary	150.00 FS	*50.00 FS
61	1		*JOINT SEALANT	Necessary	150.00 FS	*60.00 FS
62	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,195.91	11,993.69
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,721.18	2,294.74
Total Parts (\$\$)	24,474.73	9,698.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK FRONT,REAR WIRING AND LIGHTING SYSTEM	New	70.00	30.00
2	REMOVE,RENEW CONDENSER AND TOP UP GAS	New	150.00	100.00
3	REMOVE,RENEW RADIATOR AND TOP UP COOLANT	New	150.00	50.00
4	REMOVE,REFIT REAR LINING,TRIM AND GARNISH	New	200.00	50.00
5	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	20.00
6	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	50.00
7	REMOVE AND REFIT FUEL TANK	New	150.00	0.00
8	REMOVE AND RENEW FLOOR INSULATOR	New	150.00	30.00
9	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	100.00
10	TRANSFER PARTS,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	50.00
11	PANEL BEATING ON AFFECTED AREAS	New	1,500.00	1,400.00
12	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	1,400.00
13	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	30.00
Gross Labour Cost (S\$)			4,620.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >