

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 7798K

DATE 3/7/2019 14:47

MAKE :

MODEL : HYUNDAI IONIQ

| Qty  | Parts Description/ Labour                          | Type | Unit Price | Amount                |
|--|--|------|------------|-----------------------|
|  | Rear Bumper <i>X repair</i>                        |      |            | \$ 459.40             |
|  | Rear Bumper Reinforcement Bracket (LH/RH) <i>X</i> |      | \$ 138.10  | \$ 276.20             |
|  | Rear Bumper Centre Moulding Assy <i>Return</i>     |      |            | \$ 451.25             |
|  | Rear Bumper Lower Centre Moulding Assy <i>X</i>    |      |            | \$ 47.50              |
|  | Rear Bumper Side Bracket (LH/RH) <i>X</i>          |      | \$ 33.10   | \$ 66.20              |
|  | Rear Bumper Cover Clips <i>X</i>                   |      |            | \$ 22.00              |
|  | <b>SUB TOTAL</b>                                   |      |            | <b>\$ 1,322.55</b>    |
|  | <b>LESS 20%</b>                                    |      |            | <b>\$ 264.51</b>      |
|  | <b>DISCOUNTED TOTAL</b>                            |      |            | <b>\$ 1,058.04</b>    |
|  | Rear Bumper Reserve Sensor <i>X</i>                |      |            | \$ 135.70 <b>Nett</b> |
|  | Rear Bumper Rubber Mat <i>X</i>                    |      |            | \$ 50.00 <b>Nett</b>  |
|  |  |      |            | <b>\$ 185.70</b>      |
|  | <b>Labour Charge</b>                               |      |            | <b>200</b>            |
|  | Panel Beating                                      |      |            | \$ 400.00             |
|  | Spray Painting Charge                              |      |            | \$ 300.00 <b>200</b>  |
|  | Wiring Charge                                      |      |            | \$ 50.00 <i>X 20</i>  |
|  | Remove/Refix Reverse Sensor                        |      |            | \$ 120.00 <i>X 20</i> |
|  | <b>TOTAL LABOUR</b>                                |      |            | <b>\$ 870.00</b>      |
|  | <b>ESTIMATE TOTAL</b>                              |      |            | <b>\$ 2,113.74</b>    |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. |  |      |            |                       |

LKX Auto Consultants hence notify  
 the Repairer of the following:  
 • To reserve before/after spray painting  
 • To reserve damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

*Kahin 1004*  
*4/7/19 13:15h*  
*200*  
*PIP*  
*After Repair 1004*