

新合利服務公司
Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

1 July 2019

Attn: Motor Claim Department
AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

Lim Puay Tiang
c/o Sin Hup Lee Service Co.
Block 1005 Bukit Merah Lane 2 #01-20
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic Accident on 21 June 2019 at 20 Marlene Avenue, involving vehicle EE747T / SMF1410H

Quotation for Repair Vehicle No: SMF1410H, Honda Civic (Third Party Claim)

Quantity	List Item		
1	Front Grille	\$	173.80 <i>crn</i>
1	Front Grille Logo	\$	36.70 <i>per</i>
1	Front Grille Chrome	\$	247.40 <i>Crn</i>
1	Front Grille Garnish	\$	149.30 <i>crn</i>
1	Front Grille Top Cover	\$	38.20 <i>de</i>
10	Front Grille Clip	\$	39.00 <i>per</i>
2	Head Lamp LH <i>+RH</i>	<i>585.70 LH-CR</i> \$	1,171.40 <i>LH-X777</i>
1	Head Lamp Chrome LH	\$	195.60 <i>cut</i>
1	Head Lamp Lower Bracket LH <i>+RH</i>	\$ <i>de</i>	38.80 77.60
1	Head Lamp Clip	\$	3.50 <i>per</i>
1	Support Side Garnish LH <i>grille</i>	\$	59.70 <i>de</i>
1	Front Bumper	\$	597.90 <i>de</i>
1	Front Bumper Garnish	\$	96.30 <i>de + m</i>

1	Front Bumper Reinforcement	\$	345.90 <i>X n</i>
1	Front Bumper Bracket LH	\$	38.90 <i>per</i>
1	Front Bumper Side Bracket LH	\$	29.40 <i>per</i>
1	Front Bumper Side Garnish LH	\$	57.50 <i>at</i>
1	Front Bumper Lower Grille	\$	72.40 <i>X n</i>
10	Front Bumper Clip	\$	39.00 <i>per</i>
		\$	2369.20
		\$	1895.36
		Less 20%	\$ 686.14
		\$	2,744.56

S/NETT ITEM

1	Front No Plate	\$	45 <i>67</i> / 50.00
---	----------------	----	----------------------

Labour

1	To cut-weld and repair Front Fender LH, Bonnet, Support Panel and re-fix damaged parts, straighten and realign affected areas.	\$	500.00 <i>300</i>
2	To spray Bonnet, Front Fender LH, Support Panel, Front Bumper and affected area	\$	680.00 <i>400</i>
3	To programme and focus Head Lamp for function	\$	180.00 <i>100</i>

Total Amount \$ 4,154.56 *845*

Kindly arrange your surveyor to survey my vehicle.
We look forward to hear from you soon. Thank you.

Yours Faithfully
Mr Wong
81122116

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--

*To Inform Mr Wong
COR 2/582200, 3days
01/10/19*

*2740.36
4/582200
3days
Taufik 97495749
WP
3/7/19 @ 1045
Lumpsum
Resurvey after repair
taufik e lkk auto con
3days*