

INSURANCE

INS. CASE OWNER:

Shwini

CC 4 / III 1901

1851, 72

LKK:

IDAC:

Surveyor:

Tanish

DOI:

ASSIGNMENT

4/7/19

Date / Time:

4/7/19

Registered in Merimen:

4/7/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 4862E

Name of Insured:

COMFORT TRANSPORTATION PTE LTD

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

29/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SHA 959K



INSRS:
WSP:
Tel:
Liability:
RMKS:

ong
moto



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
		Non-Reporting Itr (1st):	
		Non-Reporting Itr (2nd):	
		Non-Reporting Itr (Final):	
		Notification Itr (if non-pickup):	
		Call OI:	
		After call Itr to OI:	
		Documentation Check List:	Handler Typist
		Notification Itr (if non-pickup):	☒
		After call Itr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☒
		Towing Invoice:	☒
		LTA / GIA:	☒
		Medical Bill:	☒
		PIR:	☒
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☒
		Post-Repair Photos:	☒
		Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by: Tanish
--------------	------------	---------------	--------------------

Repair Cost: PIP	SS 5334.18	(5 days) Reduction: 4378.18	% 41
------------------	------------	------------------------------	------

FINAL SETTLEMENT	Date/Time: 15/7/2020	Confirm with: Tanish	Email ☒ Call ☐
------------------	----------------------	----------------------	---

Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	26
------------------	-------	-----------------------------------	----

Repair Cost:	SS 5334.18		
--------------	------------	--	--

Loss of Rental (LOR):	SS 7170.00	(10 days) x \$717	
-----------------------	------------	--------------------	--

Loss of Use (LOU):	SS -	(5 x days)	
--------------------	------	------------	--

Loss of Income (LOI):	SS 400.00	540 x 10 days)	
-----------------------	-----------	----------------	--

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☒	[Tick only one]		
---	-----------------	--	--

GIA/LTA Search:	SS 7.45		
-----------------	---------	--	--

Medical:	SS -		
----------	------	--	--

Disbursement:	SS -	(e.g. Tow/ Independent)	
---------------	------	-------------------------	--

Legal Cost:	SS -		
-------------	------	--	--

Total:	SS 7502.23	Global Sum SS:	7500.00
--------	------------	----------------	---------

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☒ Call ☐
---------------	------------	---------------	---

Payee 1:	SS 7300.00	Name 1:	Ding Automotive Pte Ltd
----------	------------	---------	-------------------------

Payee 2: (Strike if N.A.)	SS -	Name 2:	
---------------------------	------	---------	--

Payee 3: (Strike if N.A.)	SS -	Name 3:	
---------------------------	------	---------	--

COPY SENT
4/3/2020

Tanfield

IV

SHA9759K 2019 June

Hyundai / orig 1580
Yellow 890

KMH6851CV1C4164382

Year: 2019 / 2018 / 2017 / 2016

Color: 2019 / 2018 / 2017 / 2016

Model: 2019 / 2018 / 2017 / 2016

Year: 2019 / 2018 / 2017 / 2016

195/65R15

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016


2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016

2019 / 2018 / 2017 / 2016



P/P \$5537.18/- (Red - \$3781.18/411.7)

* 5 repair days + 4. PRS + 1 Sunday = 10 days

Report Type: ☐ Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ 1st Trip: 0
☐ 2nd Trip: 0
☐ 3rd Trip: 0
☐ 4th Trip: 0

Report Format:

Emp Sum (1/1/1/1)

Customer Name	
Customer Address	
Customer Phone	
Customer Email	
Customer Signature	

DING AUTOMOTIVE PTE LTD

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575545

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

02/07/2019 18:03

OWNER'S PARTICULARS

JOB-NO: 50111791

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE

64739522

SINGAPORE 575717 0

VEHICLE DETAILS

LICENSE NO: SHA9759K

TRANS: AUTO

CHASSIS: KMHC851CVKU164382

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 Di

ENGINE: G4LEKU296066

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,100.00	0.00	1,100.00		Y	700
2 RUST PROOFING	1.00	80.00	0.00	80.00		Y	30
3 SUNDRIES <i>NL</i>	1.00	50.00	0.00	50.00		Y	30
4 R&R FRONT DOOR COMPONENTS LH	1.00	100.00	0.00	100.00		Y	60
5 R&R REAR DOOR COMPONENTS LH	1.00	100.00	0.00	100.00		Y	x nn
6 TO CALIBRATE POWER WINDOW (AUTO POSITION)	1.00	180.00	0.00	180.00		Y	180
7 DIAGNOSTIC (CLEAR FAULT CODE)	1.00	200.00	0.00	200.00		Y	100
8 RESPRAY FRONT FENDER LH	1.00	250.00	0.00	250.00		Y	200
9 RESPRAY FRONT DOOR LH	1.00	250.00	0.00	250.00		Y	200
10 RESPRAY REAR DOOR LH	1.00	250.00	0.00	250.00		Y	200
11 RESPRAY REAR FENDER LH	1.00	250.00	0.00	250.00		Y	200
12 RESPRAY FRONT WINDSCREEN PILLAR LH	1.00	250.00	0.00	250.00		Y	100
TOTAL		3,060.00	0.00	3,060.00			1900
MATERIALS							
1 FRONT FENDER LH	1.00	659.50	131.90	527.60	L	Y	bt
2 FRONT FENDER EMBLEM LOGO LH	1.00	36.50	7.30	29.20	L	Y	ne
3 FRONT FENDER QTR GARNISH LH	1.00	65.12	13.02	52.10	L	Y	but
4 SIDE MIRROR LH	1.00	1,054.60	210.92	843.68	L	Y	Rx
5 FRONT DOOR LH	1.00	2,256.83	451.37	1,805.46	L	Y	bt
6 FRONT DOOR OUTER HANDLE LH	1.00	168.90	33.78	135.12	L	Y	wt
7 FRONT DOOR OUTER MOULDING LH	1.00	87.65	17.53	70.12	L	Y	wt
8 FRONT DOOR OUTER HANDLE PAD LH	1.00	20.88	4.18	16.70	L	Y	IX nn
9 REAR DOOR LH	1.00	2,201.00	440.20	1,760.80	L	Y	Rx
10 TAIL LAMP LH	1.00	903.22	180.64	722.58	L	Y	as
11 REPAIR FRONT WINDSCREEN PILLAR LH	1.00	0.00	0.00	0.00	S	Y	Rx
12 FRONT DOOR STICKER-COMFORT DELGRO LH	1.00	100.00	0.00	100.00	S	Y	ne
13 REAR DOOR STICKER-COMFORT DELGRO LOGO LH	1.00	100.00	0.00	100.00	S	Y	ne
14 REAR DOOR STICKER-BOOK NOW & APP STORE LH	1.00	80.00	0.00	80.00	S	Y	ne
15 REPAIR REAR FENDER LH	1.00	0.00	0.00	0.00	S	Y	Rx
16 TAIL LAMP HOLD CLIP LH	1.00	15.00	0.00	15.00	S	Y	ne
TOTAL		7,749.20	490.84	6,258.36			
TOTAL PARTS & LABOUR		10,809.20	1,490.84	9,318.36			3637.18

DING AUTOMOTIVE PTE LTD

Bix 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575545

Tel: 6452 1208 Fax: 6452 0014

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

02/07/2019 18:03

JOB-NO: 50111791

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE

64739522

SINGAPORE 575717 0

VEHICLE DETAILS

LICENSE NO: SHA9759K

TRANS: AUTO

CHASSIS: KMHC851CVKU164382

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 Di

ENGINE: G4LEKU296066

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,100.00	0.00	1,100.00		Y	700
2 RUST PROOFING	1.00	80.00	0.00	80.00		Y	30
3 SUNDRIES	1.00	50.00	0.00	50.00		Y	30
4 R&R FRONT DOOR COMPONENTS LH	1.00	100.00	0.00	100.00		Y	60
5 R&R REAR DOOR COMPONENTS LH	1.00	100.00	0.00	100.00		Y	x
6 TO CALIBRATE POWER WINDOW (AUTO POSITION)	1.00	180.00	0.00	180.00		Y	180
7 DIAGNOSTIC (CLEAR FAULT CODE)	1.00	200.00	0.00	200.00		Y	100
8 RESPRAY FRONT FENDER LH	1.00	250.00	0.00	250.00		Y	200
9 RESPRAY FRONT DOOR LH	1.00	250.00	0.00	250.00		Y	200
10 RESPRAY REAR DOOR LH	1.00	250.00	0.00	250.00		Y	200
11 RESPRAY REAR FENDER LH	1.00	250.00	0.00	250.00		Y	200
12 RESPRAY FRONT WINDSCREEN PILLAR LH	1.00	250.00	0.00	250.00		Y	100
TOTAL:		3,060.00	0.00	3,060.00			
MATERIALS							
1 FRONT FENDER LH	1.00	659.50	131.90	527.60	L	Y	bt
2 FRONT FENDER EMBLEM LOGO LH	1.00	36.50	7.30	29.20	L	Y	nt
3 FRONT FENDER QTR GARNISH LH	1.00	65.12	13.02	52.10	L	Y	cut
4 SIDE MIRROR LH	1.00	1,054.60	210.92	843.68	L	Y	Rx
5 FRONT DOOR LH	1.00	2,256.83	451.37	1,805.46	L	Y	bt
6 FRONT DOOR OUTER HANDLE LH	1.00	168.90	33.78	135.12	L	Y	cut
7 FRONT DOOR OUTER MOULDING LH	1.00	87.65	17.53	70.12	L	Y	nt
8 FRONT DOOR OUTER HANDLE PAD LH	1.00	20.88	4.18	16.70	L	Y	IX
9 REAR DOOR LH	1.00	2,201.00	440.20	1,760.80	L	Y	Rv
10 TAIL LAMP LH	1.00	903.22	180.64	722.58	L	Y	as
11 REPAIR FRONT WINDSCREEN PILLAR LH	1.00	0.00	0.00	0.00	S	Y	
12 FRONT DOOR STICKER-COMFORT DELGRO LH	1.00	100.00	0.00	100.00	S	Y	nt
13 REAR DOOR STICKER-COMFORT DELGRO LOGO LH	1.00	100.00	0.00	100.00	S	Y	nt
14 REAR DOOR STICKER-BOOK NOW & APP STORE LH	1.00	80.00	0.00	80.00	S	Y	nt
15 REPAIR REAR FENDER LH	1.00	0.00	0.00	0.00	S	Y	
16 TAIL LAMP HOLD CLIP LH	1.00	15.00	0.00	15.00	S	Y	nt
TOTAL:		7,749.20	490.84	6,258.36			
TOTAL PARTS & LABOUR :		10,809.20	1,490.84	9,318.36			

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
-------------	-----	--------------	----------	------------	-----	----------	-----------

EXCESS/LOADING:SS 0.00

No. Of Day: 5RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: SSDATE OF SURVEY: 4/7/19 930amSURVEYED BY: TaylorCONTACT NO: 97445749

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

taylor@lkkauto.com
-wp-

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Satisfaction Voucher

Date: 08/07/2019

8 JUL '19 17:58

MS First Capital Insurance Limited

Collection: 9 JUL '19 8:44

Attention: MOTOR CLAIMS DEPT

Dear Sir/Madam

TAY TATT ENG

I/We hereby acknowledge having received from Singapore Technologies Kinetics

Ltd., 249 Jalan Boon Lay, Singapore 619523, my/our vehicle number SHA9759K

which has been repaired to my/our satisfaction and acceptance. I/We admit that

the payment of SGD _____ account for such repairs is in full discharge

of my/our claim upon the corporation under the policy number D-18088937MFSH

reference claim number 50111791 in respect of the damage caused to the

said vehicle in an accident that occurred thereto or about the 29/06/2019

at ALONG JUPITER RD TWS UPP THOM

Dated this day of _____, 201 _____

Signature: [Signature]

NRIC No: S06124281

Name: CityCab PTE LTD (Fleet)

Address: 383 SIN MING DRIVE
SINGAPORE 575717 0

Company Stamp if applicable

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Wednesday, 3 July, 2019 3:03 PM
To: Taxis Customer Service; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sherini Pillai
Subject: RE: ACCIDENT INVOLVING SHA9759K AND SHC2862E ON 29/06/2019 ARRANGE SURVEY
Attachments: receipt-20190629-163532.pdf; SAS2626411.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHA9759K and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

Tan Kah

P. Guang

T. 3:15 PM

V. Lu

E ✓

From: Taxis Customer Service [mailto:taxiscs@stengg.com]
Sent: 03 July, 2019 1:54 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; accounts@dingautomotive.com.sg
Subject: RE: ACCIDENT INVOLVING SHA9759K AND SHC2862E ON 29/06/2019 ARRANGE SURVEY

Dear Officer,

Kindly please revert surveyor arrangement status as until today surveyor no show up. Vehicle already grounded more than 2 days. Appreciate for your fastest response.

Thanks

Best Regards,
Guang
Ding Automotive Pte Ltd
HP : 93299929 / 62657130

From: Taxis Customer Service

Sent: Monday, July 01, 2019 10:18 AM

To: 'Motor Claim - III' <motorclaim@iii.com.sg>

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; accounts@dingautomotive.com.sg

Subject: RE: ACCIDENT INVOLVING SHA9759K AND SHC2862E ON 29/06/2019 ARRANGE SURVEY

Dear Officer,

Please arrange LKK Auto Consultants Pte Ltd come on to survey.

Thanks

Best Regards,

Guang

Ding Automotive Pte Ltd

HP : 93299929 / 62657130

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Monday, July 01, 2019 9:21 AM

To: Taxis Customer Service <taxiscs@stengg.com>

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; accounts@dingautomotive.com.sg

Subject: RE: ACCIDENT INVOLVING SHA9759K AND SHC2862E ON 29/06/2019 ARRANGE SURVEY

WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING.

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Taxis Customer Service [mailto:taxiscs@stengg.com]

Sent: 29 June, 2019 4:39 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; accounts@dingautomotive.com.sg

Subject: ACCIDENT INVOLVING SHA9759K AND SHC2862E ON 29/06/2019 ARRANGE SURVEY

Dear Officer ,

Please arrange surveyor come onto Survey **SHA9759K**

The vehicle **SHA9759K** already in 31 Corporation Road 649825 .

Thanks

Best Regards,

Guang

Ding Automotive Pte Ltd

Hp : 93299929 / 62657130

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

View Received Message

This mail is associated with :

***SHA9759K**
[SHC2862E]

TP
CITYCAB PTE LTD
Jun 29 2019 12:00PM

Ding Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 10/07/2019 16:36 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SHA9759K - Claim Handler: Sherini Pillai

Approved:0.00.

DOCUMENTS SUMMARY

There are no documents.

Print Received Message

This mail is associated with :

***SHA9759K (MCT19060766)**
[SHC2862E]
TP
CITYCAB PTE LTD
Jun 29 2019 12:00PM
[-]
Ding Automotive Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 12/11/2019 08:54 AM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SHA9759K - Claim Handler: Sherini Pillai

Maintained: To offer based on 8 days after less 3 days on delay on their part. To offer \$7,188.23 total

Print Received Message

This mail is associated with :

***SHA9759K (MCT19060766)**
[SHC2862E]

TP
CITYCAB PTE LTD
Jun 29 2019 12:00PM
[-]
Ding Automotive Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/02/2020 15:12 PM,
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7400.00) - SHA9759K - Claim Handler: Sherini Pillai

Approved:7400.00.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Nov 2019 Edit Reg		04 Jul 2019 00:00 Edit Adj Rpt	S\$5,537.18 Edit Estimates	S\$5,537.18 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G								
Vehicle Reg. No.:	SHA9759K	Date of Loss:	29/06/2019 12:00 - :59 [3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19060766	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC2862E	Policy No. (Claimant):	D-18088937MFSH						
		Excess:							
Repairer:	Ding Automotive Pte Ltd (SIN MING) BLK 10 #01-20 SIN MING, IND EST SEC C, 575645 Sin Ming - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 15/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (05/02/2020): Alert - Adj Mandate Approved (S\$7400.00) - SHA9759K - Claim Handler: Sherini Pillai - III_SG (26/12/2019): Alert - Adj Mandate Approved (S\$7188.23) - SHA9759K - Claim Handler: Sherini Pillai - III_SG (27/11/2019): Alert - Adj Mandate Approved (S\$7502.23) - SHA9759K - Claim Handler: Sherini Pillai - III_SG (12/11/2019): Alert - Adj Mandate Maintained - SHA9759K - Claim Handler: Sherini Pillai - III_SG (08/11/2019): Alert - Adj Mandate Maintained - SHA9759K - Claim Handler: Sherini Pillai - III_SG (10/07/2019): Alert - Adj Mandate Approved (S\$0.00) - SHA9759K - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA9759K (MCT19060766)
[SHC2862E]
TP
CITYCAB PTE LTD
Jun 29 2019 12:00PM
[COMFORT TRANSPORTATION PTE LTD]
Ding Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	18/10/19 11:26	General View						Load JPG	☒	
2	18/10/19 11:26	General View						Load JPG	☒	
3	18/10/19 11:26	General View						Load JPG	☒	
4	18/10/19 11:26	General View						Load JPG	☒	
5	18/10/19 11:26	General View						Load JPG	☒	
6	18/10/19 11:26	General View						Load JPG	☒	
7	18/10/19 11:26	General View						Load JPG	☒	
8	18/10/19 11:26	General View						Load JPG	☒	
9	18/10/19 11:26	General View						Load JPG	☒	
10	18/10/19 11:26	General View						Load JPG	☒	
11	18/10/19 11:26	General View						Load JPG	☒	
12	18/10/19 11:26	General View						Load JPG	☒	
13	18/10/19 11:26	General View						Load JPG	☒	
14	18/10/19 11:26	General View						Load JPG	☒	
15	18/10/19 11:26	General View						Load JPG	☒	
16	18/10/19 11:26	General View						Load JPG	☒	
17	18/10/19 11:26	General View						Load JPG	☒	
18	18/10/19 11:26	General View						Load JPG	☒	
19	18/10/19 11:26	General View						Load JPG	☒	
20	18/10/19 11:26	General View						Load JPG	☒	
21	18/10/19 11:26	General View						Load JPG	☒	
22	18/10/19 11:26	General View						Load JPG	☒	
23	18/10/19 11:26	General View						Load JPG	☒	
24	18/10/19 11:26	General View						Load JPG	☒	
25	18/10/19 11:26	General View						Load JPG	☒	
26	18/10/19 11:26	General View						Load JPG	☒	
27	18/10/19 11:26	General View						Load JPG	☒	
28	18/10/19 11:26	General View						Load JPG	☒	
29	18/10/19 11:26	General View						Load JPG	☒	
30	18/10/19 11:26	General View						Load JPG	☒	
31	18/10/19 11:26	General View						Load JPG	☒	
32	18/10/19 11:26	General View						Load JPG	☒	
33	18/10/19 11:26	General View						Load JPG	☒	
34	18/10/19 11:26	General View						Load JPG	☒	
35	18/10/19 11:26	General View						Load JPG	☒	
36	18/10/19 11:26	General View						Load JPG	☒	
37	18/10/19 11:26	General View						Load JPG	☒	
38	18/10/19 11:26	General View						Load JPG	☒	
39	18/10/19 11:26	General View						Load JPG	☒	
40	18/10/19 11:26	General View						Load JPG	☒	
41	18/10/19 11:26	General View						Load JPG	☒	
42	18/10/19 11:26	General View						Load JPG	☒	
43	18/10/19 11:26	General View						Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	18/10/19 11:26	General View		☒
45	18/10/19 11:26	General View		☒
46	18/10/19 11:26	General View		☒
47	18/10/19 11:26	General View		☒
48	18/10/19 11:26	General View		☒
49	18/10/19 11:26	General View		☒
50	18/10/19 11:26	General View		☒
51	18/10/19 11:26	General View		☒
52	18/10/19 11:26	General View		☒
53	18/10/19 11:26	General View		☒
54	18/10/19 11:26	General View		☒
55	18/10/19 11:26	General View		☒
56	18/10/19 11:26	General View		☒
57	18/10/19 11:26	General View		☒
58	18/10/19 11:26	General View		☒
59	18/10/19 11:26	General View		☒
60	18/10/19 11:26	General View		☒
61	18/10/19 11:26	General View		☒
62	18/10/19 11:26	General View		☒
63	18/10/19 11:26	General View		☒
64	18/10/19 11:26	General View		☒
65	18/10/19 11:26	General View		☒
66	18/10/19 11:26	General View		☒
67	18/10/19 11:26	General View		☒
68	18/10/19 11:26	General View		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/07/19 15:28	EMAIL FROM III DD 04072019		☐
2	04/07/19 15:28	TP GIA REPORT		☐
3	05/07/19 09:26	TP ESTIMATE- MARKED		☐
4	18/10/19 11:25	LOD AND OTHER DOCUMENTS		☐
5	18/10/19 12:12	AMENDED LOD		☐
6	08/11/19 12:23	RENTAL RECEIPT		☐
7	08/11/19 12:23	RENTAL MILEAGE		☐
8	08/11/19 12:23	LTA SEARCH		☐
9	09/03/20 09:52	WORKSHOP INVOICE		☐
10	09/03/20 09:52	AUTHORISATION TO ACT FORM		☐
11	09/03/20 09:52	DISCHARGE VOUCHER		☐
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/07/19 08:35	Singapore Accident Statement		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19011851/T1GS3Q2

Date: 09/03/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No : SHA9759K Insured Vehicle No : SHC2862E
 Date of Loss: 29/06/2019 Nature of Claim: TP Claim No: MCT19060766

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA9759K
 Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU296066
 Reg. Date: 26/06/2019 (Man. Year: 2019) Chassis No: KMHCB51CVKU164382
 Colour: Yellow Odometer: 890 km
 Engine Capacity: 1580 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm
 Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,308.36	3,667.18	2,641.18	41.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,870.00	1,140.00	37.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,318.36	5,537.18	3,781.18	40.58
+ GST 7.00/7.00% (S\$)	652.29	387.60	264.69	40.58
Nett Amount (S\$)	9,970.65	5,924.78	4,045.87	40.58
+ Loss of Use (10.0 x S\$40.00/day) (S\$)		400.00		
+ Car Rental (10.0 x S\$117.00/day) (S\$)		1,170.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,502.23		
Global Sum Settlement (S\$)		7,300.00		

INSPECTION

Date of Assignment: 04/07/2019

Date Inspected: 04/07/2019 Inspected At:

Ding Automotive Pte Ltd (SIN MING)
 BLK 10 #01-20 SIN MING, IND EST
 SEC C
 Singapore 575645

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2019)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA9759K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Bent	659.50 FL	*659.50 FL
2	1		*FRONT FENDER EMBLEM LOGO LH	Necessary	36.50 FL	*36.50 FL
3	1		*FRONT FENDER QTR GARNISH LH	Cut	65.12 FL	*65.12 FL
4	1		*SIDE MIRROR LH	Repair	1,054.60 FL	*- FL
5	1		*FRONT DOOR LH	Bent	2,256.83 FL	*2,256.83 FL
6	1		*FRONT DOOR OUTER HANDLE LH	Cut	168.90 FL	*168.90 FL
7	1		*FRONT DOOR OUTER MOULDING LH	Cut	87.65 FL	*87.65 FL
8	1		*FRONT DOOR OUTER HANDLE LH	Not Necessary	20.88 FL	*- FL
9	1		*REAR DOOR LH	Repair	2,201.00 FL	*- FL
10	1		*TAIL LAMP LH	Cracked	903.22 FL	*903.22 FL
11	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
12	1		*REPAIR FRONT WINDSCREEN PILLAR LH (NPA)	Repair	0.00 FS	*- FS
13	1		*FRONT DOOR STICKER -COMFORT DELGRO LH	Necessary	100.00 FS	*100.00 FS
14	1		*REAR DOOR STICKER -COMFORT DELGRO LH	Necessary	100.00 FS	*100.00 FS
15	1		*REAR DOOR STICKER -BOOK NOW & APP STORE LH	Necessary	80.00 FS	*80.00 FS
16	1		*REPAIR REAR FENDER LH (NPA)	Repair	0.00 FS	*- FS
17	1		*TAIL LAMP HOLD CLIP LH	Necessary	15.00 FS	*15.00 FS
					Sub Total (S\$)	7,799.20 4,502.72
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,490.84 835.54
					Total Parts (S\$)	6,308.36 3,667.18

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	1,100.00	700.00
2	RUST PROOFING	New	80.00	30.00
3	R&R FRONT DOOR COMPONENT LH	New	100.00	60.00
4	R&R REAR DOOR COMPONENTS LH	New	100.00	0.00
5	TO CALIBRATE POWER WINDOW (AUTO POSITION)	New	180.00	80.00
6	DIAGNOSTIC (CLEAR FAULT CODE)	New	200.00	100.00
7	RESPRAY FRONT FENDER LH	New	250.00	200.00
8	RESPRAY FRONT DOOR LH	New	250.00	200.00
9	RESPRAY REAR DOOR LH	New	250.00	200.00
10	RESPRAY REAR FENDER LH	New	250.00	200.00
11	RESPRAY FRONT WINDSCREEN PILLAR LH	New	250.00	100.00
Gross Labour Cost (S\$)			3,010.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >