



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19011862/R1gb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 23-10-2019



ATTN: JAS TAN

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKE 1806D	Veh. Inspected	SLZ 6093M
Policy No.	GA393679	Coverage (\$)	0.00
Claim No.	S9M01SRM	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	04/07/2019

2. Vehicle Particulars & Condition

Make & Model	HONDA STREAM 1.8L (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JHMRN68609C200093	Colour	WHITE
Odometer	141584	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/50 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/07/2019	Inspection Date	04/07/2019
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------