



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 05/07/2019

Survey Details:

Date of loss	2-Jul-19
Date of appointment	4-Jul-19
Date of survey	4-Jul-19
Location of survey	TORQUE 5 PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLZ 6093M
Make and Model	HONDA STREAM 1.8L
Date of registration	20/7/2010
Excess	
Market Value	\$23,000
Parf Rebate	\$17,983
Nett Loss	\$5,017

Repair details:

Initial Estimate	\$ 16,386.50
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 2,537.90
Check items (estimate)	\$ 431.00
Labour	\$ 1,520.00
Total	\$ 4,488.90
Lump Sum(if applicable)	\$ -
Number of days for repair	5



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs.

Mandate:

Liability(TP)	%	
Proposed repair cost	TBA	
Loss of use		no. of days
Loss of rental		no. of days
Loss of income		no. of days
LTA search fees		
Others		
Proposed Total	TBA	