

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

*(M) QBE
OD*

Your Reference : V0020325
Accident Date : 03-Jul-2019

No. : 30541

Date : 04-Jul-2019

Our Ref : 190369 / SANDRA

PAGE : 1

QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY
#29-10
SOUTH TOWER
Singapore 048583

1/2
o/s rear & ulc

Not Withark

Returning B4paim

5 days, Ref 62564315

Ex 8600

ESTIMATED COST OF REPAIR FOR SUBARU LEGACY 2.5I-S CVT (2016) SLJ828J

1 pc rear bumper	Bul/wh	350.00	c	✓
1 pc o/s rear bumper side retainer		25.00	c	✓
10 pcs rear bumper clips	@ S\$ 2.00	20.00	c	✓
1 pc o/s rear fender	wh	600.00	c	X
1 pc rear windscreen glass moulding	wh	50.00	c	X
1 pc o/s rear rim	wh	500.00	c	✓
1 pc o/s rear shock absorber		230.00	c	✓
1 pc o/s rear shock absorber mounting		45.00	c	✓
1 pc o/s rear shock absorber stopper		20.00	c	✓
1 pc o/s rear shock absorber cover	wh	20.00	c	X
1 pc o/s rear knuckle arm		180.00	c	✓
1 pc o/s rear knuckle arm bearing		140.00	c	✓
1 pc o/s rear lower arm		100.00	c	✓
1 pc o/s rear trailing arm		110.00	c	✓
1 pc o/s rear lateral link		100.00	c	✓
1 pc o/s rear upper arm		330.00	c	✓
1 pc o/s rear stablizer bar linkage	wh	50.00	c	X
		2,870.00		
	Add 10% :	287.00		
		3,157.00		
1 pc rear windscreen glass sealant	wh	40.00	sn	X
1 pc rear windscreen glass damping seal	wh	20.00	sn	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Con't Page 2 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : V0020325
Our Ref : 190369

Page : 2
No. : 30541

1 pc o/s rear tyre

320.00 ⁸⁰²ⁱⁿsn

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

700.00 ⁵⁰⁰

To remove and refit rear upholstery
trimming, roof lining, seats,
speaker board in order to
facilitate repairing works

120.00 ⁶⁰

To remove and refit rear windscreen
glass and conduct water leak test

100.00 ⁿⁿX

To dismantle and check rear under-
carriage. To replace affected
portions.

120.00 ⁷

To conduct rear wheel alignment
test.

100.00 ⁶⁰

To putty and respray on affected
portions.

650.00 ⁴⁰⁰

Total : S\$ 5,327.00
=====

Singapore Dollars Five Thousand Three Hundred
and Twenty Seven Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

\$ 1830.00 - Part

+ 102

\$ 2012.00

\$ 192.00 - sh

\$ 1,140.00 - GL

\$ 3,345.00



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Arrange By

Driver

02007



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795



Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : MENG HUAT

TAX INVOICE : AR201907-03763
DATE : 06/07/2019
CUSTOMER ID : KKI001
VEH REG. NO. : SLJ828J
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. S57704-AL120 BN9 -15 NEW	✓ RR BUMPER	PA PL4-A1-09	1	350.00	350.00
2. S28111-AL010 BN9	✓ SPORT RIM	PA PL1-B1-06B	1	500.00	500.00
3. S28411-AL000 BN9	✓ REAR KNUCKLE RH	PA PL1-C1-05B	1	180.00	180.00
4. S28473-VA000 VAG BS9VM4	✓ RR WHEEL HUB	PA PL1-C1-11A	1	140.00	140.00
5. S20250-FJ000/001 GP3/7 SJG GJ3	✓ RR TRAILING ARM	PA PL1-D1-08D	1	110.00	110.00
6. S20250-AL010/011 VAG	✓ LATERAL LINK ASSY RR	PA PL1-D1-07M	1	100.00	100.00
7. S20252-FJ020 GJ3 VM4	✓ REAR UP ARM RH	PA PL1-E1-09B	1	330.00	330.00

SUB-TOTAL : 1,710.00
ADD GST 7.00 % 119.70

E. & O.E

TOTAL AMOUNT SGD : 1,829.70

[P] 06/07/2019 11:16:46

[E] 06/07/2019 11:06:26AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: CHEN

This is computer generated document.

No signature is required.



* A R 2 0 1 9 0 7 - 0 3 7 6 3 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 6

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

60 JALAN LAM HUAT #B1-05/06 CARROS CENTRE
SINGAPORE 737869 TEL: 63625226 FAX: 63626977

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Dept Direct: 6305 9610 Dept Direct: 6305 9611 Dept Direct: 6417 9792

Dept Direct: 6417 9794 Dept Direct: 6417 9795 Dept Direct: 6417 9796 Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : MENG HUAT

TAX INVOICE : AR201907-03775
DATE : 06/07/2019
CUSTOMER ID : KKI001
VEH REG. NO. : SLJ828J
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
S20250-VA000 VAG BS9 VM4	LATERAL LINK ASSY FRT	U1 HL2-C16-C	1	100.00	100.00

CM
Q

Case 19036902	SUB-TOTAL :	100.00
Note 30541	ADD GST 7.00 %	7.00
2,7,19 QBE	TOTAL AMOUNT SGD :	107.00
[P] 06/07/2019 11:13:39AM	[E] 06/07/2019 11:13:22AM	

Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.
Sales Executive : CHEN



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

< KIM HIN AUTO PTE LTD GST REG. NO. M20119201-3 CO. REG. NO.: 199307741M

160 SIN MING DRIVE #02-18/19/20/21

SIN MING AUTOCITY

SINGAPORE 575722

TEL : 64527018 MENG FAX : 64583895

ATTN : MENG HUAT

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9839



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201907-13837

DATE : 06/07/2019

CUSTOMER ID : KKI001

VEH REG. NO. : SLJ828J

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. S90914-0007	CLIP	WH	10	2.00	20.00
LEG 99 BL5 SJG		HL2-N7-B			

SUB-TOTAL : 20.00
ADD GST 7.00 % 1.40

E. & O.E TOTAL AMOUNT SGD : 21.40

P] 03/08/2019 10:52:18AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

AE Auto Pte. Ltd.

Sales Executive : CHEN

This is computer generated document.

No signature is required.



* AR 201907-13837 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

R002892.
6.7.19 9:58
SLJ828J
160-0218



SLJ828J

Factory Japan 2018.0.2 : Subaru : Legacy : BN Series : BN9 -2017/4
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°25'	-0°25'	-1°00' 0°30'
5°40'	5°40'	5°05' 6°35'
-0°15'	-0°16'	-0°08' 0°08'
14°26'	14°26'	13°00' 15°00'
14°01'	14°01'	12°00' 15°30'
36psi	30psi	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.
Tire Pressure

Front : Right

Actual	Before	Specified Range
-0°27'	-0°26'	-1°00' 0°30'
5°44'	5°44'	5°05' 6°35'
0°07'	0°07'	-0°08' 0°08'
14°02'	14°02'	13°00' 15°00'
13°36'	13°36'	12°00' 15°30'
36psi	30psi	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°02'	0°01'	-0°45' 0°45'
-0°04'	-0°04'	-0°45' 0°45'
0°24'	0°24'	
-0°09'	-0°09'	-0°15' 0°15'

Rear : Left

Actual	Before	Specified Range
-1°53'	-1°53'	-2°10' -0°40'
0°05'	0°05'	0°00' 0°15'
36psi	30psi	

Camber
Toe
Tire Pressure

Rear : Right

Actual	Before	Specified Range
-2°54'	-2°54'	-2°10' -0°40'
-0°24'	-0°24'	0°00' 0°15'
36psi	38psi	

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
1°01'	1°01'	-0°45' 0°45'
-0°19'	-0°19'	0°00' 0°30'
0°15'	0°15'	-0°30' 0°30'
0mm	0mm	

R002911
8.7.19 14:07
SLJ828J
160-0218



SLJ828J

Subaru : Legacy
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°58'	-0°13'	-1°00' 0°30'
5°41'	5°41'	5°05' 6°35'
0°01'	-0°04'	-0°08' 0°08'
14°54'	14°08'	13°00' 15°00'
13°56'	13°56'	12°00' 15°30'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°08'	-0°38'	-1°00' 0°30'
5°20'	5°20'	5°05' 6°35'
0°00'	-0°06'	-0°08' 0°08'
13°51'	14°21'	13°00' 15°00'
13°43'	13°43'	12°00' 15°30'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°51'	0°26'	-0°45' 0°45'
0°21'	0°21'	-0°45' 0°45'
1°03'	-0°13'	
0°01'	-0°10'	-0°15' 0°15'

Rear : Left

Actual	Before	Specified Range
-1°27'	-1°33'	-2°10' -0°40'
0°07'	-0°04'	0°00' 0°15'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°27'	-0°47'	-2°10' -0°40'
0°08'	1°05'	0°00' 0°15'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
0°00'	-0°46'	-0°45' 0°45'
0°16'	1°01'	0°00' 0°30'
0°00'	-0°35'	-0°30' 0°30'
0mm	0mm	