

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwin.com.sg Website: www.abwin9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G



ATTN: MARCUS

ESTIMATED COST: HQQ000042

TO : INDIA INTERNATIONAL INSURANCE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 08-JUL-2019
MAKE : MITSUBISHI
MODEL : CANTER FEB21ER4SDEB (CBU)
CHASSIS NO : FEB21EA20111
ENGINE NO : 4P10B98367
SERVICE ADVISOR : SHARIFAH
PAGE : 1 OF 1

YM9933J
AEROGAZ (S) PTE LTD
CONTACT NO : 85788700

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FUEL TANK	1,816.02	257
Sub Total		1,816.02	0.00

SPECIAL NETT

1	REAR CABIN SIDE RAILING SAFETY BAR R/H	480.00	400
1	VINYL STICKER FOR "AEROGAZ" ADVERTISEMENT	600.00	
Sub Total		1,080.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,000.00	400
1	TO DISMANTLE, REPLACE AND/OR REPAIR FUEL TANK COMPONENTS	280.00	50
1	TO SPRAY PAINT ON AFFECTED AREAS	800.00	320
Sub Total		2,080.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ABWIN SERVICE PTE LTD

Prepared By