

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SDU 8228A

TP/AXA

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/YS

Claim Type: Third Party

Accident Date: 04/07/2019

TP Veh Reg No: SLV5424U

Estimate No: ES1991745/YISHUN

Date: 5 Jul 2019

Policy No: 5080429442-03

Veh Reg No: SDU8228A

Make/Model: NISSAN ALMERA 1.5

5MT AIRBAG 2WD 4DR

Chassis No: MNTBBAN17Z0005591

Engine No: HR15929322D

Reg. Date: 30/05/2016

Not Withheld

Recovery Bypain

6 days

11 Days @ 4400

Estimate Repair Cost to Vehicle No :SDU8228A

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR BUMPER	518.80	1 PC	518.80	✓
2 REAR BUMPER RH SIDE RETAINER	31.10	1 PC	31.10	✓
3 REAR BUMPER CLIPS	4.40	6 PCS	26.40	✓
4 REAR BUMPER RH BRACKET	86.60	1 PC	86.60	✓
5 REAR BOOT	846.00	1 PC	846.00	✓
6 REAR BOOT EMBLEM "ALMERA"	59.70	1 PC	59.70	✓
7 REAR BOOT LOGO	53.50	1 PC	53.50	✓
8 REAR BOOT INNER LOCK	64.50	1 PC	64.50	✓
9 REAR BOOT INNER RUBBER	103.90	1 PC	103.90	✓
10 REAR BOOT HINGES	87.60	2 PCS	175.20	X
11 REAR BOOT INNER SPONGE CLIPS	6.00	4 PCS	24.00	✓
12 TAILLAMP	264.40	2 PCS	528.80	✓ 264.40
13 RH TAILLAMP INNER BRACKET BEAM	31.10	1 PC	31.10	✓
14 REAR CENTRE PANEL	458.20	1 PC	458.20	✓
15 REAR CENTRE PANEL INNER TOP GARNISH	112.20	1 PC	112.20	✓
16 REAR RH FENDER INNER GARNISH	356.70	1 PC	356.70	✓
17 REAR SPARE TYRE TOP BOARD	250.00	1 PC	250.00	✓
18 REAR RH FENDER	784.50	1 PC	784.50	✓
19 REAR WINDSCREEN GLASS MOULDING	115.80	1 PC	115.80	✓
			4,627.00	
		Less 10%	462.70	4,164.30
Special Net				
20 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓ 40.00
Labour				
21 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
22 PANEL BEATING	1,200.00	1 LA	1,200.00	✓ 900
23 PUTTY & RESPRAY ON REAR BOTH FENDERS, REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR BOOT, HINGES, REAR BUMPER & REAR AFFECTED AREAS	1,200.00	1 LA	1,200.00	✓ 900
24 REMOVE & REFIX REAR SEAT, C/PET, GARNISH, TOP ROOF LINING, ETC	120.00	1 LA	120.00	✓ 90
25 RUSTPROOFING	90.00	1 LA	90.00	✓ 30
			2,730.00	2,730.00
		Total	S\$ 6,934.30	
		Add GST @ 7%	485.40	
		Total Amount Payable	S\$ 7,419.70	

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE