COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

MAKE

VEHICLE NO : SHD3054J

: HYUNDAI

DATE:

5. Jul. 2019

EL	: i40	DOA:	4. Jul. 2019	<u>AXA</u>
Qty	Parts Description/ Labour	Туре	Unit Price	Amount
	1 Front Door – RH × M			\$1,403.00
	1Rear Door – RH – Buk			\$1,351.10
	1 Rear Fender – RH			\$566.30
	1 Rocker Panel Garnish – RH	- 1		\$483.60
	1 Rear Bumper		9 76 1	\$553.00
1	Pear Bumper Clins + 43		\$2.20	\$22.00
	1 Rear Wheel Cover – RH / h-12-4			\$107.10
	SUB TOTAL			\$4,486.10
	LESS 20%			\$897.22
	DISCOUNTED TOTAL			\$3,588.88
	1 Front Door Comfort Logo × 4.4			\$75.00
	1 Rear Door APP Sticker			\$80.00
	1 Rear Bumper Rubber Mat ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓ ✓			\$50.00
				\$205.00
	Labour Charge			
	1 Panel Beating			\$750.00
	1 Spray Painting Charge			\$1,000.00
	1 Wiring Charge			
	1Tuff Kote			\$100.00
			£150.00	\$100.00
	2 Transfer of Door		\$150.00	\$300.00
	TOTAL LABOUR	ZZ Auto Con	cultants hence notify	\$2,250.00
		ne Repairer	- Doitning -	
	ESTIMATE TOTAL	To result any bit	aged part(s) during resurvey	\$6,043.88
	Ca ha (city	• Parts prices at	e subject to confirmation be subject to confirmation vey is on a Without Prejudice (fication(s) is allowed	pasis
	1 0/2/2 /	Third party Sur	illication(s) is allowed	nd
BN MB	1 6/1/11 11452	No illegal in a Supplementa	ification(s) is allowed ry item(s) must be resurveyed a inal approval from insurance (c	mpany
3(1)	2 61	is subject to		
	10/2	Acknowledge	t by Repairer	
	Ka La ICCCG ESTIMATE TOTAL. 8/2/19 1145L. 3 hs Ple Betone Part pll	Signature: Date:		
	This is an initial estimate based on a visual inspection of the	e above veh	icle. The final repair qu	antum will