

INS. CASE OWNER:

CC 4/LPC 190 120/6 / A da3

02
ITAC

Surveyor:

WJF

DOI:

ASSIGNMENT

2/7/19

Date / Time:

2/7/19

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.

YP 7384 R

Claim No. :

Name of Insured

E.S. Furniture Construction

Policy No. :

Insured Tel No.

HP:

Make / Model :

Excess Sec II :SS

D.O.A: *4/7/19*

Place of Accident :

Is driver the owner?

(YES / **NO**)

Nature of Accident :

If NO, Driver Name / Age:

Driver Tel No. :

(V/L: **YES** / NO)

OI GIA REPORT: **YES** / NO ; TP GIA REPORT: **YES** / NO

Insured Liability : % Final ? Yes / No

SKN55685



INSRS:
WSP: *SME Motor*
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

SKN55685 : X
YP 7384 R : WA/LPC190/197/24 D.O.A : 4/7/19

STAGE

DATE / PIC

2/12/19 - FILE PASS TO T/B MANDATE

15/1/2020 - FILE PASS TO MML TO LGTR

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call Of:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: *31/12/19*

Confirm with *Y/W*

Email

Call

Final Liability:

% *100*

(Agreed / Assessed) BOLA S/N No. *NIL*

If NO or B 28, Ass. Lia :

Repair Cost: (*w/hst*)

SS *3390.19*

OL HIT PARKED VEH

Loss of Rental (LOR):

SS *300.00*

(*3* days) x \$*100*

Loss of Use (LOU):

SS -

(*3* x days)

Loss of Income (LOI):

SS -

(*3* x days)

LOR only LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

SS *7.45*

Medical:

SS -

Disbursement:

SS -

(e.g Tow/Independent)

Legal Cost

SS -

1) Claim status: *Normal/Reject/Private Settle*

2) Report Format: *TP*

3) Survey fee: *\$400*

Total:

SS *3697.64*

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS *3697.64*

Name 1:

SME Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
21/1/2020

ASSIGNMENT

From: _____ Date: 8/7/2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN5568S

at Workshop n/s SME

of 1 Kabi Bukit Ave 6 #02-15

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

8/7/2019 11am Owner Waiting

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? **Yes** or **No**

GIA / PR Seen: _____ Consistent? **Yes** or **No**

Est. Repairs: 5 days Res.: **Yes** or **No**

Lum Sum: _____ % 3 Val: **Yes** or **No**

CA / REV / REP. / 24 HRS _____

Date: _____ Person Contacted: _____ Vehicle: **IN** / **OUT**

Veh No: SKN5568S Yr Regn: 2014 June

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mazda.3 cc: 1996

Colour: Silver A/C: **Insured** / Std / NI / NA

Sp. Reading: 82713 T/Radio: **Insured** / Std / NI / NA

Eng/No: _____

C/No: JM6Bm 42A8E0118448

Gen. Cond: Good / Fair / Poor / Burnt

Steering: **In order** / Jammed / Leaked / Burnt or _____

Brake: **In order** / Jammed / Leaked / Burnt or _____

Mod: **Nil** / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A. _____		D.O.I. <u>08/07/19</u>	

Survey held at SME

Des. of Damages: **Frnt** / Rear / O/S / N/S / U/C / Rooftop or _____

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>TP Loop.</u>
	<u>P/P - \$3168.40 (Red \$1345.60 / 30Z)</u>
	<u>MV: 461c.</u>
	<u>PV: 37.51c</u>
	<u>Nett: 8.51c.</u>

Order/Time, File Pass to? : **Proli. Report**

: **Final Report**

Days Of Repair: _____

Resurvey No. of Trip: _____

Arld Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Insp (\$)

: Final Insp (\$)

Survey Fee: _____

Transportation _____



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) |
 [Advertiser Login](#) |
 [Steps of Selling](#)

New 5 Years Coe Renewal Toyota Altis 1.6A

3.18% P.A \$0 Admin Fees At GV Finance. 2 Years Warranty. Monthly From \$558

KA-HUP

VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997 [View our Cars](#)

Browse by Category Sort by Date Posted 20 results/page

9 vehicles | **Search** Mazda 3 [Advanced Search](#)

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

Search Selection Mazda 3 Any Any 2014 Any Any Any Available



Mazda 3 1.5A Deluxe \$45,800 \$8,180 /yr 31-Jul-2014 1,496 cc - Sedan Available

Cheapest In Town! Easy High Loan Approval! Well Maintained By Previous Owner, Excellent Condition, Original Paintwork Since Day 1, Accident Free, Immaculate Condition, In House Loan And Bank Loans Are Available! Sims, Call Or Whatsapp Me For Discussion And View!

Heritage Auto Enterprise Pte Ltd



Mazda 3 1.5A Sunroof \$50,800 \$9,330 /yr 27-Aug-2014 1,496 cc 95,000 km Sedan Available

Very Popular Car! Powerful, Responsive Yet Fuel Efficient. Only 1 Previous Owner. Flexible Loan Packages Available With Attractive Interest Rates. Welcome All Trade In. Call Our Friendly Representatives For More Information Or For A Viewing Of The Car.

AL Autocar Pte Ltd



Mazda 3 HB 1.5A Sunroof \$51,800 \$9,410 /yr 17-Sep-2014 1,496 cc 47,800 km Hatchback Available

1 Single Owner, Rare Hatchback, Guarantee Not Grab/PHV Vehicle. Low Interest Rate, In House Loan Available, Low Mileage, Reliable Japan's Technology Engine. Smooth Running Condition, Original Condition. Fuel Efficient And Reliable.Contact Us For Viewing Now



Mazda 3 1.5A Deluxe \$51,000 \$9,010 /yr 17-Sep-2014 1,496 cc 75,941 km Sedan Available

No Dealers Or Consignment Agents. Original Elegant Blue Deluxe With Sunroof, Well Serviced And Maintained. Accident Free, Well Kept Inside Out. Front Camera. Leather Seats. Call/WhatsApp For Viewing Appointment.

- Car Buying
- Car Selling
- Car Ownership
- Car Marketplace
- On The Move
- Lifestyle

SGC Buying a pre-owned car, but unsure of its condition?

[Get](#)



Mazda 3 1.5A Sunroof \$53,800 \$9,460 /yr 29-Sep-2014 1,496 cc 43,439 km Sedan Available

1 (Teacher) Owner! Sunroof Model! High Loan Are Available At Low Interest Rate! Fully Agent (Eurokars) Servicing Records. Extended Warranty Can Be Arranged For An Added Peace Of Mind! Original Stock Condition! No Repairs Needed! High Trade In Are Welcome! 100...

Stans Automobile



Mazda 3 1.5A Deluxe \$53,600 \$9,450 /yr 30-Sep-2014 1,496 cc 57,842 km Sedan Available

1 Owner With Low Mileage Done. Beautiful Sunroof Deluxe Unit With Head Up Display. 100% Loan Approval Rate. Flexible Loan And Insurance Available. Lowest Interest Rate! No Chassis Or Structural Damage. In Pristine Showroom Condition. Well Maintained By Previ...



Mazda 3 1.5A Sunroof \$50,800 \$9,120 /yr 14-Oct-2014 1,496 cc 60,000 km Sedan Available

100% Cheapest In The Market! Quick Sales.Flexible Loan Available With Fast Approval And Low-Interest Rates, Fully Serviced By Agent Since Day 1, Accident-Free! Immaculate Condition! Very Well Taken Care Of By Previous Owner! Hurry Call Now Before It's Gone.



Mazda 3 1.5A Sunroof \$51,800 \$9,010 /yr 30-Oct-2014 1,496 cc 41,000 km Sedan Available

BEST DEAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1792D

Vehicle Details

Vehicle No.: SKN55685
Vehicle to be Exported: Yes
Intended Deregistration Date: 08 Jul 2019
Vehicle Make: MAZDA
Vehicle Model: MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour: Silver
Manufacturing Year: 2014
Engine No.: P520209284
Chassis No.: JM6BM42A8E0118448
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$18,763.00
Original Registration Date: 25 Jun 2014
First Registration Date: 25 Jun 2014
Transfer Count: 0
Actual ARF Paid: \$8,763.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Jun 2024
PARF Rebate Amount: \$6,134.00

Intended COE Rebate Details

COE Expiry Date: 24 Jun 2024
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$63,190.00
COE Rebate Amount: \$31,349.00
Total Rebate Amount: \$37,483.00

The information contained herein is correct as at 08 Jul 2019

OK

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO 201119451E



M/S: LONPAC INSURANCE BHD
 300, Beach Road, #17-04/07
 THE CONCOURSE
 Singapore 199555
 TEL: 62507388 FAX: 62963767
 ATTN: Motor Claim Department
 Your Ref No: 19/LP/TP-132(07)
 Claim Type: Third Party

Jia le

Estimate No: EST0004936
 Date: 05 Jul 2019
 Policy No: D19MTPV01007989
 Veh Reg No: SKN5568S
 Make/Model: MAZDA 3

Reg. Date:

Estimate Repair Cost to Vehicle No :SKN5568S

Description	U/Price	Quantity	Cost	Amount
			SS	SS
Parts				
1 FRT BONNET <i>Distorted</i>		1 PC	450.00	✓
2 FRT BONNET RUBBER <i>new torn</i>		1 PC	35.00	✓
3 FRT BUMPER <i>Replaced</i>		1 PC	750.00	✓
4 FRT BUMPER RETAINER RH <i>new</i>		1 PC	15.00	✓
5 FRT BUMPER CLIPS <i>new</i>		10 PC	25.00	✓
6 FRT BUMPER BEAM (BELOW HEADLAMP) <i>new</i>		1 PC	15.00	✓
7 FOG LAMP GARNISH RH <i>new</i>		1 PC	50.00	✓
8 HEADLAMP RH <i>new</i>		1 PC	920.00	✓
9 HEADLAMP PANEL RH <i>new</i>		1 PC	220.00	✓
10 FRT FENDER RH <i>Dented</i>		1 PC	160.00	✓
11 FENDER COWLING CLIPS <i>new</i>		10 PC	20.00	✓
			2,660.00	
		Add 20%	532.00	3,192.00
Labour				
12 WIRE CHECKING		1 UNIT	20.00	✓
13 LABOUR CHARGE	<i>1120</i>	1 UNIT	600.00 500	
14 SPRAY PAINTING		1 UNIT	680.00 600	
				1,270.00
				4524.40

2-pcs frt bonnet hinge \$26 x 2 ✓
Best
1707
2048.40

Amount Before Excess	SS 4,462.00
Add GST @ 7%	312.34
Total Amount payable	SS 4,774.34

TOTAL - SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED SEVENTY FOUR AND CENTS THIRTY FOUR ONLY

- LPK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

total: 368.40
(P/P)

Admin Lj
W/S 08/07/19.
05 Aug.

Part by Part

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : LONPAC INSURANCE BHD
 300, Beach Road, #17-04/07
 THE CONCOURSE
 Singapore 199555
TEL: 62507388 **FAX:** 62963767
ATTN: Motor Claim Department
Your Ref No: 19/LP/TP-132(07)
Claim Type: Third Party

Estimate No: EST0004936
Date: 05 Jul 2019
Policy No: D19MTPV01007989
Veh Reg No: SKN5568S
Make/Model: MAZDA 3

Reg. Date:

Estimate Repair Cost to Vehicle No :SKN5568S

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Parts				
1 FRT BONNET <i>visibled</i>		1 PC	450.00	—
2 FRT BONNET RUBBER <i>men</i>		1 PC	35.00	+
3 FRT BUMPER <i>2nd Rys</i>		1 PC	750.00	+
4 FRT BUMPER RETAINER RH <i>men</i>		1 PC	15.00	—
5 FRT BUMPER CLIPS <i>m</i>		10 PC	25.00	—
6 FRT BUMPER BEAM (BELOW HEADLAMP) <i>men</i>		1 PC	15.00	+
7 FOG LAMP GARNISH RH <i>cut</i>		1 PC	50.00	—
8 HEADLAMP RH <i>conced</i>		1 PC	920.00	—
9 HEADLAMP PANEL RH <i>?</i>		1 PC	220.00	—
10 FRT FENDER RH <i>Revised</i>		1 PC	160.00	—
11 FENDER COWLING CLIPS <i>men</i>		10 PC	20.00	+
			2,660.00	
	Add 20%		532.00	3,192.00
Labour				
12 WIRE CHECKING		1 UNIT	20.00	—
13 LABOUR CHARGE		1 UNIT	600.00	500
14 SPRAY PAINTING		1 UNIT	680.00	600
				1,270.00

Amount Before Excess **SS 4,462.00**
 Add GST @ 7% **312.34**
 Total Amount payable **SS 4,774.34**

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED SEVENTY FOUR AND CENTS THIRTY FOUR ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

Adrian Lij
 2/5 08/07/19.
 052471

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 5 July 2019 2:25 PM
To: ying@smemotor.com.sg; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: jacob.ang@smemotor.com.sg; sebastian@smemotor.com.sg; MT_Claim_SG
Subject: RE: Emailing: SKN5568S, SKN55568S ESTIMATE Our Ref: 18/19/19/VC05/022026 [External General] TP
Attachments: 2024_001.pdf

DI- 407384R

WA: 4/7/19

Lonpac External - General

Without Prejudice

Dear Ying

Our Insured has not reported the accident.

Do you still want to arrange TP survey? If so, please liaise with LKK Auto Consultants Pte Ltd.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ying@smemotor.com.sg [mailto:ying@smemotor.com.sg]
Sent: Friday, 5 July, 2019 2:10 PM
To: GERALD POH WEE BIN; ONG LI LI
Cc: jacob.ang@smemotor.com.sg; sebastian@smemotor.com.sg
Subject: Re: Emailing: SKN5568S, SKN55568S ESTIMATE

Dear Gerald / Lili,

Re-send estimate.

Kindly advise liability and arrange for survey.

thanks & regards
YING

Veli Out
Survey 8/7/19

From: ying@smemotor.com.sg
Sent: Friday, July 5, 2019 1:04 PM
To: geraldph@lonpac.com ; llong@lonpac.com
Cc: jacob.ang@smemotor.com.sg ; sebastian@smemotor.com.sg
Subject: Emailing: SKN5568S, SKN55568S ESTIMATE

Dear Gerald / Lili,

your ref: YP7384R

Our ref: SKN5568S

DOA ON 04/07/2019

Forwards our estimate, gia report to you.

Kindly advise liaiblity.

thanks & regards

ying

Your message is ready to be sent with the following file or link attachments:

SKN5568S

SKN5568S ESTIMATE

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : LONPAC INSURANCE BHD
300, Beach Road, #17-04/07
THE CONCOURSE
Singapore 199555

TEL: 62507388 FAX: 62963767

ATTN: Motor Claim Department

Your Ref No: 19/LP/TP-132(07)

Claim Type: Third Party

Estimate No: EST0004936

Date: 05 Jul 2019

Policy No: D19MTPV01007989

Veh Reg No: SKN5568S

Make/Model: MAZDA 3

Reg. Date:

Estimate Repair Cost to Vehicle No :SKN5568S

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Parts				
1 FRT BONNET		1 PC	450.00	
2 FRT BONNET RUBBER		1 PC	35.00	
3 FRT BUMPER		1 PC	750.00	
4 FRT BUMPER RETAINER RH		1 PC	15.00	
5 FRT BUMPER CLIPS		10 PC	25.00	
6 FRT BUMPER BEAM (BELOW HEADLAMP)		1 PC	15.00	
7 FOG LAMP GARNISH RH		1 PC	50.00	
8 HEADLAMP RH		1 PC	920.00	
9 HEADLAMP PANEL RH		1 PC	220.00	
10 FRT FENDER RH		1 PC	160.00	
11 FENDER COWLING CLIPS		10 PC	20.00	
			2,660.00	
	Add 20%		532.00	3,192.00
Labour				
12 WIRE CHECKING		1 UNIT	20.00	
13 LABOUR CHARGE		1 UNIT	600.00	
14 SPRAY PAINTING		1 UNIT	650.00	
				1,270.00

Amount Before Excess S\$ 4,462.00

Add GST @ 7% 312.34

Total Amount payable S\$ 4,774.34

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED SEVENTY FOUR AND CENTS THIRTY FOUR ONLY

For SME Motor Pte Ltd


AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19012016/Ada3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Date : 17-01-2020	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 7384R	Veh. Inspected	SKN 5568S
Policy No.	Z18VC05000354	Coverage (\$)	0.00
Claim No.	18/19/19/VC05/022026	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	05/07/2019
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JM6BM42A8E0118448	Colour	SILVER
Odometer	82713	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/07/2019	Inspection Date	08/07/2019
Survey held at	SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 5568S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BONNET (WCP)	DISTORTED	450.00	450.00
1	FRT BONNET RUBBER (WCP)	TORN	35.00	35.00
1	FRT BUMPER (WCP)	TO REPAIR SEE LABOUR	750.00	-
1	FRT BUMPER RETAINER RH (WCP)	NECESSARY	15.00	15.00
10	FRT BUMPER CLIPS (WCP)	NECESSARY	25.00	25.00
1	FRT BUMPER BEAM (BELOW HEADLAMP) (WCP)	NOT NECESSARY	15.00	-
1	FOG LAMP GARNISH RH (WCP)	CUT	50.00	50.00
1	HEADLAMP RH (WCP)	CRACKED	920.00	920.00
1	HEADLAMP PANEL RH (WCP)	NOT NECESSARY	220.00	-
1	FRT FENDER RH (WCP)	DENTED	160.00	160.00
10	FENDER COWLING CLIPS (WCP)	NOT NECESSARY	20.00	-
2	FRT BONNET HINGE @\$26.00 (ADDITIONAL)(WCP)	BENT	52.00	52.00
	COST PLUS 20%		542.40	341.40
			3,254.40	2,048.40
LABOUR				
	WIRE CHECKING.		20.00	20.00
	LABOUR CHARGE.INCLUSIVE OF THE REPAIR OF FRT BUMPER.		600.00	500.00
	SPRAY PAINTING.		650.00	600.00
			1,270.00	1,120.00
GRAND TOTAL			4,524.40	3,168.40
RECOMMENDED COST OF REPAIRS				3,168.40

Report Ref No. CC4/LPC19012016/Ada3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.