

INS. CASE OWNER: CC 4/AIG1901 W18, K K ^{S3} LKK: IDAC:

Surveyor: Kenneth DOI: 8/7/19 Date/Time: 5/3/20
 Registered in Merimen: 8/7/19

Pre-assign / CCU / FTE
 Insured Vehicle No.: SKW 9016U Claim No.: 889345870666
 Name of Insured: SOH LIM SHEN KENNETH Policy No.:
 Insured Tel No.: HP: Make / Model:
 Excess Sec II :\$\$ D.O.A.: 3/3/19 Place of Accident:
 Is driver the owner? (YES / NO) Nature of Accident:
 If NO, Driver Name / Age: one Hong YAR OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No.: (VL: YES / NO) Insured Liability: % Final? Yes / No

889345870666 → → → → →
 INSRs: WSP: Tel: Liability: RMKS: AM Lim
 INSRs: WSP: Tel: Liability: RMKS:
 INSRs: WSP: Tel: Liability: RMKS:
 INSRs: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE / PIC
<u>9/3/2020</u> <u>klhndlvn</u>	<u>File pass to MK to close.</u>	
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI	
	After call Itr to OI	<u>101119</u>
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act	<input checked="" type="checkbox"/>
	Release Voucher	<input checked="" type="checkbox"/>
	Final Repair Bill	<input checked="" type="checkbox"/>
	Car Rental Invoice	<input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/>
	LTA / GIA	<input checked="" type="checkbox"/>
	Medical Bill	<input type="checkbox"/>
	PIR	<input type="checkbox"/>
	Mandate/Reject Instruction	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form	<input type="checkbox"/>

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by:
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: <u>L15</u>	<u>\$5 1,600</u>	(<u>3</u> days) Reduction: <u>43</u> %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>5/3/2020</u>	Confirm with: <u>ke</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability: % <u>100</u>	(Agreed / Assessed) BOLA S/N No.: <u>27</u>	If NO or B 2k, Ass. Lia: <u>(01 REAR END TP)</u>	
Repair Cost: <u>(61687)</u>	<u>\$5 1,712</u>		
Loss of Rental (LOR):	<u>\$5 -</u> (<u>-</u> days)		
Loss of Use (LOU):	<u>\$5 160</u> (<u>5 66</u> x <u>3</u> days)		
Loss of Income (LOI):	<u>\$5 -</u> (<u>5 -</u> x <u>-</u> days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> (Tick only one)		
GIA/LTA Search	<u>\$5 200</u>		
Medical:	<u>\$5 -</u>	1) Claim status: Normal/Reject/Private Settle	
Disbursement:	<u>\$5 -</u> (e.g. Tow/ Independent)	2) Report Format: <u>TP</u>	
Legal Cost:	<u>\$5 -</u>	3) Survey fee: <u>8320</u>	
Total:	<u>\$5 1,894</u>	Global Sum \$\$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	<u>\$5 1,894</u>	Name 1: <u>AH LIM MOTOR COMPANY</u>	
Payee 2: (Strike if N.A.)	<u>\$5 -</u>	Name 2:	
Payee 3: (Strike if N.A.)	<u>\$5 -</u>	Name 3:	

COPY SENT
10/3/2020

ALG.

ASSIGNMENT

Title

Date: 8/7/2019

Veh No:

STY 3959P

Vt Regn:

08 10

Estimated Cost

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No: STY 3959Y

Make:

Suzuki SX4

c.c.

1586

at Workshop n/s: Ah Lim Motor.

Colour:

M. Silver

A/C:

Insured / Std / Nil / NA

at No. 10 AMIC #01-09.

Sp. Reading:

8617P

T/Radio:

Insured / Std / Nil / NA

Insured:

Eng/No:

Policy No.

C/No:

JSAGYC 21500331434

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

8/7/2019 10-12 noon.

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F:

205/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

8/86

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

03 days

Res.: Yes or No

D.O.A.

3/7/19

D.O.I.

8/7/19

Lum Sum:

20 %

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

None n/s

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

U/S \$1,600 / Red \$1,201.95 / 45.1)

Date/Time, File Pass (if)

: Prelim. Report

Days Of Repair:

1)

: Final Report

Resurvey No. of Trip:

Date/Time, File Return (if)

2)

Arid Fee:

: Site Insp \$

Survey Fee:

Transportation:

Report Format:

: Interview \$

Files:

Comp. Copy / U/C (if)

: Tech Insp \$

Notes:

: Meet with \$

Other:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopaint Singapore 588047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimco@singnet.com.sg
 GST:M9-0009639-E RCB NO:064703008

SURVEYOR COPY

M/S : SEOW CHOEN FRANCIS
 22 SARACA ROAD

SINGAPORE 807368

TEL: 92265206

ATTN:

Your Ref No: SJY3959P
 Claim Type: Third Party
 Accident Date: 03/07/2019
 TP Veh Reg No: SKW9016U

M/C
10-12

Estimate No: MC1900508
 Date: 05 Jul 2019
 Policy No: GA013720
 Veh Reg No: SJY3959P
 Make/Model: SUZUKI SX4 SEDAN 1.6
 AT

Not authorized
6/11/19 B7
Recovery After Paint 3days!

Estimate Repair Cost to Vehicle No :SJY3959P

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	<i>Per</i> 675.25	—
2 REAR BUMPER SIDE-RETAINERS LH & RH	2 PC	<i>Per</i> 60.00	X
3 REAR BUMPER CLIPS	12 PC	<i>Per</i> 36.00	—
4 REAR BUMPER LOWER SPOILER	1 PC	<i>M/M</i> 748.55	—
5 REAR BUMPER REFLECTOR	1 PC	<i>Per</i> 20.00	X
6 REAR BUMPER REINFORCEMENT	1 PC	<i>R</i> 227.20	X
		1,767.00	
	Less 15%	265.05	1,501.95
Special Nett			
7 REVERSE-SENSOR	1 SET	<i>Per</i> 300.00	X
		300.00	200.00
LABOUR			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS. TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>100</i>
9 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>500</i>
10 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD. TO KNOCK & REPAIR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>300</i>
11 TO SPRAY REAR BUMPER, REAR BOOT, REAR BUMPER LOWER SPOILER.	1 PC	500.00	<i>400</i>
		1,100.00	1,100.00
Total			S\$ 2,801.95
Add GST @ 7%			196.14
Total Amount Payable			S\$ 2,998.09

TOTAL: SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED NINETY EIGHT AND CENTS NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

For AH LIM MOTOR COMPANY


 AUTHORIZED SIGNATURE

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST-M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SEOW CHOEN FRANCIS
 22 SARACA ROAD

SINGAPORE 807368

TEL: 92265206

ATTN:

Estimate No: MC1900508

Date: 05 Jul 2019

Policy No: GA013720

Veh Reg No: SJY3959P

Make/Model: SUZUKI SX4 SEDAN 1.6
 AT

Your Ref No: SJY3959P

Claim Type: Third Party

Accident Date: 03/07/2019

TP Veh Reg No: SKW9016U

ACG
10-12

Not authorized
6/10/19
Recovery After Paint
3 days

Estimate Repair Cost to Vehicle No :SJY3959P

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BUMPER	1 PC	<i>Per</i> 675.25	—
2 REAR BUMPER SIDE RETAINERS LH & RH	2 PC	<i>50</i> 60.00	X
3 REAR BUMPER CLIPS	12 PC	<i>30</i> 36.00	—
4 REAR BUMPER LOWER SPOILER	1 PC	<i>not 10/1</i> 748.55	—
5 REAR BUMPER REFLECTOR	1 PC	<i>50</i> 20.00	X
6 REAR BUMPER REINFORCEMENT	1 PC	227.20	?
		1,767.00	
	Less 15%	265.05	1,501.95
Special Nett			
7 REVERSE SENSOR	1 SET	200.00	?
		200.00	200.00
LABOUR			
8 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>100</i>
9 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	<i>500</i>
10 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD. TO KNOCK & REPAIR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	<i>300</i>
11 TO SPRAY REAR BUMPER, REAR BOOT, REAR BUMPER LOWER SPOILER.	1 PC	500.00	<i>400</i>
		1,100.00	1,100.00
		Total	SS 2,801.95
		Add GST @ 7%	196.14
		Total Amount Payable	SS 2,998.09

Liability Contribution hence notify the Receiver of the following:

- To survey & estimate spray painting
- To remove damaged parts during survey
- Party prices are subject to confirmation
- The parts are used in a "Vehicle Preparation" tank
- To clean up, including disposal
- Supplementary work cannot be surveyed and is subject to approval from Insurance Company

Not liable to repair

TOTAL- SINGAPORE DOLLAR TWO THOUSAND NINE HUNDRED NINETY EIGHT AND CENTS NINE ONLY

Please arrange this vehicle to be surveyed soonest possible.
 Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

KF

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK, Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmco@singnet.com.sg
 GST-M9-0009639-E RCB NO:06470300B

DRAFT FINALIZATION

M/S : SEOW CHOEN FRANCIS
 22 SARACA ROAD

 SINGAPORE 807368
 TEL: 92265206
 ATTN:

Claim No: MC1900508
 No: MF1900554
 Date: 09 Sep 2019
 Policy No: GA013720
 Veh Reg No: SJY3959P
 Make/Model: SUZUKI SX4 SEDAN 1.6
 AT

Your Ref No: SJY3959P
 Claim Type: Third Party
 Accident Date: 03/07/2019
 TP Veh Reg No: SKW9016U

Repair Cost to Vehicle No (For Finalization):SJY3959P

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	675.25	
2 REAR BUMPER CLIPS	12 PC	36.00	
3 REAR BUMPER LOWER SPOILER	1 PC	748.55	
		1,459.80	
	Less 15%	218.97	1,240.83
LABOUR			
4 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	10.00	
5 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	50.00	
6 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR END PANEL INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	
7 TO SPRAY REAR BUMPER,REAR BOOT,REAR BUMPER LOWER SPOILER.	1 PC	400.00	
		760.00	760.00
	Total		S\$ 2,000.83
	Lump Sum Less 20%		-400.17
	Sub Total		S\$ 1,600.66
	Less Rounding		-0.66
	Lump Sum Repair		S\$ 1,600.00 ✓dk
	Less Excess		S\$ 0.00
	Amount Before GST		S\$ 1,600.00
	Add GST @ 7%		112.00
	Total Amount Payable		S\$ 1,712.00

TOTAL: SINGAPORE DOLLAR ONE THOUSAND SEVEN HUNDRED TWELVE ONLY

The above vehicle was surveyed by KENNETH KONG -L.KK on 08/07/2019

For AH LIM MOTOR COMPANY

(Signature)
 401-09 AMK, Singapore Tel: 6483 1244 Fax: 6483 6170
 AUTHORIZED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5426J

Vehicle Details

Vehicle No.: SJY3959P
Vehicle to be Exported: No
Intended Deregistration Date: 04 Jul 2019
Vehicle Make: SUZUKI
Vehicle Model: SX4 SEDAN 1.6 AT
Primary Colour: Silver
Manufacturing Year: 2010
Engine No.: M16A1515449
Chassis No.: JSAGYC21500331434
Maximum Power Output: 82.0 kW (109 bhp)
Open Market Value: \$14,917.00
Original Registration Date: 27 Aug 2010
First Registration Date: 27 Aug 2010
Transfer Count: 1
Actual ARF Paid: \$14,917.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Aug 2020
PARF Rebate Amount: \$8,204.00

Intended COE Rebate Details

COE Expiry Date: 26 Aug 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$29,000.00
COE Rebate Amount: \$3,313.00
Total Rebate Amount: \$11,517.00

The information contained herein is correct as at 04 Jul 2019

OK

Shu Pei (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Monday, 8 July 2019 4:27 PM
To: Shu Pei (LKKAuto); assignments
Cc: Admin A
Subject: RE: TP / OUR CLIENT SJY3959P DOA: 03/07/2019 POLICY NO. GA013720 YOUR INSURED SKW9016U

Dear Shu Pei,

Yes we have arranged.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]
Sent: Monday, 8 July 2019 4:18 PM
To: assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: FW: TP / OUR CLIENT SJY3959P DOA: 03/07/2019 POLICY NO. GA013720 YOUR INSURED SKW9016U

Hi Assignments team,

Have we arrange survey?

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Sent: Friday, 5 July 2019 4:59 PM
To: assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Subject: TP / OUR CLIENT SJY3959P DOA: 03/07/2019 POLICY NO. GA013720 YOUR INSURED SKW9016U



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ
เพื่ออ่านมัน ให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면
첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-07-12 16:59 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 5426J

Vehicle Details

Vehicle No.: SJY3959P
Vehicle to be Exported: No
Intended Deregistration Date: 04 Jul 2019
Vehicle Make: SUZUKI
Vehicle Model: SX4 SEDAN 1.6 AT
Primary Colour: Silver
Manufacturing Year: 2010
Engine No.: M16A1515449
Chassis No.: JSAGYC21500331434
Maximum Power Output: 82.0 kW (109 bhp)
Open Market Value: \$14,917.00
Original Registration Date: 27 Aug 2010
First Registration Date: 27 Aug 2010
Transfer Count: 1
Actual ARF Paid: \$14,917.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Aug 2020
PARF Rebate Amount: \$8,204.00

Intended COE Rebate Details

COE Expiry Date: 26 Aug 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$29,000.00
COE Rebate Amount: \$3,313.00
Total Rebate Amount: \$11,517.00

The information contained herein is correct as at 04 Jul 2019

OK



redefining / insurance

AXA Insurance Pte Ltd
 1800 880 4888 (Within Singapore)
 (65) 6880 4888 (International)
 (65) 6880 4740
 customer.care@axa.com.sg
 www.axa.com.sg

SEOW CHOEN FRANCIS
 22 SARACA ROAD
 SINGAPORE 807368

Renewal

date
 15/01/2019

your servicing distributor
 KHC HOLDINGS PTE LTD / 03180

your servicing distributor contact
 62538288

Policy Schedule

Your SmartDrive Comprehensive Private APW

Your policy snapshot

Policyholder name	SEOW CHOEN FRANCIS	Policy number	VA1 / GA013720
Cover	Comprehensive	FIN / NRIC	S1245426J
Period of Insurance	from 27/02/2019 to 26/02/2020 (both dates inclusive)		

Premium breakdown

Gross Premium after 40% NCD	SGD 1,128.38
Total Discounts	- SGD 60.05
7% GST	SGD 74.64
Final Premium	SGD 1,140.97

Your benefits highlights

(refer to Policy Wording for full terms and conditions)

SmartDrive Comprehensive Private APW Benefits

- 24/7 Towing & Transportation in Singapore or Overseas
- Guaranteed Repairs for twelve (12) Months
- Loss or Damage
- Legal Liability
- Loss of Personal Effects in Singapore up to \$3,000
- Daily Transport Allowance of \$50 for a maximum of five (5) days
- Personal accident benefit of up to \$30,000 for you or your named drivers while driving
- Medical and dental expenses up to \$500 per person for either you as the driver or your authorised driver and a passenger
- Basic Own Damage Excess Reduction for AXA Premium Workshop
- Windscreen Replacement with Excess OR Repair your windscreen at your preferred location and get \$50 cash reward with no excess

Vehicle details

Make & Model of Vehicle	SUZUKI SX4 1.6	Year of manufacture	2010
Vehicle registration number	SJY3959P	Type of Use	Private use
Body type	SALOON	Engine capacity (c.c.)	1586
Seating capacity (excl driver)	4	Engine number	M16A1515449
Off-Peak car	No	Chassis number	JSAGYC21S00331434

Insured's Estimated Market Value	Market Value at the time of Loss (including accessories and spare parts)
Limitation to use	As per Certificate of Insurance
Finance Loan Company	Nil

Excess applicable (refer to Policy Wording for other applicable Excesses)

Basic Own Damage Excess	SGD 250.00
Windscreen Excess	SGD 100.00

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com,assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : Syed-Yusoff, SalihaYour Ref : 8853458706SG
Our Ref : CC4/AIG19012018/KKB3
Date : 11 Nov 2019**"WITHOUT PREJUDICE"****ACCIDENT INVOLVING SKW9016U & SJY3959P ON 03/07/2019**

Refer to the above accident.

The accident occurred when it is a front to rear collision (BOLA 27). We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SKW9016U) and third party claimant (vehicle no. SJY3959P).

Summary of offer made to workshop Ah Lim Motor Company is as follows :

	Claimed	Revised
Cost of Repairs (w/GST)	\$ 2,998.09	\$ 1,712.00
Loss of Use (\$60 x 3 days)	\$ 180.00	\$ 180.00
LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 3,180.09	\$ 1,894.00

Amount of claim at **Liability 100%** \$ 1,894.00

**3 days recommendation for repair

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
Khanchna Pothuraj
LKK Auto Consultants Pte Ltd

Print Received Message

This mail is associated with :

*SJV3959P (8853458706SG)
[SKW9016U]
TP
SEOW CHOEN FRANCIS
Jul 3 2019 9:00PM
[SOH CHAI SHEN KENNETH]
Ah Lim Motor Company

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 03/03/2020 10:44 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$1894.00) - SJV3959P - Claim Handler: Syed-Yusoff, Saliha

Approved:1894.00:pls proceed with settlement @ \$1894.00 [COR- \$1712 LOU-\$180 LTA-\$2] **subject to final repair bill & ATA

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 5 March 2020 3:03 PM
To: muihong@ahlimmotor.com.sg
Cc: Admin A
Subject: YOUR CLIENT SJY3959P DOA: 03/07/2019 accident with AIG INSURED SKW9016U
Attachments: AIG DV.pdf

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as per your LOD **(\$1,894.00(all in))**.

We attach herewith a copy of the DV for your further action.

Kindly e-mail the DV to us for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

From: Mui Hong @ Ah Lim Motor
Sent: Tuesday, 10 September 2019 5:59 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Chin, Lee-Ying <Lee-Ying.Chin@aig.com>
Subject: Claim Documents for OUR CLIENT SJY3959P DOA: 03/07/2019 accident with AIG INSURED SKW9016U

Dear claims,

Pls see attached the Claim Documents for OUR CLIENT SJY3959P DOA: 03/07/2019 accident with AIG INSURED SKW9016U.

Pls advise your offer.

Thanks

Best Regards,

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jul 2019 Edit Reg		05 Jul 2019 00:00 Edit Adj Rpt	S\$1,600.00 Edit Estimates	S\$1,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: SOH CHAI SHEN KENNETH , ID: 57000346E									
Main Claimant: SEOW CHOEN FRANCIS , ID: S12454263									
Vehicle Reg. No.:	SJY3959P	Date of Loss:	03/07/2019 21:00 - :59 [106 Months and 6 Days From LTA Reg. Date (Man Yr)]						
Claim Type:	TP / 8853458706SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKW9016U	Policy No. (Claimant):	GA013720						
		Excess:							
Repairer:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6483 1244								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/07/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (03/03/2020): Alert - Adj Mandate Approved (S\$1894.00) - SJY3959P - Claim Handler: Syed-Yusoff...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJY3959P (8853458706SG)
[SKW9016U]
TP
SEOW CHOEN FRANCIS
Jul 3 2019 9:00PM
[SOH CHAI SHEN KENNETH]
Ah Lim Motor Company

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/19 17:09	Video - Accident	Load MP4	<input type="checkbox"/>
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	<input type="checkbox"/>
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/11/19 11:26	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/11/19 11:08	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	11/11/19 11:08	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	11/11/19 11:08	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	11/11/19 11:08	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	11/11/19 11:08	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	11/11/19 11:08	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	11/11/19 11:08	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	11/11/19 11:08	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	11/11/19 11:08	General View	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	11/11/19 11:08	Chassis Number	Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/07/19 16:33	EMAIL FROM AIG DD 05072019	Load PDF	<input type="checkbox"/>
2	08/07/19 16:33	TP GIA REPORT	Load PDF	<input type="checkbox"/>
3	18/10/19 15:52	LETTER TO OI	Load PDF	<input type="checkbox"/>
4	28/02/20 16:59	TP ESTIMATE-MARKED-FINAL	Load PDF	<input type="checkbox"/>
5	13/03/20 13:47	WORKSHOP INVOICE	Load PDF	<input type="checkbox"/>
6	13/03/20 13:47	AUTHORISATION TO ACT FORM	Load PDF	<input type="checkbox"/>
7	13/03/20 13:47	Release Voucher	Load PDF	<input type="checkbox"/>
8	13/03/20 13:47	GIA SEARCH	Load PDF	<input type="checkbox"/>
9	13/03/20 13:47	LOD	Load PDF	<input type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/07/19 13:26	OI GIA REPORT	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	



NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKW9016U (Insd veh)	Model:	SUZUKI SX4 1.6 (A)
	SJY3959P (TP veh)		
Date of Accident:	03/07/2019		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$	2,998.09	
Final Repair Cost	:	\$	1,712.00	
Loss of Use	:	\$	180.00	3.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	1,894.00	

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ — BOLA Scenario No: 27

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Ah Lim Motor Company	:	\$ 1,894.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

13 Mar
2020
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19012018/KKS3Q2

Date: 13/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SJY3959P

Insured Vehicle No : SKW9016U

Date of Loss: 03/07/2019

Nature of Claim: TP

Claim No: 8853458706SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY3959P**

Make & Model: SUZUKI SX4, 1.6 (A)

Engine No: M16A1515449

Reg. Date: 27/08/2010 (Man. Year: 2010)

Chassis No: JSAGYC21S00331434

Colour: Metallic Silver

Odometer: 86179 km

Engine Capacity: 1586 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/50 R17

Rear Tyre Size: 205/50 R17

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,701.95	1,240.83	461.12	27.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	760.00	340.00	30.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,801.95	2,000.83	801.12	28.59
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	2,801.95	1,600.00	1,201.95	42.90
+ GST 7.00/7.00% (S\$)	196.14	112.00	84.14	42.90
Nett Amount (S\$)	2,998.09	1,712.00	1,286.09	42.90
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,894.00		

INSPECTION

Date of Assignment: 05/07/2019

Date Inspected: 08/07/2019 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A,
#01-09 AMK Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	675.25 FL	*675.25 FL
2	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	60.00 FL	*- FL
3	12		*REAR BUMPER CLIPS	Necessary	36.00 FL	*36.00 FL
4	1		*REAR BUMPER LOWER SPOILER	Dented / Distorted	748.55 FL	*748.55 FL
5	1		*REAR BUMPER REFLECTOR	Serviceable	20.00 FL	*- FL
6	1		*REAR BUMPER REINFORCEMENT	Repair	227.20 FL	*- FL
7	1		*SET REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,967.00	1,459.80
- List Item Discount on L Items 15.00/15.00% (S\$)	265.05	218.97
Total Parts (S\$)	1,701.95	1,240.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	10.00
2	TO REMOVE AND REINSTALL /REPLACED FRONT /REAR BUMPER SENSORS	New	60.00	50.00
3	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD TO KNOCK & REPAIR END PANEL INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	500.00	300.00
4	TO SPRAY REAR BUMPER ,REAR BOOT ,REAR BUMPER LOWER SPOILER	New	500.00	400.00
Gross Labour Cost (S\$)			1,100.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >