

NATIONAL ASSESSMENT CENTRE SERVICES (LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park, Singapore 408933, TEL: 68410055 FAX: 68416315

Your Ref

: MT/1059369-002

Date: 4th September 2019

Our Ref

: NS/INC19012068/Ngf3s2

M/s NTUC Income Insurance Co-Operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556 (The Motor Claims Department)

Dear Sir/Madam,

AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO SHB 956L ACCIDENT ON 30/06/2019 INSURED SMH 3861R

Instruction was received to inspect the vehicle Reg. No. SHB 956L. The inspection was conducted on 08/07/2019 at the premises of M/s SMRT Automotive Services Pte Ltd, 60 Woodlands Industrial Park E4 Singapore 757705.

The following information were recorded: -

Registration Number

: SHB 956L

Make & Model

: Toyota Prius

Year of Registration

: 2014

Engine Capacity Body Colour

: 1798 cc : Maroon

Chassis Number

: JTDKN36U005720679

The vehicle sustained damages at the front portion. The Estimated repair cost of such vehicle is S\$19,000.00 (Sin Dollars: Nineteen Thousand only.) (Details see photographs enclosed).



NATIONAL ASSESSMENT CENTRE SERVICES (LKK GROUP)

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park, Singapore 408933, TEL: 68410055 FAX: 68416315

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as "**uneconomical Total Loss**".

Book Value S\$ 45,108.60 (est)

Less: LTA Reimbursement Value (RV) (S\$ 24,730.00)

Nett Liability S\$ 20,378.60

Vehicle Inspected By:

12

MUHD NAZRIL (NAZ)

Technical Investigator LL.B. (Hons) London

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK), MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIIE(mech), MinstAEA, MFIEA,

MIRTE, MIMI, MSAE, MCIArd, AM, NIJAAR (USA), AM CATARI (CAN), M. MATA (USA), M. MdATA (USA),

Licensed Appraiser

<u>DISCLAIMER OF LIABILITY TO THIRD PARTIES:-</u> This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.