

7/20/2019

ASS. REC. BY:

REF: CS/FCI19012071/RIV1312

Special Instructions:

Assigner: Rasi

ASSIGNMENT (Office)

From (Person): Henry Kao

of FCI

Date/Time: 8:38am @ 9/7/19

Estimated Cost:

Bill to:

OD/IT/WT/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL9404D

Insured:

SHC0117L

at Workshop m/s

cycle & Cerning

Tel:

9144 9137

of

209 Pandan Gardens

Claim No:

D1900443SMFSH

Policy No:

Sum Insured:

Excess:

D.O.A. 05/07/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time: 10:09am @ 9/7/19

Person Contacted:

Andre

Vehicle IN/OUT

Date/Time

Action/Instruction 1. shima 1 ✓

SHC0117L : CS/FCI17002542/IT1vbn2 D.O.A. 06/02/2019

SLL9404D-X

17/7/19

Email preli revised to FCI

18/8/19

@ 251pm Andre said vehicle under repair

13/9/19

@ 249pm Andre said vehicle just release

(08/11/19)

Surveyor

REF:

FC1

6440R

ASSIGNMENT

From:

Date:

4/2/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SU 9404D

at Workshop m/s

CBC

of

209 Pandan Gardens

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

4 m. Andre owner waiting
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SU 9404D

Yr Regn:

2017 / max

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Outlander 2.4 C.C. 2360

Colour:

Green

A/C: Insured / Std / NI / NA

Sp. Reading

08 2670

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYXTHF3WH 2001052

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

05/07/19

D.O.I.

16/07/19

Survey held at

CBC (Ph)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/11/19 Final fig \$ 6104 confirmed by email (Red 4041, 4019)

RECEIVED 20 SEP 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 20/11/19 - typist

Days Of Repair:

7

Resurvey No. of Trip:

-

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

170

50

44

264

Report Format:

CWS

Lump Sum / I.B.I. (\$

6104)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19004435MFSH

Our Ref: CS/FCI19012071/R1vf3

Date : 17/7/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO: SLL 9404D


We thank you for your instruction on 9/7/2019

Please be informed that we had conducted the inspection of the above mentioned
16/7/2019 at the premises of M/s CYCLE & CARRIAGE AUTOMOTIVE PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$10,118.00
Revised Estimate Amount	: S\$6,172.00
"Check" Items Amount	: S\$1,240.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
rear poriton



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-07-2019	Our Ref No. D19004435MFSH
Accident Date	05-07-2019	Claim Type. Third Party
Insured Vehicle	SHC0117L	Third Party Vehicle. SLL9404D
Survey Location	209 PANDAN GARDENS	
Contact Person.	ANDRE CHOW	
Contact No.	65684555/ 0	Fax No. 65691056
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 17 July 2019 2:15 PM
To: 'CWS Motor Claims'
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19004435MFSH/1, SLL 9404D
Attachments: SLL 9404D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLL 9404D
Date of survey: 16/7/2019
Number of days : 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 9 July 2019 10:11 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19004435MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 9 July 2019 8:37 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie

<HenryKao@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19004435MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 20 September 2019 9:41 AM
To: Loi Ai Ting; Taufikh (LKKAUTO)
Cc: Admin A; Cheng Jo Jo; Songcuan JR Lauro Araos; Andre Chow En De; SUR
Subject: RE: SLL9404D, finalisation (Mit WIP: 42075)

Dear Ms Loi,

WITHOUT PREJUDICE

Confirm finalised amount at \$6104 before GST @ 7 working days.

Kindly send Final invoice and all supporting documents directly to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Loi Ai Ting <aiting.loi@cyclecarriage.com.sg>
Sent: Wednesday, 18 September 2019 3:31 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAUTO) <admin-d@lkkauto.com>; Cheng Jo Jo <jojo.cheng@cyclecarriage.com.sg>; Songcuan JR Lauro Araos <lauro.songcuan@cyclecarriage.com.sg>; Andre Chow En De <andre.chow@cyclecarriage.com.sg>
Subject: SLL9404D, finalisation (Mit WIP: 42075)

Hi, Taufikh,


Please confirm finalised amount at \$6,531.28 after GST.

Apologise as we do not have before paint photos.

Thanks.

Best Regards,

Loi Ai Ting
Senior Officer - Admin



CYCLE & CARRIAGE

Exceptional Journeys

Cycle & Carriage Singapore • 209 Pandan Gardens, Singapore 609339
T: +65 6568 4556 • F: +65 6565 1240 • www.cyclecarriage.com.sg



MEMBER OF THE UOB GROUP

United Overseas Insurance Limited

3 Anson Road
#28-01 Springleaf Tower
Singapore 079909

Tel (65) 6222 7733
Fax (65) 6327 3869 / 6327 3870
Email: ContactUs@uoi.com.sg
uoi.com.sg

Co. Reg. No. 197100152R

Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE NO.	DHOM110160721801	Excess:	\$600/-ALL DRIVERS \$3000/-APPL TO <25 YRS & OR <3YRS EXP \$100/-WINDSCREEN DAMAGE CLAIM
Type of Cover	COMPREHENSIVE		
Vehicle Number	SLL9404D		
Name of Insured	ATS AGRO INDUSTRIES PTE LTD		
Restricted Driver(s)	NOT APPLICABLE		

Period of Insurance 16 March 2019 to 15 March 2020

Hire Purchase HL BANK

Engine# 4B12SD6403
Chassis# JMYXTGF3WHZ001052

Private Car-Office [MX 4]

AUTHORISED DRIVER

Any person who is driving on the Insured's order or with their permission

LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and for the Insured's business

THE POLICY DOES NOT COVER

- (1) Use for hire or reward or pace-making reliability trial or speed-testing
- (2) Use for the carriage of goods other than samples in connection with any trade or business
- (3) Use for any purpose in connection with the Motor Trade

Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and part IV of the Road Transport Act, 1987 (Malaysia).

UNITED OVERSEAS INSURANCE LTD

FCTTS Date : 22/02/2019

For the Company

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2688075J



Name

PUTRA FAJAR

Race

MALAY

Date of Birth

06-09-1965

Country/Place of Birth

INDONESIA

Sex

M

REPUBLIC OF SINGAPORE DRIVING LICENCE


Licence Number: S2688075J

Name

PUTRA FAJAR

Birth Date: 06 Sep 1965

Issue Date: 22 Jan 2003



000144332D

FOR C&C USE ONLY

9357010



NRIC No. S2688075J



Nationality

INDONESIAN

Date of Issue

03-01-2015

Address


APT BLK 656A JURONG WEST STREET 61
#02-347
SINGAPORE 641656

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

26 Jan 1998

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms



Licence No: S2688075J

FOR C&C USE ONLY



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Ats Agro Industries Pte Ltd 134 Gul Circle Singapore 629598 Attn: Ms Norsiah Binte Imam Contact No Mobile: 98628849	Cust No/Name	/Ats Agro Industries Pte Ltd
	Reg No/Reg Date	SLL9404D / 16/03/201
	Date In/Mileage	/ 0
	Chassis No	JMYXTGF3WHZ001052
	Engine No	4B12SD6403
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	06/07/2019/ 09:40	QUA	265 / AndreChow	42075			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000		RENEW ACCIDENT DAMAGED PORTION ON REAR BUMPER, REAR TAILGATE, REPAIR REAR END PANEL AND REALIGN BODY GAPS						1650 2750.00
E PNT88000		REMOVE AND INSTALL REVERSE SENSORS						60 150.00
E PNT88000		REMOVE AND INSTALL TAILGATE GLASS						240.00
E PNT88000		REMOVE AND INSTALL REAR TAILGATE TRIM, MECHANISM AND ELECTRONICS TO FACILITATE REPAIRS						120 550.00
E PNT88000		REMOVE AND INSTALL REAR COMPARTMENT TRIM, CARPET TO FACILITATE REPAIR						160 550.00
A 54900099		CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM						30 100.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						200.00
M SUNDRY		SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS						40 80.00
M SUNDRY		SUPPLY BODY SEALANT FOR AFFECTED PORTIONS						40 80.00
M SUNDRY		SUPPLY WINDSCREEN SEALANT						80.00
M SUNDRY		SUNDRIES						20 40.00
M SUNDRY		SUPPLY REVERSE SENSORS						250.00
E PNT98000		RESPRAY ACCIDENT DAMAGED PORTION ON REAR BUMPER, TAILGATE, REAR END PANEL AND OTHER AFFECTED PORTIONS						1260 1680.00
M FACE,RR BUMPER					1.00	873.00	00.00	873.00
M BRKT,R/BMPR FACE SIDE,RH					1.00	12.00	00.00	12.00
M BRKT,R/BMPR FACE SIDE,LH					1.00	12.00	00.00	12.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
Ats Agro Industries Pte Ltd	Cust No/Name /Ats Agro Industries Pte Ltd
134 Gul Circle	Reg No/Reg Date SLL9404D / 16/03/201
Singapore 629598	Date In/Mileage / 0
Attn: Ms Norsiah Binte Imam	Chassis No JMYXTGF3WHZ001052
Contact No Mobile: 98628849	Engine No 4B12SD6403
	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	06/07/2019/ 09:40	QUA	265 / AndreChow	42075			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	EXTENSION,RR BUMPER	de	✓		1.00	230.00	00.00	230.00
M	PANEL ASSY,TAILGATE	bt	✓		1.00	974.00	00.00	974.00
M	LATCH,TAILGATE	? x su	✓		1.00	470.00	00.00	470.00
M	DAM,TAILGATE,UPR	Rec	✓		1.00	12.00	00.00	12.00
M	FASTENER,WINDSHIELD	Rec	✓		1.00	6.00	00.00	6.00
M	DAM,TAILGATE,LWR	Rec	✓		1.00	41.00	00.00	41.00
M	STOPPER,WINDSHIELD GLASS	Rec	✓		1.00	3.00	00.00	3.00
M	DAM,TAILGATE SIDE	Rec	✓		1.00	27.00	00.00	27.00
M	W/STRIP,TAILGATE OPENING	? x su	✓		1.00	211.00	00.00	211.00
M	MARK,OUTLANDER	Rec	✓		1.00	94.00	00.00	94.00
M	REFLECTOR,TAIL LAMP,RH	X	✓		1.00	94.00	00.00	94.00
M	REFLECTOR,TAIL LAMP,LH	? x su	✓		1.00	99.00	00.00	99.00
M	MOULDING,RR BUMPER,LH	? x	✓		1.00	105.00	00.00	105.00
M	MOULDING,RR BUMPER,RH	? x	✓		1.00	105.00	00.00	105.00

SURVEYOR NAME: Rasuc - Hp 90010068

SURVEYOR SIGNATURE:

DATE: 16/07/19 @ 1600

REMARKS: 7 days

Resy before print

10,145

Confirm & accepted by

Nett 10,118.00
 7% GST on 10118.00 708.26
Total Payable 10,826.26

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Surveyor : TAUFIKH LKK
 Claim : TP FIRST CAPITAL
 DOA : 05.07.2019
 Emailed : 18.09.2019, 3.30pm
 Date survey : 16.07.2019

VEHICLE NO : SLL 9404 D
 MODEL : MIT OUTLANDER 2.4
 WIP : 42075

Material	:	\$	<u>2,204.00</u>
Labour	:	\$	<u>3,900.00</u>
Sub-Total	:	\$	<u>6,104.00</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>6,104.00</u>
GST 7%	:	\$	<u>427.28</u>
Grand Total	:	\$	<u>6,531.28</u>
Finalise By/Date	:		<u>LOI / 18/09/2019</u>

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 7 WORKING DAYS + 2 Days (1) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 9

☒ TP claim SHC117L

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE****THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
MS FIRST CAPITAL INSURANCE LIMITED	Cust No/Name /Ats Agro Industries Pte Ltd
MOTOR CLAIMS DEPARTMENT	Reg No/Reg Date SLL9404D / 16/03/2017
36 ROBINSON ROAD #16-01	Date In/Mileage 22/08/2019/ 86072
CITY HOUSE	Chassis/Package JMYXTGF3WHZ001052
SINGAPORE 068877	Engine No 4B12SD6403
Contact No	Make/Model MIT/OUTLANDER 2.4 CVT AWD (E44)
22/08/	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	16/09/2019/ 19:52	TLA	260 / AiTing	42075			
Description of Goods/Services					Qty	Unit Price	Disc%	Amount
E PNT88000								✓ 1650.00
REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REAR TAILGATE, REPAIR REAR								
END PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS								
ALIGNMENT TO THE SAME								✓ 60.00
E PNT88000								
REMOVE AND INSTALL REVERSE SENSORS TO FACILITATE REPAIR								✓ 240.00
E PNT88000								
REMOVE AND INSTALL TAILGATE GLASS TO FACILITATE REPAIR								✓ 120.00
E PNT88000								
REMOVE AND INSTALL REAR TAILGATE TRIMS, MECHANISMS AND ELECTRONICS TO								✓ 160.00
FACILITATE REPAIR								
E PNT88000								✓ 30.00
REMOVE AND INSTALL REAR COMPARTMENT TRIMS, CARPET TO FACILITATE REPAIR								
A 54900099								✓ 200.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 10028901								✓ 40.00
CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								
M SUNDRY								✓ 40.00
SUPPLY ANTI CORROSION ON AFFECTED PORTIONS								
M SUNDRY								✓ 80.00
SUPPLY BODY SEALANT ON AFFECTED PORTIONS								
M SUNDRY								✓ 20.00
SUPPLY REAR WINDSCREEN GLASS SEALANT								
M SUNDRY								✓ 1260.00
SUNDRIES								
E PNT98000								
RESPRAY ON REAR BUMPER, TAILGATE, REAR END PANEL, AND ALL OTHER								
AFFECTED PORTIONS TO THE SAME								
X FACE,RR BUMPER					873	1.00	✓ 799.00 00.00	799.00
X EXTENSION,RR BUMPER						1.00	✓ 230.00 00.00	230.00
X PANEL ASSY,TAILGATE						1.00	✓ 974.00 00.00	974.00
X DAM,TAILGATE,UPR						1.00	✓ 12.00 00.00	12.00
X DAM,TAILGATE,LWR						1.00	✓ 41.00 00.00	41.00

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS FIRST CAPITAL INSURANCE LIMITED MOTOR CLAIMS DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 Contact No 22/08/	Cust No/Name	/Ats Agro Industries Pte Ltd
	Reg No/Reg Date	SLL9404D / 16/03/2017
	Date In/Mileage	22/08/2019/ 86072
	Chassis/Package	JMYXTGF3WHZ001052
	Engine No	4B12SD6403
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (E44)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	16/09/2019/ 19:52	TLA	260 / Aiting	42075			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	DAM, TAILGATE SIDE			Supp. (1)	2.00	✓ 27.00	00.00	54.00
X	MARK, OUTLANDER				1.00	✓ 94.00	00.00	94.00
Z	TEXT							
	TP CLAIM FIRST CAPITAL SHC117L							
	DOA : 05.07.19							
	SURVEYOR TAUFIKH LKK 16.07.19							
	REPAIR 07 DAYS							
Pro Forma								
Cycle & Carriage celebrates 120 years. Visit www.cyclecarriage.com/120 for more info!								

Parts	2,204.00		Nett	6,104.00
Labour	3,720.00	7% GST on	6104.00	427.28
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	6,531.28
Sundry/Others	180.00			
Total(w/o GST)	6,104.00			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys


INSURANCE CO.: FIRST CAPITAL

Supplementary Parts For Registration No.: SLL 9404 D

<u>Material</u>	<u>Cost (\$)</u>	
1 Dam, tailgate side (x1)	27.00	rec ✓
Total Taxable	27.00	
7% GST	1.89	
Grand total	<u>28.89</u>	

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD


LOI AI TING
SENIOR OFFICER - ADMIN
DID : 6568 45556 / 6568 4501
FAX : 6567 5258 / 6565 1240




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19012071/R1vf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-09-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 117L	Veh. Inspected	SLL 9404D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19004435MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	09/07/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI OUTLANDER 2.4	c.c	2360	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JMYXTGF3WHZ001052	Colour	GREY	
Odometer	82670	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R18	DUNLOP	6 mm	
L/H Front Tyre	225/55 R18	DUNLOP	6 mm	
R/H Rear Tyre	225/55 R18	DUNLOP	6 mm	
L/H Rear Tyre	225/55 R18	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/07/2019	Inspection Date	16/07/2019	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 9404D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACE,RR BUMPER (SN)	DEFORMED	873.00	799.00
1	BRKT,R/BMPR FACE SIDE,RH (SN)	SERVICEABLE	12.00	-
1	BRKT,R/BMPR FACE SIDE,LH (SN)	SERVICEABLE	12.00	-
1	EXTENSION,RR BUMPER (SN)	DEFORMED	230.00	230.00
1	PANEL ASSY,TAILGATE (SN)	BENT	974.00	974.00
1	LATCH,TAILGATE (SN)	SERVICEABLE	470.00	-
1	DAM,TAILGATE,UPR (SN)	NECESSARY	12.00	12.00
1	FASTENER,WINDSHIELD (SN)	NOT NECESSARY	6.00	-
1	DAM,TAILGATE,LWR (SN)	NECESSARY	41.00	41.00
1	STOPPER,WINDSHIELD GLASS (SN)	NOT NECESSARY	3.00	-
1	DAM,TAILGATE SIDE (SN)	NECESSARY	27.00	27.00
1	W/STRIP,TAILGATE OPENING (SN)	SERVICEABLE	211.00	-
1	MARK,OUTLANDER (SN)	NECESSARY	94.00	94.00
1	REFLECTOR,TAIL LAMP,RH (SN)	SERVICEABLE	94.00	-
1	REFLECTOR,TAIL LAMP,LH (SN)	SERVICEABLE	99.00	-
1	MOULDING,RR BUMPER,LH (SN)	SERVICEABLE	105.00	-
1	MOULDING,RR BUMPER,RH (SN)	SERVICEABLE	105.00	-
1	SUNDRIES (SN)	NECESSARY	40.00	20.00
1	REVERSE SENSORS (SN)	NOT NECESSARY	250.00	-
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	80.00
1	DAM,TAILGATE SIDE (ADDITIONAL)(SN)	NECESSARY	27.00	27.00
			3,765.00	2,304.00
LABOUR				
RENEW ACCIDENT DAMAGED PORTION ON REAR BUMPER,REAR TAILGATE,REPAIR REAR END PANEL AND REALIGN BODY GAPS.			2,750.00	1,650.00
REMOVE AND INSTALL REVERSE SENSORS.			150.00	60.00
REMOVE AND INSTALL TAILGATE GLASS.			240.00	240.00
REMOVE AND INSTALL REAR TAILGATE TRIM,MECHANISM AND ELECTRONICS TO FACILITATE REPAIRS.			550.00	120.00

Report Ref No. CS/FCI19012071/R1vf3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND INSTALL REAR COMPARTMENT TRIM,CARPET TO FACILITATE REPAIR.		550.00	160.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		100.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
	SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS.		80.00	40.00
	SUPPLY BODY SEALANT FOR AFFECTED PORTIONS.		80.00	40.00
	RESPRAY ACCIDENT DAMAGED PORTION ON REAR BUMPER,TAILGATE,REAR END PANEL AND OTHER AFFECTED PORTIONS.		1,680.00	1,260.00
			6,380.00	3,800.00
	GRAND TOTAL		10,145.00	6,104.00
RECOMMENDED COST OF REPAIRS				6,104.00

Report Ref No. CS/FCI19012071/R1vf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.