

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOH FOOK SENG
BLK 133 PASIR RIS GROVE
#08-23
SINGAPORE 518131

ATTN: Motor Claim Department

Your Ref No: SGH2832C
Claim Type: Third Party
Accident Date: 01/07/2019

Estimate No: MC1900506
Date: 04 Jul 2019
Policy No: GA345111
Veh Reg No: SGH2832C
Make/Model: DAIHATSU TERIOS
1.5L 4WD

Estimate Repair Cost to Vehicle No :SGH2832C

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
SPARE PARTS				
1 FRONT GRILLE CHROME MOULDING		1 PC	200.00	X
2 HEADLAMP LH & RH		2 PC	1,120.00	LT
3 FRONT BUMPER		1 PC	240.00	✓
4 FRONT BUMPER SIDE RETAINER LH & RH		2 PC	64.00	✓
5 FRONT BUMPER CLIPS		15 PC	45.00	✓
6 FRONT BUMPER LOWER AIR GRILLE		1 PC	120.00	✓
7 FRONT BUMPER TOW COVER		1 PC	24.00	✓
8 FRONT BUMPER REINFORCEMENT		1 PC	280.00	✓
9 FRONT FENDER LH		1 PC	190.00	✓
10 FRONT FENDER COWLING		1 PC	58.00	?
11 FRONT FENDER COWLING CLIPS		8 PC	24.00	?
12 FOGLAMP LH		1 PC	180.00	?
13 FRONT BONNET		1 PC	380.00	X
			2,925.00	
	Add 20%		585.00	3,510.00

Special Nett

14 NUMBER PLATE

1 PC 35.00 X

35.00



LABOUR

- 15 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.
- 16 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.
- 17 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT BONNET, FRONT FENDER RH, FRONT WHEELHOUSE PANEL LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.
- 18 TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH & RH, RADIATOR SUPPORT PANEL.

1 PC 40.00 201

1 PC 80.00 X

1 PC 600.00 4001

1 PC 800.00 5401

1,520.00

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SOH FOOK SENG
BLK 133 PASIR RIS GROVE
#08-23
SINGAPORE 518131

ATTN: Motor Claim Department

Your Ref No: SGH2832C
Claim Type: Third Party
Accident Date: 01/07/2019

Estimate No: MC1900506
Date: 04 Jul 2019
Policy No: GA345111
Veh Reg No: SGH2832C
Make/Model: DAIHATSU TERIOS
1.5L 4WD

Estimate Repair Cost to Vehicle No :SGH2832C

Amount Before Excess	S\$ 5,065.00
Add GST @ 7%	354.55
Total Amount payable	S\$ 5,419.55

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND FOUR HUNDRED NINETEEN AND CENTS FIFTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE

