

RC3188

No:

Date:

SJY 8583 G

AUDI Q5

WAUZZZ8R6A054268

LIST ITEM

FRONT FENDER LH Dented	\$573.80	✓
FRONT FENDER LINER LH Men	\$155.80	+
FRONT DOOR LH Reps	\$2274.30	+
FRONT DOOR PROTECTOR LH Lt	\$224.20	✓
REAR DOOR LH Reps	\$2274.30	+
REAR DOOR PROTECTOR LH Men	\$248.90	+
FRONT SIDE MIRROR LH Cnld	\$712.50	✓
FRONT SIDE MIRROR COVER LH Cnld	\$239.40	✓
REAR SPORT RIM LH Lt	\$195.30	850(SN)

SPECIAL NETT ITEM

FRONT FENDER LINER CLIP (SET) Men	\$60	+
--------------------------------------	------	---

LABOUR CHARGE

TO KNOCKING & REPAIR ABOVE PART	\$800	400
TO TRANSFER DOOR MECHANISM	\$300	+
TO SPRAY PAINTING ON AFFECTED AREA	\$1000	700
TO REMOVE & REFIX SPORT RIM	\$80	60
TO DO 4 WHEEL ALIGNMENT	\$120	80

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

10,148.96

Adnan Lj
H/S 09/07/19.
@ 4 days.

Acknowledged by Repairer

Signature:

Date: