



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19012121/Kpa3q2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 28-04-2020



ATTN: PETER

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBH 489H	Veh. Inspected	SDN 5006E
Policy No.	P2241683	Coverage (\$)	0.00
Claim No.	S9M01T2J	Excess (\$)	0.00
Assign From		Assign Date	09/07/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MR053REH104553229	Colour	METALLIC BLUE
Odometer	70089	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	DUNLOP	5 mm
L/H Front Tyre	205/55 R16	DUNLOP	5 mm
R/H Rear Tyre	205/55 R16	DUNLOP	5 mm
L/H Rear Tyre	205/55 R16	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/07/2019	Inspection Date	09/07/2019
Survey held at	GUAN HIN MOTOR WORKSHOP BLK 10 ANG MO KIO IND PK 2A #02-03 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------