PM210	LON CHAR HAVE CC 4/AIG1901 WW	Uhly / LIKE
INS. CASE OWNE	WINCENS ASSIGNMENT	alta.
Surveyor	DOE AT LA	Date / Time :
Pre-assign / CCU	CETE	Registered in Merimen: 9 7 10
	STV 2951R	50401404006G
Insured Vehicle N	io. Chim No.	B340(4040000)
Name of Insured	ORANGE LEASING PTE LTD Policy No.	1 8
Insured Tel No.	HP: Make / Mo	odel :
Excess Sec II :SS	D.O.A: 126 (A Place of A	ccident:
Is driver the owne	r? (YES /(NO)) Nature of Accident	
If NO. Driver No	inie / Are: O Ol GlA Ri	PORT (E) NO : TP GIA REPORT (E) / NO
Driver Te		
FBK IT	31K	
INSRS:	INSRS: INSRS:	INSRS
WSP. EVO	WSP: WSP:	WSP
Tel: Liability:	Tel: Tel: Liability: Liability:	Tel: Liability:
RMKS	RMKS: RMKS:	RMKS:
Date/Time		
2000	DUTTINE - N GIVING-X	STAGE DATE/PIC
	100000000000000000000000000000000000000	Nno-Reporting ltr (1st):
207		Nnn-Reporting Itr (2nd): Non-Reporting Itr (Final):
halodild	- MUT RAVIOUSD. OLD WATCHE & PICHT	Notification ltr (if non-pickup);
5	TURA @ THE SUNDCIDOUS SHOUD UPTIFIC &	Call Ot
	further so of to posity it origin &	After call liz to Oi: 151 07 19 - VIC
	NCB 150089.	Documentation Check List: Handler Typist
	- HINTOCHED	Notification lit (if nots-pickup) After call lit to Of:
	ORIGINAL TO LOD IN	Authorisation To Act
		Release Voucher
29/08/19	+ OPVORDED HANDELE IF IN MEANINGS	Final Repair Bill
50/08/19	- ME VALLOURD MANDELE	Car Rental Invoice
	- SOUD ACCEPTANCE BUILD TO TP.	Towing Invoice
	- recieved by a high	LTA/GIA:
	+ ALL DOOD IN OPPORTS.	Medical Bill:
		PIR:
		Mandate/Reject Instruction:
		LOD
		Payment Breakdown Form
PRELIMINARY ADVICE	C Date/Time: Sent By:	Post-Repair Photos:
		Others:
FINALIZATION	Date/Time: Confirm with:	Confirm by:
Repair Cost: L/6	55 3,000.60 (5 days) Reduction: 46 %	Emmi Call
FINAL SETTLEMENT	Date/Time: 30/06/19 Confirm with Use Use	Emnil Cal
Final Liability:	% (Agree) / Assessed) BOLA S/N No.: 5	If NO or B 28, Ass. Lia:
Repair Cost:	22 31000.00	COID WHICHG PUGHT TOPA
Loss of Rental (LOR): Loss of Use (LOU):	SS — (days)	
Loss of Income (LOI):	55 160 (570 x 7 days) SS (5 & days)	
		11 1 21 2
LOR only LOU only GIA/LTA Search	LOR + LOU LOR + LO Tick only one	VIA V
Medical:		1) Claim status (CA) (Para application Status
Medicae Disbursement	SS _ (e.g. Tow/ Independent)	Claim status: \mathbb{\text{mail/Reject/Private Settle}} Remot \text{limited}
Legal Cost	SS (e.g. Tow/ Independent)	2) Report Format:
Fotal:	SS 3,140,00 Global Sum SS: -	and an investment of the second
FINAL PAYMENT	Date/Time: Confirm with:	Email Call
Payee 1:	The state of the s	OR TRADING PIE UTD
Payee 2: (Strike if N.A.)	SS — Name 2:	OR THE MO THE OID
Payee 3: (Strike if N.A.)	\$\$ - Name 2: -	
THE PERSON NAMED IN PARTY OF	Transfer at 1	

T T
A14
ASSIGNMENT Veh No: FB(C173/K Yr Regn: /1/3
The state of the s
Type: M.Car M.Cycla / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
K Make Yampling Jupiter 0.0 /3K
Colour Red Wast
Sp.Reading /) 67 0 T/Radio: Insured / Std / NI / NA
Eng/No:
CNO MH350COUZEK462872
Gen. Cond: Good (Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt @ OPLA
Brake: Morder / Jammed / Leaked / Burnt or
Modi: NII SIRIM L STD AJRIM or
Tyre Size F: 70 - 90 - 17
Tyre Size F: 70 - 90 - 17
O/S BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
TOYO/YOKO OF MEXTIS
Front Rear (3
R/Bal. mm R/Bal. mm
L/Bal mm L/Bal mm
D.O.A 12/6/18 D.O.I. 9/7/18
Survey held at
Des. of Damages : Frt Rear O/S N/S U/C Rooftop or
IN/OUT 21 0/5 35dy
The U/C / Chassis frame / Body Structure affected due to collision.
e+13123
<i>σ</i> 0. <i>σ</i> α
2.848.70 487.)
The state of the s
Days Of Repair:
Resurvey No. of Trip: Survey Fee:
Transportation.
Add Fee:
: Interview (\$) Protes
: Tech. Invs (\$) Others
: Weekend (\$
TOTAL

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883 Tel: 67527740 Fax: 67528669

Co. Reg No. 201202259N

Owner: Thivagaran Sridaran

Accident Date:

12-Jun-19

Vehicle No: FBK 1731 K

Vehicle Model: Yamaha Jupiter

Estimated Re	epair Cost	S
--------------	------------	---

Oty	Description	. A	Amount S(\$)
	List Items /		
2	Front fork tube assy	\$	They 640.00 ?
1	Front wheel rim Fork under bracket Mof High	\$	BM 280.00 7
1	Fork under bracket	\$	185.00 7
1	Front rim shaft Front rim bearing Front brake disc	\$	2 45.00 Z
1	Front rim bearing	S	. per 38.00 7
1	Front brake disc	\$	Z/ 155.00 2
1	Handle-bar	S	Ber 88.00-
1	Handle-bar end / S MIN	S	502 32.00 -
1	Hand grip (1 set)	5	n 55.00 -
1	Handle-bar inner bracket	5	3/ 68.00 =
1	Handle-bar end Hand grip (1 set) Handle-bar inner bracket Side mirror -R/H	5	Br 55.00
1	Brake lever	5	& 32.00 X
2	Front signals	50	1/5 5AD 180.00 (2 4
1	Headlamp	5	c~ 185.00_
1	Meter assy	5	My 385.00 7
1	Fairing assy (1 set)	S	Cor 495.00
1	Front footrest bracket	\$	5 65.00
1	Front footrest rubber	\$	70. 35.00
1	Brake pedal	S	1 42.00 X
1	Rear footrest	\$	5 × 40.00 ×
1	Rear footrest bracket	\$	Sec 78.00 x
1	Exhaust assy	S	·>>> 485.00
1	Exhaust protector - chrome rear	S	Scr 60.00 _
1	Exhaust protector- front	\$	54/055.00
1	Rear handle	\$	Cu) 50.00
1	Seat	S	R 235.00 X
1	Rear absorber (1 set)	s	n = 350.00g
1	Rear taillamp	S	10 135.00 X
1	Rear fender	S	120.00 ×
1	Basket	5	ca 50.00
	0.1	5	4,718.00
	drant inner Cover \$120 Less 10%	S	471.80
	HoRN cover inner \$ 95 (M)	5	4,246.20
	C.D.I will # 180 Dyl		
	front fearing Bracket \$ TO Sul		

PAGE 1 OF 2

Special Nett Items


1	Number plate (1 set)	5	sel	28.00 / 6
2	Fork oils	S	in	30.00
2	Fork oil seals	S	17	56.00 2
1	Steering cone (1 set)	5	nu	90.00
1	Front tyre	S		120.00 ×
		\$		324.00

S/No.	Labour		
1	To provide towing service.	5	3 (50.00
2	To check wiring and reset headlamp focusing	5	√1 80.00 X
3	To provide labour.	5	2 500 380.00
4	To repair body frame.	\$	20 0 350.00
		5	860.00

EROFIA MOTOR TRADING PTE LTD

Grand Total

5,430.20



EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel: 67527740 Fax: 67528669 Co. Reg No. 201202259N

Owner:

Thivagaran Sridaran

Accident Date:

12-Jun-19

Vehicle No: FBK 1731 K

Vehicle Model: Yamaha Jupiter

Estimated Repair Costs

Oty	Description			Amount S(5)		
in the	List Items	. /				
2	Front fork tube assy	not Alle	S	640.00 ?		
1	Front wheel rim	NOT AGE	S	280.00 7		
1	Fork under bracket	- Llend	5	185.00 7		
1	Front rim shaft	, ,	S	45.00 7		
1	Front rim bearing	1/2/	S	38.00 7		
1	Front brake disc	1/5/1	5	155.00 7		
1	Handle-bar	1 1/1.	S	3/ 88.00-		
1	Handle-bar end	S a l Mulh	ps	502 32.00 -		
1	Hand grip (1 set)	hotes from	5	an 55.00 -		
1	Handle-bar inner bracket	1/1/200	5	68.00 ?		
1	Side mirror -R/H	Thybrots Must	S	BA2 55.00 -		
1	Brake lever	1(7)	\$	R 32.00 a		
2	Front signals		S	در 180.00 حدد عان		
1	Headlamp		S	cae 185.00_		
1	Meter assy		\$	385.00 つ		
1	Fairing assy (1 set)		5	Cor 495.00 -		
1	Front footrest bracket		5	5/ 65.00 _		
1	Front footrest rubber		5	70 . , 35.00		
1	Brake pedal		S	1 42.00 X		
1	Rear footrest		5	5 M 40.00 0		
1	Rear footrest bracket		5	Su 78.00 x		
1	Exhaust assy		S	·>>> 485.00_		
1	Exhaust protector - chrome rear		5	SCR 60.00 -		
1	Exhaust protector- front		5	S 6 1 55.00		
1	Rear handle		S	Cu > 50.00		
1	Seat		5	2 235.00 X		
1	Rear absorber (1 set)		S	·1 350.00 x		
1	Rear taillamp		S	11 135.00		
1	Rear fender		5	✓ 120.00 ×		
1	Basket		S	ca 50.00		
			S	4,718.00		
		Less 10%	5	471.80		
			s	4,246.20		

Special Nett Items

1	Number plate (1 set)	\$	Bel	28.00 / 6
2	Fork oils	5		30.00 >
2	Fork oil seals	s		56.00 7
1	Steering cone (1 set)	s		90.00 7
1	Front tyre	\$	Su	120.00 ×
	P	\$		324.00

S/No.	Labour		
1	To provide towing service.	5	3 (50.00
2	To check wiring and reset headlamp focusing	5	√ ↑ 80.00 X
3	To provide labour.	\$	250 380.00
4	To repair body frame.	S	30つ?350.00
	Substitution & common tracking substitution of the common of	5	860.00

Grand Total

5 5,430.20

Mot Athel

EROFIA MOTOR TRADING PTE LTD



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	32441
Vehicle Details	
Vehicle No.:	FBK1731K
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	YAMAHA
Vehicle Model:	JUPITER MX (HC)
Primary Colour:	Red
Manufacturing Year:	2012
Engine No.:	50C463031
Chassis No.:	MH350C002CK462872
Maximum Power Output:	
Open Market Value:	\$1,792.00
Original Registration Date:	11 Jan 2013
First Registration Date:	11 Jan 2013
Transfer Count:	3
Actual ARF Paid: Intended PARF Rebate Details	\$269.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	10 Jan 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,933.00
COE Rebate Amount:	\$677.00
Total Rebate Amount:	\$677.00

The information contained herein is correct as at 09 Jul 2019

OK



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND	COMPENSATION) ACT (CHAPTER 189
MOTOR VEHICLES (THIRD PARTY RISKS AND	COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)	

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5071309731-03 Cover : Third Party, Fire & Theft.

Index mark and Registration Number of Vehicle ; FBK1731K

Chassis Number : MH350C002CK462872
2. Name of Policyholder : THIVAGARAN SRIDARAN

3. Effective Date of Insurance : 11 Jul 2018
4. Expiry Date of Insurance : 10 Jul 2019

5. Persons or Classes of Persons entitled to drive#

(a) Named Driver(s) Only.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

This Policy does not cover

(a) Use for hire or reward.

- (b) Use for racing, pace-making, reliability trial or speed-testing.
- (c) Use for the carriage of goods (other than samples) in connection with any trade or business.
- (d) Use for any purpose in connection with the Motor Trade.
- # Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1) : N/A EXCESS (SECTION 2) : N/A

EXCESS (THEFT OUTSIDE SINGAPORE) : PLEASE REFER OVERLEAF

INSURE WITH COE

NAMED DRIVER (1) : THIVAGARAN A/L SRIDARAN

NAMED DRIVER (2) : N/A

HIRE PURCHASE COMPANY : YEW HENG CREDIT ENTERPRISE PTE LTD

SUM INSURED : MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency

: YEW HENG CREDIT ENTERPRISE PTE LTD (00000613617)

Date of Issue

: 27 Jun 2018 13:33 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive



REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$87832441





Cartes

THIVAGARAN SRIDARAN



Race INDIAN Date of berts

09-06-1987 Country Place of birth MALAYSIA

1178326

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 2B Motorcycles =< 200 cc 19 Aug 2015 Class 3 Motor Cars =< 3000kg with =<7 passengers, exclusive 19 Aug 2015 of the driver; and other motor vehicles =< 2500kg

9368256



wee 587832441

MALAYSIAN 20-04-2015

BLK D APT SRI AKASIA, TMN TAMPOI INDAH 81200 JOHOR BAHRU, MALAYSIA NRIC No: \$87832441 Date: 28/03/2016

NF.428A

Oseu ramana Jupiter MX135 bike for Sale in Singapore - Price, Reviews & Contact Seller - SGBikemart Listing Type, Free Ad Brand Yamaha (/listing/usedbike/brand/yamaha/) Yamaha Jupiter MX135 (/listing/usedbike/model/yamaha-Model jupiter-mx135/) **Engine Capacity** 134cc Classification Class 2B (/listing/usedbike/model/motorcycle-forsale/class/class-2b/) Registration Date 24/01/2013 COE Expiry Date 23/01/2023 (3 years 6 months left)

Mileage

No. of owners 3

Type of Vehicle Cubs (/listing/usedbike/model/motorcycle-for-sale/cubs/)

Price: SGD\$4000

DETAILS

Reliable Cub For Daily Use. Currently Using The Bike As My Daily Transport. Eo Change Every 2K. Road Tax Cover Till End Of Year. Viewing Available At Tampines. Price Nego.

Accessories

Ohlins Suspension (Thailand Version). Rear Box Can Fit 1 Helmet). Fold-Able Footrest. Digital Meter.

SIMILAR BIKES

VIEW ALL (/LISTING/USEDBIKES/LISTING/)





Yamaha Jupiter MX135

PRE-REPAIR INSPECTION REQUEST - FBK1731K vs SJV3951B (OI) on D.O.A.: 12/06/2019

assignments@ikxauto.com. April A committee assault.com.)
Fong, And SV. Chin, Lee-Ying, Abu Kasaim, Noor Manesa, Azlan. Syszairdina. Chan, Yoke Shi, Lim, Sheng Yang, Mithodsingh, Assitweenjeetkaut, Subramanium, Divyashni, Tong, Wahsin

Sent: 7/9/2019 13 37 46 AM

ARRESTS THE FERNITALK FOR

Please refer to the enclosed request from K. Krishna & Partners.

Claim no

: 3040140480SG003

Case Owner : Leh Chee Heng If you have any queries/concerns, please let us know

Kindly assist to assign Marcus Chua as Single Joint Expert as requested.

Thanks & Regards,

Hor Yin Bul (Viviane)

Claim Adjuster II, Singapore FNOL, Claims Operations - Auto

Young Hoodball com I www.eig.go

From: kkrishna@singnet.com.sg [mailto:kkrishna@singnet.com.sg]

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Manesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Manesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam,

Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SIV3951B AND FBK1731K ON 12/06/2019

This message is from an external sender; be cautious with links and attachments.

We are instructed to appoint Marcus Chua from LKK Auto Consultants Pte Ltd.

Kindly liaise with our clients' workshop directly.

Farida on behalf of K. Krishna & Partners

On Mon Jul 08 2019 17:08:22 GMT+0800 (Singapore Standard Time) Hor, Yinrul <Yinrul.Hor@aig.com> wrote:

- Original Message --

Without Prejudice

Your Reference

SM.PRI EROFIA FBK 1731K

Our Reference

: 3040140480SG003

Dear Sir/Madam.

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor

Company Name

AIG In House Surveyor

AIG Asia Pacific Insurance Pte Ltd

Lawrence Ng Chun Kee Priority Services

Jeffrey Ong Leng Kiat

Priority Services

Jimmy Lee

Priority Services

EC Loni

Automobile Inspection Services Pte Ltd

Pang Kinh Keen (Frankie)

Formteam Adjusters Pte Ltd

Ng You Han

Formizam Adjusters Pte Ltd

Soon HanXin (Gary)

Formteam Adjusters Pte Ltd

Chow Bo Xiong

Formteam Adjusters Pte Ltd Chua Soo Teck (Benjamin)

Formteam Adjusters Pte Ltd

Kalvin Ang

LKK Auto Consultants Pte Ltd

11.37am@g|7/19

the fee vehicle in gue@ Many

Print Received Message

This mail is associated with:

*FBK1731K (3040140480SG) [SJV3951B] TP THIVAGARAN SRIDARAN

Jun 12 2019 12:00AM [ORANGE LEASING PTE LTD] Erofia Motor Trading Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 30/08/2019 14:14 PM.

To

LKK HQ

Subject

Alert - Adj Mandate Approved (S\$3140.00) - FBK1731K - Claim Handler: Loh, Chee-Heng

Approved:3140.00.		

Erofia Motor Trading Pte Ltd

1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883 Tel: 67527740 Fax: 67528669

E-Mail: erofia@singnet.com.sg Co Registration No: 201202259N

Ref: EMT1526/19/lt/FBK1731K

WITHOUT PREJUDICE

Your reference: TO BE ADVISED

BY HAND TO LKK

27 August 2019

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Officer-In-Charge (Motor Claims Department)

Dear Sir

Re: ACCIDENT INVOLVING SJV3951B AND FBK1731K ON 12 JUNE 2019

We are instructed by our client Thivagaran Sridaran to claim damages against your insured SJV3951B in connection with a road traffic accident on 12 June 2019 at about 05.30hrs along Esplanade Drive with our client's motorcycle registration number FBK1731K

As a result of the accident, our client's motor bike was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1.	Final repair cost as per Surveyor's recommendation	5\$ 3,000.00
2.	Loss of Use (7 days X S\$20.00/day) Repair Day + PRI	5\$ 140.00
	Total to Claim	\$\$ 3,140,00

Attached final repair bill for your early process of our claim

Kindly revert soonest

Thank you

Yours faithfully Erofia Motor Trading Pte Ltd

Teo Hwa Heng



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

15 JULY 2019

ORANGE LEASING PTE LTD 621 ALJUNIED ROAD #06-07 LIPO BUILDING SINGAPORE 389834 ATTN: THE MANAGEMENT By Post & By Email

Dear Sir/Madam,

OUR REF

: CC4/AIG19012122/Uhb3

YOUR REF

: SJV 3951B

ACCIDENT INVOLVING SJV 3951B AND FBK 1731K ALONG NICOLL HIGHWAY ON 12.06.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of FBK 1731K against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle FBK 1731K. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD - if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter if not provided at AIG's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- · Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

- Video footage of accident (if any)
- · Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely

Vic Alpeh Case/Handler DID:6841 2096 FAX: 6741 4108

Email: vicalpeh@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd (Motor Claims Dept)

> Victor.ong@bluestarconcierge.com.sg (Email)

Vic (LKKAuto)

From:

Vic (LKKAuto)

Sent:

Monday, 15 July, 2019 3:12 PM

To:

Victor.ong@bluestarconcierge.com.sg

Cc:

Admin A; Vic (LKKAuto)

Subject:

YOUR REF: SJV 3951B ACCIDENT INVOLVING SJV 3951B AND FBK 1731K ALONG

By Post & By Email

NICOLL HIGHWAY ON 12.06.2019



Consultants Pte Ltd

51 UBLAVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

15 JULY 2019

ORANGE LEASING PTE LTD 621 ALJUNIED ROAD #06-07 LIPO BUILDING SINGAPORE 389834

ATTN: THE MANAGEMENT

Dear Sir/Madam,

OUR REF

: CC4/AIG19012122/Uhb3

YOUR REF

: SJV 3951B

ACCIDENT INVOLVING SJV 3951B AND FBK 1731K ALONG NICOLL HIGHWAY ON 12.06.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from Body Repairer/Workshop acting on behalf of the owner of FBK 1731K against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had collided to the Third-Party vehicle FBK 1731K. As such, liability may not be on your favour.

Please be informed that your No Claim Discount (NCD - if any) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defense, please reply to us within 10 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to vicalpeh@lkkauto.com within 10 days from the date of this letter if not provided at AIG's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us
 informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AIG's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AIG of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AIG shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at vicalpeh@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Save the Earth Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



AUTHORIZATION TO ACT (AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

of BIKD Apt sin atasia Thin Pampoi Indah 8000 JB (address), owner of FBK1731K (vehicle no.) hereby authorize	
("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. F6K 1731K that was damaged pursuant to the accident which occurred on 12 06 2019 (date) along 25planade 2019 (location)	
Involving vehicle no/sSTV_39STB("the accident"). I further authorize the workshop to settle the above mentioned claim in a	
manner that they deem fit and the workshop is further authorized to receive payment furtherto settlement of my claim with payment cheque/s being made in favour of the workshop.	
I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.	
Date this day of (month) 20 (year) Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not preside or affect or preclude me from making a further claim for general and spaced disciplines for my personal injuries sustained in the same accident.	
Signed by "the third party claimant" Signed by "the workshop"	

RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, <u>EROFIA MOTOR TRADING PTE LTD</u> ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd <u>LKK AUTO CONSULTANTS PTE LTD</u> (name of surveyor) with respect to the amount claimed for <u>S\$3.000.00</u> (Repair Cost), <u>S\$140.00</u> (Loss of <u>Rental/Use</u>), <u>S\$--</u> (Disbursement), for vehicle no. <u>FBK 1731K</u> that was damaged pursuant to the accident which occurred on <u>12/06/2019</u> (date) along <u>ESPLANADE DRIVE</u> (location) involving vehicle no/s <u>SJV 3951B</u>. This is pursuant to the inspection conducted on <u>09/07/2019</u> (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner <u>THIVAGARAN SRIDARAN</u> ("the third party claimant") of vehicle no. <u>FBK 1731K</u> make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to FBK 1731K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 80/08/19

(LKK) CKS

Signed by appointed surveyor

Signed by "the workshop" (with chop)

Provide always that this discharge of my claim for damages relating to the damage to my vehicle shall not prejudice or affect or preclude my from making a further claim for general and special damages for my personal injuries sustained in the same accident.

...CLAIM SUBFOLDER...(Pending for Survey Report)

	FOLDER TRA	Est Submitted	240 240 1144	Ady Rpt		Add #	ubmitted	Ins Authled	Status		
Case Main	Notified 13 Jun 2019 Edit Reg	Est Submitted	Adj Assigned 09 Jul 2019 00:00 Edit Adj Rot	S\$3,000 Edit Esti	control - T	5\$3,	000.00 w Rpt	Ins Author	Pending for Survey Report Cancel Case		
	Main	R	eference	l c	laim De	ails		Documents		Show All	
CLAIM SU	BFOLDER DE	TAILS					[Created	by adjuster]			
Insured:	ORANGE	LEASING PTE LT	D, Co. Reg. No.: -								
Main Claimant:	THIVAGA	THIVAGARAN SRIDARAN, Co. Reg. No.: 587832441									
Vehicle Rep No.:	FBK173	FBK1731K			Date of	Loss:	12/06/2019 00:00 - :59 [77 Months and 1 Days From LTA Reg Date (Man Yr)]			Man Yr)]	
Claim Type	TP / 304	TP / 3040140480SG				over	(Comprehensive)				
Vehicle Reg No. (Insured):		SJV3951B			Policy N (Claima		50713097	31-03			
Repairer:	Erofia Mo	tor Trading Pte	Ltd (KAKI BUKIT)	1 KAKI BUK	IT AVE	#02-	62, 417883	Kaki Bukit - Tel:			
Handling Insurer:	AIG Asia	Pacific Insuranc	e Pte. Ltd. (Expre	ss) - Tel: 65	5-6419-3	000	. [Handled b	y Loh, Chee-Heng] Chee-Heng.L	oh@aig.com	
Claimant's Insurer:	100000000000000000000000000000000000000		Co-operative Ltd (District to Chillian							
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	256-3561	[Handle	by M	ARCUS CH	UA] [Final Rp	t due 18/07/	2019]	
ASSOCIA	TED MAIL RE	CEIVED						Viev	All Compo	se Case Mail	
 AIG_5G 	(10/07/2019)	: Request To Up	- Adj Mandate Ap load TP GIA Repo	proved (S\$ rt	3140.00) - F8	K1731K -	Claim Handler: Lo	h, Chee-H		
Due Dat No results.	710074040	i bernati entre	Group Subje	ct Hand	ler i	-	view All ned By	Search Tasks Cr Completed On	Created O	Complete n Done	

Claim Documents

*FBK1731K (3040140480SG) [SJV3951B] TP THIVAGARAN SRIDARAN Jun 12 2019 12:00AM [ORANGE LEASING PTE LTD] **Erofia Motor Trading Pte Ltd**

Lett	ters/Corresponder	ices	1 per :	page V	8
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	0	Edit	
Ass	essment Reports		1 per	page [V]	Ø
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	-
1	(Draft)	Adjuster Immediate Advice	0	(Protected)	
2	29/08/19 10:27	Adjuster Immediate Advice	0	Load HTM	
Pho	tos/Images		3 per	page V	12
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	09/07/19 18:22	Odometer Reading	0	Load JPG	2
2	09/07/19 18:23	General View	0	Load JPG	
3	09/07/19 18:23	General View	0	Load JPG	W
4	09/07/19 18:23	General View	0	Load JPG	12
5	09/07/19 18:23	General View	0	Load JPG	1
6	09/07/19 18:23	General View	0	Load JPG	Ø
7	09/07/19 18:23	General View	0	Load JPG	Ø
8	09/07/19 18:23	General View	0	Load JPG	Ø
9	09/07/19 18:23	General View	0	Load JPG	82
10	09/07/19 18:23	General View	0	Load JPG	V
11	09/07/19 18:23	General View	0	Load JPG	2
12	09/07/19 18:23	General View	0	Load JPG	Ø
13	09/07/19 18:23	General View	0	Load JPG	Ø
14	09/07/19 18:23	General View	0	Load JPG	8
15	09/07/19 18:23	General View	0	Load JPG	Ø
16	09/07/19 18:23	General View	0	Load JPG	Ø
17	09/07/19 18:23	General View	0	Load JPG	Ø
18	09/07/19 18:23	General View	0	Load JPG	8
19	09/07/19 18:23	General View	0	Load JPG	Ø
20	09/07/19 18:23	General View	0	Load JPG	Ø
21	09/07/19 18:23	General View	o	Load JPG	Ø
22	09/07/19 18:23	General View	0	Load JPG	Ø
23	09/07/19 18:23	General View	0	Load JPG	82
24	09/07/19 18:23	General View	0	Load JPG	82
_		General View	0	Load JPG	₩
25	09/07/19 18:23	5.5 (2012) 2012 2012	0	Load JPG	2
26	09/07/19 18:23	General View General View	0	Load JPG	N
_	09/07/19 18:23		0	Load JPG	<u>S</u>
28	09/07/19 18:23	General View	0		82
29	09/07/19 18:23	General View		Load JPG	120
30	09/07/19 18:23	General View	0	Load JPG Load JPG	₩.
31	09/07/19 18:23	General View	0	Load 3PG	2
32	09/07/19 18:23	General View		1000000000	+
33	09/07/19 18:23	General View	0	Load JPG	Z
34	09/07/19 18:23	General View	0	Load JPG	82
35	09/07/19 18:23	General View	0	Load JPG	M

Lett	ers/Corresponde	nces	1 per page	-
Vo	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai Load JPG	
16	09/07/19 18:23	General View		2
7	09/07/19 18:23	General View	■ Load 3PG	82
8	09/07/19 18:23	General View	■ Load JPG	12
9	09/07/19 18:23	General View	1 Load JPG	2
0	09/07/19 18:23	General View	1 Load JPG	82
1	09/07/19 18:23	General View	■ Load JPG	2
12	09/07/19 18:23	General View	1 Load JPG	82
3	09/07/19 18:23	General View	■ Load JPG	2
14	09/07/19 18:23	General View	€ Load 3PG	2
5	09/07/19 18:23	General View	■ Load JPG	V
-	H19704 C-00-51/81-7/903	General View	O Load JPG	V
6	09/07/19 18:23		Load 3PG	82
17	09/07/19 18:23	General View		400
18	09/07/19 18:23	General View	€ Load JPG	
19	09/07/19 18:23	General View	1 Load JPG	
50	09/07/19 18:23	General View	1 Load JPG	_
51	09/07/19 18:23	General View	① Load JPG	_
52	09/07/19 18:23	General View	■ Load JPG	12
3	09/07/19 18:23	General View	■ Load JPG	2
54	09/07/19 18:23	General View	3 Load 3PG	2
55	09/07/19 18:23	General View	■ Load JPG	
56	09/07/19 18:23	General View	■ Load JPG	
57	09/07/19 18:23	General View	O Load JPG	100
58	09/07/19 18:23	General View	Load 3PG	1
127	DOMESTIK CO. CO. CO.	Western Committee	Load 3PG	_
59	09/07/19 18:23	General View		-
50	09/07/19 18:23	General View	€ Load JPG	-
51	09/07/19 18:23	General View	Load JPG	_
52	09/07/19 18:23	General View	1 Load 3PG	-
53	09/07/19 18:23	General View	1 Load JPG	-
64	09/07/19 18:23	General View	■ Load 3PG	1
55	09/07/19 18:23	General View	■ Load JPG	V
56	09/07/19 18:23	General View	Load JPG	R
57	09/07/19 18:23	General View	■ Load 3PG	R
5B	09/07/19 18:23	General View	Load 3PG	8
59	09/07/19 18:23	General View	■ Load JPG	-
70	09/07/19 18:23	General View	Load JPG	_
		General View	■ Load JPG	
71	09/07/19 18:23	(C)		
72	09/07/19 18:23	General View	■ Load JPG	_
73	09/07/19 18:23	General View	8 Load JPG	-
74	09/07/19 18:23	General View	1 Load JPG	-
75	09/07/19 18:23	General View	1 Load JPG	_
76	10/07/19 18:35	Reinspection Photo	■ Load 3PG	V
77	10/07/19 18:35	Reinspection Photo	■ Load JPG	2
78	10/07/19 18:35	Reinspection Photo	■ Load JPG	8
79	10/07/19 18:35	Reinspection Photo	1 Load JPG	8
90	10/07/19 18:35	Reinspection Photo	O Load JPG	_
11	10/07/19 18:35	Reinspection Photo	O Load JPG	
12	10/07/19 18:35	Reinspection Photo	■ Load JPG	1
-			① Load JPG	1 2
13	10/07/19 18:35	Reinspection Photo	The second secon	-
14	10/07/19 18:35	Reinspection Photo	€ Load JPG	-
85	10/07/19 18:35	Reinspection Photo	1 Load JPG	-
36	10/07/19 18:35	Reinspection Photo	1 Load JPG	_
57	10/07/19 18:35	Reinspection Photo	Load JPG	_
88	10/07/19 18:35	Reinspection Photo	1 Load 3PG	_
89	10/07/19 18:35	Reinspection Photo	■ Load 3PG	82
90	10/07/19 18:35	Reinspection Photo	■ Load JPG	V
91	10/07/19 18:35	Reinspection Photo	■ Load 3PG	V

Lett	ers/Corresponden	ces	1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbni	ill Prin
92	10/07/19 18:35	Reinspection Photo	■ Load JPC	M
93	10/07/19 18:35	Reinspection Photo	1 Load JPC	; 2
94	10/07/19 18:35	Reinspection Photo	€ Load JPC	· 2
95	10/07/19 18:35	Reinspection Photo	€ Load JPC	. 2
96	10/07/19 18:35	Reinspection Photo	€ Load 3PC	- E
97	10/07/19 18:35	Reinspection Photo	■ Load JPC	· 2
98	10/07/19 18:35	Reinspection Photo	■ Load 3P0	· 2
99	10/07/19 18:35	Reinspection Photo	■ Load 3PG	-
-19	10/07/19 18:35	Reinspection Photo	€ Load 3PG	-
100			■ Load JP6	-
101	10/07/19 18:35	Reinspection Photo		-
102	10/07/19 18:35	Reinspection Photo		_
103	10/07/19 18:35	Reinspection Photo	1 Load JPG	_
104	10/07/19 18:35	Reinspection Photo	1 Load 3PG	-
105	10/07/19 18:35	Reinspection Photo	6 Load 3Pt	
106	10/07/19 18:35	Reinspection Photo	■ Load 3P0	
107	10/07/19 18:35	Reinspection Photo	■ Load 3PC	· 1
108	10/07/19 18:35	Reinspection Photo	■ Load 3Pt	· 2
109	10/07/19 18:35	Reinspection Photo	O Load JP	-
110	HAMOTA COLSCIAN	Reinspection Photo	■ Load 3Pi	
111	10/07/19 18:35	Reinspection Photo	■ Load JP	
112	10/07/19 18:35	Reinspection Photo	Load 3Pc	
-			O Load 3P	
113	10/07/19 18:35	Reinspection Photo		_
114	28/08/19 07:49	After Repair Photo		- 100
115	28/08/19 07:49	After Repair Photo	1 Load JP	-
116	28/08/19 07:49	After Repair Photo	Load 3Pt	-
117	28/08/19 07:49	After Repair Photo	6 Load JP	_
118	28/08/19 07:49	After Repair Photo	1 Load JP	_
119	28/08/19 07:49	After Repair Photo	■ Load 3Pt	3 2
120	28/08/19 07:49	After Repair Photo	€ Load 3P	: 2
121	28/08/19 07:49	After Repair Photo	€ Load 3P	a 123
_				7 2
-	umentation	Towns B to be determined	Appel and the part of the part	The second
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbn Load PD	
2	09/07/19 16:26	NOTICE	O Load PD	-
3	11/07/19 09:36	TP ESTIMATE- MARKED	O Load PD	-
4	11/07/19 09:36	TP GIA REPORT	■ Load PD	
5	15/07/19 15:16	EMAIL TO OI	■ Load PD	F
6	15/07/19 15:16	LETTER TO OI	Load PD	F
7	29/08/19 10:18	TP ESTIMATE - FINALIZED	■ Load PD	E
8	29/08/19 10:18	TP LOD	Load PD	F.
9	16/09/19 10:20	WORKSHOP INVOICE	€ Load PD	_
10	16/09/19 10:20	AUTHORISATION TO ACT FORM	1 Load PD	_
11	16/09/19 10:20	Release Voucher	Load PD	$\overline{}$
12	16/09/19 10:20	LOD	1 Load PD	
No:	Finalized On:	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbn	en Lexiu

Documents Checklist

	^
	~

NOTE: 1	TO RE	COMPL	FTFD	RY	SURVEYOR

TEAM	
IEAW	

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJV3951B (Insd veh)			Mod	iel:	YAMAHA JUPITER MX	
FBK1731K (TP veh		LL			134CC HC		
Date of Accident:	12/06/2019						
Global Sum Settler	nent :	[] Yes	\rightarrow	[X]	No		
Repair Estimate			: \$		5,848.70		
Final Repair Cost		: \$		3,000.00			
Loss of Use			: \$		140.00	7.00 days at \$20.00 per day	
Rental (if any)			: \$		0,00	days	
LTA / GIA Search F	ee		: \$		0.00		
Others:			: \$		0.00		
			: \$				
Final Settlement St	um:		: \$		3,140.00		
Is Third Party Wor below) A) For Non GIA F				[]	YES ed Liability	[X] NO (Kindly indicate	
B) For GIA Regis BOLA Liability: * Assessed Liability:		(%)	or cha	Asse	ssed Liabil	le: Yes/ No BOLA Scenario No: lity (*):(%) cases where BOLA does not apply	
Remarks							
Payment Instructi			wn		La	277222	
Erofia Motor 7	rading F	Pte Ltd			: \$	3,140.00	
2)					: \$		
JOANNE				20	Sep 019		
LKK Auto C	onsultar	nts Pte Ltd		D	ate		

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25. Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG19012122/UHB3Q2

Date:

16/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No:

FBK1731K

Insured Vehicle No: SJV3951B

Date of Loss:

12/06/2019

Nature of Claim:

Policy No:

TP

Claim No: 3040140480SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FBK1731K

Make & Model:

YAMAHA JUPITER MX, 134cc HC

Engine No:

50C463031

12678 km

Reg. Date:

11/01/2013 (Man. Year: 2012)

Chassis No: Odometer:

MH350C002CK462872

Colour: Engine Capacity: Red/Black

134 cc

Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

70-90-17

Rear Tyre Size: Rear Left Side:

80-90-17 Maxxis 6 mm

Front Left Side: Front Right Side: Maxxis 6 mm 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,988.70	3,408.40	1,580.30	31.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	485.00	375.00	43.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,848.70	3,893.40	1,955.30	33.43
Approved Total (Overridden) (S\$)		3,000.00		
Nett Amount (S\$)	5,848.70	3,000.00	2,848.70	48.71
+ Loss of Use (7.0 x S\$	20.00/day) (S\$)	140.00		
Ne	tt Liability (S\$)	3,140.00		

INSPECTION

Date of Assignment:

09/07/2019

Date Inspected:

09/07/2019 Inspected At:

Erofia Motor Trading Pte Ltd (KAKI

BUKIT)

1 KAKI BUKIT AVE 6 #02-62

Singapore 417883

Estimated Period of Repair:

5.0 days

Manager: VIC ALPEH Adjuster: MARCUS CHUA

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

	*FRONT FORK TUBE ASSY *FRONT WHEEL RIM *FORK UNDER BRACKET *FRONT RIM SHAFT *FRONT RIM BEARING *FRONT BRAKE DISC *HANDLE -BAR *HANDLE -BAR END *SET HAND GRIP *HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP *METER ASSY	Twisted Bent Bent Necessary Necessary Bent Bent Scratched Necessary Bent Broken Repair O/S Broken	640.00 FL 280.00 FL 185.00 FL 45.00 FL 38.00 FL 155.00 FL 32.00 FL 55.00 FL 68.00 FL 55.00 FL 180.00 FL	*640.00 FL *280.00 FL *185.00 FL *45.00 FL *155.00 FL *88.00 FL *32.00 FL *55.00 FL *55.00 FL
	*FORK UNDER BRACKET *FRONT RIM SHAFT *FRONT RIM BEARING *FRONT BRAKE DISC *HANDLE -BAR *HANDLE -BAR END *SET HAND GRIP *HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Bent Necessary Necessary Bent Bent Scratched Necessary Bent Broken Repair O/S Broken	185.00 FL 45.00 FL 38.00 FL 155.00 FL 88.00 FL 32.00 FL 55.00 FL 68.00 FL 55.00 FL 32.00 FL	*185.00 FL *45.00 FL *38.00 FL *155.00 FL *88.00 FL *55.00 FL *55.00 FL *55.00 FL
	*FRONT RIM SHAFT *FRONT RIM BEARING *FRONT BRAKE DISC *HANDLE -BAR *HANDLE -BAR END *SET HAND GRIP *HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Necessary Necessary Bent Bent Scratched Necessary Bent Broken Repair O/S Broken	45.00 FL 38.00 FL 155.00 FL 88.00 FL 32.00 FL 55.00 FL 68.00 FL 55.00 FL 32.00 FL	*45.00 FL *38.00 FL *155.00 FL *88.00 FL *32.00 FL *55.00 FL *55.00 FL *55.00 FL
	*FRONT RIM SHAFT *FRONT RIM BEARING *FRONT BRAKE DISC *HANDLE -BAR *HANDLE -BAR END *SET HAND GRIP *HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Necessary Bent Bent Scratched Necessary Bent Broken Repair O/S Broken	38.00 FL 155.00 FL 88.00 FL 32.00 FL 55.00 FL 68.00 FL 55.00 FL 32.00 FL	*38.00 FL *155.00 FL *88.00 FL *32.00 FL *55.00 FL *55.00 FL *55.00 FL
	*FRONT BRAKE DISC *HANDLE -BAR *HANDLE -BAR END *SET HAND GRIP *HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Bent Bent Scratched Necessary Bent Broken Repair O/S Broken	155.00 FL 88.00 FL 32.00 FL 55.00 FL 68.00 FL 55.00 FL 32.00 FL	*155.00 FL *88.00 FL *32.00 FL *55.00 FL *55.00 FL *55.00 FL
	*FRONT BRAKE DISC *HANDLE -BAR *HANDLE -BAR END *SET HAND GRIP *HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Bent Bent Scratched Necessary Bent Broken Repair O/S Broken	88.00 FL 32.00 FL 55.00 FL 68.00 FL 55.00 FL 32.00 FL	*88.00 FL *32.00 FL *55.00 FL *68.00 FL *55.00 FL *- FL
	*HANDLE -BAR END *SET HAND GRIP *HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Scratched Necessary Bent Broken Repair O/S Broken	32.00 FL 55.00 FL 68.00 FL 55.00 FL 32.00 FL	*32.00 FL *55.00 FL *68.00 FL *55.00 FL *- FL
	*SET HAND GRIP *HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Necessary Bent Broken Repair O/S Broken	55.00 FL 68.00 FL 55.00 FL 32.00 FL	*55.00 FL *68.00 FL *55.00 FL *-FL
	*HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Bent Broken Repair O/S Broken	68.00 FL 55.00 FL 32.00 FL	*68.00 FL *55.00 FL *-FL
	*HANDLE -BAR INNER BRACKET *SIDE MIRROR -R/H *BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Bent Broken Repair O/S Broken	55.00 FL 32.00 FL	*55.00 FL *- FL
	*BRAKE LEVER *FRONT SIGNALS *HEADLAMP	Repair O/S Broken	32.00 FL	*-FL
	*BRAKE LEVER *FRONT SIGNALS *HEADLAMP	O/S Broken		
	*FRONT SIGNALS *HEADLAMP	O/S Broken	180.00 FL	405.000
	*HEADLAMP	Canalisad		*90.00 FL
	* 1000 (1000 1000 1000 1000 1000 1000 10	Cracked	185.00 FL	*185.00 FL
		Not Necessary	385.00 FL	*-FL
	*SET FAIRING ASSY	Cracked	495.00 FL	*495.00 FL
	*FRONT FOOTREST BRACKET	Bent	65.00 FL	*65.00 FL
	*FRONT FOOTREST RUBBER	Torn	35.00 FL	*35.00 FL
	*BRAKE PEDAL	Repair	42.00 FL	*-FL
	*REAR FOOTREST	Serviceable	40.00 FL	*-FL
	*REAR FOOTREST BRACKET	Serviceable	78.00 FL	*-FL
	*EXHAUST ASSY	Dented	485.00 FL	*485.00 FL
	*EXHAUST PROTECTOR -CHROME REAR	Scratched	60.00 FL	*60.00 FL
		Scratched	55.00 FL	*55.00 FL
	A TO CONTRACT OF THE PROPERTY	Cut	50.00 FL	*50.00 FL
	*SEAT		235.00 FL	*-FL
	*SET REAR ABSORBER		350.00 FL	*-FL
	*REAR TAILLAMP	111111111111111111111111111111111111111	135.00 FL	*- FL
	*REAR FENDER		120.00 FL	*-FL
	*BASKET	Cracked	50.00 FL	*50.00 FL
		Cracked	120.00 FL	*120.00 FL
		Cracked	95.00 FL	*95.00 FL
	- 1 dark (1 a) (1 a) (1 a) (1 a) (1 a) (1 a)		180.00 FL	*180.00 FL
		Carlo	70.00 FL	*70.00 FL
			28.00 FS	*10.00 FS
				*-F\$
				*-FS
		200		*90.00 FS
1				*-FS
hise part. S=Sp				
		Sub Total (S\$)	5,507.00	3,776.00
	- List Item Discount on L Item		518.30	367.60
		Total Parts (S\$)	4,988.70	3,408.40
	se part. S∞Sp	*BRAKE PEDAL *REAR FOOTREST *REAR FOOTREST BRACKET *EXHAUST ASSY *EXHAUST PROTECTOR -CHROME REAR *EXHAUST PROTECTOR -FRONT *REAR HANDLE *SEAT *SET REAR ABSORBER *REAR TAILLAMP *REAR FENDER *BASKET *FRONT INNER COVER *HORN COVER INNER *CDI UNTIL *FRONT FAIRING BRACKET *SET NUMBER PLATE *FORK OILS *FORK OIL SEALS *SET STEERING CONE *FRONT TYRE se part. S=SpcNett. L=ListItemDisc List Item Discount on L Item	*BRAKE PEDAL *REAR FOOTREST *REAR FOOTREST BRACKET *EXHAUST ASSY *EXHAUST PROTECTOR -CHROME REAR *EXHAUST PROTECTOR -FRONT *REAR HANDLE *SEAT *SET REAR ABSORBER *REAR TAILLAMP *REAR FENDER *BASKET *FRONT INNER COVER *Cracked *CDI UNTIL *FRONT FAIRING BRACKET *SET NUMBER PLATE *FORK OILS *SET STEERING CONE *FRONT TYRE *SET SEPONENT. L=ListHemDisc *SET VERNER Serviceable *SET SERVICE SERVICE *SET NUMBER CONE *SET NUMBER PLATE *SET SERVICE SERVICE *SET SET SERVICE SERVICE *SET SET SERVICE *SET SERVICE SERVICE *SET SET SERVICE *SET SET SERVICE *SET SET SERVICE *SET SET SERVICE *SET SERVICE *SET SERVICE *SET SERVICE *SET SERVICE *SET SERVICE *SET SET SERVICE *SET SET SET SET SET SERVICE *SET SET SET SET SET SET SET SET SET SET	*BRAKE PEDAL Repair 42.00 FL *REAR FOOTREST Serviceable 40.00 FL *REAR FOOTREST BRACKET Serviceable 78.00 FL *EXHAUST ASSY Dented 485.00 FL *EXHAUST PROTECTOR -CHROME REAR Scratched 60.00 FL *EXHAUST PROTECTOR -FRONT Scratched 55.00 FL *REAR HANDLE Cut 50.00 FL *SEAT Repair 235.00 FL *SEAT Repair 235.00 FL *SEAT REAR ABSORBER Not Necessary 350.00 FL *REAR TAILLAMP Not Necessary 135.00 FL *BASKET Cracked 50.00 FL *FRONT INNER COVER Cracked 120.00 FL *HORN COVER INNER Cracked 95.00 FL *CDI UNTIL Damaged 180.00 FL *FRONT FAIRING BRACKET Bent 70.00 FL *SET NUMBER PLATE Bent 228.00 FS *FORK OILS Not Necessary 30.00 FS *FORK OILS Not Necessary 90.00 FS *SET STEERING CONE Necessary 90.00 FS *SET STEERING CONE Necessary 90.00 FS *FRONT TYRE Serviceable 120.00 FS *FRONT TYRE Serviceable 120.00 FS *FORN TYRE Serviceable 120.00 FS *SET STEERING CONE Necessary 90.00 FS *FORN TYRE Serviceable 120.00 FS *SET STEERING CONE Necessary 90.00 FS *SET STEERING CONE NECESTARY 90.00 FS *SET STEERING CONE NECESTARY 90.00 FS *SE

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	380.00	250.00
4	TO REPAIR BODY FRAME	New	350.00	200.00
	Gross Labou	Gross Labour Cost (S\$)		485.00
_	Report was unsubmitted during			

< END OF ESTIMATES >