

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Thivagaran Sridaran

Accident Date : 12-Jun-19

Vehicle No : FBK 1731 K

Vehicle Model : Yamaha Jupiter

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
2	Front fork tube assy	\$ 640.00 ?
1	Front wheel rim	\$ 280.00 ?
1	Fork under bracket	\$ 185.00 ?
1	Front rim shaft	\$ 45.00 ?
1	Front rim bearing	\$ 38.00 ?
1	Front brake disc	\$ 155.00 ?
1	Handle-bar	\$ 88.00 —
1	Handle-bar end	\$ 32.00 —
1	Hand grip (1 set)	\$ 55.00 —
1	Handle-bar inner bracket	\$ 68.00 ?
1	Side mirror -R/H	\$ 55.00 —
1	Brake lever	\$ 32.00 x
2	Front signals	\$ 180.00 120
1	Headlamp	\$ 185.00 —
1	Meter assy	\$ 385.00 ?
1	Fairing assy (1 set)	\$ 495.00 —
1	Front footrest bracket	\$ 65.00 —
1	Front footrest rubber	\$ 35.00 —
1	Brake pedal	\$ 42.00 x
1	Rear footrest	\$ 40.00 x
1	Rear footrest bracket	\$ 78.00 x
1	Exhaust assy	\$ 485.00 —
1	Exhaust protector - chrome rear	\$ 60.00 —
1	Exhaust protector- front	\$ 55.00 —
1	Rear handle	\$ 50.00 —
1	Seat	\$ 235.00 x
1	Rear absorber (1 set)	\$ 350.00 x
1	Rear taillamp	\$ 135.00 x
1	Rear fender	\$ 120.00 x
1	Basket	\$ 50.00 —
		\$ 4,718.00
	Less 10%	\$ 471.80
		\$ 4,246.20

c/f: \$ 4,246.20

Special Nett Items

1	Number plate (1 set)	\$ <i>3el</i>	28.00	/o
2	Fork oils	\$	30.00	7
2	Fork oil seals	\$	56.00	7
1	Steering cone (1 set)	\$	90.00	7
1	Front tyre	\$ <i>en</i>	120.00	x
		\$	324.00	

S/No. **Labour**

1	To provide towing service.	\$ <i>35</i>	50.00	
2	To check wiring and reset headlamp focusing	\$ <i>11</i>	80.00	x
3	To provide labour.	\$ <i>250</i>	380.00	
4	To repair body frame.	\$ <i>300?</i>	350.00	
		\$	860.00	

Grand Total **\$ 5,430.20**



EROFIA MOTOR TRADING PTE LTD

Not Attend

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: