Weekend (\$

TOTAL

From:

of

Insured:

Policy No.

Claims No.

Sum Insured:

Make of Veh:

Lum Sum:

Date:

Lump Sum / I.B.I: (\$

Not Authornal Lack 2/5#18.000 9/7/19

FASTECH AUTO PTE LTD 1 Kaki Bukit Ave 6 #01-46,48,50 Autobay SINGAPORE 417883

VELUCIENO	250/1225	(dy.
QTY) SCR 6133 E	(
	PARTICULAR BOOTLID 1812-32	2 (1
1 PCS		Rodso \$2,118.30
1 PCS	BOOTLID REAR LOGO	24 \$68.00
1 PCS	BOOTLID 1160 EMBLEM	\$65.00
2 PCS	BOOTLID HINGES @\$166.00	↑↑ \$332.00 ×
1 PCS	BOOTLID INNER LOCK	\$299.08
1 PCS	BOOTLID INNER TRIM	Re/Tun \$295.43
1 SET	BOOTLID INNER TRIM CLIPS	nu \$50.00
2 PCS	BOOTLID REFLECTORS @\$420.00	(19 \$840.00
1 PCS	BOOTLID WEATHERSTRIP	Tn/ \$312.00
1 PCS	REAR BUMPER /0/0-35	17 \$1,850.00
1 PCS	REAR BUMPER LOWER DIFFUSER	√ 5 \$640.00
1 PCS	REAR BUMPER REINFORCEMENT 6/5.30	Bay \$720.00
2 PCS	REAR BUMPER SIDE HOLDERS @\$305.00	17 \$420.00X
1 PCS	REAR BUMPER TOWING COVER	70,7 \$30.00
4 PCS	REAR BUMPER PDC SENSORS @\$305.00 260 x 4 = /	040 ships \$1,220.00
1 PCS	REAR BUMPER PDC SENSORS WIRE	8VC \$313.54 CX
1 PCS	REAR BUMPER TOP GUIDE	CM \$205.00
1 PCS	REAR BUMPER LOWER GUIDE	NS \$202.00 X
1 SET	REAR BUMPER CLIPS	ner \$50.00
2 PCS	REAR BUMPER reflectors @\$115.00	£ 12 \$230.00
1 PCS	REAR END PANEL	3-50 \$1,068.00
1 PCS	REAR END PANEL TOP GARNISH	TM \$290.50
1 PCS	REAR FLOOR PANEL	L \$1,120.20X
1PCS	REAR FLOOR PANEL TOP BOARD	Su \$650.00X
1 PCS	REAR FLOOR PANEL CENTRE WELL (FIBRE)	17 \$882.00 X
2 PCS	REAR FENDERS @\$2150.00	A \$4,300.00 ×
2 PCS	REAR FENDER INNER Tring @\$320.00	17 \$640.00 ×
2 PCS	TAILLAMPS @\$680.00	, Cre \$1,360.00
1 PCS	REAR EXHAUST MUFFLER	DO/ Sef \$1,480.00
1 PCS	REAR EXHAUST HEAT SHIELD	Ser \$311.30
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00	ser \$90.00
1 PCS	CENTRE EXHAUST PIPE	\$1,880.00
1 PCS	BONNET	\$2,135.00×
1 PCS	furf LOGO	ner \$80.00
2 PCS	BONNET DAMPERS @\$170.00	\$340.00
2 PCS	BONNET HINGES @\$140.00	11 \$280.00 €

5%

1 PCS	BONNET INNER HANDLE W/CABLE	11 \$92.00 X
1 PCS	BONNET INSULATOR	1 1 \$193.00 x
1 SET	BONNET INSULATOR CLIPS	17 \$50.00 €
1 PCS	BONNET LOCK LEVEL	17 \$190.00
2 PCS	BONNET LOCK CATCHS @\$25.00	17 \$50.00X
2 PCS	BONNET MECHANISM LOCK L/R @\$266.00	11 \$532.00 %
2 PCS	BONNET RUBBER GUIDE STOPPERS @\$15.00	11 \$30.00 %
1 PCS	BONNET WEATHERSTRIP	,11 \$92.00 ×
1 PCS	FRONT BUMPER /0/55.000	DO/OL \$1,615.00
1 PCS	FRONT BUMPER INNER SPONGE	75 m \$98.00
1 PCS	FRONT BUMPER REINFORCEMENT	\$712.00X
1 PCS	FRONT BUMPER NUMBER PLATE GARNISH	Su \$110.00 X
1 PCS	FRONT BUMPER TOW COVER N/S	
2 PCS	FRONT BUMPER FOG LAMPS@\$280.00	1.2 \$35.00 × 1.2 \$560.00×
2 PCS	FRONT BUMPER SIDE HOLDERS @\$115.00	4000.000
1 SET	FRONT BUMPER CLIPS	\$230.00° ×
1 PCS	FRONT BUMPER CENTRE GRILLE O	+
2 PCS	FRONT BUMPER REINFORCEMENT BRACKETS @\$105.00	5C/ \$56.00/
1 PCS	FRONT BUMPER TOP RUBBER SEAL	\$210.000
2 PCS	FRONT GRILLES @\$180.00	SLR \$45.00
2 PCS	HEADLAMPS @\$2800.00 300	400000
2 PCS	HEADLAMP LOWER BRACKETS @\$185.00	cre \$5,600.00
1 PCS	HEADLAMP NOZZLE N/S	11 \$370.00X
1 PCS	HEADLAMP TOP BRACKET N/S	11 \$180.00 X
1 PCS	FRONT SUPPORT PANEL	\$100.00
1 PCS	ENGINE TOP COVER	\$027.00
1 PCS	AIR CLEANER BOX	4200.00
2 PCS	ENGINE MOUNTINGS L/R @\$350.00	11 \$766.50 ★ 11 \$700.00 ★
1 PCS	FRONT AIR CON CONDENSER AIR GUIDE ASSY	4700.005
1 PCS	AIR CON CONDENSER	17 \$199.20X
1 PCS	AIR CON SUCTION HOSE	17 \$1,220.00
1 PCS	AIR CON DISCHARGE HOSE	17 \$295.00
1 PCS	AIR CON TEMPERATURE SENSOR	\$230.000
1 PCS	RADIATOR	\$155.00%
1 PCS	RADIATOR AUXILLIARY FAN ASSY	17 \$922.00 X
1 PCS	RADIATOR BY PASS HOSE	\$1,000.00
1 PCS	RADIATOR LOWER HOSE	\$32.00
1 PCS	RADIATOR TOP HOSE	\$122.50 💸
2 PCS	FRONT FENDERS @\$919.00	\$133.50
2 PCS	FRONT FENDER INNER SHIELDS @\$211.30	17 \$1,838.00 X
1 PCS	FRONT OIL COOLING PIPE	\$422.00 X
2 PCS	FRONT HEADRESTS @\$650.00	\$266.30 \(\)
2 PCS		\$7.300.00
2 000	FRONT SAFETY BELT BUCKLES @\$290.00	1 . /
2 PCS	FRONT SAFETY BELT BUCKLES @\$290.00 FRONT HEADREST REPAIR KITS @\$155.00	Acul \$580.00 \$310.00 X

19760.8f 18772.97

me a	200	5.25
407	36.4	77

S.NETT	401,000.20	
REAR LICENCE PLATE W/HOLDER	sen	\$100.00 YO
REAR END PANEL SEALANT	ren	\$80.00 50
REAR EXHAUST CHROME	11	
REAR FLOOR PANEL CENTRE WELL SEALANT	11	
FRONT LICENCE PLATE W/HOLDER	sey	
RADIATOR COOLANT	11	\$80.00 ×
LABOUR CHRAGES:		
TO CHECK WIRING		\$100.00 3 0
TO DISMENTLE & REPLACING PDC SENSOR		\$100.00 52
TO DISMENTLE & REFIX BOOTLID MECHANISM		\$180.00 80
TO DISMENTLE & REPLACING REAR EXHAUST		\$380.00/0/2
TOWING CHARGE KING ROLLER	11	\$180.00 ×
TO REPROGRAMME & CLEAR FAULT CODE	, ,	
TO MOUNT VEHICLE ON CAR O-LINER	1.0	\$200.00/80
TO DISMENTLE AIR CON ASSY, VACUUM AND CHARGE IN GAS	17	\$380.00 ×
TO DISMENTLE & REFIX SEAT, CUSHION, UPHOLSTREY	11	4100.00 51
TO SPRAY RUST PROOFING		\$180.00 /00
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED		\$180.00 A
& REPLACING PARTS	,	\$3,800.00/500
TO PUTTY & SPRAY PAINTING	5	\$2,800.00 (SU)
TOTAL		61,125.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 PCS 1 PCS 1 PCS 1 PCS 1 PCS 1 BOT

22572.93

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	61431
Vehicle No.:	SCR6133E
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2019
Vehicle Make:	B.M.W.
Vehicle Model:	116D 5DR HATCHBACK DSC LED
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	32459373B37D15A
Chassis No.:	WBA1V720X0V250048
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,855.00
Original Registration Date:	27 Nov 2015
First Registration Date:	27 Nov 2015
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$10,397.00 1198
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Nov 2025
PARF Rebate Amount: Intended COE Rebate Details	\$7,797.00
COE Expiry Date:	26 Nov 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$59,200.00
COE Rebate Amount:	\$37,772.00
Total Rebate Amount:	\$45,569.00

The information contained herein is correct as at 09 Jul 2019

OK

