

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X

Kanchana



Final Report

Estimate No. :
Date Estimated : **09/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Low Siow Tiong
38 Upper Boon Keng Road
#23-618

- ACCOUNT -
AIG ASIA PACIFIC INSURANCE
78 SHENTON WAY
#08-16 CHARTIS BUILDING
SINGAPORE 079120

Singapore 382003

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ4609Z	GA69247	28/11/2014	428IA GC	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments including to remove and install body parts in order to carry out painting job	850.00	0	850.00 ✓
To respray front bumper	934.00	0	934.00 ✓
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0	150.00 ✓
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00	0	150.00 ✓
Sundries.	80.00	0	80.00 ✓
# To supply front Emboss number plate.	83.00	0	83.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# LICENCE PLATE BASE ECE	69.25	1	0	69.25 ✓
FRT BUMPER PANEL PRIMED (SRA)	1,078.65	1	0	1,078.65 ✓
SET MOUNTING PDC/PMA SENSOR FRT	75.30	1	0	75.30 ✓
# PLAQUE 82MM	71.25	1	0	71.25 ✓
(DG/SL) ADHESIVE SET K6	53.05	1	0	53.05 ✓
#				

SUPPLEMENTARY ITEMS

DATE	WORKING DAYS
Rasul LKK 20/8/19	3

Total Labour :	2,247.00
Total Parts :	1,347.50
Total Repair Costs less Excess:	3,594.50
GST @7%:	251.62
Grand Total :	3,846.12

CONFIRMED DATE
PLEASE FINALISE

LOSS OF USE = \$120 X 3 DAYS
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. :
Date Estimated : 09/07/2019
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Low Siow Tiong
38 Upper Boon Keng Road
#23-618

Singapore 382003

- ACCOUNT -

AIG ASIA PACIFIC INSURANCE
78 SHENTON WAY
#08-16 CHARTIS BUILDING
SINGAPORE 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ4609Z	GA69247	28/11/2014	428IA GC	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			
# To supply front Emboss number plate. <i>lt ✓</i>	83.00		0	83.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLAQUE 82MM	71.25	1	0	71.25
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	83.00
Total Parts :	71.25
Total Repair Costs less Excess:	154.25

- arrange rental car from BEW

23/07 @ 10am

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

09 JUL 2019

ESTIMATE

Estimate No. : b1 51884	Page No. : 1 of 4
Date Estimated : 09/07/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Low Siow Tiong 38 Upper Boon Keng Road #23-618 Singapore 382003	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ4609Z	GA69247	28/11/2014	428IA GC	0

DESCRIPTION	VALUE
To replace front bumper and attachments.	850 1,275.00
Painting front bumper.	934 1,088.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
Sundries.	? 80.00
Total Labour 1:	2,747.00

DESCRIPTION	QTY	PRIC	VALUE
LICENCE PLATE BASE ECE de- ? crn	1	69.25	69.25
FRT BUMPER PANEL PRIMED (SRA) ? crn	1	1,078.65	1,078.65
SET MOUNTING PDC/PMA SENSOR FRT ? crn	1	75.30	75.30
FRT LH GRILLE (LUXURY) ? x 500	1	128.60	128.60
FRT RH GRILLE (LUXURY) ?	1	128.60	128.60
(DG/SL) ADHESIVE SET K6 ? crn	1	53.05	53.05

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	Total Parts : 1,533.45
--	------------------------

Date & Time: 23/07/19 @ 1510 Surveyor's Name: RASUL Surveyor's Tel: 90060068 Authorised Date: 3 days Surveyor's Email:	Claim No.: Excess \$: Sign: Authorised Yes / No: Time: RESURVEYOR Yes / No PML Yes / No	Labour 1 : 2,747.00 Parts : 1,533.45 Labour 2 : 0.00 Excess : 0.00 Total GST @ 7% : 299.63 Grand Total : 4,580.08
--	---	--

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **