

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

09 JUL 2019

E S T I M A T E

Estimate No. : b1 51884
Date Estimated : 09/07/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Low Siow Tiong
38 Upper Boon Keng Road
#23-618

Singapore 382003

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ4609Z	GA69247	28/11/2014	428IA GC	0

DESCRIPTION

To replace front bumper and attachments.

VALUE

850 1,275.00

Painting front bumper.

934 1,038.00

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: 2,747.00

DESCRIPTION

LICENCE PLATE BASE ECE de- ?
FRT BUMPER PANEL PRIMED (SRA) ?
SET MOUNTING PDC/PMA SENSOR FRT ?
FRT LH GRILLE (LUXURY) ?
FRT RH GRILLE (LUXURY) ?
(DG/SL) ADHESIVE SET K6 ?

QTY	PRIC	VALUE
1	69.25	69.25
1	1,078.65	1,078.65
1	75.30	75.30
1	128.60	128.60
1	128.60	128.60
1	53.05	53.05

Total Parts : 1,533.45

Claims OD / Ord Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 23/07/19 @ 15:10 Excess S\$

Survivor's Name Rasul Sign

Survivor's Tel 90060018 Authorised Yes / No

Authorised Date Time

RESUME FOR S PHOIC BY SURVEYOR Yes / No PML Yes / No

Survivor's Email 3 days

Labour 1	:	2,747.00
Parts	:	1,533.45
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	299.63
Grand Total	:	4,580.08

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **