



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SKT9812D

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 28/06/2019

TP VEH REG NO : SKT9812D

ESTIMATE

NO : QUOT201907-000029(00)

DATE : 08/07/2019

POLICY NO : 999995580

VEH REG NO : GBJ2923Y

MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR

CHASSIS NO : WDF44760323566325

ENGINE NO : 65195034991890

REG. DATE : 2019

05059.90

Estimate Repair Cost to Vehicle No : GBJ2923Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Tailgate	1	2,105.00	2,105.00
2 Tailgate weathstrip	1	191.00	191.00
3 Tailgate lock	1	222.00	222.00
4 Tailgate centre inner trim	1	65.00	65.00
5 Tailgate center logo	1	84.00	84.00
6 Tailgate VITO emblem	1	49.00	49.00
7 Tailgate C&C emblem	1	38.00	38.00
8 Tailgate 114 CDI emblem	1	58.00	58.00
9 Rear end panel (outer)	1	380.00	380.00
10 Taillamp assy - LH	1	330.00	330.00
11 Taillamp lower garnish LH/RH	2	67.00	134.00
Rear bumper (deformed) \$1,065.00 - Bu			3,656.00
reinforcement \$290 - Bu			365.60
Less 10%			3,290.40
SPECIAL NET			
12 Rear windscreen sealant	1	60.00	60.00
13 Rear bumper reverse sensor (set)	1	380.00	380.00
14 Rear number plate	1	40.00	40.00
15 Tailgate "70km/h" sticker	1	25.00	25.00
16 Tailgate "6pax" sticker	1	25.00	25.00
			530.00
LABOUR			
17 To remove and refit rear windscreen glass	1	120.00	120.00
18 To transfer damage tailgate interior mechanism to new tailgate	1	150.00	150.00
19 To panel beat and straighten rear chassis frame, rear floorboard panel, to cut and weld rear end panel, including replacement of parts and align where necessary action, to refit and adjust the same	1	1,000.00	1,000.00
20 To putty and spray paint on affected areas	1	800.00	800.00
21 To apply rust-proofing on replaced and repaired panels (end panel)	1	80.00	80.00
22 To supply artwork and paste advertisement on tailgate	1	500.00	500.00
(Bill)			2,650.00

11440



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SKT9812D
CLAIM TYPE : THIRD PARTY
TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD
ACCIDENT DATE : 28/06/2019
TP VEH REG NO : SKT9812D

ESTIMATE

NO : QUOT201907-000029(00)
DATE : 08/07/2019
POLICY NO : 999995580
VEH REG NO : GBJ2923Y
MAKE/MODEL : MERCEDES BENZ VITO 114 CDI
PANEL VAN LONG AT ABS 5DR
CHASSIS NO : WDF44760323566325
ENGINE NO : 65195034991890
REG. DATE : 2019

Estimate Repair Cost to Vehicle No : GBJ2923Y

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 6,470.40
		ADD GST @ 7%	452.93
		GRAND TOTAL	S\$ 6,923.33

SINGAPORE DOLLAR SIX THOUSAND NINE HUNDRED TWENTY-THREE AND CENTS THIRTY-THREE ONLY

5
\$ 5,069.90
7% 354.89
\$ 5,424.79

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

**PRINT LAB PTE LTD**

25 Ubi Road 4 #01-01 Weltech Building Singapore 408621
Tel : 6749 0526 Fax : 6749 0683 Email: info@printlab.com.sg

Co. Reg No. 200711847C
GST No. 200711847-C

Sold To:

Tong Luck Auto Pte Ltd
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722

Attn: Terence Tan

Tel: 6250 0088

TAX INVOICE

Invoice No : IV-113822

Date : 16-Jul-19

Reference No.	Customer P.O. No.	Payment Terms	Due Date	Job Issue By
J00129771		0	16/07/19	Terence
Quantity	Description		Unit Price	Total Amount
1	RE: GBJ2923Y_Mercedes Benz Vito Vito_GBJ2923Y_ACCIDENT Rear Door Subject : L_LGG_G_24/7 HOTLINE—CUT STICKER Material : Permanent Solvent Sticker Finishing :		280.00	280.00

Please note that any overdue payment/s will be listed in the Singapore Commercial Credit Bureau (SCCB) records and this record may be assessed by financial institutions and other approving Credit companies.

*** BANK Information**

Name: PRINT LAB PTE LTD
Bank Name: Standard Chartered Bank, Singapore Branch
Bank Code: 7144
Branch Code: 001
Account No.: 0119156805
Swift code: SCBLSGSG
Address: 6 Battery Road Singapore 049909

Subtotal	280.00
GST@7%	19.60
Total (SGD)	299.60

Received, checked & accepted by

E. & O.E

This is a computer generated form.
No signature is required.

Cheques should be crossed and made payable to PRINT LAB PTE LTD
All goods sold are not refundable. Interest at 1.5% per month will charged on unpaid invoices.