NEW YORK		REF:	CIT	R01901	28cc	NC	\$5	recial Latences	n	7
ST REC. BY:		_	ASS	GNMEN	T (On	ice)			. deli-	
From (Person):	Kamaliah Ke	mic	of	SPF				Date/Tune	20/6/2015	1
Parimated Coal	(*)		11551		Bill to: _					
OD/TT/WS	TTP RES ! OD I	UES / EV	AINV	/MV / CS			Incorpor	4-		
To Inspect Vehicle No: TMB AA90					-	-	1000	-		
100	n/s				-		16			_
of		H					Tolog) अभन्नड	Novel -	
Policy No. MHASPFO6COCOSOIST									- CAT	
Sum Inqued:					Exc	c33		DOA	PIOCH F	
Make of Vehi			-					, , , , , , ,	11/	
CA / REV / REP. / REV 24 FORS								H.O.D. E	odorsement:	
Date/Time Person Contacted: _					Vehicle INLOUT					
Date/Time	Action/Instruction	on E) 8	ctimate						
	JMB7793		0073980		0.87					<u> </u>
						400	- N		-1	
									-/(-/	-
								1	1/	1
2 5								IVS	1)
					- water			00		
	-			-			-			

On 25 May 2019, sometime before 4.33 p.m., the Involved Party (GBB5739K) was travelling along Sheares Avenue towards Central Boulevard and at the junction of Marina Boulevard, B1 saw is red light and B1 changed to lower gear but the clutch did not release back. He also try to brake but the brake also faulty. B1 passed the junction and A1 came from his right side. A1 front collided into his right side.

Vehicles to be inspected: GBB5739K - Involved Party

10 In-Charge: 10 Afig

Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, FBG6864Z (TP/IP/12743/2019)

g) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Trailer, BJQ6562 (TP/IP/12743/2019)

On 04 March 2019 (Monday) at or about 7.54 p.m, the Deceased was riding his motor cycle along BKE towards the direction of Woodlands, on Lane 1 of 3 lanes, when he lost control of the vehicle and skidded. The Deceased then fell underneath the moving trailer which was travelling abreast on Lane 2. As a result, the Deceased's was caught in between the 2 rear right wheels of the trailer and he was dragged for a short distance before the trailer came to a stop. The Deceased suffered fatal injuries and was pronounced dead at scene by SCDF Paramedic at 8.22 p.m on the same day.

Vehicles to be inspected: FBG6864Z - Rider (Deceased) BJQ6562 - Involved Party

10 In-Charge: SIO Saleha

h) Case IAFP-IB-20190614 - Mechanical Inspection of Motor Car, SLT9282X (TP/IP/22305/2019)

On 1 April 2019 at about 9.58pm, motor car was travelling along lane 1 of the 2 lanes road of Hougang Ave 8 towards Hougang Ave 10, when its front left portion collided onto a pedestrian. The pedestrian was crossing the road from the left to right side of the motor car. The pedestrian was conveyed to Tan Tock Seng Hospital and was pronounced dead by Dr Su Jun, on 2 April 2019 at 4.38pm.

Vehicles to be inspected: SLT9282X - Defendant

IO In-Charge: SIO Saleha

Case IAFP-IB-20190614 - Mechanical Inspection of Motorcycle, JMB7792 (TP/IP/23475/2019)

Case IAFP-IB-20190614 - Mechanical Inspection of Pickup, GX820R (TP/IP/23475/2019)

On 07 April 2019 at or about 8.33 a.m., a case of Road Traffic Accident had occurred along Mandai Ave towards Yishun Ave 1, L/P 70 involving one Malaysian motor cycle, JMB7792 and one Singapore motor pick up. The driver of the motor pick up informed that he was travelling along Mandai Ave towards Yishun Ave 1 on the centre of 3 lanes road and his vehicle came to a stop due to heavy traffic ahead. As the driver was stationary, approximately 5-6 seconds later, he suddenly felt an impact from the rear and realized that the rider (deceased) had collided onto his vehicle right rear portion. As a result of the collision, the rider suffered severe head injuries and multiple fractures on his body and was conveyed to Khoo Teck Phuat Hospital by ambulance. The rider succumbed to his injuries and was pronounced dead on 10 April 2019 at 4.05pm by Dr Stacey Goh,

Vehicles to be inspected: JMB7792 - Rider (Deceased) GX820R - Involved Party

10 In-Charge: SIO Saleha